r Mour	Ntain Valley		Visual	I Si	te Ins	specti	on Repo	ort		
Project Name H-600 Pipeline Spread G			AFE 124300137		Spread	H-600 Pipeline Spread G				
Contractor Precision		I			Report #	6671				
Inspect	tor Clinton Ba	anks					Date/Time	8/2 [.]	1/2018 3:46	6 AM
Permit # TBD		Inspection Type VA SWPP		A SWPP		Station Begin 11		11552+77	1552+77	
State	VA	Inspection Area Full			Station End 11436+00					
County	County Craig		Ground W		Vet		Temperature (ºF		ture (ºF)	740.00
Municipality	N/A		Weath	er Cl	oudy		Rain Gauge (in)			0.05
GPS Location	37.32674789	15279, -80.426	2657184903			Rain Ac	cumulation Time (days)		e (days)	1.00
1. Are the appr	oved (stampe	ed) E&S Plan	and PCSM Plan present on site?							Yes
			the limits of distu ermitting Coordin					?		No
	Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes				
4. E&S BMPs is required.)	(List BMPs an	d note if insta	illed and maintain	ned as	per the	e plan. If c	corrective acti	ion i	s needed,	a picture
E&S BMPs		Complianc Level	e		Corrective Action			Corrective Time Frame		
Silt Fence (Filter	Fabric Fence)		Problem Area		See Co	omments			24 Hou	irs
Silt Fence (Filter	Fabric Fence)		Problem Area						24 Hou	irs
Silt Fence (Filter	Fabric Fence)		Problem Area						24 Hou	irs
Silt Fence (Filter	Fabric Fence)		Problem Area						24 Hou	irs
Sump Pit			Problem Area						24 Hou	irs
Silt Fence (Filter	Fabric Fence)		Problem Area						24 Hou	irs
Silt Fence (Filter Fabric Fence)			Problem Area						24 Hou	irs
Silt Fence (Filter Fabric Fence)			Problem Area						24 Hou	irs
Silt Fence (Filter	Fabric Fence)		Problem Area						24 Hou	irs
5. Site Conditi	ions									
beyond defined	limits of distu	irbance resulti	iment, gravel, oil, ing from earth dis ironmental Permi	turba	nce activ	vity or ine	-		-	No
Have inactive di	isturbed area	s (stockpiles,	final grade) been	stabil	ized per	r state req	uirements?			Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? Yes							Yes			
Has a new slip/s	las a new slip/slide been observed? (If yes, complete Slide Report Form) No									

AFE 124300137	Date/Time 8/21/20)18 3:46 AM	Report #	6671			
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a							
picture is required.)							
PCSM BMPs	Compliance Level	Corrective Ac	tion	Corrective Time Frame			
7. Identify all remedial measures that have	been taken since the r	previous inspection was	conducted.				
Identify all remedial measures that have been taken since the previous inspection was conducted.							
Comments (Reference above questions as appropriate.)							
Conducted Weekly VA SWPP. Bridge at station 11519+16 Stream S-PP4 Sediment off ROW between Sock and P-1 under Bridge, see picture. Station 11513+27 Sock is overwhelmed with Top Soil, see picture. Sump at Station 11513+27 same area as Sock is low on one side allowing the Sump to overflow and undermine P-1 see picture. Station 11507+05 P-1 Silt Fence is Tom (Hole) see picture. Station 11506+00 P-1 Silt Fence is undermine need to be key in, see picture. Station 11502+02 P-1 Silt Fence is undermine need to be key in next to Plunge Poole, see picture. Station 11502+02 P-1 Silt Fence undermine allowing Sediment off ROW in same area as Plunge Pool, see picture. Station 11502+02 P-1 Silt Fence undermine allowing Sediment off ROW in same area as Plunge Pool, see picture. Station 11502+02 P-1 Silt Fence undermine need to be key in, see picture. Went from Station 11552+77 M.P. 218.5 To Station 11436+00 M.P. 216.5							
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.							

AFE 12430013	7	Date/Time 8/21/201	8 3:46 AM	Report # 6671
		Pictures		· ·
Onto: Time Tie work commentation (1994) Annuit Benning (1994) Annuit Benning (1994) Horzon Angle of 1997 Bridge at Station (1997) 19	2012 or 10 42 EDT the present of 2014 4 Seamon of 2014 Company of 2014	Ally Ally But Ally Al	After a pice are pice for a calculation of a pice of a p	
GPS Location	37.3284780839806, -80.422778		ocation 37.3277251	795282, -80.4244403076176
Description	Sediment off ROW between P-1 Station 11519+16 Stream S-		ription Sock overwi	nelmed with Top Soil Station
Alfride 22471 Datum 105235 Datum 10525 Datum 2002 Datum 105 Datum	BE LIDU INITIA TIAN		8 Time Tuo Aug 21, 2018, 09 25, 47 507 min 207, 2018, 1000 (2457) min 2020 (2188) - (2000 (2000)) min 2020 (2188) min 2020 (2000) min 2020 (20	
GPS Location	37.3275946313863, -80.424661	2545852 GPS Lo	ocation 37.3275805	916985, -80.4245341849331
Description	P-1Silt Fence overwhelmed Sed ROW Station 11513+27 (Same area a	Deer	Water Bar lo	w on one side Station 11513+27
Sprite & Hunse Hans Jenne 2000 Spritten & State 2000 Julian Website 2001 Julian Websit	Ger Zelozanius, musi	Allin	S himoshipo kang 21 colle 94 sepelet iam elboration en 21 colle 94 sepelet iam elboration elboration elboration in visation in visation elboration elboration elboration intervando elboration interva	
GPS Location	37.3266693950047, -80.426329	6724115 GPS Lo	ocation 37.32660110	663129, -80.4265571572636
Description	Torn P-1 Silt Fence Station 1150 Plunge Pool		P-1 Silt Fend	ce undermine Station 11506+00 s Plunge Pool