Moun	Va	alley		Visua	l Sit	te In:	specti	on Repo	ort			
Project Name H-600 Pipeline Spread G		AFE 124300137)137	Spread	H-60	00 Pipeline S	pread G				
Contractor Precision			·			Report #	1634					
Inspector Garrett Barclay						Date/Time	Time 5/10/2018 3:3		7 PM			
Permit #	Permit # TBD		Inspection Type Wee		eekly		Station Begin 10920+00					
State	VA			Inspection Are	ea Fu	ıll		Station End 1162		11620+00	520+00	
County	Giles	i		Grour	nd Dr	Dry		Temperati		ture (ºF)	73.00	
Municipality	nicipality N/A		Weather		Cloudy		Rain Gauge (uge (in)	0.00		
GPS Location	37.3 ²	10261232	8132, -80.5156	6166386609			Rain Ac	ccumulation Time (days			1.00	
1. Are the appro	oved	(stampe	d) E&S Plan a	and PCSM Plan p	oresei	nt on sit	e?				Yes	
					ne limits of disturbance shown on the plan drawings? rmitting Coordinator and explain in comments.)					No		
		•		e construction no ntal Permitting Co			•			et being	Yes	
E&S BMPs (is required.)	List E	BMPs and	d note if insta	lled and maintair	ned as	per the	e plan. If o	corrective act	on i	s needed,	a pictu	
E&S BMPs			Complianc Level	е		Corrective Action			Corrective Time Fram			
Compost Filter Sock			Acceptable		N/A			See Co	See Comments			
Erosion Control Blanket			Acceptable		N/A	N/A			See Comments			
Rock Construction Entrance		Acceptable		N/A				See Comments				
Silt Fence (Filter Fabric Fence)		Acceptable		N/A				See Comment				
Vegetative Stabilization (Temporary)			Acceptable		N/A			See Comments				
Waterbar				Acceptable		N/A				See Co	omments	
5. Site Condition	ons											
ls an unauthorize beyond defined l	ed di	of distur	bance resulti	iment, gravel, oil, ng from earth dis ironmental Permi	turba	nce acti	vity or ine				No	
ls an unauthorize beyond defined I a photo and imm	ed di limits nedia	of distur	bance resulti act MVP Env		turba tting (nce acti Coordin	vity or ine ator.	ffective BMP?			ı	

MVP-34 REV 0 Page 1 of 3

No

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

AFE 124300137	Date/Time 5/10/201	8 3:37 PM	Report #	1634	
6. PCSM BMPs (List BMPs and note	if installed and maintained as	per the plan. If c	orrective action is	needed, a	
picture is required.)					
PCSM BMPs	Compliance Level	Correctiv	Corrective		
	Level			Time Frame	
					
7. Identify all remedial measures tha	t have been taken since the pre	evious inspection	was conducted.		
comments (Reference above question	ons as appropriate.)				
SWPP Report Fraveled from MP 206.5 - 219.5 and insp Dbserved ECD's installed in these location All correction action peopled at this time.	pected areas of the ROW where the	ere is ground distur	bance. nd installed per pla		
No corrective action needed at this time. Crews installed RCE's @ MN-258.01 and Fop soil stockpiles have been stabilized a Erosion Control Blankets to road approa Since the last SWPP the crews have bee stabilization to soil stock piles and installing the control of the crews have bee the control of the crews have been control of the crews and installing the crews the crews are the crews and the crews are the crews and the crews are the crews are the crews are the crews are the crews and the crews are the crew are the crews are the crews are the crews are the crew are	d the road approach @ Doe Creek and signed for identification och @ MP 219.5 on clearing grade and installing RC	MP 206.7 E's , installing eros			
crews installed RCE's @ MN-258.01 and op soil stockpiles have been stabilized a Erosion Control Blankets to road approadince the last SWPP the crews have bee tabilization to soil stock piles and installing the crews have been tabilization to soil stock piles and installing the crews have been tabilization to soil stock piles and installing the crews have been tabilization to soil stock piles and installing the crews have the crews have been tabilization to soil stock piles and installing the crews have the crew have the crews have the crew have the cre	d the road approach @ Doe Creek and signed for identification ich @ MP 219.5 en clearing grade and installing RC ing water bars at the end of the day	MP 206.7 E's , installing eros			
crews installed RCE's @ MN-258.01 and op soil stockpiles have been stabilized a Erosion Control Blankets to road approablince the last SWPP the crews have bee tabilization to soil stock piles and installi	d the road approach @ Doe Creek and signed for identification ich @ MP 219.5 en clearing grade and installing RC ing water bars at the end of the day	MP 206.7 E's , installing eros			
Crews installed RCE's @ MN-258.01 and Fop soil stockpiles have been stabilized a Erosion Control Blankets to road approa Since the last SWPP the crews have bee	d the road approach @ Doe Creek and signed for identification ich @ MP 219.5 en clearing grade and installing RC ing water bars at the end of the day	MP 206.7 E's , installing eros			
Crews installed RCE's @ MN-258.01 and op soil stockpiles have been stabilized a Erosion Control Blankets to road approa Since the last SWPP the crews have bee stabilization to soil stock piles and installing the crews have been the crews have been the last SWPP the crew the last SWPP the last SWPP the last SWPP the crew the last SWPP the last SWPP the last SWPP the last SWPP the crew the last SWPP the last SW	d the road approach @ Doe Creek and signed for identification ich @ MP 219.5 en clearing grade and installing RC ing water bars at the end of the day	MP 206.7 E's , installing eros			
Crews installed RCE's @ MN-258.01 and op soil stockpiles have been stabilized a Erosion Control Blankets to road approa Since the last SWPP the crews have bee tabilization to soil stock piles and installi	d the road approach @ Doe Creek and signed for identification ich @ MP 219.5 en clearing grade and installing RC ing water bars at the end of the day	MP 206.7 E's , installing eros			

MVP-34 REV 0 Page 2 of 3

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

Date/Time 5/10/2018 3:37 PM **AFE** 124300137 Report # 1634 **Pictures** GPS Location 37.3102135397841, -80.5157034751778 **GPS Location** 37.3102135397841, -80.5157034751778 Priority One Silt fence installed @ MLV 25 Priority One Silt Fence @ MLV 25 **Description** Description **GPS Location** GPS Location 37.3102135397841, -80.5157034751778 37.3102135397841, -80.5157034751778 Erosion Control Blanket @ MP 219.5 RCE, Silt Fence, Erosion Control Blanket, and Temporary Stabilization @ MP 219.5 Description Description **GPS Location** 37.3102135397841, -80.5157034751778 **GPS Location** 37.3102135397841, -80.5157034751778 Top Soil stabilization @ MP 206.5 Temporary stabilization @ MP 219.5 Description Description

MVP-34 REV 0 Page 3 of 3