| Mour Mour | ain Valley | Visual Site Inspection Report | | | | | | | | | | | |
|--|------------------|-------------------------------|-----------------|--------------------------------|-----------------------------------|-------------------|---------------------|--------------------|------------------------|----------------------------|------|--------------|--|
| Project Name H-600 Pipeline Sprea | | Spread H | | E 124300138 | | | Spread | H-600 Pipeli | ne S _l | oread H | | | |
| Contractor Precision | | | | | | • | | | Report # | 8306 | | | |
| Inspector Joe Scott | | | | | | | | | ate/Time | te/Time 9/24/2018 10:09 AM | | | |
| Permit # TBD | | | | Inspection Type VA SWPP | | | | St | Station Begin 13024+00 | | | | |
| State | VA | | Inspection Area | | Partial S | | Station E | ation End 13120+17 | | | | | |
| County | County Franklin | | | Ground | | Muddy | | | Temperature (°F) | | | 70.00 | |
| Municipality | Municipality N/A | | | Weather | | Light Rain | | | Rain Gauge (in) | | | 0.25 | |
| GPS Location 37.1268093260351, -80.111 | | | 7177867145 | Rain Accum | | mulation | ulation Time (days) | | 1.00 | | | | |
| 1. Are the approved (stamped) E&S Plan a | | | | and PCSM Plan present on site? | | | | | | | | Yes | |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | | | | | | | | | | No | | | |
| Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, and plan in the plan in the | | | | | | | | | | Yes | | | |
| is required.) | LIST | BMPs and no | te if insta | ilea and mair | itained | as per tr | ie pian. | If corre | ective acti | on is need | iea, | a picture | |
| | E&S BMPs | | | compliance Level | | Corrective Action | | | | rective e Frame | R | Date epaired | |
| Compost Filter Sock | | | Cor | nmunication | Need maintenance after rain event | | | nt 24 Hou | ırs | | | | |
| Erosion Control Blanket | | | Acc | eptable | | | | | | | | | |
| Housekeeping | | | Acc | eptable | | | | | | | | | |
| Rock Construction Entrance | | | Acc | eptable | | | | | | | | | |
| Waterbar | | | Cor | mmunication | Need maintenance after rain e | | | ain ever | nt 24 Hou | 24 Hours | | | |
| Sump Pit | | | Cor | mmunication | Need cleaned out mechanical | | | nically | 24 Hou | 24 Hours | | | |
| Silt Fence (Reinfo | rce | d Filter Fabric F | ence) Cor | mmunication | Need cl | eaned ou | t when a | ccessib | le 24 Hou | ırs | | | |
| | | | | | | | | | | | | | |
| 5. Site Condition | ons | } | | | | | | | | | | | |
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | | | | | | | | | Yes | | | | |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | | | | | | | | | Yes | | | | |
| Are slopes 3:1 a | nd | greater stabiliz | zed with a | ppropriate Bl | MPs as | per E&S | plans? | | | | | Yes | |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | | | | | | | | | | No | | | |

MVP-34 REV 0 Page 1 of 3

| AFE 124300138 | Date/Ti | me 9/24/2018 10:09 AM | Report # 8306 | | | | | | | |
|---|---------------------|---|--------------------------|------------------|--|--|--|--|--|--|
| PCSM BMPs (List BMPs and note if inspicture is required.) | stalled and ma | intained as per the plan. If corre | ective action is nee | eded, a | | | | | | |
| | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Comments (Reference above questions a Attended the MVP inspectors morning meeting | • • • • | | ı. Met with lead El a | nd discussed | | | | | | |
| Attended the MVP inspectors morning meeting activities for the day. Traveled to access road I and discussed their plans for the day. | FR-289 and rep | orted rainfall total from the rain gaug | ge. Met with Environ | mental crew | | | | | | |
| Crew members from the Bending and Lowering-in crews were assisting performing maintenance with the area from 13120+17 to 13062+00. The environmental crew was performing maintenance to ECD's from 13024+00 to 13062+00. Sumps were being | | | | | | | | | | |
| cleaned out with shovels until the ROW is dry enough for equipment to access them. No stream impacts were noted today. Extra measures were implemented to ECD's near capacity where it was possible. | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Note: It is a condition of National Pollutant maintenance program be conducted to pro | | | | | | | | | | |

MVP-34 REV 0 Page 2 of 3

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300138 Date/Time 9/24/2018 10:09 AM Report # |8306 **Pictures** 13024+00 S-G24 and S-G25 show no signs of impact GPS Location |37.1268772194508, -80.1116932277382 **GPS Location** 37.1262266580361, -80.1185583417119 No impacts were observed at S-G26 and Silt fence needs maintenance Description Description 13052+00 ECD's a **GPS Location** GPS Location 37.1261287154976, -80.1184852515162 37.1261961898181, -80.1184192021192 No impacts were observed and EIS's fish nets Secondary sock behind the j hook prevented a are still present. sediment release in this area. Description Description GPS Location 37.1261530230168, -80.1184554119409 **GPS Location** 37.1260706708181, -80.1185281668604 No sediment observed in streams S-G26 and ECD's at capacity near access road FR-290 S-G27 and stream crossing S-G26 Description Description

MVP-34 REV 0 Page 3 of 3