



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	7059
Inspector	John Brcic			Date/Time	8/28/2018 9:54 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12071+00
State	VA	Inspection Area	Partial	Station End	12198+90
County	Montgomery	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.2584174853165, -80.2982144617292			Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame
Vegetative Stabilization (Temporary)	Communication	12078+00: stabilize subsoil pile	24 Hours
Silt Fence (Filter Fabric Fence)	Communication	12076+00: repair P1 around topsoil	24 Hours
Erosion Control Blanket	Communication	12100+00: remove subsoil from curlex	24 Hours
Erosion Control Blanket	Communication	12007+00: key in curlex	24 Hours
Waterbar	Acceptable		
Housekeeping	Acceptable		
Rock Construction Entrance	Acceptable		
Sump Pit	Acceptable		
Compost Filter Sock	Acceptable		

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	8/28/2018 9:54 AM	Report #	7059
Pictures					
 <p>DIRECTION N (T) 37.25838°N 080.29796°W ACCURACY 5 m DATUM WGS84</p> <p>2018-08-28 09:24:37-04:00</p>		 <p>DIRECTION E (T) 37.25850°N 080.29729°W ACCURACY 10 m DATUM WGS84</p> <p>2018-08-28 09:58:39-04:00</p>			
GPS Location	37.2583872685556, -80.298073981032	GPS Location	37.2587421164264, -80.2959592268619		
Description	Bending pipe @ access MVP-MN-270.	Description	Pipe strung from station 12078+00 to 12082+00.		
 <p>DIRECTION SW (T) 37.25872°N 080.29599°W ACCURACY 5 m DATUM WGS84</p> <p>2018-08-28 10:03:31-04:00</p>		 <p>DIRECTION SE (T) 37.25856°N 080.29678°W ACCURACY 5 m DATUM WGS84</p> <p>2018-08-28 10:01:01-04:00</p>			
GPS Location	37.2586721694444, -80.2960052435103	GPS Location	37.2580091783706, -80.2900953157512		
Description	Spoil pile needs to be moved uphill and stabilized @ 12078+00.	Description	12076+00: repair P1 silt fence around topsoil pile, ~MP 228.55~.		
 <p>DIRECTION E (T) 37.25820°N 080.28860°W ACCURACY 5 m DATUM WGS84</p> <p>12100+00: pull spoil back off curlex and blend into ROW</p> <p>2018-08-28 10:24:39-04:00</p>		 <p>DIRECTION E (T) 37.25816°N 080.28636°W ACCURACY 10 m DATUM WGS84</p> <p>12107+00: curlex needs to be keyed in</p> <p>2018-08-28 10:37:07-04:00</p>			
GPS Location	37.2582438122828, -80.29813994661	GPS Location	37.2580813290898, -80.2981540282073		
Description	12100+00: remove spoil from erosion control blanket, MP 229.0, and blend into ROW.	Description	Erosion control blanket needs to be keyed in at station 12007+00.		