Mountain Valley				Visual Site Inspection Report									
Project Name H-600 Pipeline Sprea			eline Spread	Н	Al	FE 124300138			Spre	Spread H-600 Pipeline S		oread H	
Contractor Precision				· ·				Repo	port # 2506				
Inspector Randy Clark									Date/Ti	e/Time 5/24/2018 7:26 PM			
Permit #	Permit # TBD			Inspection Type VA SWPP					Station	ation Begin 12371+00			
State	VA			Inspection	Area	Full			Statio	Station End 13415+00			
County	Franklin			Ground		Damp			Temperature (°F)				76.00
Municipality	ty N/A			Weathe		Sunny		Rain Gauge (in)			0.80		
GPS Location	GPS Location 37.2692790790981, -80.03			2703848001		•	Rain Accı			cumulation Time (days)			4.00
1. Are the approved (stamped) E&S Plar				and PCSM Plan present on site?								Yes	
 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being 										No			
	No,	notify MV	P Environm	ental Permitting	g Coor	dinato	or and	d explain i	in comme	ents.)		_	Yes a picture
E8	E&S BMPs			Compliance Level		Corrective Action					rective Frame	R	Date epaired
Sensitive Resource	ce S	ignage	A	cceptable									
Sensitive Resource Buffer			A	cceptable									
Waterbar			A	cceptable									
Compost Filter Sock			A	cceptable									
Housekeeping			A	cceptable									
Rock Construction Entrance			A	cceptable									
5. Site Conditi	ons												
Is an unauthoriz			(such as se	ediment gravel	oil Hr	OD flu	id et	c.) occurr	ing to wat	ters	wetlands	Or	
beyond defined a photo and imn	limi	ts of distu	bance resu	Iting from earth	distur	bance	activ	ity or ine	-				No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									N/A				
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?									N/A				
Has a new slip/s	slide	been obs	served? (If	yes, complete S	Slide R	eport	Form)					No


MVP-34 REV 0 Page 1 of 3

AFE 124300138	Date	/Time 5/24/2018 7:26 PM	Report # 250	Report # 2506						
PCSM BMPs (List BMPs and note if picture is required.)	installed and	maintained as per the plan. If	f corrective action is ne	eded, a						
PCSM BMPs	Compliand Level	e Corrective Action	Corrective Time Frame	Date Repaired						
			7,000,000							
- 11(* -11										
 Identify all remedial measures that have been taken since the previous inspection was conducted. Compost filter sock and silt fencing sections have been cleared of sediment since last inspection. 										
Compost liner sock and six remaining sections have been deared of seament since last inspection.										
O		L. \								
Comments (Reference above questions as appropriate.) Spread 10 summary during this inspection period the contractor continued the installation of erosion control devices, performed										
mechanical clearing, and right of way grade between stations (12005+00 and 12015+84). All erosion control devices were found to be in working order and no environmental concerns were noted.										
J === ================================										
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a										

MVP-34 REV 0 Page 2 of 3

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.



MVP-34 REV 0 Page 3 of 3