



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H	
Contractor	Precision			Report #	14429	
Inspector	Pat Davis			Date/Time	2/28/2019 5:30 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	+0	
State	VA	Inspection Area	Partial	Station End	+0	
County	Montgomery	Ground	Muddy	Temperature (°F)	56.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00	
GPS Location	37.2356988396842, -80.2295867075028			Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Buffer		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300138	Date/Time	2/28/2019 5:30 PM	Report #	14429
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
(Summary Spread 9). Checked rain gauge in the yard MVP-PY-006 and found 0 rainfall in the raingauge. EI preformed SWPPP Inspection on the MVP-PY-006. EI observed no trash in the yard. Secondary containment's were in good condition. EI observed no fluid deposits on the stone on the either side of the bulk fuel tanks. The flagging to mark the 100 foot boundary was in place. EI found no leaky equipment. The wash rack that was clean and in good condition. No other environmental issues were noted during today's inspection. SEAP Training was not given due to no new hires. No environmental issues were noted during today's inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	2/28/2019 5:30 PM	Report #	14429
Pictures					
 <p>DIRECTION SE (T) +37.23540° -080.22971° ACCURACY 16 ft DATUM WGS84</p> <p>2019-02-28 08:37:57-05:00</p>		 <p>DIRECTION E (T) +37.23522° -080.22977° ACCURACY 16 ft DATUM WGS84</p> <p>2019-02-28 08:38:42-05:00</p>		GPS Location 37.2355921799664, -80.2296085004511	
Description MVP-PY-006_022819 condition of containment under light plant. Looking SE. See photo for gps data.		Description MVP-PY-006_022819 condition of compost filter sock on south boundary. Looking E. See photo for gps data.		GPS Location 37.2355921799664, -80.2296085004511	
 <p>DIRECTION NE (T) +37.23538° -080.22867° ACCURACY 16 ft DATUM WGS84</p> <p>2019-02-28 08:40:18-05:00</p>		 <p>DIRECTION NE (T) +37.23548° -080.22704° ACCURACY 16 ft DATUM WGS84</p> <p>2019-02-28 08:41:14-05:00</p>		GPS Location 37.2355926828806, -80.2296103444698	
Description MVP-PY-006_022819 condition of containment under light plant. Looking NE. See photo for gps data.		Description MVP-PY-006_022819 no fluid on the south side of the bulk fuel tanks. Looking NE. See photo for gps data.		GPS Location 37.2356049204592, -80.2296061535182	
 <p>DIRECTION W (T) +37.23548° -080.22642° ACCURACY 16 ft DATUM WGS84</p> <p>2019-02-28 08:42:12-05:00</p>		 <p>DIRECTION SW (T) +37.23572° -080.22673° ACCURACY 16 ft DATUM WGS84</p> <p>2019-02-28 08:42:53-05:00</p>		GPS Location 37.2356067263954, -80.2296121460997	
Description MVP-PY-006_022819 condition of containment under supplies. Looking W. See photo for gps data.		Description MVP-PY-006_022819 crew pumping rainwater out of containment. Looking SW. See photo for gps data.		GPS Location 37.2356072254826, -80.2295888867976	



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H	
Contractor	Precision			Report #	14430	
Inspector	Pat Davis			Date/Time	2/28/2019 5:30 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	+0	
State	VA	Inspection Area	Partial	Station End	+0	
County	Roanoke	Ground	Muddy	Temperature (°F)	56.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00	
GPS Location	37.2710610833366, -80.1221789886059			Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Safety fence		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300138	Date/Time	2/28/2019 5:30 PM	Report #	14430
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. The crew continues to perform maintenance on the stone surface. Crews have kept loose trash picked up around dumpster area. Area around both dumpster areas free of loose trash.					
Comments (Reference above questions as appropriate.) (Summary Spread 10) EI preformed SWPPP Inspection on MVP-LY-049 check rain gauge found 0 rainfall in the gauge. EI checked the boundary of the LOD and found the triple stack compost filter sock in good condition. EI observed no trash along the boundary safety fence and by the timber mats. Observed the safety fence along the boundary was in good condition. The rock approaches are in good condition no mud on the stone. Contractor continues to pick up trash in the yard. No other environmental issues were noted during today's inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					






A/E	124300138	Date/Time	2/28/2019 5:30 PM	Report #	14430
Pictures					
DIRECTION SE (T) +37.27197° -080.12277° ACCURACY 16 ft DATUM WGS84  2019-02-28 09:01:34-05:00		DIRECTION E (T) +37.27099° -080.12202° ACCURACY 16 ft DATUM WGS84  2019-02-28 09:06:53-05:00		GPS Location 37.2710770927717, -80.1221256797017 Description MVP-LY-049_022819 condition of rock approach. Looking SE. See photo for gps data.	
DIRECTION NW (T) +37.27153° -080.12044° ACCURACY 16 ft DATUM WGS84  2019-02-28 09:07:42-05:00		DIRECTION SW (T) +37.27070° -080.12003° ACCURACY 16 ft DATUM WGS84  2019-02-28 09:08:23-05:00		GPS Location 37.2710770927717, -80.1221256797017 Description MVP-LY-049_022819 condition of CFS and safety fence along north boundary. Looking E. See photo for gps data.	
GPS Location 37.2710905038167, -80.1221302897484 Description MVP-LY-049_022819 dumpster area free of loose trash. Looking NW. See photo for gps data.		GPS Location 37.2710905038167, -80.1221302897484 Description MVP-LY-049_022819 condition of CFS and safety fence along south boundary. Looking SW. See photo for gps data.		DIRECTION E (T) +37.27070° -080.12003° ACCURACY 16 ft DATUM WGS84  2019-02-28 09:08:27-05:00	
GPS Location 37.2710905038167, -80.1221302897484 Description MVP-LY-049_022819 condition of CFS and safety fence in south eastern corner. Looking E. See photo for gps data.		GPS Location 37.2710905038167, -80.1221302897484 Description MVP-LY-049_022819 condition of CFS and safety fence along north drive. Looking N. See photo for gps data.		DIRECTION N (T) +37.27089° -080.12385° ACCURACY 16 ft DATUM WGS84  2019-02-28 09:10:54-05:00	



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	14431
Inspector	Pat Davis			Date/Time	2/28/2019 5:30 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13315+70
State	VA	Inspection Area	Incident/Complaint	Station End	13415+51
County	Franklin	Ground	Muddy	Temperature (°F)	56.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
GPS Location	37.0948068492816, -79.9824677210263			Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Mat bridges	Acceptable				
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Clean water conveyance	Communication	Install P1 around pool, geotech and			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300138	Date/Time	2/28/2019 5:30 PM	Report #	14431
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. Environmental crews have preformed maintenance on sumps. Crews have installed erosion control blanket between station 13409+00 and station 13407+00 in the slide area. Crew has replaced the compost filter sock at station 13342+50. Crew has installed erosion control blanket on the slope at station 13404+00 completing the DEQ punchlist item 1914. Crew have installed Earth Guard between station 13403+08 to station 13410+00 on the travel lane.					
Comments (Reference above questions as appropriate.) (Summary Spread 10) EI preformed SWPPP Inspection between Wades Gap station 13316+34 to Cahas Mt station 13415+51. EI observed 0 rainfall in the raingauge at Cahas Mountain Road. Environmental crew has installed erosion control blanket between station 13409+00 to station 13407+00 in the area of the slide. EI observed the installed erosion control blanket on steep slopes was in good condition between station 13358+64 to station 13371+50. EI observed timber mat bridges were clean and closed. No stream impacts were observed. The rock approaches at Wades Gap Road station 13315+70 and the rock approaches at Webster's Corner Road station 13342+67 were in good condition and free of sediment. EI observed cattle on the spoil piles at station 13323+43. No environmental issues were noted during today's inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	2/28/2019 5:30 PM	Report #	14431
Pictures					
					
GPS Location	37.1038826415661, -80.0434391387552	GPS Location	37.1038826415661, -80.0434391387552		
Description	13345+00_022819 condition of plunge pool. Looking SE. See photo for gps data.	Description	13348+46_022819 S-RR08 mat bridge over feature clean and closed. Looking SE. See photo for gps data.		
					
GPS Location	37.103878576343, -80.0434329361469	GPS Location	37.103878576343, -80.0434329361469		
Description	13352+23_022819 S-RR09 mat bridge clean and closed. Looking SE. See photo for gps data.	Description	13348+00_022819 condition of plunge pool. Looking SE. See photo for gps data.		
					
GPS Location	37.1038799593571, -80.0434256438911	GPS Location	37.1038799593571, -80.0434256438911		
Description	13413+05_022819 S-IJ1 mat bridge over feature clean and closed. Looking NW. See photo for gps data.	Description	13404+00_022819 waterbar opened spoil pile smoothed. Blanket installed. Looking SW. See photo for gps data.		



Visual Site Inspection Report






Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	14443
Inspector	Joe Scott			Date/Time	2/28/2019 6:16 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12686+00
State	VA	Inspection Area	Partial	Station End	13143+00
County	Franklin	Ground	Muddy	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.1918773698036, -80.1575384662302			Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Erosion Control Blanket	Acceptable			
Sump Pit	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	2/28/2019 6:16 PM	Report #	14443
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Attended the morning meeting with MVP staff and PPL management at 7:00 am. Met with lead EI and fellow EI's and discussed activities for the day. Traveled to the Honeysuckle road crossing. Inspected the installed ECD's, RCE's, and stabilized work area. No issues or impacts were observed. Traveled to Bottom Creek road. No ECD deficiencies were found. RCE's, stabilized ROW and spoil piles were in compliance. Traveled to RO-288. All ECD's, stabilized ROW and the RCE/access road were adequate and in good condition. No impacts in the area or on the access road. Traveled to the US-221 road crossing. From 12993+00 to 13143+00, no deficiencies or impacts were found throughout the the area, except the issues that have been noted on the punch list and are being addressed by the contractor as ROW conditions allow.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	2/28/2019 6:16 PM	Report #	14443
Pictures					
<p>Date & Time: Thu, Feb 28, 2019, 10:32:32 EST Position: +037.191904° / -080.157539° Altitude: 2641 ft Datum: WGS-84 Azimuth Bearing: 329° NS1W 5240mils (True) Elevation Grade: -033% Horizon Grade: +000% Zoom: 1X 12657+00 GIS of the Raccoon Creek road crossing</p> 		<p>Date & Time: Thu, Feb 28, 2019, 11:00:46 EST Position: +037.155514° / -080.128435° Altitude: 2640 ft Datum: WGS-84 Azimuth Bearing: 298° NS2W 4089mils (True) Elevation Grade: -001% Horizon Grade: +001% Zoom: 1X 12865+00 Bottom Creek Road</p> 			
GPS Location	37.1919246018279, -80.157522121519	GPS Location	37.1555930329833, -80.1284580399097		
Description	No deficiencies in ECD's and no off ROW impacts found in the work area.	Description	All P1 silt fence and RCE's in good condition. Curlex and Straw mulch adequate. No off ROW or stream/wetland impacts.		
<p>Date & Time: Thu, Feb 28, 2019, 11:51:11 EST Position: +037.130308° / -080.136707° Altitude: 2779 ft Datum: WGS-84 Azimuth Bearing: 329° NS1W 5240mils (True) Elevation Grade: -033% Horizon Grade: +002% Zoom: 1X 12974+00 GAS of RO-288</p> 		<p>Date & Time: Thu, Feb 28, 2019, 12:52:24 EST Position: +037.125274° / -080.120811° Altitude: 2659 ft Datum: WGS-84 Azimuth Bearing: 298° NS2W 3928mils (True) Elevation Grade: -036% Horizon Grade: +005% Zoom: 1X 12024+00 S-G24 and S-G25 GAS of the BRP</p> 			
GPS Location	37.1303206729117, -80.1367066708208	GPS Location	37.1252599312338, -80.1208820567281		
Description	No issues or impacts were found in this area today.	Description	All ECD's, BMP's, mat bridge, and stabilized row remain in good condition. No impacts observed.		
<p>Date & Time: Thu, Feb 28, 2019, 14:13:01 EST Position: +037.127859° / -080.117464° Altitude: 2620 ft Datum: WGS-84 Azimuth Bearing: 077° S68E 3740mils (True) Elevation Grade: +007% Horizon Grade: +003% Zoom: 1X 13063+00 S-G17 from the S25</p> 		<p>Date & Time: Thu, Feb 28, 2019, 15:15:51 EST Position: +037.127854° / -080.117508° Altitude: 2631 ft Datum: WGS-84 Azimuth Bearing: 114° S44E 3740mils (True) Elevation Grade: +007% Horizon Grade: +001% Zoom: 1X 13062+00 S-G26 and S-G27</p> 			
GPS Location	37.1278591594073, -80.1174655091764	GPS Location	37.1269244933847, -80.1114684250952		
Description	The S-H1 stream crossing and surrounding area remains in good condition. No impacts found throughout the area.	Description	No stream impacts observed at S-G26 and S-G27		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	14449
Inspector	Dustin Lyons			Date/Time	2/28/2019 12:19 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12119+17
County	Montgomery	Ground	Damp	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.2702110326265, -80.3138949909064			Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Erosion Rill		Communication	Rake out rills and restabilize	24 Hours	2/28/2019
Sump Pit		Communication	Cleaned sump pit	24 Hours	2/28/2019
Compost Filter Sock		Acceptable			
Erosion Control Blanket		Acceptable			
Waterbar		Acceptable			
Rock Construction Entrance		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300138	Date/Time	2/28/2019 12:19 PM	Report #	14449
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. The following mitigation measures were performed since the last SWPPP inspection: 12013+97: CFS adjacent to the bridge over SG36 was reinstalled 12051+50 to 12054+00: erosion control blanket was reinstalled and secured with additional pins 12031+50: CFS was moved back from stream S-G39, diversion trench and SSF was installed to divert water away from the tension crack near S-G39 12030+00: sump was cleaned out 12068+30 to 12070+50: undermined j-hooks were repaired					
Comments (Reference above questions as appropriate.) I met with the inspection team at the main yard this morning at 7:00 am, then went to the ROW and performed a SWPPP inspection from station 12005+00 to 12199+17. No measurable rainfall was recorded at Catawba Road or at Half Acre of Rock Road. During the SWPPP inspection I identified two issues. I observed erosion rills within workspace ATWS-1162 and a sump along access road MVP-MN-270 which needed to be cleaned out. No other environmental issues were observed within this area today. I informed Precision about the issues and their environmental crew (Matt Myer - forman) repaired the items. Precision raked out the rills in ATWS-1162 and re-mulched the area. They also cleaned out the sump along MVP-MN-270 and replaced the CFS and straw bales at the sump. Precision also performed maintenance on ECDs between stations 12009+00 and 12011+00. No other environmental issues, off-ROW sediment or stream impacts were observed in today.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					







A/E	124300138	Date/Time	2/28/2019 12:19 PM	Report #	14449
Pictures					
					
GPS Location	37.2702948516582, -80.3139082343134	GPS Location	37.270297030953, -80.3139057197425		
Description	See photo for gps data. Photo shows the sump along MVP-MN-270 that needs to be cleaned out.	Description	See photo for gps data. Photo shows the cleaned out sump along MVP-MN-270.		
					
GPS Location	37.2702797642325, -80.3139147721979	GPS Location	37.2702797642325, -80.3139147721979		
Description	See photo for gps data. Photo shows the rill erosion within ATWS-1162.	Description	See photo for gps data. Photo shows ATWS-1162 after precision raked out the rills and re-mulched the area.		
					
GPS Location	37.2702797642325, -80.3139147721979	GPS Location	37.2702797642325, -80.3139147721979		
Description	See photo for gps data. Photos shows stream S-MM15.	Description	See photo for gps data. Photo shows precision performing maintenance between stations 12009+00 and 12011+00.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H		AFE	124300138	Spread	H-600 Pipeline Spread H	
Contractor	Precision				Report #	14461	
Inspector	Jason Nielsen				Date/Time	2/28/2019 9:36 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	12119+17	
State	VA	Inspection Area	Partial		Station End	12445+00	
County	Montgomery	Ground	Damp		Temperature (°F)	53.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
GPS Location	37.3314704130466, -79.9581498708274				Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Erosion Control Blanket		Acceptable					
Rock Construction Entrance		Acceptable					
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
Waterbar		Acceptable					
Waterbar Outlet Protection		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300138	Date/Time	2/28/2019 9:36 PM	Report #	14461
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. Since the last inspection the environmental crew have performed maintenance on ECDs as needed.					
Comments (Reference above questions as appropriate.) Went to Flatwoods road to begin my SWPPP. While walking the ROW I inspected all ECDs for damaged portions. I also inspected the RCEs, and stabilization of the ROW. Everything was in good shape and had no need for maintenance.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	2/28/2019 9:36 PM	Report #	14461
Pictures					
					
GPS Location	37.2356322228115, -80.2295569709611	GPS Location	37.2356322228115, -80.2295569709611		
Description	12163+05_022819 Bridge crossing S-C25. Looking E. See picture for GPS data.	Description	12165+00_022819 Stabilized ROW. Looking W. See picture for GPS data.		
					
GPS Location	37.2356414664847, -80.2296806069147	GPS Location	37.2356112147138, -80.229562088918		
Description	12180+00_022819 Sump pit. Looking NE. See picture for GPS data.	Description	12126+00_022819 Water bar crossing ROW. Looking SW. See picture for GPS data.		
					
GPS Location	37.2356321857891, -80.2295790838018	GPS Location	37.2356289890954, -80.229574965328		
Description	12121+29_022819 Bridge crossing multiple wetlands and streams. Looking E. See picture for GPS data.	Description	12119+25_022819 RCE. Looking SE. See picture for GPS data.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	14463
Inspector	Dawn McCullough			Date/Time	2/28/2019 10:40 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13188+66
State	VA	Inspection Area	Partial	Station End	13315+70
County	Franklin	Ground	Damp	Temperature (°F)	45.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.3256223611787, -80.0287909764818			Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Erosion Rill	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Straw Bale Barrier	Acceptable				
Sump Pit	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300138	Date/Time	2/28/2019 10:40 PM	Report #	14463
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Attended morning inspection and contractor meeting for Spread H. Discussed daily tasks with EI team. Performed SWPPP inspection between Sta. No. 13188+66 to Sta. No. 13315+17. Access roads and road crossing were maintained at MVP-MLV-29, Dillons Mill, MVP-FR-293.01 (Flanders Road), and Wade's Gap, with Flanders Road showing minor wear from logging traffic. ECDs at stream crossings S-D10, S-D8, S-II4, S-MM27, and S-GH7 were functioning acceptably. Waterbars and waterbar outlets functioning acceptably with no off ROW impacts observed. No additional environmental concerns were noted during this in this inspection area.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					







A/E	124300138	Date/Time	2/28/2019 10:40 PM	Report #	14463
Pictures					
<p> <small> Date & Time: Thu, Feb 28, 2019, 12:16:17 EST Position: +037.106677° / -080.028625° Altitude: 1364ft Datum: WGS-84 Azimuth/Bearing: 004° N04E 0071mils (True) Elevation Angle: -08.9° Horizon Angle: +02.3° Zoom: 1X S-GH7 </small> </p> 		<p> <small> Date & Time: Thu, Feb 28, 2019, 12:16:17 EST Position: +037.106677° / -080.028625° Altitude: 1364ft Datum: WGS-84 Azimuth/Bearing: 004° N04E 0071mils (True) Elevation Angle: -08.9° Horizon Angle: +02.3° Zoom: 1X S-GH7 </small> </p> 		<p> <small> Date & Time: Thu, Feb 28, 2019, 12:16:17 EST Position: +037.106677° / -080.028625° Altitude: 1364ft Datum: WGS-84 Azimuth/Bearing: 004° N04E 0071mils (True) Elevation Angle: -08.9° Horizon Angle: +02.3° Zoom: 1X S-GH7 </small> </p> 	
GPS Location	37.3255577450966, -80.0286245439947	GPS Location	37.3256225538925, -80.0287912849081	Description	Please see photo for coordinates. S-GH7, upstream of bridge, ECDs functioning acceptably.
<p> <small> Date & Time: Thu, Feb 28, 2019, 12:44:10 EST Position: +037.076826° / -080.053499° Altitude: 1381ft Datum: WGS-84 Azimuth/Bearing: 239° S59W 4249mils (True) Elevation Angle: -04.4° Horizon Angle: -01.9° Zoom: 1X S-II4 </small> </p> 		<p> <small> Date & Time: Thu, Feb 28, 2019, 12:46:17 EST Position: +037.115840° / -080.060226° Altitude: 1437ft Datum: WGS-84 Azimuth/Bearing: 078° N78E 1387mils (True) Elevation Angle: -10.2° Horizon Angle: -01.0° Zoom: 1X 1055 W-II4 </small> </p> 		GPS Location	37.3256876645957, -80.0287807826698
Description	Please see photo for coordinates. S-II4, ECDs functioning acceptably at stream crossing.	Description	Please see photo for coordinates. W-II4, ATWS-1055, perimeter controls functioning acceptably.	GPS Location	37.3255850281914, -80.0287551340461
<p> <small> Date & Time: Thu, Feb 28, 2019, 13:29:12 EST Position: +037.123163° / -080.074506° Altitude: 1429ft Datum: WGS-84 Azimuth/Bearing: 285° N75W 5067mils (True) Elevation Angle: -12.6° Horizon Angle: -01.1° Zoom: 1X S-D8 </small> </p> 		<p> <small> Date & Time: Thu, Feb 28, 2019, 13:30:19 EST Position: +037.122857° / -080.074578° Altitude: 1459ft Datum: WGS-84 Azimuth/Bearing: 095° S84E 1707mils (True) Elevation Angle: -00.3° Horizon Angle: -00.3° Zoom: 1X GAS dillons mill </small> </p> 		GPS Location	37.3256412707617, -80.0287846383453
Description	Please see photo for coordinates. S-D8, looking towards MLV-AR-29, no environmental issues noted.	Description	Please see photo for coordinates. ~Sta. No. 13197+47, Dillons Mill road crossing, ECDs functioning acceptably.	GPS Location	37.3256429471423, -80.0287268032134



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	14468
Inspector	Jason Nielsen			Date/Time	2/28/2019 7:10 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12445+00
State	VA	Inspection Area	Partial	Station End	12450+00
County	Montgomery	Ground	Damp	Temperature (°F)	53.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.2356439203327, -80.2296739917579			Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300138	Date/Time	2/28/2019 7:10 AM	Report #	14468
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. Since the last inspection there has been no PPL activity.					
Comments (Reference above questions as appropriate.) Went to Cove hollow road to perform a SWPPP. While in the area I inspected all ECDs, RCEs and stabilization. Everything was in great shape and no need for maintenance.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	2/28/2019 7:10 AM	Report #	14468		
Pictures							
<div>DIRECTION SE (T)</div> <div>37.23110°N 080.19831°W</div> <div>ACCURACY 6 m DATUM WGS84</div>  <div>2019-02-28 10:56:11-05:00</div>			<div>DIRECTION E (T)</div> <div>37.23115°N 080.19824°W</div> <div>ACCURACY 6 m DATUM WGS84</div>  <div>2019-02-28 10:56:24-05:00</div>				
GPS Location		37.2356438612268, -80.2295617156984		GPS Location		37.2356438612268, -80.2295617156984	
Description		12445+86_022819 Stabilized ROW. Looking SE. See picture for GPS data.		Description		12445+86_022819 Stabilized topsoil pile. Looking E. See picture for GPS data.	
<div>DIRECTION E (T)</div> <div>37.23068°N 080.19894°W</div> <div>ACCURACY 19 m DATUM WGS84</div>  <div>2019-02-28 10:54:27-05:00</div>			<div>DIRECTION E (T)</div> <div>37.23063°N 080.19894°W</div> <div>ACCURACY 6 m DATUM WGS84</div>  <div>2019-02-28 10:54:38-05:00</div>				
GPS Location		37.2357269310532, -80.2297636542715		GPS Location		37.2356438612268, -80.2295617156984	
Description		12448+12_022819 RCE. Looking E. See picture for GPS data.		Description		12448+12_022819. Top soil pile. Looking E. See picture for GPS data.	
<div>DIRECTION SW (T)</div> <div>37.23126°N 080.19918°W</div> <div>ACCURACY 200 m DATUM WGS84</div>  <div>2019-02-28 10:59:20-05:00</div>			<div>DIRECTION S (T)</div> <div>37.23109°N 080.19832°W</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>2019-02-28 10:56:08-05:00</div>				
GPS Location		37.2356511753118, -80.2296644858843		GPS Location		37.2356170013869, -80.2296434370488	
Description		12449+00_022819 Stabilized ROW and top soil in variance disturbance. Looking SW. See picture for GPS data.		Description		12445+86_022819 Curlexed Area where water is crossing ROW. Looking S. See picture for GPS data.	



Visual Site Inspection Report






Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	14491
Inspector	Glenn Mike Renfro			Date/Time	3/1/2019 12:27 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13416+00
State	VA	Inspection Area	Full	Station End	13670+00
County	Franklin	Ground	Muddy	Temperature (°F)	40.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.10
GPS Location	36.9717720451465, -79.8700608501039			Rain Accumulation Time (days)	4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Maintenance needed		
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Erosion Control Blanket	Communication	Maintenance needed		
Rock Construction Entrance	Communication	Maintenance needed		
Silt Fence	Communication	Maintenance needed		
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Communication	Maintenance needed		

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	3/1/2019 12:27 PM	Report #	14491
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP inspection of Spread H section of RoW. This RoW section has received approximately .10" of rainfall since the last inspection and was raining at the time of inspection. All perimeter ECD's were inspected and issues were observed with P1 and CFS needing maintenance. There were issues observed with the RCE at Monty Rd. Both permanent and temporary waterbars were observed to be functioning properly. There were some temporary end treatments found that will require maintenance. There are some minor rill erosion issues near 13632+00 that will need to be monitored. All issues observed during the inspection were placed on a punch list and given to the contractor to address.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	3/1/2019 12:27 PM	Report #	14491
Pictures					
					
GPS Location	36.9721465325327, -79.8701346573232		GPS Location	36.9721110351728, -79.8700349964945	
Description	Stabilization and perimeter controls in good condition at 13633+00.		Description	Temporary stabilization near valve location at 13644+41	
					
GPS Location	36.9720056327404, -79.8700231780111		GPS Location	36.9721211353661, -79.8700166401266	
Description	Flume pipe at stream crossing S-E28 beginning to dam and divert water.		Description	Sump needs maintenance at 13577+00	
		Insert image here			
GPS Location	36.9720474165277, -79.8699629121272		GPS Location		
Description	P1 silt fence near 13640+00 requires maintenance.		Description		