



Visual Site Inspection Report





Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5637
Inspector	Logan Box			Date/Time	11/7/2019 11:16 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13415+55
State	VA	Inspection Area	Partial	Station End	13670+00
County	Franklin	Ground	Damp	Temperature (°F)	61.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	11/7/2019 11:16 AM	Report #	5637
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Traveled and checked all ECDs throughout the row, monitored vegetation growth during the warmer days to see how well the vegetation was starting to grow. Observed the contractor working on punch list items making repairs to erosion issues caused from storm events. Checked punch list items after being repaired by the contractor. Monitored stream and wetland crossings, checked RCEs while crews were working in the area to be sure they were clear from mud and debris. Total measurable rainfall for this period was 0.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	11/7/2019 11:16 AM	Report #	
Pictures					
					
GPS Location	00000	GPS Location	0000		
Field Station#	13620+00	Field Station#	13630+00		
Pic 1 Desc.	Photo showing winter grass growing	Pic 2 Desc.	ROW view		
					
GPS Location	00000	GPS Location	00000		
Field Station#	13620+00	Field Station#	13618+21		
Pic 3 Desc.	Photo showing vegetation	Pic 4 Desc.	Photo showing access rd in good shape leading up to the row.		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300138	Date/Time	11/7/2019 11:16 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300138	Date/Time	11/7/2019 11:16 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5651
Inspector	Pat Davis			Date/Time	11/7/2019 5:19 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	+0
State	VA	Inspection Area	Partial	Station End	+0
County	Montgomery	Ground	Wet	Temperature (°F)	62.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300138	Date/Time	11/7/2019 5:19 PM	Report #	5651
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. Contractor continues to pick up and remove loose trash. Contractor continues to pump out secondary containments after rain events as needed. Contractor has secondary containment for tanks to park in while loading and off loading fuel.					
Comments (Reference above questions as appropriate.) (Summary Spread 9) check the rain gauge in the yard MVP-PY-006 and found 0 rainfall in the raingauge. Attended morning Spread Inspectors meeting. No SEAP Training due to no New Hires. EI preformed SWPPP Inspection on MVP-PY-006. Both the North and West rock entrances were in good condition. The flagging to mark the 100 foot buffer boundary and the signage were in place for the feature W-008. The Secondary containment's under the light plants are in good condition. The containments and trays under the toilets were in good condition. No fluid deposits were observed on the stone surface on either side of the bulk fuel tanks. EI observed no loose trash in the yard, or around the dumpsters. EI went through the old FAB Area and found no loose trash. Secondary containment on site for tankers to park on during loading and off loading fuel at both the Blue Bulk Fuel tank and Off Road Fuel tanks. The containment around the Blue Bulk Fuel Tanks was holding a small amount of stormwater and a sheen was observed. The Blue Bulk fuel tanks were inspected for leaky fittings. No fittings were leaking. Check the nozzles, swivel fittings and on both side of the Blue Bulk Fuel tanks. No leaks observed. Check the internal drip tray in the Off Road bulk fuel unit. The drip tray was empty and no leaky fittings were observed. The containment around the unit was holding a small amount of stormwater, sheen was not noted. The triple stack compost filter sock along the yard boundary was in good condition, but over grown with tall weeds and grasses. The four temporary containments with poly liners were free of stormwater. No other environmental issues were noted during today's inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	11/7/2019 5:19 PM	Report #	
Pictures					
					
GPS Location	MVP-PY-006 See photo for gps data		GPS Location	MVP-PY-006 See photo for gps data	
Field Station#	+0		Field Station#	+0	
Pic 1 Desc.	Signage and buffer flagging for feature pff LOD. Looking NE.		Pic 2 Desc.	Condition of containment under light plant. Looking SW.	
					
GPS Location	MVP-PY-006 See photo for gps data		GPS Location	MVP-PY-006 See photo for gps data	
Field Station#	+0		Field Station#	+0	
Pic 3 Desc.	Off Road Fuel unit no leaky fittings. Looking NW.		Pic 4 Desc.	Blue Bulk Fuel tanks no leaky fittings. Looking SW.	
					
GPS Location	MVP-PY-006 See photo for gps data		GPS Location	MVP-PY-006 See photo for gps data	
Field Station#	+0		Field Station#	+0	
Pic 5 Desc.	No loose trash around dumpsters. Looking SE.		Pic 6 Desc.	No fluid deposits North of bulk tanks. Looking SW.	

A/E	124300138	Date/Time	11/7/2019 5:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300138	Date/Time	11/7/2019 5:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5652
Inspector	Pat Davis			Date/Time	11/7/2019 5:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	+0
State	VA	Inspection Area	Partial	Station End	+0
County	Roanoke	Ground	Wet	Temperature (°F)	62.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300138	Date/Time	11/7/2019 5:21 PM	Report #	5652
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. Contractor continues to pick up and remove loose trash. Crew continues to preform maintenance on the stone after off loading equipment					
Comments (Reference above questions as appropriate.) (Summary Spread 10) EI preformed SWPPP Inspection on MVP-LY-049. Check raingauge and found 0 rainfall in the gauge. The rock approaches are in good condition, and no sediment on the stone. EI checked the boundary of the LOD and found the triple stack compost filter sock and the safety fence were functioning. The CFS is over grown with tall grasses and weeds. EI observed no loose trash in the yard. No loose trash was noted at either of the two dumpster areas (FAB area, West dumpster). EI observed the three covered dumpsters for the collection of contaminated materials located on the ROW are still in the yard. The containments and trays under the toilets were in good condition. The ECD's, signage and buffers at features W-CV21A, W-CV21B in good condition and being observed. EI observed a landowner has caused earth disturbance and parked his equipment next to feature CV21B. No impact to the CFS or the feature. EI observed the following activities in the yard: mechanics preforming maintenance on equipment stored in the yard, crew loading and hauling empty pallets off project, crew loading and hauling super sacks of old concrete of project, crew preforming maintenance on the stone. No other environmental issues were noted during today's inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	11/7/2019 5:21 PM	Report #	
Pictures					
					
GPS Location	MVP-LY-049 See photo for gps data		GPS Location	MVP-LY-049 See photo for gps data	
Field Station#	+0		Field Station#	+0	
Pic 1 Desc.	Condition of compost filter sock and safety fence along south LOD. Looking E.		Pic 2 Desc.	Condition of compost filter sock around sand pile. Looking SE.	
					
GPS Location	MVP-LY-049 See photo for gps data		GPS Location	MVP-LY-049 See photo for gps data	
Field Station#	+0		Field Station#	+0	
Pic 3 Desc.	No loose trash around West dumpster. Looking W.		Pic 4 Desc.	Condition of trays and containment under toilets. Looking NE.	
					
GPS Location	MVP-LY-049 See photo for gps data		GPS Location	MVP-LY-049 See photo for gps data	
Field Station#	+0		Field Station#	+0	
Pic 5 Desc.	Condition of compost filter sock and safety fence at feature CV-21A. Looking W.		Pic 6 Desc.	Landowner has parked his equipment next to compost filter sock and feature CV-21B. No impacts. Looking S.	

A/E	124300138	Date/Time	11/7/2019 5:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300138	Date/Time	11/7/2019 5:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5656
Inspector	Tammy Kruizenga			Date/Time	11/7/2019 6:34 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12001+00
State	VA	Inspection Area	Partial	Station End	12119+17
County	Montgomery	Ground	Damp	Temperature (°F)	50.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Compost Filter Sock	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	11/7/2019 6:34 AM	Report #	5656
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<p>Work was completed on punch list items at stations 12049+00 and 12050+50. Water bar slips and gullied areas were reworked and graded. Two sumps were cleaned out and five water bars were redressed. All areas that were disturbed while performing this work were graded, seeded, and blanketed following completion. Area meets stabilization specs.</p> <p>New 12" CFS, erosion blanket, and seed were put down on the north banks of the bridges area over S-G36 on AR-268.01, 12013+97. Due to rain event, ECDs became dislodged and damaged.</p> <p>Sumps were cleaned out on MVP-MN-270.</p>					
Comments (Reference above questions as appropriate.)					
<p>Attended general inspection meeting at inspection trailer.</p> <p>Attended EI Team meeting with other EI s and lead,</p> <p>12001+00 to 12119+17. SWPP</p> <p>Performed SWPPP inspection of ROW, including streams and access roads between Station # 12001+00 to Station #12119+17. Access roads MVP-MN-268, MVP-MN-268.01,(12013+97), MVP-MN-270(12071+80), MVP-MN-270.01, Half Acre of Rocks Rd.,(12102+69), MVP-MN-271,(12109+62), and Flatwoods Rd./Route 622,(12119+17) were maintained and in acceptable condition. Sumps and perimeter controls on MVP-MN-268(12007+00), MVP-MN-268.01(12013+97), MVP- MN-270(12071+80), and Half Acre of Rocks Rd., 270.01, (12102+69)were in acceptable condition at time of inspection.</p> <p>S-G36(12008+69), S-G38(S-12015+84, S-G39(12031+51), S-G40(12035+11), S-PP23(12035+75), MM15(12076+95, S-MM14(12086+56), S-MM13(12098+44), S-MM11(12101+57), S-F15(12108+41), and S-F16AB(12112+13) .There was no sediment impact to all streams at time of inspection. Equipment bridges, stream buffers, ECDs, and sensitive resource signage were all in acceptable condition at time of inspection.</p> <p>In this inspection area all water bars, clean water crossings, and plunge pools were in acceptable condition at time of this inspection. And P1, triple stack CFS end treatments, and sumps were in acceptable condition at time of inspection. ROW perimeter controls including SSF, CFS, and P1 were all in acceptable condition at time of inspection.</p>					
<p>Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.</p>					

A/E	124300138	Date/Time	11/7/2019 6:34 AM	Report #	
Pictures					
					
GPS Location	See photo GPS for location		GPS Location	See photo GPS for location	
Field Station#	12049+00		Field Station#	12050+50	
Pic 1 Desc.	Punch list item completed.		Pic 2 Desc.	Punch list item completed.	
					
GPS Location	See photo GPS for location		GPS Location	See photo GPS for location	
Field Station#	12101+57		Field Station#	12101+57	
Pic 3 Desc.	No sediment impact in stream.		Pic 4 Desc.	ECDs functioning acceptably.	
					
GPS Location	See photo GPS for location		GPS Location	See photo GPS for location	
Field Station#	12098+44		Field Station#	12098+44	
Pic 5 Desc.	ECDs functioning acceptably.		Pic 6 Desc.	No sediment impact in stream.	

A/E	124300138	Date/Time	11/7/2019 6:34 AM	Report #	
Pictures					
					
GPS Location	See photo GPS for location		GPS Location	See photo GPS for location	
Field Station#	12097+46		Field Station#	12086+56	
Pic 7 Desc.	Water bar and sump are in acceptable condition.		Pic 8 Desc.	No sediment impact in stream.	
					
GPS Location	See photo GPS for location		GPS Location	See photo GPS for location	
Field Station#	12076+95		Field Station#	12076+95	
Pic 9 Desc.	ECDs functioning acceptably.		Pic 10 Desc.	No sediment impact in stream.	
					
GPS Location	See photo GPS for location		GPS Location	See photo GPS for location	
Field Station#	12071+80		Field Station#	12010+00	
Pic 11 Desc.	Sumps were cleaned out on AR-270.		Pic 12 Desc.	Vegetation is acceptable on ATWS-473.	

A/E	124300138	Date/Time	11/7/2019 6:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5672
Inspector	Dustin Lyons			Date/Time	11/7/2019 5:18 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13315+00
State	VA	Inspection Area	Partial	Station End	13416+00
County	Franklin	Ground	Damp	Temperature (°F)	56.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	11/7/2019 5:18 PM	Report #	5672
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. The following mitigation measures were performed since the last SWPPP inspection: - 13387+00: Undermined SSF was repaired and off ROW straw bales were retrieved - 13370+50: perimeter SSF was repaired - 13376+15: sump pit was repaired - 13402+00: SSF was repaired - 13343+00 to 13353+50: ROW was seeded and erosion control blanket was installed - 13316+00 to 13342+00: Flexterra was applied to the ROW.					
Comments (Reference above questions as appropriate.) I met with the inspection team at the main yard this morning at 6:30 am, then traveled to the ROW near Cahas Mountain Road. No measurable rainfall was recorded at Cahas Mountain Road within the last 24 hours. I performed a SWPPP inspection of the ROW to observe the general ROW condition, ECDs and stream conditions between stations 13315+00 and 13416+00. Precision's crew (Jason Stromberg - foreman) installed erosion control blanket from 13349+00 to 13353+00 and performed ECD maintenance from 13370+00 to 13403+00. It began to rain about 2:30 pm and the crew rained out about 4:00 pm. The crew removed a fallen tree and repaired the perimeter SSF at 13402+00. No environmental issues, off-ROW sediment or stream impacts were observed during this SWPPP inspection. The ROW between 13317+00 and 13342+00 has been stabilized with ProGanics Dual and Flexterra. Currently the vegetative growth in this area is about 40%. No vegetative growth was observed between 13343+00 and 13416+00.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	11/7/2019 5:18 PM	Report #	
Pictures					
					
GPS Location	See photo for gps data.		GPS Location	See photo for gps data.	
Field Station#	13340+00		Field Station#	13325+30	
Pic 1 Desc.	Photo shows the ROW condition from about 13338+00 to 13340+00.		Pic 2 Desc.	Photo shows the bridge over stream S-GH14.	
					
GPS Location	See photo for gps data.		GPS Location	See photo for gps data.	
Field Station#	13321+47		Field Station#	13413+00	
Pic 3 Desc.	Photo shows the bridge over stream S-GH15.		Pic 4 Desc.	Photo shows stream S-IJ1.	
					
GPS Location	See photo for gps data.		GPS Location	See photo for gps data.	
Field Station#	13402+00		Field Station#	13358+64	
Pic 5 Desc.	Photo shows the area where the fallen tree was removed and the perimeter SSF was repaired. Punch list item 454.		Pic 6 Desc.	Photo shows stream S-RR11.	

A/E	124300138	Date/Time	11/7/2019 5:18 PM	Report #	
Pictures					
GPS Location	See photo for gps data.		GPS Location	See photo for gps data.	
Field Station#	13352+25		Field Station#	13348+46	
Pic 7 Desc.	Photo shows the contractor cleaning the bridge over S-RR09.		Pic 8 Desc.	Photo shows the bridge over stream S-RR08	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 9 Desc.			Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300138	Date/Time	11/7/2019 5:18 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5675
Inspector	Joe Scott			Date/Time	11/7/2019 1:04 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12865+00
State	VA	Inspection Area	Partial	Station End	13143+00
County	Franklin	Ground	Damp	Temperature (°F)	61.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Energy Dissipater	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Hydraulically Applied Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			


5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	11/7/2019 1:04 PM	Report #	5675
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Riprap Apron	Acceptable				
Other	Acceptable	Permanent slope breakers			
7. Identify all remedial measures that have been taken since the previous inspection was conducted. The undermined CFS and the erosion rills on the CIS of FR-290 were addressed by PPL along with the sagging geotech under the equipment bridge over S-G26 on 11/04/19. These issues were extended on the punch list due to the saturated ROW and the water in the geotech was allowed to dry out to prevent a stream impact.					
Comments (Reference above questions as appropriate.) Attended the morning meeting with MVP staff at 6:30 am. Met with lead EI and fellow EI's and discussed activities for the day. Traveled to FR-289 and reported the rainfall total from the rain gauge at Callaway road. No accumulation to report today. Traveled to RO-288, RO-287, US-221 and Bottom Creek Road and found no issues or impacts to report at these locations. Walked the ROW from US-221 to FR-289 and then traveled to FR-291 and walked from 13120+17 to FR-289. Permanent restoration has been performed in these areas from approximately 13064+00 to 13114+00, 12995+50 to 13022+50 and 13044+00 to 13061+00 areas in between and near stream crossing where equipment bridges remain are temporarily stabilized. Stream crossings S-G24,S-G25,S-G26,S-G27, and S-H1 showed no signs of impact from the project. No deficiencies or impacts to report throughout the ROW today.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	11/7/2019 1:04 PM	Report #	
Pictures					
					
GPS Location	See pic for GPS location		GPS Location	See pic for GPS location	
Field Station#	13033+59		Field Station#	12974+29	
Pic 1 Desc.	No rainfall accumulation to report in the Callaway Road rain gauge.		Pic 2 Desc.	CFS is discoloring from the sun but remains in functional state.	
					
GPS Location	See pic for GPS location		GPS Location	See pic for GPS location	
Field Station#	12974+29		Field Station#	12957+30	
Pic 3 Desc.	Upstream condition of the S-Q20 crossing on access road RO-288.		Pic 4 Desc.	Down stream of access RO-287, stream S-217.	
					
GPS Location	See pic for GPS location		GPS Location	See pic for GPS location	
Field Station#	12957+30		Field Station#	12995+50	
Pic 5 Desc.	Upstream side of RO-287 crossing damned up with leaves and tree limbs from upstream and no influence from the project.		Pic 6 Desc.	Substantial temporary stabilization present on the GAS of US-221.	

AFE	124300138	Date/Time	11/7/2019 1:04 PM	Report #	
Pictures					
<p>Date & Time: Thu, Nov 07, 2019, 11:02:14 EST Position: +037.129540° / -080.130796° (±561.4M) Altitude: 2663ft (±116.8M) Datum: WGS-84 Azimuth/Bearing: 149° 53'E 264Ymils True (±78°) Elevation Grade: -0.84 Horizontal Grade: 0.02 Project: OK Location: 124300138 (12999+50) (±107) MVP Screen 11</p> 		<p>Date & Time: Thu, Nov 07, 2019, 11:04:28 EST Position: +037.129540° / -080.129276° (±170.1M) Altitude: 2663ft (±116.8M) Datum: WGS-84 Azimuth/Bearing: 149° 53'E 264Ymils True (±78°) Elevation Grade: -0.84 Horizontal Grade: 0.02 Project: OK Location: 124300138 (12999+50) (±107) MVP Screen 11</p> 			
GPS Location	See pic for GPS location		GPS Location	See pic for GPS location	
Field Station#	12999+50		Field Station#	12998+50	
Pic 7 Desc.	BRP has substantial amount of permanent vegetative stabilization throughout the area.		Pic 8 Desc.	The GAS of US-221 where permanent restoration was performed has a substantial amount of permanent vegetative growth.	
<p>Date & Time: Thu, Nov 07, 2019, 11:05:13 EST Position: +037.128670° / -080.128789° (±16.4M) Altitude: 2591ft (±16.4M) Datum: WGS-84 Azimuth/Bearing: 149° 53'E 264Ymils True (±78°) Elevation Grade: -0.84 Horizontal Grade: 0.02 Project: OK Location: 124300138 (12867+50) (±107) MVP Screen 11</p> 		<p>Date & Time: Thu, Nov 07, 2019, 11:05:13 EST Position: +037.128660° / -080.128789° (±16.4M) Altitude: 2591ft (±16.4M) Datum: WGS-84 Azimuth/Bearing: 149° 53'E 264Ymils True (±78°) Elevation Grade: -0.84 Horizontal Grade: 0.02 Project: OK Location: 124300138 (12866+50) (±107) MVP Screen 11</p> 			
GPS Location	See pic for GPS location		GPS Location	See pic for GPS location	
Field Station#	12867+50		Field Station#	12866+50	
Pic 9 Desc.	No issues were observed with the P1 perimeter.		Pic 10 Desc.	No issues or impacts observed on the GAS of the Bottom Creek road crossing.	
<p>Date & Time: Thu, Nov 07, 2019, 11:10:37 EST Position: +037.128660° / -080.128789° (±16.4M) Altitude: 2591ft (±16.4M) Datum: WGS-84 Azimuth/Bearing: 149° 53'E 264Ymils True (±78°) Elevation Grade: -0.84 Horizontal Grade: 0.02 Project: OK Location: 124300138 (12866+50) (±107) MVP Screen 11</p> 		<p>Date & Time: Thu, Nov 07, 2019, 11:05:58 EST Position: +037.127733° / -080.117433° (±12.8M) Altitude: 2740ft (±12.8M) Datum: WGS-84 Azimuth/Bearing: 149° 53'E 264Ymils True (±78°) Elevation Grade: -0.84 Horizontal Grade: 0.02 Project: OK Location: 124300138 (127733+50) (±107) MVP Screen 11</p> 			
GPS Location	See pic for GPS location		GPS Location	See pic for GPS location	
Field Station#	12866+00		Field Station#	13040+00	
Pic 11 Desc.	No issues or impacts observed on the CIS of the Bottom Creek Road crossing.		Pic 12 Desc.	No issues or impacts to report near stream S-H1 or the GAS of FR-289.	

AFE	124300138	Date/Time	11/7/2019 1:04 PM	Report #	
Pictures					
<small> Date & Time: Thu, Nov 07, 2019, 14:32:33 EST Position: +037.326224° / -080.118701° (s15704.28) Altitude: 2713ft (s127.56) Datum: WGS-84 Azimuth/Bearing: 288° N72W S120mils True (s78°) Elevation Grade: -011% Horizon Grade: +001% Zoom: 1.0X 13030+50 CIS of FR-289 overlooking GAS of the BRP has been permanently restored MVP Spread H </small> 					
		Insert image here			
GPS Location	See pic for GPS location		GPS Location		
Field Station#	13030+50		Field Station#		
Pic 13 Desc.	GAS of the BRP has been permanently restored and has a good amount of permanent vegetation growing. No issues or impacts.		Pic 14 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 15 Desc.			Pic 16 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 17 Desc.			Pic 18 Desc.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5677
Inspector	Kaitlyn Ball			Date/Time	11/7/2019 1:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12233+00
State	VA	Inspection Area	Partial	Station End	12443+08
County	Montgomery	Ground	Dry	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable	N/A		
Erosion Control Blanket	Acceptable	N/A		
Cleanwater Diversion Berm	Acceptable	N/A		
Cleanwater Diversion Pipe	Acceptable	N/A		
Waterbar	Acceptable	N/A		
Waterbar End Treatment	Acceptable	N/A		
Slope Drain Pipe	Acceptable	N/A		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable	N/A		
Sump Pit	Communication	Clean out sediment and key-in erosi		

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300138	Date/Time	11/7/2019 1:36 PM	Report #	5677
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Assigned to the section between Reese Mountain and Rte 11 for today's SWPPP inspection. At the time of my inspection, crews were actively working to put waterbars back and stabilize the travel lane in the V. They had completed PL item #413 and were working their way back up the hill. Sediment has undermined the erosion control blanketing at 12334+50 and has partially filled-in the sump, this item has been communicated to the LEI's in Spread H and it will be put on the punchlist. In addition, some erosion/subsidence has developed at 12356+00 and caused the CFS to fall into the sump, this item has also been communicated and will be put on the punchlist. There is some subsidence also occurring at 12356+50 but will remain as a maintenance item at this time, continue to monitor this area closely. The waterbars and end treatments in the switchback section were in good condition and functioning. Slope drains near 12330+16 are keyed-in and in good condition. Controls are in place and in good condition for the bridge crossings at 12379+95 and 12382+42. The MLV-27 section was in acceptable condition and no issues were noted there. I did observe some excavating and grading work occurring adjacent to the ROW near 12414+00. MLV-AR-27 and AR-276.03 are in good condition. Controls are in place and in good condition from 12443+08 to RTE 11.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	11/7/2019 1:36 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo.		
Field Station#	12233+00	Field Station#	12295+01		
Pic 1 Desc.	Controls in place and in good condition along the Reese Mtn. Switchback	Pic 2 Desc.	Crews working to put back waterbars and stabilize the travel lane in the V.		
GPS Location	See photo	GPS Location	See photo		
Field Station#	12292+64	Field Station#	12334+50		
Pic 3 Desc.	Punchlist item #413 repaired and completed.	Pic 4 Desc.	Sediment has undermined the erosion control blanketing and partially filled-in this sump, this item has been communicated to LEI's in spread H.		
GPS Location	See photo	GPS Location	See photo		
Field Station#	12330+10	Field Station#	12356+00		
Pic 5 Desc.	Slope drain keyed-in and in good condition.	Pic 6 Desc.	Erosion and subsidence occurring in this area, CFS has dislodged and fallen into the sump, this item has been communicated to the LEIs.		

A/E	124300138	Date/Time	11/7/2019 1:36 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12356+50	Field Station#	12379+95		
Pic 7 Desc.	Subsidence occurring in this area, this will be a maintenance item, continue to monitor this area closely.		Pic 8 Desc.	Bridge controls in good condition.	
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12380+00	Field Station#	12417+00		
Pic 9 Desc.	CFS controls in good condition		Pic 10 Desc.	Waterbars and controls in good condition along this slope (MLV-27).	
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12414+00	Field Station#	12443+08		
Pic 11 Desc.	Excavating and grading work occurring adjacent to the ROW		Pic 12 Desc.	Controls in good condition between Roanoke River Crossing and Rte 11.	

A/E	124300138	Date/Time	11/7/2019 1:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5678
Inspector	Ben Farmer			Date/Time	11/7/2019 2:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12640+00
State	VA	Inspection Area	Partial	Station End	12711+00
County	Roanoke	Ground	Dry	Temperature (°F)	60.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable	n/a		
Erosion Control Blanket	Acceptable	n/a		
Hydraulically Applied Blanket	Acceptable	n/a		
Rock Construction Entrance	Acceptable	n/a		
Silt Fence (Filter Fabric Fence)	Acceptable	n/a		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable	n/a		
Vegetative Stabilization (Temporary)	Acceptable	n/a		
Waterbar	Acceptable	n/a		
Waterbar End Treatment	Acceptable	n/a		

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300138	Date/Time	11/7/2019 2:13 PM	Report #	5678
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>I was instructed by Randy Clark to perform a SWPPP inspection in the Honeysuckle Rd. area (12711+00-12640+00). Upon arrival I found 0.00" of rain in the rain gauge. Sunny, 60 F.</p> <p>12690+29 Both CE's at Honeysuckle remain in good condition with controls and adequate stone in place</p> <p>12687+00 CIS slope of Honeysuckle is in good condition. Sumps have received minimal amounts of rain water and waterbars appear stable. Vegetation continues to fill in on the ROW. SSF appears to be in good condition and CFS check dams appear to be functioning. Sand bag reinforcement at ~12674+00 is still in tact and functioning. No signs of erosion or sediment deposition.</p> <p>12692+00 GAS slope of Honeysuckle in good condition. Sumps have received minimal rain and waterbars are in good condition. SSF and checks along the edge of the ROW are functioning well. Vegetation continues to fill in on the ROW.</p> <p>12640+00 GAS slope of AR-279.01 in good condition. Sumps and waterbars remain in good condition. Vegetation is filling in very well on this slope.</p> <p>AR-280/279.01 Both of these roads are in good shape with stone and CFS in place.</p> <p>No PL items</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	11/7/2019 2:13 PM	Report #	
Pictures					
GPS Location	see photo	GPS Location	see photo		
Field Station#	12690+29	Field Station#	12687+00		
Pic 1 Desc.	CE's at Honeysuckle Rd. crossing in good condition.	Pic 2 Desc.	Workspace at this location remains temporarily stabilized.		
GPS Location	see photo	GPS Location	see photo		
Field Station#	12684+47	Field Station#	12683+09		
Pic 3 Desc.	Sumps on this slope received minimal amounts of rain water	Pic 4 Desc.	Vegetation filling in on ROW.		
GPS Location	see photo	GPS Location	see photo		
Field Station#	12674+00	Field Station#	12670+00		
Pic 5 Desc.	Sandbag reinforcement in good condition.	Pic 6 Desc.	Waterbars remain in good condition.		

AFE	124300138	Date/Time	11/7/2019 2:13 PM	Report #	
Pictures					
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	12692+33		Field Station#	12700+00	
Pic 7 Desc.	Controls in place and in good condition on this slope.		Pic 8 Desc.	Waterbars on this slope in good condition.	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	12702+00		Field Station#	280+00	
Pic 9 Desc.	Vegetation filling in on this slope.		Pic 10 Desc.	AR-280 controls in place	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	1225+00		Field Station#	12642+00	
Pic 11 Desc.	ATWS-1225 remains inactive with controls in place		Pic 12 Desc.	GAS slope of ar-279.01 in good condition.	

A/E	124300138	Date/Time	11/7/2019 2:13 PM	Report #	
Pictures					
		<p>Insert image here</p>			
GPS Location	see photo	GPS Location			
Field Station#	279+01	Field Station#			
Pic 13 Desc.	AR-279.01 controls in place	Pic 14 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5682
Inspector	Dawn McCullough			Date/Time	11/7/2019 3:06 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13188+66
State	VA	Inspection Area	Partial	Station End	13315+70
County	Franklin	Ground	Dry	Temperature (°F)	55.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	11/7/2019 3:06 PM	Report #	5682
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<p> Attended morning inspection meetings for Spread H. Performed routine SWPPP inspection of ROW and access roads between Sta. No. 13188+66 to Sta. No. 13315+70. MVP-MLV-AR-29, Dillons Mill Road, Flanders Road, and Wade's Gap road crossings were in acceptable condition. Rock construction entrances in acceptable condition. Temporary vegetation establishing well on the GAS of Dillon's Mill Road crossing, and permanent vegetation establishing between Sta. No. 13213+00 to 13258+00. Permanent vegetation noted on waterbars and sparse to moderate conversation noted between approximate Sta. No. 13294+00 and Sta. No. 13312+00. Vegetation beginning to establish on restored section of ATWS-1055. No PPL crews noted in the area; DEQ observed walking down ROW on the CIS of Wade's Gap. No environmental impacts or concerns noted at S-II4, S-GH7, S-D10, or S-D8; no changes observed to stream beds or banks; no ECD failures noted at stream crossings or along ROW perimeter. No additional concerns noted during this inspection period. </p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	11/7/2019 3:06 PM	Report #	
Pictures					
					
GPS Location	See photo for coordinates.		GPS Location	See photo for coordinates.	
Field Station#	13260+70		Field Station#	13252+00	
Pic 1 Desc.	S-II4, looking upstream of equipment bridge, ECDs functioning acceptably, geotech and sideboards in acceptable condition.		Pic 2 Desc.	ROW, head of drainage feature, vegetation taking hold, erosion control blanket stable, some sediment noted in SSF.	
					
GPS Location	See photo for coordinates.		GPS Location	See photo for coordinates.	
Field Station#	13251+00		Field Station#	13246+00	
Pic 3 Desc.	ROW, permanent vegetation establishing across limits of disturbance, waterbars stable..		Pic 4 Desc.	ROW, good vegetative cover noted, some bare areas on waterbar berms.	
					
GPS Location	See photo for coordinates.		GPS Location	See photo for coordinates.	
Field Station#	13237+00		Field Station#	13314+00	
Pic 5 Desc.	ROW, vegetation noted across right of way, moderate ground cover.		Pic 6 Desc.	CIS of Wade's Gap, germination noted in temporary stabilized section, sparse growth noted in permanent.	

A/E	124300138	Date/Time	11/7/2019 3:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300138	Date/Time	11/7/2019 3:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5685
Inspector	John Brcic			Date/Time	11/7/2019 10:05 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12119+17
State	VA	Inspection Area	Partial	Station End	12234+50
County	Montgomery	Ground	Damp	Temperature (°F)	58.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) Yes
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sump Pit	Acceptable			
Erosion Control Blanket	Acceptable			
Hydraulically Applied Blanket	Acceptable			
Housekeeping	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	11/7/2019 10:05 AM	Report #	5685
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Rock weirs			
Other	Acceptable	Earthen berms			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Station 12119+17 to 12234+50.....Activities since last SWPPP inspection. An environmental crew repaired a washed spot of ROW at station 12213+50 and restabilized. A grade crew and environmental crew cleaned up an off ROW impact at station 12148+00 and restabilized the area on both sides of the ravine in this location. Arnold's Seeding performed more aerial seeding for temporary stabilization between access road MVP-MN-273 and Bradshaw Road where they had to make touch ups due to minor ground disturbances. Other minor maintenance and repairs were performed throughout this inspection area.					
Comments (Reference above questions as appropriate.)					
<p>At the beginning of the day, I attended the morning meetings at the MVP inspection trailer in the Precision Pipeline yard. I then performed a SWPPP inspection on the right-of-way between Flatwoods Road and the switchback at Reese Mountain. Included in today's inspection were streams S-C33, S-C36, S-MM31, S-C29, S-C25, S-C24, S-C21 and S-OO11. There were no issues observed at any of these streams.</p> <p>Jordan Davis' grade crew and John Davis' environmental crew continued working in the drainage feature between access roads MVP-MN-272 and 273. They finished cleaning up the sediment and debris outside of the LOD this morning and stabilized the denuded channel with erosion control blanket. They then spent the rest of the day stabilizing the slope that washed out in the first place. The SC250 erosion control blanket was used to stabilize the banks of the drainage feature, approximately 50 feet up both sides. It was also used to stabilize the channel within the LOD. Super silt fence was installed through the bottom of the ravine on the perimeter, with triple stacked 18" CFS in front of it where the sediment and debris went off the ROW. The top of the hill on the coming in side of the ravine is slated to be stabilized by helicopter tomorrow.</p> <p>Temporary stabilization incomplete from station 12119+17 to 12148+00, permanent stabilization from station 12148+00 to 12151+00 is approximately 30% vegetated, temporary stabilization from 12151+00 to 12180+00 is approximately 55% vegetated, temporary stabilization 12180+00 to 12191+00 is incomplete, temporary stabilization from 12191+00 to 12211+00 is approximately 30% vegetated, permanent stabilization from 12211+00 to 12215+25 is approximately 5% vegetated, temporary stabilization from 12215+25 to 12234+50 is approximately 25% vegetated.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	11/7/2019 10:05 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12196+00		Field Station#	12192+50	
Pic 1 Desc.	Stream S-0011, facing southeast, upstream		Pic 2 Desc.	Stream S-C21, Bradshaw Creek, facing southeast, downstream	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12188+40		Field Station#	12166+47	
Pic 3 Desc.	Arnold's Seeding was staging from the coming in side of Bradshaw Road again today.		Pic 4 Desc.	Stream S-C24, facing east	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12163+05		Field Station#	12148+00	
Pic 5 Desc.	Stream S-C25, facing east		Pic 6 Desc.	Sediment and debris have been clean up from off ROW in the drainage feature between AR 272 and 273 and channel was stabilized.	

A/E	124300138	Date/Time	11/7/2019 10:05 AM	Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12132+73		Field Station#	12121+83	
Pic 7 Desc.	Stream S-C29, facing south, downstream		Pic 8 Desc.	Stream S-C36, facing southeast, downstream	
GPS Location	See photo		GPS Location	See photo	
Field Station#	12121+33		Field Station#	12125+65	
Pic 9 Desc.	Stream S-C33, facing south, downstream		Pic 10 Desc.	Stream S-MM31, facing south, downstream	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300138	Date/Time	11/7/2019 10:05 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5697
Inspector	Jason Nielsen			Date/Time	11/7/2019 7:50 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12450+87
State	VA	Inspection Area	Partial	Station End	12543+56
County	Montgomery	Ground	Damp	Temperature (°F)	62.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	11/7/2019 7:50 PM	Report #	5697
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. Since the last inspection the environmental crew has continued working on waterbars and stabilization of the area.					
Comments (Reference above questions as appropriate.) Went to access road MVP-MLV-AR-28 and met with the environmental crew and security to ride back to yellow finch road and begin my SWPPP inspection of the disturbed ROW. While in the area the environmental crew worked on repairing the punchlist items in the area. I inspected all ECDs and everything was in good condition with no need for maintenance. The grade crew finished installing the waterbars for winter stabilization.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	11/7/2019 7:50 PM	Report #	
Pictures					
					
GPS Location	See picture for GPS data		GPS Location	See picture for GPS data	
Field Station#	12542+00		Field Station#	12541+50	
Pic 1 Desc.	Sediment field waterbar.		Pic 2 Desc.	Environmental crew cleaning out waterbars.	
					
GPS Location	See picture for GPS data		GPS Location	See picture for GPS data	
Field Station#	12519+49		Field Station#	12537+00	
Pic 3 Desc.	Bridge crossing S-EF19		Pic 4 Desc.	Repaired rill erosion within the row.	
					
GPS Location	See picture for GPS data		GPS Location	See picture for GPS data	
Field Station#	12542+00		Field Station#	12543+56	
Pic 5 Desc.	Environmental crew rolling out curlex over the repaired waterbars.		Pic 6 Desc.	Opposition wall and trash just outside the LOD	

A/E	124300138	Date/Time	11/7/2019 7:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300138	Date/Time	11/7/2019 7:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		