




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G		AFE	124300137	Spread	H-600 Pipeline Spread G	
Contractor	Precision				Report #	3936	
Inspector	Clinton Banks				Date/Time	7/2/2018 7:55 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	+37	
State	WV	Inspection Area	Full		Station End	+37	
County	Monroe	Ground	Damp		Temperature (°F)	70.00	
Municipality	N/A	Weather	Cloudy		Rain Gauge (in)	0.00	
GPS Location	37.4113760113894, -80.7533274774915				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level		Corrective Action		Corrective Time Frame	
Silt Fence (Filter Fabric Fence)		Acceptable					
Compost Filter Berm		Acceptable					
Permanent Diversion Berm		Acceptable					
Culvert (Ditch Relief)		Acceptable					
Rock Construction Entrance		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? WV: Exceeding 7 days if to be left inactive for more than 21 days							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300137	Date/Time	7/2/2018 7:55 AM	Report #	3936
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
After morning meeting, travel to LY 37 for equipment check, also conducted Weekly SWPP at LY 37.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/2/2018 7:55 AM	Report #	3936
Pictures					
 <p><small>Date & Time: Mon Jul 2 08:24:35 EDT 2018 Position: -83.74169697, -80.742315 Altitude: 1000 ft Datum: WGS-84 Geoidal Separation: 33.23 ft (32.24 m) Elevation Angle: 17.1 Horizon Angle: -02.7 Zoom: 1X Wetland Crossing W-IJ81 & Stream Crossing S-CV2 at LY 37</small></p>			 <p><small>Date & Time: Mon Jul 2 08:45:01 EDT 2018 Position: -83.74169697, -80.741558 Altitude: 119.7 ft Datum: WGS-84 Geoidal Separation: 210.53 ft (64.17 m) Elevation Angle: 4.94 Horizon Angle: -07.3 Zoom: 1X Rock Entrance To LY 37</small></p>		
GPS Location	37.4175047921365, -80.7424433436997		GPS Location	37.4168934999382, -80.7416033931828	
Description	Wetland Crossing W-IJ81 & Stream Crossing S-CV 2 at LY 37		Description	Rock Construction Entrance To LY 37	
Insert image here			Insert image here		
GPS Location			GPS Location		
Description			Description		
Insert image here			Insert image here		
GPS Location			GPS Location		
Description			Description		