








# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6981
<b>Inspector</b>	Clinton Banks			<b>Date/Time</b>	8/27/2018 4:01 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11436+00
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	71.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.3217431409632, -80.4358016420905			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Silt Fence (Filter Fabric Fence)	Problem Area	P-1 Need to be Key in undermine		Addressed	
Silt Fence (Filter Fabric Fence)	Problem Area	P-1 Need to be Key in undermine		Addressed	
Sump Pit	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Rock Construction Entrance	Acceptable				
Bridge	Acceptable				
Plunge Poole	Acceptable				
Sump Pit	Acceptable	Up graded EndTreatment Triple Soc		Addressed	
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No





<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2018 4:01 AM	<b>Report #</b>	6981
<b>Pictures</b>					
					
<b>GPS Location</b>	37.3208804335793, -80.4363324680183	<b>GPS Location</b>	37.3206847999592, -80.4364864435796		
<b>Description</b>	P-1 Silt Fence undermine need to be Key in Station 11468+00	<b>Description</b>	P-1 undermine need to be Key in Station 11466+79		
					
<b>GPS Location</b>	37.3191375844528, -80.4405953363333	<b>GPS Location</b>	37.3285603942697, -80.4226167407636		
<b>Description</b>	Rain Gauge at Steel Acres	<b>Description</b>	Bridge being repair		
					
<b>GPS Location</b>	37.3247356480335, -80.4313755781208	<b>GPS Location</b>	37.3285450131867, -80.4226184102725		
<b>Description</b>	Added Rock to Plunge Poole at Station 11488+81 Stevers Gap Trail	<b>Description</b>	Clean out Sump at Station 11450+93		