
| Mountain Valley | | Visual Site Inspection Report | | | | | | | | | | |
|---|------------------|-------------------------------|---------------------|--------------------------------|---------|----------------------|------------------------------------|------------------------|------------------|------|--------------|-----|
| Project Name H-600 Pipeline Sprea | | G | Al | FE 124300137 | | Spread H-600 Pipelin | | ne Sp | ne Spread G | | | |
| Contractor Precision | | | | • | | | | Repo | ort# | 7742 | | |
| Inspect | | | | | | | Date/Time 9/12/2018 4:51 AM | | | | | |
| Permit # TBD | | | Inspection | Inspection Type VA SWPP | | | | Station Begin 11524+16 | | | | |
| State | VA | | Inspection | Inspection Area | | Full | | Station End 11436+00 | | | | |
| County Craig | | Gr | ound | Wet | | | Temperature (°F) | | | | 69.00 | |
| Municipality | lunicipality N/A | | | ather | Cloud | Cloudy | | Rain Gauge (in) | | | 0.06 | |
| GPS Location 37.320338307384, -80.6581 | | | 81853332981 | 853332981 | | | Rain Ac | cumulation Time (days) | | | 1.00 | |
| 1. Are the appro | oved (stam | ed) E&S Pla | n and PCSM Pla | and PCSM Plan present on site? | | | | | | | | Yes |
| Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture | | | | | | | | | | | Yes | |
| is required.) | | | | | | | | | | | | |
| E&S BMPs | | | Compliance Level | Corrective Action | | | | | rective Frame | R | Date epaired | |
| Waterbar | | £ | Acceptable | | | | | | | | | |
| Stream S-0013 | | | Acceptable | | | | | | | | | |
| Plunge Pool | | P | Acceptable | | | | | | | | | |
| Silt Fence (Filter Fabric Fence) | | | Acceptable | | | | | | | | | |
| Karst Area | | | Acceptable | | | | | | | | | |
| Compost Filter Sock | | | Acceptable | | | | | | | | | |
| Silt Fence (Reinforced Filter Fabric Fence) | | | Acceptable | | | | | | | | | |
| Waterbar Outlet Protection | | Acceptable | | | | | | | | | | |
| | | | | | | | | | | | | |
| 5. Site Conditi | | | | | | | | | | | | |
| Is an unauthoriz beyond defined a photo and imn | limits of dis | urbance resi | ulting from earth | distur | bance | activ | ity or inef | - | | | | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | | | | | | | | Yes | | | | |
| Are slopes 3:1 a | and greater | stabilized with | h appropriate BN | MPs as | s per l | E&S p | olans? | | | | | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | | | | | | | | | | No | | |

MVP-34 REV 0 Page 1 of 3

| AFE 124300137 | Date/Tir | me 9/12/2018 4:51 AM | Report # 774 | Report # 7742 | | | | | | |
|---|---|----------------------|-----------------------|------------------|--|--|--|--|--|--|
| | 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a | | | | | | | | | |
| picture is required.) PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | | | | | | |
| | 2010. | | 11110114115 | Nopulio | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Conducted Weekly VA SWPP Stream S-001 | | | e Pool at Station 11 | 465+03 was | | | | | | |
| Conducted Weekly VA SWPP Stream S-0013 at Station 11451+41 no Sediment in Stream. Plunge Pool at Station 11465+03 was Acceptable. Karst Area at Station 11479+65 was Acceptable. Karst Area at Station 11530+47 near AR 258.02 no issues in the area. | | | | | | | | | | |
| Went from Station 11524+16 M.P. 218.0 To 11436+00 M.P. 215.5 | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3



MVP-34 REV 0 Page 3 of 3