





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	1339
Inspector	Frank Weaver			Date/Time	4/30/2018 5:34 PM
Permit #	TBD	Inspection Type	Weekly	Station Begin	+0
State	WV	Inspection Area	Full	Station End	+0
County	Monroe	Ground	Dry	Temperature (°F)	71.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.1857567686108, -80.4224082282852			Rain Accumulation Time (days)	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame
Silt Fence (Filter Fabric Fence)	Acceptable	None	
Rock Construction Entrance	Acceptable	None	
Compost Filter Sock	Acceptable	None	
Vegetative Stabilization (Temporary)	Acceptable	None	

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? WV: Exceeding 7 days if to be left inactive for more than 21 days	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/30/2018 5:34 PM	Report #	1339
Pictures					
					
GPS Location	37.185866602036, -80.4224719117955	GPS Location	37.1858522614632, -80.4223994210618		
Description	Priority 1 silt fence functioning as intended on west side of Yard. See photo for gps location.	Description	Priority 1 silt fence on north side of site. No issues at time of inspection. See photo for gps location.		
		Insert image here			
GPS Location	37.1859821470456, -80.422414546146	GPS Location			
Description	Stabilized topsoil stockpile.	Description			
Insert image here		Insert image here			
GPS Location		GPS Location			
Description		Description			