









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G		AFE	124300137	Spread	H-600 Pipeline Spread G	
Contractor	Precision				Report #	1823	
Inspector	Garrett Barclay				Date/Time	5/16/2018 4:15 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	+0	
State	VA	Inspection Area	Full		Station End	+0	
County	Giles	Ground	Wet		Temperature (°F)	67.00	
Municipality	N/A	Weather	Light Rain		Rain Gauge (in)	0.05	
GPS Location	37.1835081708938, -80.4096972167846				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level		Corrective Action		Corrective Time Frame	
Compost Filter Sock		Acceptable		N/A		See Comments	
Rock Construction Entrance		Acceptable		N/A		See Comments	
Silt Fence (Filter Fabric Fence)		Acceptable		N/A		See Comments	
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300137	Date/Time	5/16/2018 4:15 PM	Report #	1823
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPP inspection Inspected ECD's and perimeter controls @ Yard 26 and Yard 28 RCE's, CFS, SF, and other controls observed were in good working condition and were in compliance No environmental or compliance issues to report at this time					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/16/2018 4:15 PM	Report #	1823
Pictures					
<p>Date & Time: Wed May 16 08:30:50 EDT 2018 Position: +037°19'18.95" / -080°39'31.70" Altitude: 1777ft Datum: WGS-84 Azimuth/Bearing: 081° S04E 1818mils (True) Elevation Angle: -12.3° Horizon Angle: -00.3° Zoom: 1X</p> 		<p>Date & Time: Wed May 16 08:36:35 EDT 2018 Position: +037°19'19.95" / -080°39'31.70" Altitude: 1777ft Datum: WGS-84 Azimuth/Bearing: 192° S08E 3058mils (True) Elevation Angle: -05.3° Horizon Angle: -00.3° Zoom: 1X</p> 			
GPS Location	37.1836629789669, -80.4094993975762		GPS Location	37.1835565064067, -80.4096830267524	
Description	CFS @ Yard 26		Description	CFS @ Yard 26	
<p>Date & Time: Wed May 16 08:07:53 EDT 2018 Position: +037°19'9.85" / -080°39'28.31" Altitude: 1807ft Datum: WGS-84 Azimuth/Bearing: 168° S12E 2987mils (True) Elevation Angle: -10.0° Horizon Angle: -00.4° Zoom: 1X</p> 		<p>Date & Time: Wed May 16 08:08:35 EDT 2018 Position: +037°20'10.07" / -080°40'11.35" Altitude: 1538ft Datum: WGS-84 Azimuth/Bearing: 168° S12E 2987mils (True) Elevation Angle: -10.0° Horizon Angle: -00.4° Zoom: 1X</p> 			
GPS Location	37.1837343508724, -80.4094171711061		GPS Location	37.1837574011061, -80.4093595874313	
Description	CFS @ Yard 26		Description	CFS @ Yard 28	
<p>Date & Time: Wed May 16 09:40:59 EDT 2018 Position: +037°20'4.58" / -080°48'5.50" Altitude: 1524ft Datum: WGS-84 Azimuth/Bearing: 283° S87W 4741mils (True) Elevation Angle: +01.4° Horizon Angle: -08.3° Zoom: 1X</p> 		<p>Date & Time: Wed May 16 09:46:10 EDT 2018 Position: +037°20'2.00" / -080°48'16.50" Altitude: 1524ft Datum: WGS-84 Azimuth/Bearing: 314° N48W 5383mils (True) Elevation Angle: -00.3° Horizon Angle: -01.3° Zoom: 1X</p> 			
GPS Location	37.1837574011061, -80.4093595874313		GPS Location	37.1837835107345, -80.4094342701886	
Description	CFS @ Yard 28		Description	CFS @ Yard 28	