



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	8314
Inspector	Garrett Barclay			Date/Time	9/24/2018 11:46 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11255+00
State	VA	Inspection Area	Full	Station End	11550+00
County	Giles	Ground	Muddy	Temperature (°F)	74.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
GPS Location	37.296687159722, -80.4798042868082			Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable		Addressed		
Rock Construction Entrance	Acceptable		Addressed		
Silt Fence (Filter Fabric Fence)	Acceptable		Addressed		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable		Addressed		
Sump Pit	Problem Area		24 Hours		
Vegetative Stabilization (Temporary)	Problem Area		24 Hours		
Waterbar	Acceptable		Addressed		
Waterbar Outlet Protection	Problem Area		24 Hours		
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300137	Date/Time	9/24/2018 11:46 AM	Report #	8314
Pictures					
<p>Date & Time: Mon, Sep 24, 2018, 09:37:15 EDT Position: +037°17'47.09" / -080°29'52.21" Altitude: 2112ft Datum: WGS-84 Azimuth/Bearing: 222° S 42W 3947mils (True) Elevation Angle: +14.9° Horizon Angle: +03.3° Zoom: 1X 11291+00</p> 		<p>Date & Time: Mon, Sep 24, 2018, 09:44:21 EDT Position: +037°17'45.17" / -080°29'4.99" Altitude: 2240ft Datum: WGS-84 Azimuth/Bearing: 275° N 84W 4907mils (True) Elevation Angle: +18.6° Horizon Angle: +01.7° Zoom: 1X 11282+00</p> 			
GPS Location	37.2966954997157, -80.479719126672	GPS Location	37.2966954997157, -80.479719126672		
Description	Top soil eroded @ 11291+00	Description	Rill erosion @ 11282+00		
<p>Date & Time: Mon, Sep 24, 2018, 09:57:41 EDT Position: +037°17'44.88" / -080°29'9.87" Altitude: 2237ft Datum: WGS-84 Azimuth/Bearing: 367° N 03W 4347mils (True) Elevation Angle: +05.4° Horizon Angle: +02.1° Zoom: 1X 11286+00</p> 		<p>Date & Time: Mon, Sep 24, 2018, 10:03:42 EDT Position: +037°17'45.93" / -080°29'15.10" Altitude: 2289ft Datum: WGS-84 Azimuth/Bearing: 219° S 69W 3694mils (True) Elevation Angle: +23.1° Horizon Angle: +05.7° Zoom: 1X 11279+00</p> 			
GPS Location	37.2967888322075, -80.4798358027641	GPS Location	37.2967410972689, -80.4798124172543		
Description	Erosion and CWD with sediment @ 11283+00	Description	Sediment erosion around slope drain @ 11279+00, sump full		
<p>Date & Time: Mon, Sep 24, 2018, 12:22:35 EDT Position: +037°18'6.92" / -080°28'16.62" Altitude: 2225ft Datum: WGS-84 Azimuth/Bearing: 349° N 11W 6204mils (True) Elevation Angle: +07.1° Horizon Angle: +01.1° Zoom: 1X 11320+00</p> 		<p>Date & Time: Mon, Sep 24, 2018, 12:44:41 EDT Position: +037°17'57.03" / -080°28'28.37" Altitude: 2277ft Datum: WGS-84 Azimuth/Bearing: 349° N 11W 6204mils (True) Elevation Angle: +07.1° Horizon Angle: +02.0° Zoom: 1X 11320+00</p> 			
GPS Location	37.2967410972689, -80.4798124172543	GPS Location	37.2967410972689, -80.4798124172543		
Description	End treatment undermined and causing rill erosion @ ATWS 633	Description	Crews tracking through ROW rebuilding water bars @ 11320+00		