



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G		AFE	124300137	Spread	H-600 Pipeline Spread G	
Contractor	Precision				Report #	2810	
Inspector	Jared Saunders				Date/Time	6/8/2018 9:30 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	11789+00	
State	VA	Inspection Area	Partial		Station End	11900+00	
County	Montgomery	Ground	Dusty		Temperature (°F)	85.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
GPS Location	37.27655145, -80.41688768				Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level		Corrective Action		Corrective Time Frame	
Compost Filter Sock		Acceptable		N/A		See Comments	
Silt Fence (Filter Fabric Fence)		Acceptable		N/A		See Comments	
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable		N/A		See Comments	
Vegetative Stabilization (Temporary)		Communication		N/A		See Comments	
Sump Pit		Acceptable		N/A		See Comments	
Waterbar		Acceptable		N/A		See Comments	
Waterbar Outlet Protection		Acceptable		N/A		See Comments	
Temporary Diversion Berm		Acceptable		N/A		See Comments	
Rock Construction Entrance		Acceptable		N/A		See Comments	
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300137	Date/Time	6/8/2018 9:30 AM	Report #	2810
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPP inspection from MP 223.3 to 225.4. Since last inspection Precision Pipeline has worked on grading, ECD installation, stabilization, ditch line force excavation assistance, and ECD maintenance. Stabilization needed on spoil pile at station number 11873+50. Issue communicated with Precision Environmental Crew. All other items were installed to E&S plans.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/8/2018 9:30 AM	Report #	2810
Pictures					
					
GPS Location	37.2789263079159, -80.4091368900156	GPS Location	37.2765697553198, -80.4168279371778		
Description	See photo for GPS location and station number. Reinforced Silt fence installed at karst where DEQ approved elimination of diversion	Description	See photo for GPS location and station number. RCE located at Mt. Tabor access point.		
					
GPS Location	37.2765559699159, -80.4168729284122	GPS Location	37.2765525010361, -80.4168842497476		
Description	See photo for GPS location and station number. Top soil pile stabilized with seed and mulch.	Description	See photo for GPS location and station number. RCE at access road 266.03.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Description		Description			