



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6083
Inspector	Jared Saunders			Date/Time	8/9/2018 6:01 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10883+75
State	VA	Inspection Area	Partial	Station End	11060+00
County	Giles	Ground	Dry	Temperature (°F)	80.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
GPS Location	37.206033018661, -80.3941328368787			Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
Compost Filter Sock		Acceptable	See comments		
Erosion Control Blanket		Acceptable	See comments		
Rock Construction Entrance		Problem Area	See comments	24 Hours	
Silt Fence (Filter Fabric Fence)		Acceptable	See comments		
Sensitive Resource Signage		Acceptable	See comments		
Waterbar		Acceptable	See comments		
Waterbar Outlet Protection		Acceptable	See comments		
Sump Pit		Acceptable	See comments		
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					Yes
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					No
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300137	Date/Time	8/9/2018 6:01 PM	Report #	6083
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPP inspection from MP 206 to 209.5. Since last inspection Precision Pipeline has conducted ECD maintenance throughout the section and installation near resources. Along access road 242.01 non compliance report was issued on two stream crossing due to ECDs not being install. One problem area was reported on access road 242.01 due to brush piles being pushed out side the LOD. Another problem area report was issued because RCE at Doe Creek Farm Ln. is not in place but equipment has been using crossing. Spoil pile at station number 10928+00 needs stabilized and spoil piles along access road 244 needs stabilized.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	8/9/2018 6:01 PM	Report #	6083
Pictures					
<p>Date & Time: Thu Aug 9 13:31:02 EDT 2018 Position: +037.337420° / -080.562509° Altitude: 2551ft Datum: WGS-84 Azimuth/Bearing: 284° N76W 5049mils (True) Elevation Angle: +23.1° Horizon Angle: +06.1° Zoom: 1X 10985+00</p> 		<p>Date & Time: Thu Aug 9 14:13:34 EDT 2018 Position: +037.332967° / -080.559234° Altitude: 3031ft Datum: WGS-84 Azimuth/Bearing: 017° N12E 0302mils (True) Elevation Angle: +0.6° Horizon Angle: +02.0° Zoom: 1X AR 242.01</p> 			
GPS Location	37.2060958731172, -80.3942149129845		GPS Location	37.2061305027802, -80.3938816488538	
Description	See photo for GPS location and station number. Triple stacked 18" CFS in place.		Description	See photo for GPS location and station number. Bridge on access road 242.01 over stream S-MN11 ECDs not installed.	
<p>Date & Time: Thu Aug 9 14:27:15 EDT 2018 Position: +037.332352° / -080.560161° Altitude: 2931ft Datum: WGS-84 Azimuth/Bearing: 348° N16W 2187mils (True) Elevation Angle: +17.6° Horizon Angle: +02.2° Zoom: 1X AR 242.01</p> 		<p>Date & Time: Thu Aug 9 14:40:14 EDT 2018 Position: +037.333317° / -080.559201° Altitude: 2940ft Datum: WGS-84 Azimuth/Bearing: 010° N00W 0311mils (True) Elevation Angle: +23.1° Horizon Angle: +01.8° Zoom: 1X 10955+74</p> 			
GPS Location	37.2062201891441, -80.3940390609953		GPS Location	37.2060677139828, -80.394238309548	
Description	See photo for GPS location and station number. Brush piles on access road 242.01 outside the LOD.		Description	See photo for GPS location and station number. RCE needed at road crossing.	
<p>Date & Time: Thu Aug 9 15:26:27 EDT 2018 Position: +037.329243° / -080.589180° Altitude: 2116ft Datum: WGS-84 Azimuth/Bearing: 322° N38W 5724mils (True) Elevation Angle: +03.4° Horizon Angle: +03.4° Zoom: 1X 10927+50 S-Y2</p> 		Insert image here			
GPS Location	37.206052006257, -80.3940153402094		GPS Location		
Description	See photo for GPS location and station number. Stream S-Y2 crossing. ECDs in place.		Description		