









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G		AFE	124300137	Spread	H-600 Pipeline Spread G	
Contractor	Precision				Report #	8859	
Inspector	Jared Saunders				Date/Time	10/4/2018 4:45 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	11670+00	
State	VA	Inspection Area	Partial		Station End	11766+80	
County	Montgomery	Ground	Damp		Temperature (°F)	85.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
GPS Location	37.2233883992397, -80.4042471321244				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Erosion Control Blanket		Acceptable					
Rock Filter Outlet		Acceptable					
Sensitive Resource Buffer		Acceptable					
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Stone Inlet Protection		Acceptable					
Sump Pit		Acceptable					
Waterbar		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300137	Date/Time	10/4/2018 4:45 PM	Report #	8859
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPPP inspection from 11600+00 (MP 219.7) to station number 11670+00 (MP 221) in the Jefferson National Forest. Since last inspection Precision Pipeline has conducted work on ECD maintenance and ECD upgrades. Precision Pipeline has also wrapped all pipe on brush mountain in preparation for stabilization. Stabilization will be conducted using helicopter and hydro mulch.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	10/4/2018 4:45 PM	Report #	8859
Pictures					
<p>Date & Time: Thu Oct 4 11:31:50 EDT 2018 Position: +037.303602 / -080.395261* Altitude: 279ft Datum: WGS-84 Azimuth/Bearing: 117° S63E 2080mils (True) Elevation Angle: -06.5° Horizon Angle: -02.1° Zoom: 1X 11670+00</p> 		<p>Date & Time: Thu Oct 4 11:12:06 EDT 2018 Position: +037.303647 / -080.395318* Altitude: 279ft Datum: WGS-84 Azimuth/Bearing: 297° N65W 5280mils (True) Elevation Angle: -31.9° Horizon Angle: -02.3° Zoom: 1X 11668+00</p> 			
GPS Location	37.2235272685413, -80.4040236678723	GPS Location	37.2234782662308, -80.4043647845716		
Description	Environmental crew installing unpassable berm to prevent traffic from area that will be stabilized.	Description	Reinforced silt fence used to separate top soil from subsoil spoil piles.		
<p>Date & Time: Thu Oct 4 11:28:02 EDT 2018 Position: +037.310308 / -080.397357* Altitude: 2117ft Datum: WGS-84 Azimuth/Bearing: 021° N71E 0373mils (True) Elevation Angle: -25.3° Horizon Angle: -04.0° Zoom: 1X 11622+00</p> 		<p>Date & Time: Thu Oct 4 11:35:49 EDT 2018 Position: +037.313909 / -080.398477* Altitude: 1948ft Datum: WGS-84 Azimuth/Bearing: 295° N65W 5244mils (True) Elevation Angle: -30.7° Horizon Angle: -03.4° Zoom: 1X 11626+04 S-HH18</p> 			
GPS Location	37.2233516257603, -80.4040749651197	GPS Location	37.2233516257603, -80.4040749651197		
Description	Reinforced silt fence ECD in place.	Description	100 foot buffer zone stabilized with seed and mulch. Priority one silt fence installed in travel lane to protect stream.		
<p>Date & Time: Thu Oct 4 11:39:35 EDT 2018 Position: +037.314248 / -080.400745* Altitude: 1925ft Datum: WGS-84 Azimuth/Bearing: 010° N60W 5511mils (True) Elevation Angle: -29.5° Horizon Angle: -02.3° Zoom: 1X 11619+00</p> 		<p>Date & Time: Thu Oct 4 11:52:07 EDT 2018 Position: +037.314167 / -080.401107* Altitude: 1813ft Datum: WGS-84 Azimuth/Bearing: 014° N16E 0284mils (True) Elevation Angle: -09.3° Horizon Angle: -01.6° Zoom: 1X 11618+91</p> 			
GPS Location	37.2233516257603, -80.4040749651197	GPS Location	37.2233516257603, -80.4040749651197		
Description	Plunge pool in place	Description	Area blocked off for stabilization and pipe is wrapped in plastic in preparation for stabilization.		