Mountain Valley				Visual Site Inspection Report							
Project Name H-600 Pipelin		ne Spread G AFE 124300137			Spread	H-60	H-600 Pipeline Spread G				
Contractor Precision						Report #	7448				
Inspector Rob Robertson						Date/Time	9/6/	PM			
Permit #	Permit # TBD			Inspection Type VA SWPP			Station Beg	jin			
State	VA			Inspection Area	Full		Station End 10459+03				
County	Gile	es		Ground	Dry		Temperature (ºF)			86.00	
Municipality	N/A	\		Weather	Sunny		Rain Gauge (in)			0.00	
<b>GPS Location</b>	ation 37.133150699205, -80.39448			04810907 Rain A		ccumulation Time (days)			1.00		
1. Are the appro	1. Are the approved (stamped) E&S Plan a				and PCSM Plan present on site?						
Are there activities occurring outside of the limits of disturbance shown on the plan drawings?  (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)									No		
<ol> <li>Is Construction sequence outlined in the construction notes of the E&amp;S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)</li> <li>E&amp;S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, and plan in the construction notes of the E&amp;S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)</li> </ol>								Yes			
is required.)	LIST	. BMPS and	i note ir insta	iled and maintained	as per tr	ie pian. If (	corrective acti	ion is	s needed,	a picture	
E&S BMPs			Compliance Level		Correc	tive Action			Corrective Time Frame		
Housekeeping				Acceptable							
Silt Fence (Filter Fabric Fence)			Acceptable								
Waterbar			Acceptable								
Waterbar Outlet Protection			Acceptable								
5. Site Conditi											
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.										No	
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									Yes		
Are slopes 3:1 a	ınd	greater sta	abilized with a	ppropriate BMPs as	per E&S	S plans?				N/A	
Has a new slip/s	Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No	

MVP-34 REV 0 Page 1 of 3

<b>AFE</b> 124300137	Date/Time 9/6/201	18 7:23 PM	Report #	7448							
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)											
PCSM BMPs	Compliance Level	Corrective Ac	tion	Corrective Time Frame							
7. Identify all remedial measures that have been taken since the previous inspection was conducted.											
Comments (Reference above questions as											
Conducted required VADEQ SWPPP inspectior yesterday completing routine maintenance. Bot functional. No resource impact or environmenta	h roads are currently stab	l Mystery Ridge Road. The	e contractor wa are in place a	as on location nd appear							
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a											

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or

MVP-34 REV 0 Page 2 of 3

AFE 124300137 Date/Time 9/6/2018 7:23 PM Report # 7448 **Pictures** GPS Location 37.1331224078658, -80.3945452441279 **GPS Location** 37.1331938908604, -80.3944710184712 Correct coordinates on photo. Mystery Ridge Correct coordinates on photo. Mystery Ridge Road ECDs in place and operable. Road ECDs in place and operable. Description Description **GPS Location GPS Location** 37.1330722421754, -80.394447762594 37.1330722421754, -80.394447762594 Correct coordinates on photo. Pocahontas Correct coordinates on photo. Pocahontas Road ECDs in place and operable Road ECDs in place and operable. Description Description GPS Location 37.1330722421754, -80.394447762594 GPS Location 37.1330722421754, -80.394447762594 Correct coordinates on photo. Pocahontas Correct coordinates on photo. Pocahontas Road ECDs in place and operable. Road ECDs in place and operable. Description Description

MVP-34 REV 0 Page 3 of 3