Mour Mour	ita V	alley		Visual S	Site In	specti	on Repo	ort	t		
Project Name H-600 Pipeline Spread G		AFE 124300137			Spread	H-600 Pipeline Spread		oread G			
Contractor Precision						Report #	141				
Inspector Tim Bowen						Date/Time	5/3	/2018 5:22	PM		
Permit #	ТВС)		Inspection Type Weekly			Station Beg	ation Begin 10459+70			
State	VA			Inspection Area	Full		Station End 10460+00				
County	Gile	s		Ground	Dry		Temperature (ºF)			87.00	
Municipality	N/A			Weather	Sunny		Rain Gauge (in)			0.00	
GPS Location	37.3	350683622	7486, -80.7656	6688880253		Rain Ad	cumulation	0.00			
1. Are the appre	ovec	d (stamped	d) E&S Plan a	and PCSM Plan pre	sent on sit	e?					
				the limits of disturba				?		No	
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes					
				lled and maintained				_	is needed,	a picture	
ı	E&S	BMPs		Compliance Level		Corrective Action				Corrective Time Frame	
5. Site Conditi	ons								<u>'</u>		
beyond defined a photo and imn	limit nedi	s of distur ately conta	bance resulti act MVP Envi	ment, gravel, oil, HI ng from earth distur ironmental Permittin	bance act g Coordin	vity or ine ator.	ffective BMP?			No	
Have inactive di	sturk	oed areas	(stockpiles, f	final grade) been sta	abilized pe	r state rec	uirements?			N/A	
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A				
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No					

MVP-34 REV 0 Page 1 of 3

AFE	124300137	Date/Time 5/3/201	8 5:22 PM	Report #	1415			
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a								
picture is required.) PCSM BMPs		Compliance Level	Corrective Action		Corrective Time Frame			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.								
Comments (Reference above questions as appropriate.)								
Traveled to Pocahontas Road and traveled the entire length of the road and continued to the end of the project approved access on Mystery Ridge Road inspecting environmental controls and the installation of water bars and end treatments for each. No compliance issues were observed today.								

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3

AFE 12430013	7	Date/Time 5/3/2018 5:22 PM			Report #	1415		
	Pictures							
Date & Time. Thu May 3 Pesilien. —137. 22. 33.79 Altitude: 380/0 Pesilien. W65-82 Arimuth/Bearing 342 N Elevation Angle —15.9 Henzen Angle —10.6 Zosin 1X Positionia's Read stream	18W 668mits/frue//		Date Millian That Man of Person and 2 23 Stock Annual Sto	SW, \$133mils (frue)				
	37.3506860574611, -80.7656672		GPS Location					
Description	Pocahontas Road - see photo for lat/long and details.	r correct	Description	Pocahontas Road - see photo for correct lat/long and details.				
Elevation Angle: -28.9 Horizon Angle: -02.8 Zoom: 1X	poiss sa BortizonesQuo de Sis ses -23W 5991mils (Tota) Sit Forechilo (de Sis at station 10-de)-pois			Insert ima	age here			
GPS Location	37.3506736624749, -80.7656276	6016113	GPS Location					
Description	Pocahontas Road - see photo for lat/long and details.	r correct	Description					
	Insert image here			Insert ima	age here			
GPS Location			GPS Location					
Description			Description					

MVP-34 REV 0 Page 3 of 3