Viour	ntain Valley		Visual 9	Sit	e Ins	specti	on Repo	ort	İ		
Project Name H-600 Pipeline Spread G		<b>AFE</b> 124300137		Spread	Spread H-600 Pipeli		eline Spread G				
Contractor Precision			LL				Report #	2775			
Inspector Tim Bowen							Date/Time	6/7	/2018 6:39	PM	
Permit # TBD		Inspection Type Weekly			Station Begin 1		10459+70				
State	VA		Inspection Area F		Full		Station End 116		11668+44	<del></del>	
County	Montgomery		Ground	Du	sty		Temperature (ºF)		77.00		
Municipality	N/A		Weather	Sui	nny		Rain Gauge (in) 0.0		0.00		
GPS Location	S Location 37.4520905955183, -81.0624			1925132911 Rai			Accumulation Time (days)			1.00	
. Are the appro	Are the approved (stamped) E&S Plan and PCSM Plan present on site?								Yes		
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings?  (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)								No			
Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)									Yes		
4. E&S BMPs ( is required.)	List BMPs and	I note if insta	lled and maintained	d <b>a</b> s	per the	plan. If o	corrective act	ion	is needed,	a pictu	
E&S BMPs		Compliance Level		Corrective Action				Corrective Time Frame			
Compost Filter Sock		Acceptable		N/A	/A			See Co	See Comments		
Sensitive Resource Signage		Acceptable		N/A			See Co	See Comments			
Silt Fence (Filter Fabric Fence)		Acceptable		N/A			See Commen		omments		
Waterbar		Acceptable		N/A				See Comments			
									+		
5. Site Conditi											
eyond defined	limits of distur	bance resulti	iment, gravel, oil, H ng from earth distui ironmental Permittii	rban	ce activ	vity or ine	•			No	
t prioto and imi		activivi Liiv.	ii Oriii ileritar i eriiiittii	19 0	OUI GII I	2101.					
·			final grade) been st	<u> </u>			uirements?			N/A	

MVP-34 REV 0 Page 1 of 3

No

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

<b>AFE</b> 124300137	<b>Date/Time</b> 6/7/201	8 6:39 PM	Report #	2775								
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a												
picture is required.)												
PCSM BMPs	Compliance Level	Corrective A	Corrective Time Frame									
7. Identify all remedial managers that have	boon taken since the r	rovious inspection wa	a conducted									
<ol> <li>Identify all remedial measures that have been taken since the previous inspection was conducted.</li> <li>Maintenance activities occur after every rain event. All problem areas have been addressed.</li> </ol>												
maintenance activities occur after every rain event. All problem areas have been addressed.												
Comments (Reference above questions as appropriate.)												
Traveled to Pocahontas Road and Mystery Ridge Road inspecting all environmental controls and for the presence of sediment outside of the LOD. All environmental controls have recently been cleaned out and additional layers of controls have been added in places where there is evidence of controls reaching maximum capacity during heavy rainfall events. There have been no significant rainfall events since the installation of controls on Brush Mountain and Sinking Creek Mountain. No compliance issues were observed today.												
,												

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3

AFE 124300137 Date/Time 6/7/2018 6:39 PM Report # 2775 **Pictures** GPS Location 37.4520926450319, -81.0624964710471 **GPS Location** 37.4523430830217, -81.0623712838451 Pocahontas Road - No impacts to resources. Pocahontas Road - Routine maintenance See photo for correct coordinates. completed. See photo for correct coordinates. Description Description GPS Location 37.4523430830217, -81.0623712838451 **GPS Location** 37.4523430830217, -81.0623712838451 Mystery Ridge Road - Routine maintenance completed. See photo for correct coordinates. Mystery Ridge Road - Routine maintenance completed. See photo for correct coordinates. Description Description om travel lane stabilized Sinking Creek Mounta GPS Location 37.4523664685315, -81.0625431966791 **GPS Location** 37.4520990038304, -81.0624319402667 Sinking Creek Mountain - Temporary bridge controls added at stream S-PP22. See photo See photo for correct coordinates. Sinking Creek Mountain. Topsoil from travel lane

MVP-34 REV 0 Page 3 of 3

Description

for correct coordinates.

Description

stabilized.