Mour 🏳	Ntain Valley		Visual	l Sit	te Ins	specti	on Repo	ort		
Project Nar	ne H-600 Pipe	eline Spread G		AFE	124300)137	Spread	H-600 I	Pipeline S	pread G
Contract	tor Precision						Report #	3070		
Inspect	t or Timothy W	/atson					Date/Time	6/14/2	2018 2:48	B PM
Permit #	TBD		Inspection Typ	oe VA	A SWPP		Station Beg	gin 10)557+28	
State	VA		Inspection Are	ea Pa	artial		Station E	nd 11	227+59	
County	Giles		Groun	1d Dr	у		Temp	peratu	re (ºF)	85.00
Municipality	N/A		Weath	er Su	inny		Raiı	n Gau	ge (in)	0.01
GPS Location	37.348487363	32317, -80.655	1226881152			Rain Ac	cumulation	Time	(days)	1.00
1. Are the appr	oved (stampe	d) E&S Plan	and PCSM Plan p	oreser	nt on site	e?				Yes
			the limits of distured ermitting Coordination					?		No
			e construction not ntal Permitting Co						being	Yes
4. E&S BMPs (is required.)	(List BMPs and	d note if insta	lled and maintain		per the	e plan. If c	corrective act	ion is I		-
1	E&S BMPs		Compliance Level	e		Correc	tive Action			rective Frame
Compost Filter So	ock		Acceptable		NA				See Co	omments
Silt Fence (Filter	Fabric Fence)		Acceptable		NA				See Co	omments
Rock Constructio	n Entrance		Acceptable		NA				See Co	omments
Silt Fence (Filter	Fabric Fence)		Problem Area		Repair	fence dam	aged by cattle		See Co	omments
5. Site Conditi								-		
beyond defined	limits of distu	rbance resulti	iment, gravel, oil, ing from earth dis ironmental Permit	turba	nce activ	vity or ine	•			No
Have inactive di	sturbed areas	s (stockpiles,	final grade) been	stabil	ized per	r state req	uirements?			Yes
Are slopes 3:1 a	and greater st	abilized with a	appropriate BMPs	s as p	er E&S	olans?				Yes
Has a new slip/s	slide been obs	served? (If ye	es, complete Slide	e Rep	ort Form	ı)				No

AFE 124300137	Date/Time 6/14/20	18 2:48 PM	Report #	3070				
 PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) 								
PCSM BMPs	Compliance Level	Corrective Ac	tion	Corrective Time Frame				
7. Identify all remedial measures that have b	peen taken since the p	revious inspection was	conducted.					
Comments (Reference above questions as a	appropriate.)							
Attended am inspection meeting and environmen RCE 241.01no issues mp 202.4 Made a visit to Access 238 and Norcross Rd crev seeded and strawed all worked areas, crew on o Ferc monitor stopped by and checked area at Big Made visit to and checked access 240 station106 and Mp 202.0 Checked area around Winding Way no issues wit 25 meet, must have been cut buy land owner. Se Checked area at access (241.01 Mp 211.3 off Mt Access 241.00 off Mtn Lake no issues Mp 211.2 S Access 242.01 Mp 208.4 ok no issues Mp 206.9 Kow Camp Rd 2 no issues with Rce Mp 206.0	v having JSA meeting DI n standby waiting on ner Stoney Creek, no comr 70+00 off Big Stoney an h Ecds , observed since e 1st photo below. Statio n Lake Rd. J hooks dam Station 11157+31	EQ present checked all Eq w bridge approved. Mp 20 nents. d RCE crossings station1 last visit a Access cut off on 11227+59 mp 212.5.	cds no issues o 0.4 station 105 0675+39 no is were the Atws	cleaned and 593+00 no issues sues Mp 201.9 and Access MLV				
Gravely Hill Rd. Checked access 237 no issues of	ompleted 6-12-18 Mp 19	19.6.						
Note: It is a condition of National Pollutant D maintenance program be conducted to provi weekly basis and after each stormwater ever replacement are needed or have been made inspection may result in permit suspension o as part of a permit condition this form may be	de for the operation ar nt. Please list in the sp for BMPs as a result r the imposition of civi	nd maintenance of all B bace provided commen of the inspection. Failu I penalties. If supplement	MPs to be ins ts to note if re re to conduct ental monitori	spected on a epairs or the required				

AFE	12430013 ⁻	7	Date/Time	6/14/2018 2:48 P	PM Report # 3070	
			Pict	ures		
P A D A H	brite & Thone There Jean 16 honoldon extension of the second sec	And the least appe		Dire 6 Time Thu Jun 14 Pesition - 100, indexes entropy of the second second entropy was ex- ected and the second second second entropy of the second second entropy of the second second entropy of the second second entropy of the second second second second entropy of the second second second second entropy of the second second second second second entropy of the second second second second second second entropy of the second second second second second second second entropy of the second second second second second second second entropy of the second second second second second second second second entropy of the second s		
GPS L		37.3586763628175, -80.6818305		GPS Location	37.38197601, -80.66636044	
Des	scription	Use photo GPS Winding Way At Access to valve 25 no issues not temper for drive leaving area. To	ws and e owner cut p left of Photo	Description	Use photo for gps silt fence damage access 241.01 off Mtn Lake Rd	d by cat
	Janes Inne, Fru Jun 14 Janes Inne, Fru Jun 14 Jacimin - 1007 (2016) Altitude 2022(f) Jacum W05-84 Jacum W05-84 Jacum Biological (2017) Levaton Grade - 2016 Jacum Biological (2017) Altitude - 2017 Altitude -			Diffe & Time: Thiu Jun 2014 Pearline - 0027 2014 22 Alfridge: 147978 Datimut W55-84 Elevation Grade - 002 2001112		
GPS L	Location	37.3585582198923, -80.6818549	0242622	GPS Location	37.3586173542192, -80.681842519	0455
Des	scription	Access RCE 241.01 completed c Anklets Rd	off Buffalo	Description	Area cleaned up and seeded and st Station 10595+ 95 off Norcross Rd a Stoney Creek buffer	rawed at at Big
A A E H	bate 64 mee, 100 106 80 20 batem Works as batem Works as timuth 86 merging 241 55 tevation Grade - 005 tevation Grade - 010 form, 1X			Date & Time: the United Position = 0071 (9:20) Attitude = 21/241 Datum V055-94 Azimuth/Perming=187* S Elevation Grade = 00/4 Zorm 1X	LI OPIOLE EDT 2018 BOD 24/58 46* SOTW 3324mils (True)	
GPS L	ocation	37.3585471557801, -80.6817493	3961012	GPS Location	37.3586834874352, -80.681643700	3022
Des	scription	Use photo on GPS RCE off Mtn I 242.01	Lake Rd.	Description	Use photo gps Doe Creek Rd RCE i	no issue