




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G		AFE	124300137	Spread	H-600 Pipeline Spread G	
Contractor	Precision				Report #	4468	
Inspector	Timothy Watson				Date/Time	7/12/2018 1:31 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	10510+78	
State	VA	Inspection Area	Partial		Station End	11236+10	
County	Giles	Ground	Dry		Temperature (°F)	82.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.01	
GPS Location	37.3115467653026, -80.5162240751837				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level		Corrective Action		Corrective Time Frame	
Compost Filter Sock		Acceptable		See Comments			
Silt Fence (Filter Fabric Fence)		Acceptable		See Comments			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable		See Comments			
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300137	Date/Time	7/12/2018 1:31 PM	Report #	4468
Pictures					
 <p>Date & Time: Thu Jul 12 08:42:09 EDT 2018 Position: +037° 18' 40.39" / -080° 31' 12.22" Altitude: 1817ft Datum: WGS-84 Azimuth/Bearing: 201° S21W 3573mils (True) Elevation Grade: +020% Horizon Grade: +005% Zoom: 1X covered bridge access249</p>		 <p>Date & Time: Thu Jul 12 09:21:55 EDT 2018 Position: +037° 18' 59.83" / -080° 33' 10.67" Altitude: 2096ft Datum: WGS-84 Azimuth/Bearing: 288° 145W 1294mils (True) Elevation Grade: +002% Horizon Grade: +002% Zoom: 1X access 242 off Brickyard Rd</p>			
GPS Location	37.3102200817983, -80.516336383467	GPS Location	37.3112292588104, -80.5166775361453		
Description	Covered bridge cultural inspection on site Mp211.1	Description	Use photo GPS Access 244 off Brickyard Rd in progress building access		
 <p>Date & Time: Thu Jul 12 15:42:20 EDT 2018 Position: +037° 18' 56.19" / -080° 31' 42.12" Altitude: 2010ft Datum: WGS-84 Azimuth/Bearing: 270° N97W 4800mils (True) Elevation Grade: -003% Horizon Grade: +008% Zoom: 1X station 1118+00</p>		 <p>Date & Time: Thu Jul 12 08:44:12 EDT 2018 Position: +037° 18' 39.70" / -080° 31' 3.36" Altitude: 1808ft Datum: WGS-84 Azimuth/Bearing: 266° S86W 4729mils (True) Elevation Grade: -010% Horizon Grade: +007% Zoom: 1X access 249</p>			
GPS Location	37.3112650914465, -80.5168587528919	GPS Location	37.3113961005931, -80.5167729222034		
Description	Use photo gps install super silt fence station 11118+00 to 11116+00 mp 210.4	Description	Access Rd 249 in progress needs brush removed Ecds installed and gravel to reduce run off		
 <p>Date & Time: Thu Jul 12 15:43:34 EDT 2018 Position: +037° 18' 36.31" / -080° 30' 29.29" Altitude: 1850ft Datum: WGS-84 Azimuth/Bearing: 022° N29E 6516mils (True) Elevation Grade: +000% Horizon Grade: +005% Zoom: 1X access249.01 repaired</p>		Insert image here			
GPS Location	37.320784621428, -80.637625298036	GPS Location			
Description	Use photo gps access 249.01 repaired silt fence 7-8-18	Description			