









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8038
<b>Inspector</b>	Timothy Watson			<b>Date/Time</b>	9/18/2018 9:57 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10510+78
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10883+50
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.50
<b>GPS Location</b>	37.1193505098817, -80.6680094454508			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Straw Bale Barrier	Communication	Staked down hay bays along 234		Addressed	9/18/2018
Waterbar	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

[illegible]

AFE	124300137	Date/Time	9/18/2018 9:57 AM	Report #	8038
Pictures					
<p>Date &amp; Time: Tue, Sep 18, 2018, 07:58:56 EDT Position: +037.349234° / -080.652507° Altitude: 2068ft Datum: WGS-84 Azimuth/Bearing: 158° S22E 2809mils (True) Elevation Angle: -03.9° Horizon Angle: -01.3° Zoom: 1X buffalo Anklets</p> 		<p>Date &amp; Time: Tue, Sep 18, 2018, 08:28:44 EDT Position: +037.372478° / -080.679726° Altitude: 1776ft Datum: WGS-84 Azimuth/Bearing: 088° N88E 1564mils (True) Elevation Angle: -05.2° Horizon Angle: -02.3° Zoom: 1X Access 234</p> 			
GPS Location	37.1191747149549, -80.6680562887647	GPS Location	37.1191747149549, -80.6680562887647		
Description	Buffalo Anklets Rain Gauge .5 over night	Description	Access 234 rain gauge over night .25 Mp 199		
<p>Date &amp; Time: Tue, Sep 18, 2018, 08:08:12 EDT Position: +037.349172° / -080.685217° Altitude: 2068ft Datum: WGS-84 Azimuth/Bearing: 120° S40E 4133mils (True) Elevation Angle: +04.7° Horizon Angle: +00.8° Zoom: 1X buffalo Anklets</p> 		<p>Position: +037.367175° / -080.685297° Altitude: 1952ft Datum: WGS-84 Azimuth/Bearing: 232° S52W 4124mils (True) Elevation Angle: +07.4° Horizon Angle: +01.4° Zoom: 1X Access 237</p> 			
GPS Location	37.1191747149549, -80.6680562887647	GPS Location	37.1191747149549, -80.6680562887647		
Description	Buffalo Anklets at stream and area above stream S G32 MP 205.5	Description	Access 237 some rutting on road by gravel movement		
<p>Date &amp; Time: Tue, Sep 18, 2018, 08:08:26 EDT Position: +037.348601° / -080.647562° Altitude: 2312ft Datum: WGS-84 Azimuth/Bearing: 108° S72E 1920mils (True) Elevation Angle: +07.0° Horizon Angle: -02.0° Zoom: 1X buffalo Anklets</p> 		<p>Date &amp; Time: Tue, Sep 18, 2018, 08:35:33 EDT Position: +037.370220° / -080.682195° Altitude: 1897ft Datum: WGS-84 Azimuth/Bearing: 284° S84W 4693mils (True) Elevation Angle: -00.6° Horizon Angle: -00.4° Zoom: 1X Access 23</p> 			
GPS Location	37.3475738926623, -80.6073855423253	GPS Location	37.3475780266361, -80.6073875979423		
Description	Buffalo Anklets and Row stream S G33 no Issues MP 205.6	Description	Access 236 no issues		