Mour	Ntain Valley		Visua	al S	ite	e Ins	specti	on Re	epo	ort		
Project Nan	ne H-600 Pipe	eline Spread G		AF	E	124300	0137	Spr	ead	H-600 F	Pipeline S	Spread G
Contract	or Precision							Repo	ort #	8843		
Inspect	or Timothy W	/atson						Date/Ti	ime	10/4/2	018 11:	04 AM
Permit #	TBD		Inspection T	ype	VA	SWPP		Station	Beg	in 10	501+00)
State	VA		Inspection A	Area	Par	tial		Statio	on Ei	nd 10	885+50)
County	Giles		Gro	und	Dry			Т	emp	eratu	re (⁰F)	88.00
Municipality	N/A		Wea	ther	Sur	nny			Rain	Gau	ge (in)	0.00
GPS Location	37.349555119	2182, -80.603	119444865				Rain Ac	cumulat	tion	Time	(days)	1.00
1. Are the appro	oved (stampe	d) E&S Plan	and PCSM Plai	n pres	ent	on sit	e?					Yes
2. Are there act (If yes, notify		•	the limits of dis ermitting Coord						ings?)		No
3. Is Constructi followed? (If			e construction r ntal Permitting								being	Yes
4. E&S BMPs (is required.)	(List BMPs and	d note if insta	lled and mainta	ained	as	per the	e plan. If c	corrective	e acti	on is r	needed	, a picture
E٤	&S BMPs	C	Compliance Level		Corrective Action					rectiv e Fran		
Compost Filter So	ock	Acc	eptable									
Silt Fence (Filter Fabric Fence)		Acc	ceptable									
Compost Filter Be	erm	Acc	eptable									
Sediment Filter Lo	og	Acc	ceptable									
Waterbar		Acc	ceptable									
5. Site Conditi	ons											
Is an unauthoriz beyond defined a photo and imn	limits of distu	rbance resulti	ing from earth c	listurb	ano	ce acti	vity or inef	-				No
Have inactive di	sturbed areas	s (stockpiles, t	final grade) bee	en stat	siliz	zed pe	r state req	uirement	ts?			Yes
Are slopes 3:1 a	and greater sta	abilized with a	appropriate BM	Ps as	pei	r E&S	plans?					Yes
Has a new slip/s	slide been obs	served? (If ye	es, complete Sli	de Re	epo	rt Forn	n)					No

AFE 124300137	Date/Tir	ne 10/4/2018 11:04 AM	Report # 884	13		
 PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) 						
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired		
	Level			Repaired		
7. Identify all remedial measures that h	ave been taken s	since the previous inspection was	s conducted.			
Comments (Reference above questions	s as appropriate.)					
Spread 8 Attended am inspection and environmental 10510+78 to 10501+10 Checked Access 23 Checked access 235,236 ok no issues. 10556+00 area were Access 237 hits Row of 10602+18 Access 238 and Norcross Rd to I 10675+04 Big Stoney Creek Rd ok ,no issue 10692+42 Mp 202.4 Access 241 off Buffalo mulched along the Access rd. 10696+42 Buffalo Anklets Rd. S G 32 good 10710+00 to 10736+50 off Buffalo Anklets F 10860+ 75 Kow Camp Rd 2 checked condit No issues 10856+70 Kow Camp Rd 2 P1silt fence ok r 10883+08 Kow Camp Rd 1 stream S A32 r	34 ok in area, P 1 s ok no Issues. Mp 1 Big Stoney Creek r es stream S G30 g Anklets Rd , no iss I Mp 202.5 area sta Rd access 241.01 r ions of Row no issu	ilt fence ok.Mp 198.9 no issues with 99.9 no Issues. ood, no Issues. sues good growth on Row and recen abilized and not washing. no issues wet land WZ11 MP203.1 ues ,Sump pits full some water, but i ng at stream S A33 & 34 Issues.	ntly disturbed area s no Issues.	seeded and		
Note: It is a condition of National Polluta maintenance program be conducted to weekly basis and after each stormwater replacement are needed or have been r inspection may result in permit suspens as part of a permit condition this form m	provide for the op event. Please li made for BMPs a ion or the imposi	beration and maintenance of all E st in the space provided commer s a result of the inspection. Failu tion of civil penalties. If supplem	BMPs to be inspected on the second of the se	cted on a irs or e required		

AFE 12	2430013	7	10/4/2018 11:04 /	۹M	Report # 8843				
			Pict						
Altitu Datun Azimu Eleva Horiza Zoom	8, Times Thu Oct 04, ion, +027 376458' 7 - de 2060ft m WOS-94 Uth (Bearing) 053 'N W Iton Angle + 06 3 or Angle + 00 8 - i 22 is 234			Date & times time, 0ct 0k Position 4039 34831 AL Attitude 2365ft Datum: WOS-84	DEP reducers				
GPS Lo		37.3372893920516, -80.6046311		GPS Location		0516, -80.6046311092382			
Desc	ription	Access 234 station 10510+00 P1 place not disturbed by land owner		Description	10712+00 look no issues	king toward Buffalo Anklets Rd			
Positi Altitu Datun Azimu Eleva		080.643089°		Date & Time Thu, De Due Position, 1997 37587 ** Altitude: 22081 Datum WGS-84 Azimuth/Bearing. 3874 ** Horizon Angle: +0.02* Zoom 1X kow Camp Rd 2	080-605286				
GPS Lo	ocation	37.3371673934509, -80.6046247		GPS Location		2139, -80.6045489665871			
Desc	ription	10732+38 wet land north of Hend issues my 203.1	lerson Rd no	Description	Kow Camp Ro Issues	l 2 stream S A 33,&34 ok no			
Altitu Datur Azimu Eleva Horizo Zoom	8 Imme Thu, Oct 04, oni – 037 336682 / de 2 38616 / de 2 38616 / de 2 38616 / de 2 38616 / de 2 38616 / de 2 38616 / de 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			Date & Time: Thu: Oct 04, Posifion; 1097336711 / Attitude 24401 Datum: W058-94 Azimuth/Gearing: 3157 N Elevation Angle: 10.30 Horizon Angle: 00.21 Zoom: 1X kow Camp Rd 2					
GPS Lo	ocation	37.3372978577738, -80.6044778	042292	GPS Location	37.337308125	6052, -80.6044884492462			
Desc	ription	Water bar and out let treatment o 2 10860+50	ff Kow Camp	Description	10861+00 betw Row some gro	ween Kow Camp Rd 2 and 1 owth on travel lane.			