Mountain Valley			Visual Site Inspection Report										
Project Name H-600 Pipeline Spread				Al	<b>FE</b> 124300137			Spread H-		H-600 Pipelii	1-600 Pipeline Spread G		
Contract			•			Repo	ort#	8865					
Inspect					<b>Date/Time</b> 10/4/2018 2:10				) PM				
Permit # TBD			Inspection Type VA SWPP				Station Begin 10885+50						
State	VA		Inspection Are		Partial			Station End 10929+50					
County Giles		Ground		Dry			Temperature (°F)				88.00		
Municipality	N/A	Weather		Sunny		Rain Gauge (in)			0.00				
GPS Location	37.334954119	96455, -80.596°	7662759847			Rain Ac		cumulation Time (days)			1.00		
1. Are the appre	and PCSM Plan present on site?								Yes				
Are there activities occurring outside of the limits of disturbance shown on the plan drawings?  (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)										No			
<ul> <li>3. Is Construction sequence outlined in the construction notes of the E&amp;S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)</li> <li>4. E&amp;S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)</li> </ul>													
E&S BMPs		C	Compliance Level	Corrective Action					rective Frame	R	Date epaired		
Compost Filter So	ock	Acc	ceptable										
Rock Construction Entrance		Acc	ceptable										
Silt Fence (Filter Fabric Fence)		Acc	eptable										
Silt Fence (Reinfo	orced Filter Fab	oric Fence) Acc	eptable										
Sump Pit		Acc	ceptable										
5. Site Conditi	ons												
		(such as sad	iment gravel	oil Hr	)D fluid	etc	) occurr	ing to wa	atore	wetlands	Or		
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.										No			
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									Yes				
Are slopes 3:1 a	and greater st	abilized with a	appropriate BN	лРs as	per E&S	S pla	ans?					Yes	
Has a new slip/slide been observed? (If yes, complete Slide Report Form)										No			


MVP-34 REV 0 Page 1 of 3

<b>AFE</b> 124300137	Di	ate/Ti	me 10/4/2018 2:10 PM	Report # 8865						
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)										
· · · · · · · · · · · · · · · · · · ·		ince I	Corrective Action	Corrective Time Frame	Date Repaired					
	<u> </u>									
7. Identify all remedial measures that have been taken since the previous inspection was conducted.										
7. Identify all remediar measures that have been taken since the previous inspection was conducted.										
Comments (Reference above questions as appropriate.)										
Spread 9 Attended am inspection and environmental meeting. 10885+00 Checked area off Row from Kow Camp Rd 1 to Dow Creek road. 10925+25 sump holding a lot of water but not much sediment percent. Water bars still working properly. No issues with outlet treatments at this time. All P1 silt fence ok and all super silt fence ok.										
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a										
maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a										

MVP-34 REV 0 Page 2 of 3

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.



MVP-34 REV 0 Page 3 of 3