r Mour	Ntain Valle	uc	Visual	Site	e Ins	specti	on Repo	ort			
Project Nar	<b>ne</b> H-600 F	ipeline Spread G		AFE	124300	137	Spread	H-600 I	Pipeline S	pread G	
Contractor Precision						Report #	2069				
Inspect	tor Trey Ing	ram					Date/Time	5/22/2	2018 1:5	3 PM	
Permit # TBD			Inspection Type VA SWPP				Station Beg	<b>jin</b> 11900+00			
State VA			Inspection Area Full		111		Station End 12007-		2007+00		
County Montgomery			Ground D		Damp		Temperature		re (ºF)	77.00	
Municipality N/A			Weather Cloudy		udy	Rai		n Gauge (in)		0.00	
GPS Location	37.2873982	088987, -80.336	3600644919 Rair			Rain Ac	Accumulation Time (days)			1.00	
1. Are the appr	oved (stam	oed) E&S Plan	and PCSM Plan p	present	on site	e?				Yes	
			the limits of disture					?		No	
			e construction not ental Permitting Co						being	Yes	
4. E&S BMPs ( is required.)	(List BMPs a	ind note if insta	alled and maintain	ied as p	per the	e plan. If c	orrective acti	ion is I	needed,	a picture	
E&S BMPs		Compliance Level	e		Corrective Action			Corrective Time Frame			
Compost Filter Sock			Problem Area		Filed Fl	ed FERC variance to reclaim sedime			Addressed		
Culvert			Acceptable		None			See Comments			
Housekeeping			Acceptable		None				See Co	omments	
Rock Construction Entrance			Acceptable	Acceptable None					See Co	omments	
Rock Filter Outlet			Acceptable	ceptable None			See (		See Co	Comments	
Silt Fence (Filter Fabric Fence)			Acceptable		None		See C		See Co	omments	
Vegetative Stabilization (Temporary)		Acceptable None				See Comments					
Waterbar		Acceptable	e None			See		See Co	Comments		
Waterbar Outlet Protection			Acceptable	None			See Co			omments	
5. Site Conditi	ons										
beyond defined	limits of dis	turbance result	iment, gravel, oil, ing from earth dis rironmental Permit	turband	ce activ	vity or inef				No	
Have inactive di	sturbed are	as (stockpiles,	final grade) been	stabiliz	ed per	state req	uirements?			Yes	
Are slopes 3:1 a	and greater	stabilized with a	appropriate BMPs	as per	E&S p	olans?				Yes	
Has a new slip/s	slide been o	bserved? (If ye	es, complete Slide	Repor	rt Form	ı)				No	

AFE 124300137	Date/Time 5/22/20	018 1:53 PM	Report #	2069				
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)								
PCSM BMPs	Compliance Level	Corrective Ac	tion	Corrective Time Frame				
7. Identify all remedial measures that have	been taken since the p	previous inspection was	conducted.					
<b>Comments</b> (Reference above questions as Since last storm water inspection: No Significan								
Percision worked on grade, ECD installs, stabili:	zing topsoil piles, continue	ed constructing AR-266						
Checked all completed ECDs from MP-225.7 to 227.3 observed 1 area of concern st#11992+00 where sediment had overwhelmed the filter sock and over ran causing sediment to leave workspace. Additional ECDs P1 were added and the landowner will be contacted to retrieve sediment.								
Environmental crew continued installing ECDs per plans. Observed installation of filter fence and filter sock, crew installed per specs and no issues observed.								
Observed flumes, ditch checks, RCEs, RFOs, filter sock, feature crossing, water breakers, housekeeping. No issues observed.								
Note: It is a condition of National Pollutant	Discharge Elimination S	System and Erosion and	Sediment pe	ermits that a				
maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or								
replacement are needed or have been mad	le for BMPs as a result	of the inspection. Failu	re to conduct	the required				
inspection may result in permit suspension as part of a permit condition this form may be				ng is required				

AFE 1	124300137	7	5/22/2018 1:53 Pl	M	Report #	2069	
Pict							
Athi Dati Ziti Elec Hor Zoo	te & Time, 'uL May 22 H sition - 403/28738' 7 htude 22191 um/ WS-84 imut/WBaaring 227 Nk um/th/Baaring 227 Nk um/t			Data Strime Tun May 22 Posi on - 007 225515 - Anthone 2010th - 2020 Anarhum Bearing, 1021 A Brevallon Angler - 213 Bronzon Angler - 0138 down - 1X	11.13.54.EDT.2018 080.311.13; 52: 1722;nilis Exrohut 10:10:10:10:10:10:10:10:10:10:10:10:10:1		
GPS L		37.2770783588397, -80.3942023		GPS Location	37.2772992728625, -80.3945866507296		
Description Filter fence in good working condition.   Coordinates located in picture above			Description	Sock overwheli st#11992+00	mea with sedi	ment	
<b>西</b> 南京市 28 1997年1月1日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日	itude 2114ft tum: WGS-84	5 60 20 TO 2018 TAR		Dele & Time Jue May 22 Pesition 4.097 278697 Alfitude 2006H Datum W05-60 Alfitude 2006H Hortzon Angle - 200 Hortzon Angle - 100 Zoom 1X	15.12.33 EDT 2016 080.027.070 WW Xadaemis moe		
GPS L		37.2773710219537, -80.3945884		<b>GPS</b> Location			
Dese	cription	Additional ECDs added st#11992	2+00	Description	Installing ECDs loss. 11992+00	s to prevent ac )	ditional sediment
		Insert image here		Date & Time: Tue May 22 Position - 022 22211 And an USE Sector Se	13 do. 3 vi EUT 2018 do. 3 di Sos evenemente en per		
GPS L	ocation			GPS Location	37.2773599159	932, -80.3946	106229726
Dese	cription			Description	Stone added to	access rd 26	6