Mour Mour	ita V	ain Valley		Visu	ıal S	Site Ins	specti	on Rep	ort	
Project Nan	ne	H-600 Pipelir	ne Spread H		Al	FE 124300	0138	Spread	H-600 Pipeline	Spread H
Contractor Precision				•			Report #	Report # 4153		
Inspector Casey McGaha							Date/Time	ate/Time 7/3/2018 6:53 PM		
Permit #	ТВІ	D		Inspection	Inspection Type VA SWPP			Station Beg	50	
State	VA			Inspection Area		Full	Full Sta		nd 13670+0	00
County	County Franklin		Ground		Dry		Tem	98.00		
Municipality	N/A	\		We	ather	Sunny	Rain Gauge (in)			0.00
GPS Location	36.	97181420406	642, -79.870	0142147477		-	Rain Ac	cumulation	0.00	
1. Are the appro	ove	d (stamped)	E&S Plan	and PCSM Pl	an pres	sent on sit	e?			Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)										
 Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture 								Yes		
is required.)	LISC	. Di ii 3 di ia i	note ii iiiste	anca ana man	itairica	us per tric	piani ii c	orrective act	ion is neede	a, a picture
Εδ	<u> </u>		Compliance Level	Corrective Action				rrective e Frame	Date Repaired	
	5. Site Conditions Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or									or
beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.										
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes			
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes			
Has a new slip/slide been observed? (If yes, complete Slide Report Form)								No		

MVP-34 REV 0 Page 1 of 3

AFE 124300138	Date/T	ime 7/3/2018 6:53 PM	Report # 415	53				
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)								
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired				
				-				
7. Identify all remedial measures that h	ave been taken	since the previous inspection was	conducted.					
• (0.6								
Comments (Reference above questions as appropriate.) Precision continues to make repairs to BMPs and ensure all measures are installed to spec during the shutdown period. The El team continues to travel the ROW to monitor the work performed and to identify new issues.								
team continues to travel the ROW to monitor	r the work periorr	ned and to identify new issues.						
Note: It is a condition of National Polluta	ant Discharge E	limination System and Frasion on	d Sediment norm	its that a				
maintenance program be conducted to weekly basis and after each stormwater	provide for the c	pperation and maintenance of all E	BMPs to be inspec	cted on a				

MVP-34 REV 0 Page 2 of 3

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300138	3	Date/Time 7/3/2018 6:53 PM			Report #	4153
Pictures							
					Control of Control o	Notes to the second sec	The state of the s
GPS L		36.9718926666043, -79.8701035		GPS Location	ı		0519869668
Des	scription	Rip rap installed on fill slope at bi 13531+00	reaker end sta	Description	Punchlist 7-3-1	18	
		Insert image here			Insert im	age here	
GPS L	_ocation			GPS Location			
Des	scription			Description			
		Insert image here			Insert im	age here	
GPS L	_ocation			GPS Location			
Des	scription			Description			

MVP-34 REV 0 Page 3 of 3