🌄 Mour	Valley		Visual	Sit	e Ins	specti	on Repo	ort		
Project Nar	ne H-600 Pip	eline Spread H		AFE	124300)138	Spread	H-60	0 Pipeline S	pread H
Contractor Precision						Report #	313	3136		
Inspector Dawn McCullough						Date/Time	6/15	6/15/2018 8:02 PM		
Permit #	TBD		Inspection Type		/A SWPP		Station Beg	gin +00		
State	VA		Inspection Area		Full		Station End +00		+00	
County	Montgomery		Ground		Dry		Temperature (^e l		ture (ºF)	74.00
Municipality	N/A		Weather		Sunny		Rain Gauge (in		uge (in)	0.00
GPS Location	37.27324847	27217, -80.057	1908103915			Rain Ac	cumulation	Tim	e (days)	1.00
1. Are the appr	oved (stampe	ed) E&S Plan	and PCSM Plan p	reser	nt on sit	e?				Yes
			the limits of distur					?		No
			e construction not ntal Permitting Co						et being	Yes
4. E&S BMPs (is required.)	(List BMPs an	d note if insta	lled and maintain	ed as	per the	e plan. If c	corrective act	ion i	s needed,	a picture
E&S BMPs		Compliance Level	e		Correc	Corrective Action			Corrective Time Frame	
Compost Filter So	ock		Acceptable							
Housekeeping			Acceptable							
Other		Communication	Remove diesel o		ve diesel co	overed gravel		Addres	Addressed	
Rock Construction Entrance		Acceptable								
Sensitive Resource Buffer		Acceptable								
Sensitive Resour	ce Signage		Acceptable							
Waste Management		Acceptable								
5. Site Conditi	ons									
beyond defined	limits of distu	irbance resulti	iment, gravel, oil, ing from earth dist ironmental Permit	turbar	nce acti	vity or ine	•			No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A				
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A			
Has a new slip/slide been observed? (If yes, complete Slide Report Form)								No		

AFE 124300138	Date/Time 6/15/20)18 8:02 PM	Report #	3136
 PCSM BMPs (List BMPs and note if insi picture is required.) 	talled and maintained a	s per the plan. If correct	ctive action is	needed, a
PCSM BMPs	Compliance Level	Corrective Ac	tion	Corrective Time Frame
 Identify all remedial measures that have Unmarked storage containers were marked, wit 		·		
Comments (Reference above questions as Attended morning inspectors meeting for Sprea Rain gauge at MVP-PY-006 measured 0.0 inche Sections were the contractor repaired the CFS is portable toilets were all in acceptable secondary on sleds in the welding area of the yard were no dumpsters need housekeeping. No smoking sig ordered. No additional environmental concerns	d H. Discussed daily task es of rainfall. CFS along the need staking or repaired p y containment. Rock cons oted and will be addressed ns are needed at fuel stol	ne perimeter of the site wa per manufacture's specific truction entrances were m I if secondary containmen age locations - contractor	as functioning a ations. Tempor naintained. Gen nt is required. G	acceptably. ary lights and erators operating arbage
Note: It is a condition of National Pollutant	Discharge Elimination 9	System and Frosion and	d Sediment of	ermits that a
maintenance program be conducted to prov weekly basis and after each stormwater ever replacement are needed or have been mad inspection may result in permit suspension as part of a permit condition this form may	vide for the operation a ent. Please list in the s le for BMPs as a result or the imposition of civi	nd maintenance of all B pace provided comment of the inspection. Failu I penalties. If supplement	MPs to be ins ats to note if re are to conduct ental monitori	spected on a epairs or the required

AFE	124300138	B Date/Time		6/15/2018 8:02 PI	M Report #	3136	
Pict				ures	·		
A D A	ate & Time Fin den 19 0 osition: +007/045595 Ultitude: 128/h atum: WGS-84 Zimuth Bearing: 250 - S3 Levation Angle: +017 Open: 11 Yangs	OW 4444mils(True)		Date & Time FréJun 15 0 Position + 037 235806 / - Altitude 12241 Datum W05-24 22 35 Elevation 4010 2 7 Rescale and the second of the monomorphism	84 / 24 / 27 / 2018 080 / 226:249 862 / 2169mils (Fgab) 100 / 2		
GPS L		37.2732899767044, -80.057213		GPS Location	37.2732822847199, -80.057		
Des	Description Please see photo for coordinates. MVP-PY-006, diesel noted on gravel and fueling stations.			Description	Please see photo for coordinates. MVP-PY-006, CFS repair needs stakes additional repair.		
D A E HH	lititude 12771 bitm: WES-54 zimuth Bearine 218,55 extension Annuel 19, 200 bitm: 200 b			Altimological control with the second	544 Sc40mits (True)		
GPS L	ocation	37.2732777087232, -80.057265	7497173	GPS Location	37.2732775919367, -80.057	266291947	
Description Please see photo for of MVP-PY-006, generate activities.		Please see photo for coordinates MVP-PY-006, generator on sled activities.	s. for welding	Description	Please see photo for coordir MVP-PY-006, secondary cor addressed.	noto for coordinates. secondary containment liquid	
P A D A E	ate & Time: Fri Jun 19 11 osition - H07 238876' / - Hittode: 12887' (Intern-WGS-84 (Intern-WGS-84 (Intern-Garing: 113' SE tevation Angle - 09.8' opm 12 (-006)	080 2271910		Date & Time, Fin Jun 15 () Posten - 030/234247 V Attinea 19801 Ontern Wolssen Brance - Marcine - 1000 Branch - Marcine - 1000 Branch - Marcine - 1000 Posten - 4000 Posten	080.227829		
GPS L	ocation	37.2732848591178, -80.057203	8036519	GPS Location	37.2732893653252, -80.057	165290966	
Des	scription	Please see photo for coordinate MVP-PY-006, signage installed.	S.		Please see photo for coordir MVP-PY-006, portable fuel s signage.	ates.	