C Mour	nta V	alley		Visu	ual S	Site	e Ins	specti	on Re	por	ť		
Project Name H-600 Pipeline Spread H		Н	AFE 124300138			Sprea	Spread H-600 Pipeline S		Spread	ΙH			
Contractor Precision				• •				Report	port # 2196				
Inspector Dennis Evans								Date/Time 5/24/2018 9		:14 PM	I		
Permit #	TBD Inspection Typ			Туре	VA SWPP		Station Begin 1237		12371+(71+00			
State	State VA			Inspection	Inspection Area		Partial		Station End 128		12807+4	2807+43	
County Roanoke		Gr	Ground		Damp		Temperate		ature (°F	76.0)0		
Municipality N/A			Weather		Sunny		Rain Gauge (in)) 0.00)		
GPS Location	GPS Location 37.2800337572915, -80.0294			94118342718	118342718 Rain A			ccumulation Time (days)			;) 1.00)	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Y								í es					
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)									No				
3. Is Constructi followed? (If		•		he construction ental Permitting				•			set being	Y	⁄es
4. E&S BMPs (is required.)	(Lis	t BMPs and	note if inst	talled and main	tained	as p	per the	e plan. If c	corrective a	iction	is neede	d, a pi	icture
E٤	E&S BMPs		Compliance Level		Corrective Action					ctive Frame			
5. Site Conditi	ons	6											
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No						
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?								٩/A					
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? N/A								√/A					
Has a new slip/slide been observed? (If yes, complete Slide Report Form) No								No					

AFE 124300138	124300138 Date/Time 5/24/2018 9:14 PM			Report # 2196				
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)								
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired				
7. Identify all remedial measures that h	have been taken s	since the previous inspection wa	as conducted.					
Comments (Reference above question I performed a SWPP inspection on SP 10 fr	om Sta:# 12371+0	0 to Sta:# 12807+43. The only acti	vity or ground distur	pance found				
between these station numbers, was Line L 12690+43. No more activity in this area at t	ocating/Pot Holing his time.	being performed at ROW crossing	on Honeysuckle Rd	. at Sta:#				
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a								
weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required								
inspection may result in permit suspens as part of a permit condition this form m				s required				

AFE 12430	138	Date/Time 5/24/20	18 9:14 PN	Report # 2196				
Pictures								
Altimite Statu Branchen Weiter Branchen Angles Branchen Angles Branchen Angles			Insert image here					
GPS Locati	on 37.2795497716329, -80.029221		ocation					
Descripti	Line Locating/Pot Holing at Sta: See photo for accurate coordina	# 12690+43 tes. Des	cription					
	Insert image here			Insert im	age here			
GPS Locati	on	GPS L	ocation					
Descripti	on	Des	cription					
	Insert image here			Insert im	age here			
GPS Locati	on	GPS L	ocation					
Descripti	on	Des	cription					