C Mour	Nalley		Visual	Si	te Ins	specti	on Repo	ort		
Project Name H-600 Pipeline Spread H		AFE 124300138		Spread	H-600 Pipeline Spread H					
Contractor Precision		•				Report #	3997			
Inspect	tor Dennis Ev	ans					Date/Time	7/3/	2018 1:05	PM
Permit #	твр		Inspection Typ	e VA	SWPP		Station Beg	gin	12991+00	
State VA		Inspection Area		Partial		Station E	Station End 12999+30			
County Roanoke		Ground		Dry		Temperature		ture (ºF)	97.00	
Municipality	Municipality N/A		Weather		Sunny		Rain Gauge (ii		uge (in)	0.00
GPS Location	37.27974926	9579, -80.02924	411944862			Rain Accumulation		Time (days)		1.00
1. Are the appr	oved (stampe	ed) E&S Plan	and PCSM Plan present on site?					Yes		
			the limits of distur ermitting Coordina					?		No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes				
4. E&S BMPs ( is required.)	(List BMPs an	d note if insta	lled and maintain	ed as	per the	e plan. If c	corrective act	ion is	s needed,	a picture
	E&S BMPs		Compliance Level	e		Correc	tive Action			rective e Frame
Compost Filter Se	ock		Acceptable							
Dewatering Work	Area		Acceptable							
Housekeeping			Acceptable							
Pumped Water F	ilter Bag		Acceptable							
Rock Constructio	n Entrance		Acceptable							
Silt Fence (Filter Fabric Fence)		Acceptable								
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable								
Temporary Diversion Berm		Acceptable								
Waterbar		Acceptable								
5. Site Conditi	ons									
beyond defined	limits of distu	rbance resulti	iment, gravel, oil, ing from earth dist ironmental Permit	turba	nce acti	vity or ine	•			No
Have inactive di	sturbed areas	s (stockpiles,	final grade) been :	stabil	ized pe	r state req	uirements?			Yes
Are slopes 3:1 a	and greater st	abilized with a	appropriate BMPs	as p	er E&S	plans?				N/A
Has a new slip/s	slide been ob	served? (If ye	es, complete Slide	Rep	ort Forn	n)				No

AFE 124300138	Date/Time 7/3/201	8 1:05 PM	Report #	3997				
6. PCSM BMPs (List BMPs and note if inst			-					
picture is required.)								
PCSM BMPs	Compliance Level	Corrective Ac	tion	Corrective Time Frame				
	2010.							
7. Identify all remedial measures that have	been taken since the p	revious inspection was	conducted.					
Comments (Reference above questions as appropriate.)								
SP 10 Summary: The 12" composite filter sock, priority #1 silt fence, and SSF along the LOD are in compliance. The water bars, sumps, and J-Hooks have been cleaned out and are functioning properly. The top soil, sub soil piles, and the temporary clean water								
diversion berm is stabilized, and in compliance. The RCE is in compliance on the East side of Hwy 221. The Port-A-Toilets are secured. The de-watering structure @ Sta:# 12991+00 is in compliance, and the stream S-B21 below the de-watering structure is								
clear. The de-watering structure @ sta# 12995+00 is in compliance. The water pump was in containment. There has been no activity in this location since the last SWPPP report due to environmental shut down. The SWPPP inspection is at MP 246.0.								
Note: It is a condition of National Ballutant (	Discharge Elimination (	Notom and Eracian and	1 Sodimont n	armite that a				
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a								
weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or								
replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required								
as part of a permit condition this form may be used to meet those monitoring requirements.								

<b>AFE</b> 12	4300138	8	Date/Time	7/3/2018 1:05 PN	A Report # 3997
			Pict	ures	
Control of Sector	Illinois Taxo Judi 2008 in editory 1 subscript of a subscript of a subscript of a subscript of a			Contro & Timme Time, Ad. 9, 00 Providinan 4 (2017) (SUBJYP / A SUBJAC SUBJAC	DRUG 14 BIERTY 2008 4-000: 1300728* HDEF 1422mils (Trus) Bi 1294-02 road bore
GPS Lo		37.2796647152781, -80.0294853		GPS Location	37.280021421646, -80.0294462219626
Descr	iption	Hwy 221 W-B24-PSS West side See photo for accurate coordinat	MP 246.0 es.	Description	Hwy 221 road bore East side MP 246.0 See photo for accurate coordinates.
	And Field And Field And And And And And And And And And And And And And And And And And And	Teres and the result of the re		Garran W39-40 Actinator Augusta (Marcha) Actinator Augusta (Marcha) Basantan August (Marcha) Hanteon Angusta (Marcha) Hanteon Angusta (Marcha) Hanteon Angusta (Marcha) Hang 201 month home & an	A 1000-KVI puth and adultion
GPS Lo	cation	37.280156035011, -80.02948746	609262	GPS Location	37.2801702423368, -80.0294718705863
Descr	iption	RCE Hwy 221 East side MP 246. See photo for accurate coordinat	.0 es	Description	MP 246.0 sub soil pile stabilized See photo for accurate coordinates
Dong & Postbar Dollaring Adonati Commit Hvy 22	Time Tue Jul 2 06	DOD 1 SENDS* EL 2026 - 00 va un r. Al a un partico - 1 Partico - 00 va un r. Al a un partico - 00 va un r. Al a un partico - 00 va un partico -		Date & the base of problem in the period of problem in the period of problem in the period of the pe	
GPS Lo		37.2801619861622, -80.0294458		GPS Location	37.2801557416444, -80.0294402708113
Descr		MP 246.0 water bars installed, to stabilized. See photo for accurate coordinat	-	Description	MP 246.0 bore pit See photo for accurate coordinates.