Mour	Ntain Valley		Visu	ial S	Site	e Ins	specti	on Rej	oor	t	
Project Nar	ne H-600 Pip	eline Spread H	ł	Α	FE	124300	0138	Sprea	d H-(	600 Pipeline	Spread H
Contract	or Precision			•				Report	<b>#</b> 64	130	
Inspector Glenn Mike Renfro							Date/Tim	<b>e</b> 8/	8/16/2018 1:19 PM		
Permit #	TBD	BD		Inspection Type		VA SWPP		Station B	ion Begin 13415+0		C
State	VA		Inspection Area		Full		Station End 13670+0		C		
County	Franklin		Gr	ound	Dry			Tei	nper	ature (°F)	87.00
Municipality	ality N/A		Weather		Cloudy		Rain Gauge (in)			0.00	
GPS Location 36.9719488519908, -79.870			1207304504	-	Rain Accumu		cumulatio	llation Time (days)		1.00	
1. Are the approved (stamped) E&S Plan			and PCSM Plan present on site?						Yes		
<ol> <li>Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)</li> </ol>									No		
<b>3.</b> Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)								Yes			
4. E&S BMPs ( is required.)	(List BMPs an	d note if insta	alled and main	tained	as p	per the	e plan. If c	corrective a	ction	is needed	l, a picture
E&S BMPs		(	Compliance Level		Corrective Action					ective Date Frame Repaired	
Compost Filter Sock		Ace	ceptable								
Housekeeping		Ace	ceptable								
Rock Construction Entrance		Ace	ceptable								
Silt Fence (Filter Fabric Fence)			mmunication	Repair	P1 s	ilt fenc	e at 13631 <sup>.</sup>	+00			
Silt Fence (Reinforced Filter Fabric Fence)		oric Fence) Acc	ceptable								
Waterbar		Ace	ceptable								
Temporary Diversion Berm		Aco	ceptable								
5. Site Conditi	ons										
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.											
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?								Yes			
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?								Yes			
Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No		

AFE 124300138	Date/Tir	<b>me</b> 8/16/2018 1:19 PM	Report # 643	30
<ol> <li>PCSM BMPs (List BMPs and note if picture is required.)</li> </ol>	installed and ma	intained as per the plan. If corre	ctive action is nee	eded, a
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
7. Identify all remedial measures that h	ave been taken s	since the previous inspection was	s conducted.	
Comments (Reference above questions				
Performed SWPPP inspection of the spread found that needs to be addressed by the co and end treatments were in good condition.	ntractor. The RCE	s were in acceptable condition throu	ghout the section.	The waterbars
reclamation to began in the next few days. (	Clean up operation	s include the installation of permane	nt waterbars and o	ther PCSM's.
Note: It is a condition of National Polluta	ant Discharge Eli	mination System and Erosion an	d Sediment perm	its that a
maintenance program be conducted to weekly basis and after each stormwater	provide for the op	peration and maintenance of all E	BMPs to be inspec	cted on a
replacement are needed or have been r inspection may result in permit suspens	made for BMPs a	s a result of the inspection. Failu	ure to conduct the	e required
as part of a permit condition this form m				3 IEquileu

AFE 124300138		Date/Time	8/16/2018 1:19 PI	M Report # 6430
		Pict	ures	
	36.9719268090816, -79.8701969		GPS Location	36.9719244001883, -79.8702499658714
Description	Putting back topsoil near kickoff (13418+00)		Description	Installation of permanent waterbar on GAS 13425+01
GPS Location	36.9719339503563, -79.8702133			36.9719318971341, -79.8702231657139
Description	Stabilization and ECD installatior S-IJ4 (13425+01)	n at stream	Description	Silt fence outlet with j-hook at 13423+00
				Insert image here
GPS Location	36.971906390759, -79.87025405	594684	GPS Location	
Description	Stabilization on the GAS of Mont 13575+35	y Rd	Description	