Mountain Valley			Visual Site Inspection Report									
Project Name H-600 Pipeline Sprea		eline Spread H	1	Al	FE 124300138		Spr	ead	H-600 Pipel	ine S _l	oread H	
Contractor Precision				•	•			Repo	rt #	7508		
Inspect						Date/Ti	Date/Time 9/7/2018 4:19 F					
Permit #	Permit # TBD			Inspection Type VA SWPP				Station	Station Begin 13415+00			
State	VA		Inspection Area		Full		Statio	Station End 13670+00				
County	Franklin		Ground		Dry		Temperature (°F)				91.00	
Municipality	N/A		Weather		Sunny		Rain Gauge (in)			0.00		
GPS Location	37.48611628	31476, -79.17	9074056222			Rain Ac		ccumulation Time (days)			1.00	
1. Are the appro	1. Are the approved (stamped) E&S Plan a				and PCSM Plan present on site?							
Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)											No	
 Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, 											Yes	
is required.)	LIST BMPS ar	a note if inst	alled and mair	ntainea	as per t	ne	pian. If o	corrective	e actio	on is need	iea,	a picture
E&S BMPs			Compliance Level	Corrective Action					rective Frame	R	Date epaired	
Compost Filter Sock		Ac	cceptable									
Housekeeping		Co	ommunication	Clean bridge crossing (S-II6)								
Waterbar		Co	ommunication	Maintenance needed								
Waterbar Outlet Protection		Co	ommunication	Maintenance needed								
Silt Fence (Filter Fabric Fence)		Ac	cceptable									
Silt Fence (Reinforced Filter Fabric Fence)		oric Fence) Co	ommunication	Maintenance needed								
Rock Construction	n Entrance	Ac	cceptable									
5. Site Condition												
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.											No	
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									Yes			
Are slopes 3:1 a	and greater s	abilized with	appropriate BI	MPs as	per E&	Sp	olans?					Yes
Has a new slip/s	slide been ob	served? (If y	es, complete S	Slide R	eport Fo	rm	1)					No


MVP-34 REV 0 Page 1 of 3

AFE 124300138	Date/T	ime 9/7/2018 4:19 PM	Report # 750	Report # 7508					
6. PCSM BMPs (List BMPs and note if	installed and m	aintained as per the plan. If corre	ective action is nee	eded, a					
picture is required.) PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired					
	Level		Time Traine	Repaired					
7. Identify all remedial measures that have been taken since the previous inspection was conducted.									
Comments (Reference above questions as appropriate.)									
Performed SWPPP inspection on Spread H at 13617+00. There were also possible issu. All the RCE's were in compliance. All obse completed crossing and bank stabilization of Cahas Mt #2. The reclamation crew has conhydromulching from 13452+00 back toward	section. All perimines observed with rved issues were of stream(S-II7) at mpleted hydromul	neter ECD's were inspected and the vaterbars and end treatments be added to the Punch List and given to 13539+14. Clean up operations area	etween 13575+25 au the contractor. The a continuing to work	nd 13670+00. contractor towards					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a									

MVP-34 REV 0 Page 2 of 3

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.



MVP-34 REV 0 Page 3 of 3