









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	4028
Inspector	Jason Nielsen			Date/Time	7/3/2018 5:15 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12298+39
State	VA	Inspection Area	Partial	Station End	12190+85
County	Montgomery	Ground	Dry	Temperature (°F)	92.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.2667543357585, -80.03103836447			Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame
Compost Filter Sock	Acceptable		
Rock Construction Entrance	Acceptable		
Erosion Control Blanket	Acceptable		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable		
Waterbar	Communication	See comments	
Waterbar Outlet Protection	Communication	See comments	

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	7/3/2018 5:15 AM	Report #	4028
Pictures					
					
GPS Location	37.2670509836245, -80.0309595095477	GPS Location	37.2670510551308, -80.0309489295632		
Description	070318 Super sack full of sediment filled sand bags. Looking E. See picture for GPS data.	Description	070318 Area that crew as cleaned up sediment run off. Looking SE. See picture for GPS data.		
					
GPS Location	37.2668098239575, -80.0309150666744	GPS Location	37.2668201756079, -80.0308839698136		
Description	12290+50_070318 Rocks piled up in water bar drain. Looking SW. See picture for GPS data.	Description	12286+00_070318 Water bar doesn't continue past sump. Looking S. See picture for GPS data.		
					
GPS Location	37.2668201756079, -80.0308839698136	GPS Location	37.2667690879081, -80.0308229495585		
Description	070318 Crew loading super sack with sediment filled sand bags for helicopter to pick up. Looking E. See picture for GPS data.	Description	12289+50_070318 Rocks filling up water bar. Looking SW. See picture for GPS data.		