



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	5512
Inspector	Pat Davis			Date/Time	7/31/2018 5:10 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	+0
State	VA	Inspection Area	Partial	Station End	+0
County	Montgomery	Ground	Damp	Temperature (°F)	74.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
GPS Location	37.2787892042343, -80.1251260391649			Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame
Compost Filter Sock	Acceptable		
Housekeeping	Acceptable		
Other	Communication	Clean up fluid deposits on stone	Immediate
Rock Construction Entrance	Acceptable		

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300138	Date/Time	7/31/2018 5:10 PM	Report #	5512
Pictures					
					
GPS Location	37.2703964403246, -80.1217383519561	GPS Location	37.2703964403246, -80.1217383519561		
Description	MVP-PY-006_073118 fluid deposit under a John Henry. Looking S. See photo for gps data.	Description	MVP-PY-006_073118 fluid deposit under dozer. Looking N. See photo for gps data.		
					
GPS Location	37.2703592246745, -80.1216914132984	GPS Location	37.2703204164629, -80.1217196603121		
Description	MVP-PY-006_073118 fluid deposit on stone. Looking S. See photo for gps data.	Description	MVP-PY-006_073118 secondary containment's under ports toilets and light plant. Looking W. See photo for gps data.		
					
GPS Location	37.2702734358956, -80.1217211690546	GPS Location	37.270285002922, -80.1217210014166		
Description	MVP-PY-006_073118 no fluid deposits on north side of bulk fuel tanks. Looking SE. See photo for gps data.	Description	MVP-PY-006_073118 crew cleaning up fluid deposit on south side of bulk fuel tank. Looking SE. See photo for gps data.		