



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H	
Contractor	Precision			Report #	7810	
Inspector	Pat Davis			Date/Time	9/13/2018 7:46 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	+0	
State	VA	Inspection Area	Partial	Station End	+0	
County	Montgomery	Ground	Muddy	Temperature (°F)	81.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20	
GPS Location	37.0943958359185, -80.0180308242142			Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Signage		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300138	Date/Time	9/13/2018 7:46 PM	Report #	7810
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted. Crews have cleaned up the fluid deposits around the bulk fuel tanks. Crews have picked up and removed loose trash in the yard. The secondary containment's have been pumped out after the last rain event.					
Comments (Reference above questions as appropriate.) (Summary Spread 9). Checked rain gauge in the yard MVP-PY-006 and found 0.2 inch of rainfall in the raingauge. EI preformed SWPPP Inspection on the MVP-PY-006. EI walked the boundary of the LOD and observed the compost filter sock around the boundary was installed and in good condition. EI observed no misc trash in the yard. Secondary containment's were empty. EI observed no fluid deposits on the stone on either side of the bulk fuel tanks. No other environmental issues were noted during today's inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	9/13/2018 7:46 PM	Report #	7810
Pictures					
					
GPS Location	37.0943949558186, -80.0180288125575	GPS Location	37.0943721151325, -80.0180318300426		
Description	MVP-PY-006_091318 no fluid deposits on the north side of the bulk fuel tanks. Looking E. See photo for gps data.	Description	MVP-PY-006_091318 no fluid deposits on the south side of the bulk fuel tanks. Looking NE. See photo for gps data.		
					
GPS Location	37.0943719055849, -80.0180319138616	GPS Location	37.0943698520186, -80.0180344284326		
Description	MVP-PY-006_091318 area around dumpsters clean. Looking E. See photo for gps data.	Description	MVP-PY-006_091318 secondary containment's free of fluids. Looking W. See photo for gps data.		
					
GPS Location	37.0943680499094, -80.0180330873281	GPS Location	37.0943686366427, -80.0180349313468		
Description	MVP-PY-006_091318 no leaks under equipment. Looking SE. See photo for gps data.	Description	MVP-PY-006_091318 no leaks under equipment. Looking NE. See photo for gps data.		