Moun	ain Valley		Visual Site Inspection Report									
Project Name H-600 Pipeline Sprea				d H AFE 124300138				Spi	read	H-600 Pipeli	ne S	oread H
Contractor Precision				•				Repo	port # 3774			
Inspector Tracey Hilbun								Date/T	e/Time 6/27/2018 7:17 PM			
Permit # TBD				Inspection	VA SWPP Stat		Station	on Begin 13415+51				
State	VA			Inspection Area		Full St		Stati	ation End 13670+00		+00	
County	County Franklin			Gı	Ground		Wet		Temperature (°F)			83.00
Municipality	Municipality N/A			We	Weather		Cloudy		Rain Gauge (in)		in)	4.00
GPS Location 36.971694121165, -79.86994				699453903736		Rain Accumu		cumula	ılation Time (days)			4.00
1. Are the appro	ove	d (stamped	d) E&S Pla	an and PCSM PI	and PCSM Plan present on site?						Yes	
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)											No	
 Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, 										Yes		
4. E&S BMPs (is required.)	List	: BMPs and	I note if in		ntained	as per the	e plan. If o	corrective			led,	-
E&S BMPs				Compliance Level		Corrective Action				rective Frame	R	Date epaired
Compost Filter Sock				Communication	Repair plan needed			4	48 Hours			
Compost Sediment Trap			Communication	Repair plan needed			4	48 Hours				
Housekeeping			Acceptable									
Rock Construction Entrance			Communication	Repair plan needed			4	48 Hours				
Silt Fence (Filter Fabric Fence)			Communication	Repair plan needed			4	48 Hours				
Silt Fence (Reinforced Filter Fabric Fence)				Communication	Repair plan needed			48 Hours				
Waterbar			Communication	Repair plan needed			4	48 Hours				
5. Site Condition	ons	.			<u> </u>						<u> </u>	
beyond defined l	limi	ts of distur	bance res	sediment, gravel, sulting from earth Environmental Pe	disturl	oance acti	vity or inet	-				No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?										Yes		
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?											Yes	
Has a new slip/slide been observed? (If yes, complete Slide Report Form)										No		


MVP-34 REV 0 Page 1 of 3

AFE 124300138	Date	/Time 6/27/2018 7:17 PM	Report # 377	' 4							
PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)											
PCSM BMPs	Complianc Level	Corrective Action	Corrective Time Frame	Date Repaired							
7. Identify all remedial measures that have been taken since the previous inspection was conducted.											
Comments (Reference above questions as appropriate.)											
Area has been inspected due to recent hear overtopped ECD's and water bar issues are shutdown by MVP occurred and contractor	main problem	s. Contractor is making plans to repair	r. At days end an envi	ronmental							
Note: It is a condition of National Polluta maintenance program be conducted to weekly basis and after each stormwater replacement are needed or have been replacement.	provide for the event. Pleas	e operation and maintenance of all e list in the space provided comm	I BMPs to be inspect ents to note if repair	cted on a rs or							

MVP-34 REV 0 Page 2 of 3

inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.



MVP-34 REV 0 Page 3 of 3