## Certification Statement

I certify under penalty of law that I have read and understand this document and that this document and all attachments were prepared in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Inspector's Name (printed): Mille Ken fro

Inspector's Signature:

Date: 10-15-18

Spread I Laydown Yard
Report # 9443
SWIN1369
ESIN 0946

Project Nar	ne H-60	00 Pipeline Sp	read I		Al	FE 12430	0139	S	pread	H-600 Pipe	line S	pread I
Contractor Precision				Type The Transfer			Re	Report # 9443		P GA		
Inspect	or Gle	nn Mike Renfr	0					Date	/Time	10/15/201	8 3:	51 PM
Permit # TBD			1	Inspection Type VA SW			SWPP Statio		on Begin 0000+00			
State	State VA			Inspection Area		Full		Sta	Station End 0000+00		-00	
County Franklin				Ground		Dry		Temperature ( )		°F)	76.00	
Municipality N/A				Weather				rtain sauge (iii)			4.00	
GPS Location	36.971	8635129446, -	79.870123	37199889			Rain A	ccumu	lation <sup>*</sup>	Time (da	ys)	4.00
L. Are the appr												Yes
<ol><li>Are there ac (If yes, notify</li></ol>		occurring outs /P Environme										No
3. Is Construct followed? (If		uence outline tify MVP Envi									g	Yes
4. E&S BMPs			-		-		THE PARTY NAMED IN		Name of Street	And in case of the last of the	ded,	a pictu
is required.)			Cor	npliance		6 "	0 1		Cor	rective		Date
E	&S BM	PS		Level		Correcti	ve Actioi	1	Time	Frame	R	epaire
Compost Filter S	ock		Comm	nunication	Mainte	nance need	ded					
Housekeeping			Accep	table								
Rock Construction	n Entrai	nce	Accep	table					took top	2,000		
Silt Fence (Filter	Fabric F	ence)	Accep	table		An implicit			100			
			16-3 %		77.19				27365	Alternative statements		
											-	
	-										$\vdash$	
								-				
5. Site Conditi												
ls an unauthoriz beyond defined a photo and imr	limits o	f disturbance	resulting	from earth	n distur	bance act	ivity or in	rring to effective	waters, e BMP?	wetlands If yes, to	, or ake	No
Have inactive di	sturbed	areas (stock	cpiles, fina	al grade) b	een sta	abilized pe	er state re	equireme	ents?			N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							-					
Are slopes 3:1 a	and area	ater stabilized	d with app	propriate BI	MPs as	per E&S	plans?					N/A

DCSM RMDs Compilative Action	AFE 124300139	Date/Time	10/15/2018 3:51 PM	Report # 94	43
PCSM BMPs  Compliance Level  Corrective Action  Corrective Time Frame  Repair  7. Identify all remedial measures that have been taken since the previous inspection was conducted.  Comments (Reference above questions as appropriate.)  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4° of rainfall since the last inspection. All perimeter ECD's ware einspected and one potential issue was observed in the far northwest orner, the triple stad condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we All potential issues were put on a punch list and given to the confractor to address.		note if installed and main	tained as per the plan. If co	rrective action is ne	eded, a
7. Identify all remedial measures that have been taken since the previous inspection was conducted.  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4° of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stacker of the protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The Rock was clear and the road was clear of debris as we All potential issues were put on a punch list and given to the contractor to address.			Corrective Action		Date Repaired
Comments (Reference above questions as appropriate.)  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.	4 %		31 74 3		
Comments (Reference above questions as appropriate.)  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.		4	l second	5 7	
Comments (Reference above questions as appropriate.)  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.		7 34.5			
Comments (Reference above questions as appropriate.)  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.					
Comments (Reference above questions as appropriate.)  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.					
Comments (Reference above questions as appropriate.)  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.			Day of		
Comments (Reference above questions as appropriate.)  Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.	164	- 100	100	0	p
Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.	7. Identify all remedial measures	that have been taken sir	ice the previous inspection w	as conducted.	
Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. the site has received 4" of rainfall since the last inspection. All perimeter ECD's were inspected and one potential issue was observed in the far northwest corner, the triple stack CFS needs to be restacked and sediment removed. The inlet protection on the three drains in the paved yard were in good condition. All secondary containment structures were in compliance. The RCE was clean and the road was clear of debris as we all potential issues were put on a punch list and given to the contractor to address.	Comments (Deference shake au	ections as annonviate \			
	Performed SWPPP inspection of mai inspection. All perimeter ECD's were CFS needs to be restacked and sedii condition. All secondary containment	in laydown yard in Rocky Minspected and one potential ment removed. The inlet prostructures were in compliant	ll issue was observed in the far otection on the three drains in th nce. The RCE was clean and th	northwest corner, the	triple stacked
Note: It is a condition of National Pollutant Discharge Flimination System and Erosion and Sediment normals that a					
ARTER OF A TERRORITOR PERSONAL FUNDAGES LASTINGED. CONTRIBUTION STREET AND LIVES OF A SECURITIES OF A SECOND CONTRIBUTION	Note: It is a condition of National	Pollutant Discharge Elim	ination System and Erosion	and Sediment perm	uts that a

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 12	24300139	9	Date/Time	10/15/2018 3:51 F	PM	Report # 9443
			Pict	ures		
GPS Lo		36.9718433967097, -79.870031975		<b>GPS Location</b>	Account of the second of the second	2945, -79.8702043642242
Desc	ription	RCE clean and road clear of debris.	•	Description	Secondary cor condition	ntainment structure in good
GPS Lo	cation	36.9721039943741, -79.869992835				1842, -79.8699715454875
Desc	ription	The triple stacked CFS needs to be and sediment removed in northwest	restacked t corner.	Description	Inlet protection	in good condition.
					Insert im	age here
GPS Lo	cation	36.9720529066743, -79.870042037	2932	GPS Location		
		Perimeter ECD's on south end of pa in good condition.		Description		

MVP-34 REV 0 Page 3 of 3