









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	17462
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	5/20/2019 9:26 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13670+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	16027+46
<b>County</b>	Franklin/Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Communication				
Silt Fence (Filter Fabric Fence)	Communication				
Sump Pit	Communication				
Waterbar End Treatment	Communication				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Cleanwater Diversion Berm	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	5/20/2019 9:26 AM	<b>Report #</b>	17462
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
-Performed SWPPP inspection of Spread I section -Multiple rain events occurred during inspection period; See rainfall log for totals -Perimeter controls and ECD's were inspected and any maintenance was forwarded to the contractor for repair -Inspection observed condition of water bars, sumps, and end treatments along ROW -Inspection completed of condition of RCE's and found to be in acceptable condition -Clean up crew restored subsoil to pre-construction conditions CIS Webster Rd -Environmental crews continue to perform environmental maintenance along entire ROW -EI team continues to travel ROW to identify environmental maintenance and compliance issues. All issues identified will continue to be communicated to contractor for completion.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300139		Date/Time		5/20/2019 9:26 AM		Report #		17462	
Pictures											
											
GPS Location		36.96		Field Station#		14062+50		GPS Location		36.96	
Field Station#		14066+00		Description				Description			
Vegetation growing along ROW with ECD's Installed. No erosion issues have occurred.				Vegetation growing along ROW with ECD's Installed. No erosion issues have occurred.				Vegetation growing along ROW with ECD's Installed. No erosion issues have occurred.			
											
GPS Location		36.96		Field Station#		14530+00		GPS Location		36.96	
Field Station#		14551+60		Description				Description			
Sump dug to specifications with newly installed CFS triple stack.				Erosion control blanket installed to slow down water flow causing rill erosion.				Erosion control blanket installed to slow down water flow causing rill erosion.			
											
GPS Location		36.96		Field Station#		15258+50		GPS Location		36.96	
Field Station#		15851+90		Description				Description			
Functioning ECD's outside of HDD exit site along perimeter of ROW.				Equipment bridge and ECD's in good condition over S-G2.				Equipment bridge and ECD's in good condition over S-G2.			

<b>A/E</b>	124300139	<b>Date/Time</b>	5/20/2019 9:26 AM	<b>Report #</b>	17462
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



<b>A/E</b>	124300139	<b>Date/Time</b>	5/20/2019 9:26 AM	<b>Report #</b>	17462
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report

<b>Project Name</b>	Transco Interconnect Station		<b>AFE</b>	124300113	<b>Spread</b>	Transco Interconnect Station	
<b>Contractor</b>	Kanahwa				<b>Report #</b>	17463	
<b>Inspector</b>	Ben Davenport				<b>Date/Time</b>	5/20/2019 9:29 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP		<b>Station Begin</b>	0+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full		<b>Station End</b>	0+00	
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry		<b>Temperature (°F)</b>	82.00	
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny		<b>Rain Gauge (in)</b>	0.00	
					<b>Rain Accumulation Time (days)</b>	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Housekeeping		Acceptable					
Culvert		Acceptable					
Rock Construction Entrance		Acceptable					
Compost Filter Sock		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Rock Check Dam		Acceptable					
Erosion Control Blanket		Acceptable					
<b>5. Site Conditions</b>							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

<b>A/E</b>	124300113	<b>Date/Time</b>	5/20/2019 9:29 AM	<b>Report #</b>	17463
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
-Performed SWPPP inspection of the Transco facility and lay down yard -Multiple rain events during inspection period; see rainfall log for totals -Issues with drainage and vegetation have been addressed and did not present issues during inspection -Regular inspections of facility continue to be conducted and any issues communicated to the contractor -No issues to report at time of inspection					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300113		Date/Time		5/20/2019 9:29 AM		Report #		17463	
Pictures											
											
GPS Location		36.96		Field Station#		0+00		GPS Location		36.96	
Field Station#		0+00		Description		Equipment/material surrounded by safety fence on RCE		Description		Channel with growing vegetation and installed CFS check dams	
											
GPS Location		36.96		Field Station#		0+00		GPS Location		36.96	
Field Station#		0+00		Description		Rock outlet protection appears to be in good working condition		Description		Functioning CFS and view of sediment trap	
											
GPS Location		36.96		Field Station#		0+00		GPS Location		36.96	
Field Station#		0+00		Description		CFS check dam and erosion control blanket performing intended function		Description		Grass growing around Station and functioning rock-lined channel	

<b>A/E</b>	124300113	<b>Date/Time</b>	5/20/2019 9:29 AM	<b>Report #</b>	17463
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300113	<b>Date/Time</b>	5/20/2019 9:29 AM	<b>Report #</b>	17463
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		










# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	17562
<b>Inspector</b>	Glenn Mike Renfro			<b>Date/Time</b>	5/20/2019 4:32 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	0000+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	0000+00
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	87.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Roadside Ditch	Acceptable				
Secondary Containment	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	5/20/2019 4:32 PM	<b>Report #</b>	17562
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP inspection of Spread I Laydown yard in Rocky Mount, Va. All perimeter ECD's were inspected and no problems were observed. The RCE was clean and the road was clear of debris. The secondary containment issue from the previous inspection was found to be addressed. All secondary containment structures were found to be in good condition. The inlet protection for the parking lot drains in the paved yard were in acceptable condition but the drain inlet on the south end of paved yard needs the sediment accumulation removed from around the drainage site. The construction permits are posted at the main entrance of the paved yard as required. There were no issues observed during the inspection today. Site is in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300139		Date/Time 5/20/2019 4:32 PM		Report # 17562	
Pictures					
					
GPS Location	36.97	Field Station#	0000+00	GPS Location	36.97
Description		Perimeter ECD's in good condition on west side of paved yard		Description	
					
GPS Location	36.97	Field Station#	0000+00	GPS Location	36.97
Description		Secondary containment structure for fuel cell in good condition.		Description	
			<p>Insert image here</p>		
GPS Location	36.97	Field Station#	0000+00	GPS Location	
Description		Perimeter ECD's on northwest corner of gravel yard in good condition.		Description	



<b>A/E</b>	124300139	<b>Date/Time</b>	5/20/2019 4:32 PM	<b>Report #</b>	17562
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	5/20/2019 4:32 PM	<b>Report #</b>	17562
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	17663
<b>Inspector</b>	Glenn Mike Renfro			<b>Date/Time</b>	5/24/2019 1:06 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	0000+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	0000+00
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Roadside Ditch	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Communication	Maintenance needed			
Silt Fence (Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	5/24/2019 1:06 PM	<b>Report #</b>	17663
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP inspection of main laydown yard in Rocky Mount, Va. All perimeter ECD's were inspected and no issues were observed. The RCE at the gravel yard was found to be in good condition. All secondary containment structures were found to be in good condition except the containment structure for the light plant near the inspectors office needs the plastic liner replaced. The inlet protection for parking lot drains in the paved yard were in good condition. The construction permits are posted at the main entrance of the paved yard as required. The site is in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300139		Date/Time 5/24/2019 1:06 PM		Report # 17663			
Pictures							
							
GPS Location 36.97		Field Station# 00000+00		GPS Location 36.97		Field Station# 00000+00	
Description		Secondary containment structure for light plant near inspectors office needs plastic liner replaced.		Description		Inlet protection for parking lot drain on near equipment storage building in good condition.	
							
GPS Location 36.97		Field Station# 00000+00		GPS Location 36.97		Field Station# 00000+00	
Description		Secondary containment structure for fuel cell in compliance		Description		Perimeter ECD's on south end of paved yard in good condition.	
							
GPS Location 36.97		Field Station# 00000+00		GPS Location 36.97		Field Station# 00000+00	
Description		RCE at gravel yard in good condition.		Description		Perimeter ECD's on south end of gravel yard in acceptable condition.	

<b>A/E</b>	124300139	<b>Date/Time</b>	5/24/2019 1:06 PM	<b>Report #</b>	17663
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	5/24/2019 1:06 PM	<b>Report #</b>	17663
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		