



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1373
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/26/2019 8:39 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	3.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock		Acceptable			
Culvert		Acceptable			
Housekeeping		Acceptable			
Rock Construction Entrance		Acceptable			
Waste Management		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 8:39 AM	<b>Report #</b>	1373
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: LY-29 AR-238.00- There is some rill erosion on slopes of access road, overall road is acceptable. CFS triple stack perimeter controls are in acceptable condition. House keeping is acceptable. Yard rock surface is maintained in acceptable condition. Culvert and drainage feature are in acceptable condition. Rain recorded over past three days- 0.10"					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/26/2019 8:39 AM	<b>Report #</b>	1373
<b>Pictures</b>					
 <p>Date &amp; Time: Mon Aug 26, 2019, 07:15:52 EDT Position: 43°27'27.01N - 78°02'49.85W Altitude: 1450 ft Datum: WGS-84 Azimuth/Bearing: 310° N50W 50° West (True) Elevation Angle: +75.8° Horizon Angle: -08.5° Zoom: IX AR-234- Rain gauge reading - 0.10 inch</p>		 <p>Date &amp; Time: Mon Aug 26, 2019, 07:15:52 EDT Position: 43°27'27.01N - 78°02'49.85W Altitude: 1201 ft Datum: WGS-84 Azimuth/Bearing: 195° S15W 3447 m (1131 ft) Elevation Angle: +26.4° Horizon Angle: -06.3° Zoom: IX LY-29- Arnold's materials storage</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	AR-234 rain gauge reading - 0.10"		<b>Pic 2 Desc.</b>	LY-29- Arnold's materials storage, no issues.	
 <p>Date &amp; Time: Mon Aug 26, 2019, 07:29:41 EDT Position: 43°28'10.11N - 78°01'42.11W Altitude: 1471 ft Datum: WGS-84 Azimuth/Bearing: 125° N25E 25° East (True) Elevation Angle: +78.1° Horizon Angle: -06.1° Zoom: IX LY-29- Culvert and drainage feature are in acceptable condition</p>		 <p>Date &amp; Time: Mon Aug 26, 2019, 07:29:41 EDT Position: 43°28'10.11N - 78°01'42.11W Altitude: 1471 ft Datum: WGS-84 Azimuth/Bearing: 125° N25E 25° East (True) Elevation Angle: +78.1° Horizon Angle: -06.1° Zoom: IX LY-29- Rock surface maintained in acceptable condition</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	LY-29- Culvert and drainage feature are in acceptable condition.		<b>Pic 4 Desc.</b>	LY-29- Rock surface is maintained in acceptable condition.	
 <p>Date &amp; Time: Mon Aug 26, 2019, 08:00:00 EDT Position: 43°28'25.00N - 78°01'45.00W Altitude: 1450 ft Datum: WGS-84 Azimuth/Bearing: 281° N79W 49° West (True) Elevation Angle: +23.2° Horizon Angle: -06.3° Zoom: IX LY-29- Precision materials storage, housekeeping is acceptable</p>		 <p>Date &amp; Time: Mon Aug 26, 2019, 08:00:00 EDT Position: 43°28'25.00N - 78°01'45.00W Altitude: 1450 ft Datum: WGS-84 Azimuth/Bearing: 281° N79W 49° West (True) Elevation Angle: +23.2° Horizon Angle: -06.3° Zoom: IX LY-29- Precision materials storage, housekeeping is acceptable</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	CFS triple stack perimeter controls are in acceptable condition.		<b>Pic 6 Desc.</b>	LY-29- Precision Materials storage, house keeping is acceptable.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 8:39 AM	<b>Report #</b>	1373
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 8:39 AM	<b>Report #</b>	1373
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1392
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/26/2019 2:32 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11740+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
Waste Management	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 2:32 PM	<b>Report #</b>	1392
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Conducted VA SWPPP inspection at lay down yard 26.          Checked equipment in yards for leaks. No leaks observed.          All perimeter ECDs in place and functional.          Secondary containment in place at stationary equipment.          No deficiencies located during inspection.</p> <p>After completing VA SWPPP inspection of yard 26 went to MLV 26 and pointed out two waterbar end treatments that needed to be reworked in order for water to discharge off ROW. Talk to environmental foreman regarding issue and witnessed repairs being made. Crew was also re-stabilizing area with seed and mulch.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 2:32 PM	<b>Report #</b>	1392
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Triple stack compost filter sock in place at yard 26.		<b>Pic 2 Desc.</b>	Light plant and ports potties at lay down yard 26 in secondary containment.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	18 inch compost filter sock in place.		<b>Pic 4 Desc.</b>	RCE in place at yard 26.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11990+00		<b>Field Station#</b>	11767+00	
<b>Pic 5 Desc.</b>	Rain gauge at Catawba Road reads 0.1 inches.		<b>Pic 6 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.0.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 2:32 PM	<b>Report #</b>	1392
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		







<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 2:32 PM	<b>Report #</b>	1392
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision	<b>Report #</b>	1395		
<b>Inspector</b>	Garrett Barclay	<b>Date/Time</b>	8/26/2019 3:38 PM		
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11350+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11520+00
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	69.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.05
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 3:38 PM	<b>Report #</b>	1395
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting and attended contractor weekly safety meeting Performed SWPP for LDY 28 and LDY 37 No damaged ECD's observed during inspection and ECDs installed per spec and per E&S plans No signs of sediment outside of LOD or impacting any sensitive resources Walked ROW from MP 218 - MP 215 ROW conditions showing signs of erosion from last Rain event. Observed damaged P1SF from livestock , item pin flagged and added to punch list Observed undermined end treatment, item added to punch list and pin flagged					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 3:38 PM	<b>Report #</b>	1395
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+28		<b>Field Station#</b>	+28	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+28		<b>Field Station#</b>	11447+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11492+00		<b>Field Station#</b>	11450+00	
<b>Pic 5 Desc.</b>	Damaged P1		<b>Pic 6 Desc.</b>	ECD's and row conditions	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 3:38 PM	<b>Report #</b>	1395
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		






<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 3:38 PM	<b>Report #</b>	1395
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1396
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	8/26/2019 3:53 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11669+87
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+12
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	74.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.15
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock					
Equipment Bridge					
Rock Construction Entrance					
Sensitive Resource Signage					
Compost Filter Berm					
Silt Fence (Filter Fabric Fence)					
Waterbar					
Waterbar End Treatment					
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 3:53 PM	<b>Report #</b>	1396
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>The contractor is on location in the JNF re-setting pipe cribbing. Slope breakers are being removed daily to allow access to the ROW. The breakers are replaced daily. An environmental crew is scheduled tomorrow to begin replacement of worn ECDs between the JNF property line and Craig Creek Road for winter stabilization of the ROW. Materials have been brought to the location. Soil analysis has been completed but selection of a seed mix has not been determined. Equipment being used is being inspected by Transcon for cleanliness to minimize the spread of invasive weeds. The contractor has staged the required fire fighting equipment on the JNF. The equipment bridges are in acceptable condition. The bridge at the S-HH18 (11626+04) crossing will have new geotech fabric installed by the environmental crew as a preventative measure. Disturbed soils will be temporarily stabilized with annual grasses and straw as the crew works it's way out of an area. Portable restroom facilities have been delivered today. The units will be placed as far as possible from the nearby stream and set inside containment. No environmental concerns were identified.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	8/26/2019 3:53 PM	Report #	1396
Pictures					
					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11613+69		Field Station#	11614+20	
Pic 1 Desc.	The equipment bridge at the S-RR13 crossing is in good condition.		Pic 2 Desc.	The equipment bridge at the S-RR14 crossing is in good condition with well vegetated buffers.	
					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11626+04		Field Station#	11656+00	
Pic 3 Desc.	S-HH18 crossing buffers well vegetated. Travel lane currently disturbed while area is active.		Pic 4 Desc.	Travel lane disturbed during re-setting of pipe.	
					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11668+00		Field Station#	11668+75	
Pic 5 Desc.	Pipe cribbing being repaired or replaced as needed.		Pic 6 Desc.	End caps being installed to prevent soil amendments and animals from entering pipe.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 3:53 PM	<b>Report #</b>	1396
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11659+00	<b>Field Station#</b>	11655+00		
<b>Pic 7 Desc.</b>	Pipe being re-set on cribbing.	<b>Pic 8 Desc.</b>	Travel lane disturbed from activity. Will be stabilized and hydro seeded once work is completed.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 3:53 PM	<b>Report #</b>	1396
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread	
<b>Contractor</b>	Precision			<b>Report #</b>	1417	
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/26/2019 2:29 PM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	+37	
<b>State</b>	WV	<b>Inspection Area</b>	Partial	<b>Station End</b>	+37	
<b>County</b>	Monroe	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	69.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.05	
				<b>Rain Accumulation Time (days)</b>	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Buffer		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sensitive Resource Signage		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
Waterbar End Treatment		Acceptable				
Secondary Containment		Acceptable				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? WV: Exceeding 7 days if to be left inactive for more than 21 days						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No



<b>AFE</b>	124300137	<b>Date/Time</b>	8/26/2019 2:29 PM	<b>Report #</b>	1417
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+37		<b>Field Station#</b>	+37	
<b>Pic 1 Desc.</b>	.05" of rain recorded		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+37		<b>Field Station#</b>	+37	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	Stabilization for disturbed	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+37		<b>Field Station#</b>	+37	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 2:29 PM	<b>Report #</b>	1417
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2019 2:29 PM	<b>Report #</b>	1417
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1435
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/27/2019 7:19 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11022+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Broad-Based Dip	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>AFE</b>	124300137	<b>Date/Time</b>	8/27/2019 7:19 AM	<b>Report #</b>	1435
<b>Pictures</b>					
<p>Date &amp; Time: Tue Aug 27, 2019 09:20:38 EDT Position: -037.31975, -080.53168 Altitude: 2426 ft Datum: WGS-84 Azimuth Bearing: 327. N329.5812mag (True) Elevation Angle: +25.0 Horizon Angle: -02.8 Zoom: IX AR-244 rain gauge reading: 0.10</p>		<p>Date &amp; Time: Tue Aug 27, 2019 09:20:38 EDT Position: -037.32226, -080.53168 Altitude: 2426 ft Datum: WGS-84 Azimuth Bearing: 002. N025.0036mag (True) Elevation Angle: +16.9 Horizon Angle: -02.8 Zoom: IX Stream S-IJ18- ECD's, buffers, signage &amp; Equipment bridge are in acceptable condition</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11022+00		<b>Field Station#</b>	11022+00	
<b>Pic 1 Desc.</b>	AR-244 rain gauge reading - 0.10"		<b>Pic 2 Desc.</b>	Stream S-IJ18- ECD's, buffers, signage & Equipment bridge are in acceptable condition	
<p>Date &amp; Time: Tue Aug 27, 2019 09:44:50 EDT Position: -037.32373, -080.55491 Altitude: 2476 ft Datum: WGS-84 Azimuth Bearing: 329. N319.5846mag (True) Elevation Angle: +26.6 Horizon Angle: -02.7 Zoom: IX Stream S-RR5- Buffers, ECD's, signage &amp; Equipment bridge are in acceptable condition</p>		<p>Date &amp; Time: Tue Aug 27, 2019 09:44:50 EDT Position: -037.32373, -080.55491 Altitude: 2476 ft Datum: WGS-84 Azimuth Bearing: 334. N249.5846mag (True) Elevation Angle: +15.3 Horizon Angle: -02.9 Zoom: IX Stream S-E24- Equipment bridge, ECD's signage, &amp; buffalo are in acceptable condition</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11017+00		<b>Field Station#</b>	10986+00	
<b>Pic 3 Desc.</b>	Stream S-RR5- Buffers, ECD's, signage & Equipment bridge are in acceptable condition		<b>Pic 4 Desc.</b>	Stream S-E24- Equipment bridge, ECD's signage, & buffalo are in acceptable condition.	
<p>Date &amp; Time: Tue Aug 27, 2019 09:44:50 EDT Position: -037.32373, -080.55491 Altitude: 2476 ft Datum: WGS-84 Azimuth Bearing: 334. N249.5846mag (True) Elevation Angle: +15.3 Horizon Angle: -02.9 Zoom: IX Stream S-E24 - Buffers, signage, ECD's , equipment bridge are in acceptable condition</p>		<p>Date &amp; Time: Tue Aug 27, 2019 09:44:50 EDT Position: -037.32373, -080.55491 Altitude: 2476 ft Datum: WGS-84 Azimuth Bearing: 334. N249.5846mag (True) Elevation Angle: +15.3 Horizon Angle: -02.9 Zoom: IX Karst &amp; Karst ECD's are in acceptable condition</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10985+00		<b>Field Station#</b>	10965+00	
<b>Pic 5 Desc.</b>	Stream S-E24 - Buffers, signage, ECD's , equipment bridge are in acceptable condition.		<b>Pic 6 Desc.</b>	Karst & Karst ECD's are in acceptable condition.	



<b>AFE</b>	124300137	<b>Date/Time</b>	8/27/2019 7:19 AM	<b>Report #</b>	1435
<b>Pictures</b>					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10983+00	<b>Field Station#</b>	11227+00		
<b>Pic 7 Desc.</b>	Landowner ran over triple stack perimeter controls damaging them.	<b>Pic 8 Desc.</b>	Winding Way rain gauge reading- 0.10"		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>			
<b>Field Station#</b>	11471+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Steel Acres rain gauge reading- 0.10"	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2019 7:19 AM	<b>Report #</b>	1435
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		







# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1463
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/27/2019 4:01 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10650+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10834+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300137	<b>Date/Time</b>	8/27/2019 4:01 PM	<b>Report #</b>	1463
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 204.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, natural vegetation, and earth guard pellets. No deficiencies during VA SWPPP inspection. Checked rain gauge at Buffalo Anklets Road-0.0 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	8/27/2019 4:01 PM	<b>Report #</b>	1463
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	10712+50	
<b>Pic 1 Desc.</b>	Sock checks in place along access road 241.04 in bar ditch.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G33.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00		<b>Field Station#</b>	10700+00	
<b>Pic 3 Desc.</b>	ROW has is stabilized with natural vegetation.		<b>Pic 4 Desc.</b>	Waterbar in place across travel lane with CFS as end treatment.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10696+00		<b>Field Station#</b>	10674+00	
<b>Pic 5 Desc.</b>	0.1 inches of rain fall at Buffalo Anklets Road.		<b>Pic 6 Desc.</b>	RCE in place Old Stoney Road.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2019 4:01 PM	<b>Report #</b>	1463
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		






<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2019 4:01 PM	<b>Report #</b>	1463
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1466
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/27/2019 2:21 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10840+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10925+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	69.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar End Treatment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2019 2:21 PM	<b>Report #</b>	1466
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	2+34	
<b>Pic 1 Desc.</b>	.2" of rain recorded @ Pocahontas		<b>Pic 2 Desc.</b>	ECD's and row conditions @ AR 234	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10852+00		<b>Field Station#</b>	10854+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions @ SA33 & SA34		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10892+00		<b>Field Station#</b>	10869+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2019 2:21 PM	<b>Report #</b>	1466
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2019 2:21 PM	<b>Report #</b>	1466
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1487
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/28/2019 7:24 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11354+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11161+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | No  |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)  |     |



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2019 7:24 AM	<b>Report #</b>	1487
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11354+00 to 11161+00. MP- 214.8 to 211.00 Light rain this morning, the row is wet & slippery, but in stable condition. The contractor is moving equipment into Seven Oaks to start stabilization. Rills and gulley erosion will be graded, sumps cleaned and seeding, mulching & crimping will take place. Perimeter controls are in acceptable condition. Sump pits and end treatments are in acceptable condition. Slope drains, CWD pipes and plunge pools are in acceptable condition. Access roads and RCE's are maintained in acceptable condition. Stream ECD's, equipment bridges, buffers. Signage are in acceptable condition. Environmental crew is working on stabilization and has seeded, mulched and crimped from sta#11169+00 to 11190+00.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/28/2019 7:24 AM	<b>Report #</b>	1487
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Aug 28, 2019, 08:56:44 EDT Position: -087.296199° / -080.490762° Altitude: 221m Datum: WGS-84 Azimuth/Bearing: 354° N06W 6293mils (True) Elevation Angle: +14.1° Horizon Angle: -11.8° Zoom: 1x Start: 11265+00 - P1 perimeter controls are down</p>		 <p>Date &amp; Time: Wed, Aug 28, 2019, 09:02:37 EDT Position: -087.2972403° / -080.498799° Altitude: 227m Datum: WGS-84 Azimuth/Bearing: 337° N21W 6027mils (True) Elevation Angle: +14.1° Horizon Angle: -11.8° Zoom: 1x Start: 11270+72 - SSF fabric detached from chain link</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11265+00	<b>Field Station#</b>	11270+72		
<b>Pic 1 Desc.</b>	P1 perimeter controls are down, stake snapped off.	<b>Pic 2 Desc.</b>	SSF fabric detached from chain link.		
 <p>Date &amp; Time: Wed, Aug 28, 2019, 09:14:59 EDT Position: -089.299776° / -88.500000° Altitude: 220m Datum: WGS-84 Azimuth/Bearing: 360° N20W 6040mils (True) Elevation Angle: +13.7° Horizon Angle: -12.1° Zoom: 1x Start: 11293+00 - P1 perimeter controls are down</p>		 <p>Date &amp; Time: Wed, Aug 28, 2019, 09:36:10 EDT Position: -089.300000° / -88.500000° Altitude: 220m Datum: WGS-84 Azimuth/Bearing: 360° N00W 6040mils (True) Elevation Angle: +13.7° Horizon Angle: -12.1° Zoom: 1x Start: 11306+00 - P1 perimeter controls are down</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11293+00	<b>Field Station#</b>	11306+00		
<b>Pic 3 Desc.</b>	P1 down in stream buffer.	<b>Pic 4 Desc.</b>	P1 perimeter controls are are down		
 <p>Date &amp; Time: Wed, Aug 28, 2019, 09:37:34 EDT Position: -089.300000° / -88.49668° Altitude: 231m Datum: WGS-84 Azimuth/Bearing: 823° N23E 0409mils (True) Elevation Angle: +19.5° Horizon Angle: -18.1° Zoom: 1x Start: 11316+00 - P1 perimeter controls are down, electric fence down, cattle on row</p>		 <p>Date &amp; Time: Wed, Aug 28, 2019, 09:47:00 EDT Position: -087.299348° / -88.497200° Altitude: 231m Datum: WGS-84 Azimuth/Bearing: 327° N03W 634mils (True) Elevation Angle: +19.5° Horizon Angle: -18.1° Zoom: 1x Start: 11323+50 - Slope drain inlet filter rock is full of sediment</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11316+00	<b>Field Station#</b>	11323+50		
<b>Pic 5 Desc.</b>	P1 perimeter controls are down, electric fence down, cattle on row.	<b>Pic 6 Desc.</b>	Slope drain inlet filter rock is full of sediment.		



<b>AFE</b>	124300137	<b>Date/Time</b>	8/28/2019 7:24 AM	<b>Report #</b>	1487
<b>Pictures</b>					
 <p><small>Date &amp; Time: Wed, Aug 28, 2019, 07:55:02 EDT Position: +337.301270° / -090.071364° Altitude: 2229ft Datum: WGS-84 Azimuth/Bearing: 021° N21E 0301-mils (True) Elevation Angle: +20.6° Horizon Angle: -06.9° Pitch: 18° Roll: 11332+50 - P1 down at stream bridge entrance</small></p>		 <p><small>Date &amp; Time: Wed, Aug 28, 2019, 08:00:04 EDT Position: +337.301370° / -090.067533° Altitude: 2229ft Datum: WGS-84 Azimuth/Bearing: 021° N21E 0301-mils (True) Elevation Angle: +20.6° Horizon Angle: -06.9° Pitch: 18° Roll: 11352+00 - Remove sediment build up on CFS.</small></p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11332+50	<b>Field Station#</b>	11352+00		
<b>Pic 7 Desc.</b>	CFS checks under cut in water bar flow line into sump.	<b>Pic 8 Desc.</b>	Remove sediment build up on CFS.		
 <p><small>Date &amp; Time: Wed, Aug 28, 2019, 10:16:41 EDT Position: +337.305537° / -090.062481° Altitude: 1720ft Datum: WGS-84 Azimuth/Bearing: 010° N10E 0178-mils (True) Elevation Angle: +09.2° Horizon Angle: -04.4° Pitch: 18° Roll: 11352+60 - P1 down at stream bridge entrance</small></p>		 <p><small>Date &amp; Time: Wed, Aug 28, 2019, 11:00:04 EDT Position: +337.301370° / -090.067533° Altitude: 2229ft Datum: WGS-84 Azimuth/Bearing: 021° N21E 0301-mils (True) Elevation Angle: +20.6° Horizon Angle: -06.9° Pitch: 18° Roll: 11227+00 - Winding Way rain gauge reading- 0.20"</small></p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11352+60	<b>Field Station#</b>	11227+00		
<b>Pic 9 Desc.</b>	P1 down at stream bridge entrance.	<b>Pic 10 Desc.</b>	Winding Way rain gauge reading- 0.20"		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2019 7:24 AM	<b>Report #</b>	1487
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1502
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/28/2019 3:15 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11351+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11526+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Berm	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Broad-Based Dip	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2019 3:15 PM	<b>Report #</b>	1502
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Environmental crew recently completed spreading new seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. At station number 11472+50 ECB needs to be repaired on two-tone bank and at 11457+00 rock check needs maintenance.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2019 3:15 PM	<b>Report #</b>	1502
<b>Pictures</b>					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11505+00		<b>Field Station#</b>	11502+00	
<b>Pic 1 Desc.</b>	Plunge pool in place.		<b>Pic 2 Desc.</b>	Conveyance channel in place with rock checks.	
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11489+00		<b>Field Station#</b>	11476+00	
<b>Pic 3 Desc.</b>	RCE in place at Stevers Gap Road.		<b>Pic 4 Desc.</b>	Two tone bank stabilized with ECB with slope drains in place.	
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11472+50		<b>Field Station#</b>	11471+00	
<b>Pic 5 Desc.</b>	Two tone bank sloughed off. ECB needs maintenance.		<b>Pic 6 Desc.</b>	0.2 inches of rain fall at Steele Acres Road.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2019 3:15 PM	<b>Report #</b>	1502
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2019 3:15 PM	<b>Report #</b>	1502
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1504
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/28/2019 2:36 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11025+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11150+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	8/28/2019 2:36 PM	<b>Report #</b>	1504
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	11025+00	
<b>Pic 1 Desc.</b>	.2" of rain recorded @ Pocahontas		<b>Pic 2 Desc.</b>	ECD's and row conditions @ SIJ18	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11034+00		<b>Field Station#</b>	11067+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11138+00		<b>Field Station#</b>	11073+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2019 2:36 PM	<b>Report #</b>	1504
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		







<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2019 2:36 PM	<b>Report #</b>	1504
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		




# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1533
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/29/2019 7:37 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11900+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12001+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Culvert	Acceptable				
Rock Check Dam	Acceptable				
Sensitive Resource Signage	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Waterbar	Acceptable				
Waterbar Outlet Protection	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 7:37 AM	<b>Report #</b>	1533
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>SWPPP inspection: Sta#11841+00 to 12001+00. MP- 224.3 to 227.3          Sta#11841 to 11857+00 has been recently restored and new growth is starting to grow.          Sta#11857+00 to 11900+00 the travel lane has been seeded &amp; mulched &amp; crimped and has good uniform growth.          Sta#11841+00 to 12001+00- P1 silt fence, CFS, SSF perimeter controls are in acceptable condition.          Water bars and level spreaders are in good condition.          Water bar outlet protection controls are in acceptable condition.          Karst's and Karst ECD's are in acceptable condition.          Access road and RCE are in good condition.          Final restoration crew were working between sta# 11836+00 &amp; 11830+00.</p> <p>After SWPPP inspection I went to check on the environmental crew at Winding Way. They started seeding, mulching and crimping at sta#11190+00 and got to 11226+00 today. They have approximately 100 ft to completion in this area.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/29/2019 7:37 AM	<b>Report #</b>	1533
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11833+00	<b>Field Station#</b>	11834+00		
<b>Pic 1 Desc.</b>	Dozers spreading topsoil	<b>Pic 2 Desc.</b>	Environmental crew installing CFS perimeter controls.		
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11836+00	<b>Field Station#</b>	11900+00		
<b>Pic 3 Desc.</b>	Sta#11836+00 to 11841+00- Final restoration completed.	<b>Pic 4 Desc.</b>	CFS checks along AR-266.03 are clean & in good condition.		
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11942+00	<b>Field Station#</b>	11975+00		
<b>Pic 5 Desc.</b>	Karst and Karst ECD's are in acceptable condition.	<b>Pic 6 Desc.</b>	Triple stack CFS perimeter controls in Karst area are in acceptable condition.		



<b>AFE</b>	124300137	<b>Date/Time</b>	8/29/2019 7:37 AM	<b>Report #</b>	1533
<b>Pictures</b>					
		<p>Insert image here</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>			
<b>Field Station#</b>	11225+00	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Marooka blowing mulch, dozer crimping mulch.	<b>Pic 8 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 7:37 AM	<b>Report #</b>	1533
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1548
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/29/2019 2:49 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11520+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11610+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	8/29/2019 2:49 PM	<b>Report #</b>	1548
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11520+00		<b>Field Station#</b>	11534+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	End treatment stabilized	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11551+00		<b>Field Station#</b>	11555+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	P1SF end treatment repaired	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11566+00		<b>Field Station#</b>	11584+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	Crews repaired P1SF	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 2:49 PM	<b>Report #</b>	1548
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 2:49 PM	<b>Report #</b>	1548
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1551
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/29/2019 4:28 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11789+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11841+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Energy Dissipater	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Temporary Diversion Berm	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 4:28 PM	<b>Report #</b>	1551
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Checked the rain gauge at Catawba Rd, .1" accumulation was indicated. Performed SWPPP inspection from MP 223.3 to MP 224.3. No issues were located. Restoration crews are currently working in this section between 11824+00 and 11833+00.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	8/29/2019 4:28 PM	Report #	1551
Pictures					
 <p>Date &amp; Time: Thu Aug 29, 2019 12:00:00 EDT Position: 11833+00 Altitude: 2250 ft Datum: WGS 84 Azimuth Bearing: 054.554E 0.948mils (True) Elevation Angle: -07.1° Horizon Angle: -23.6° Zoom: 1X Final grade: 11833+00</p>		 <p>Date &amp; Time: Thu Aug 29, 2019 12:00:00 EDT Position: 11829+50 Altitude: 2250 ft Datum: WGS 84 Azimuth Bearing: 011.571E 1.219mils (True) Elevation Angle: -16.6° Horizon Angle: -23.6° Zoom: 1X Final grade: 11829+50</p>			
GPS Location	1	GPS Location	2		
Field Station#	11833+00	Field Station#	11829+50		
Pic 1 Desc.	Rock picking topsoil.	Pic 2 Desc.	Putting back to final grade.		
 <p>Date &amp; Time: Thu Aug 29, 2019 12:00:00 EDT Position: 11827+50 Altitude: 2250 ft Datum: WGS 84 Azimuth Bearing: 152.208E 0.848mils (True) Elevation Angle: -05.4° Horizon Angle: -24.6° Zoom: 1X Pulling topsoil: 11827+50</p>		 <p>Date &amp; Time: Thu Aug 29, 2019 12:00:00 EDT Position: 11833+00 Altitude: 2250 ft Datum: WGS 84 Azimuth Bearing: 066.544E 1.172mils (True) Elevation Angle: -06.4° Horizon Angle: -23.1° Zoom: 1X Fertilizer: 11833+00</p>			
GPS Location	3	GPS Location	4		
Field Station#	11827+50	Field Station#	11833+00		
Pic 3 Desc.	Pulling topsoil.	Pic 4 Desc.	Spreading fertilizer.		
 <p>Date &amp; Time: Thu Aug 29, 2019 13:29:46 EDT Position: 11833+00 Altitude: 2250 ft Datum: WGS 84 Azimuth Bearing: 129.551E 1.928mils (True) Elevation Angle: -05.1° Horizon Angle: -23.4° Zoom: 1X Discing post soil amendments</p>		 <p>Date &amp; Time: Thu Aug 29, 2019 14:58:09 EDT Position: 11827+00 Altitude: 2250 ft Datum: WGS 84 Azimuth Bearing: 122.598E 2.169mils (True) Elevation Angle: -16.6° Horizon Angle: -23.4° Zoom: 1X Restoration activities: 11827+00</p>			
GPS Location	5	GPS Location	6		
Field Station#	11833+00	Field Station#	11827+00		
Pic 5 Desc.	Discing post soil amendments.	Pic 6 Desc.	Restoration activities.		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 4:28 PM	<b>Report #</b>	1551
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 4:28 PM	<b>Report #</b>	1551
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1553
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/29/2019 4:48 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Berm	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/29/2019 4:48 PM	<b>Report #</b>	1553
<b>Pictures</b>					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11674+00		<b>Field Station#</b>	11687+00	
<b>Pic 1 Desc.</b>	Sump pit and waterbar end treatment in place.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-MN21.	
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11737+00		<b>Field Station#</b>	11767+00	
<b>Pic 3 Desc.</b>	Waterbars in place and ROW has been stabilized with seed and mulch.		<b>Pic 4 Desc.</b>	RCE in place at main line valve 26.	
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	Spoil pile removed by land owner along buffalo anklets Road.		<b>Pic 6 Desc.</b>	Spoil place next to stream bank S-G32 on apposing side of Buffalo Anklets Road.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 4:48 PM	<b>Report #</b>	1553
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/29/2019 4:48 PM	<b>Report #</b>	1553
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1581
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/30/2019 8:04 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	2.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Culvert	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Waste Management	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 8:04 AM	<b>Report #</b>	1581
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection- LY- 29 Access road 238.00 is maintained in acceptable condition. CFS triple stack perimeter controls are in acceptable condition. House keeping is acceptable. The rock surface of the yard is maintained in acceptable condition. Culvert and drainage feature are in acceptable condition. Goal posts are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/30/2019 8:04 AM	<b>Report #</b>	1581
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Aug 30, 2019 08:25:54 EDT  Position: -037.362196 / -88.672211  Altitude: 1696ft  Datum: WGS-84  Azimuth/Bearing: 307° N55W 5458mils (True)  Elevation Angle: +28.5°  Horizon Angle: -04.1°  Zoom: IX  LY-29: Arnold's materials storage.</p> 		<p>Date &amp; Time: Fri, Aug 30, 2019 08:25:54 EDT  Position: -037.362196 / -88.672211  Altitude: 1696ft  Datum: WGS-84  Azimuth/Bearing: 307° N55W 5458mils (True)  Elevation Angle: +28.5°  Horizon Angle: -04.1°  Zoom: IX  LY-29: Culvert and drainage feature are in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Arnold's materials storage.		<b>Pic 2 Desc.</b>	Culvert and drainage feature are in acceptable condition.	
<p>Date &amp; Time: Fri, Aug 30, 2019 08:30:09 EDT  Position: -037.363062 / -88.672899  Altitude: 1706ft  Datum: WGS-84  Azimuth/Bearing: 163° S17E 2038mils (True)  Elevation Angle: +24.1°  Horizon Angle: -04.9°  Zoom: IX  LY-29: CFS triple stack perimeter controls are in acceptable condition.</p> 		<p>Date &amp; Time: Fri, Aug 30, 2019 08:34:05 EDT  Position: -037.363062 / -88.674835  Altitude: 1706ft  Datum: WGS-84  Azimuth/Bearing: 163° S17E 2038mils (True)  Elevation Angle: +24.1°  Horizon Angle: -04.9°  Zoom: IX  LY-29: Rock surface of the yard is maintained in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	CFS triple stack perimeter controls are in acceptable condition. See		<b>Pic 4 Desc.</b>	Rock surface of the yard is maintained in acceptable condition.	
<p>Date &amp; Time: Fri, Aug 30, 2019 09:45:28 EDT  Position: -037.362215 / -88.676765  Altitude: 1700ft  Datum: WGS-84  Azimuth/Bearing: 307° N55W 5458mils (True)  Elevation Angle: +25.5°  Horizon Angle: -02.5°  Zoom: IX  LY-29: Pipe, side boom and materials stored, house keeping is acceptable.</p> 		<p>Date &amp; Time: Fri, Aug 30, 2019 09:53:28 EDT  Position: -037.364518 / -88.672717  Altitude: 1821ft  Datum: WGS-84  Azimuth/Bearing: 182° S02W 3023mils (True)  Elevation Angle: +24.2°  Horizon Angle: -04.4°  Zoom: IX  AR-238.00 is maintained in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	Pipe, side boom and materials stored, house keeping is acceptable.		<b>Pic 6 Desc.</b>	AR- 238.00- Access road is maintained in acceptable condition.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 8:04 AM	<b>Report #</b>	1581
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	


<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 8:04 AM	<b>Report #</b>	1581
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1602
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/30/2019 2:58 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	1200+50
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
Waste Management	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 2:58 PM	<b>Report #</b>	1602
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/30/2019 2:58 PM	<b>Report #</b>	1602
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	CFS in place along LOD.		<b>Pic 2 Desc.</b>	18 inch compost filter sock in place.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Secondary containment in place under light plant and porta potties.		<b>Pic 4 Desc.</b>	Secondary containment in place under fuel cell.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	RCE in place lay down yard 26 employee parking.		<b>Pic 6 Desc.</b>	Triple stack compost filter sock in place around drainage.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 2:58 PM	<b>Report #</b>	1602
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 2:58 PM	<b>Report #</b>	1602
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	1608
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/30/2019 10:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11610+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11620+00
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	76.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 10:56 AM	<b>Report #</b>	1608
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Crews damaged bridge @ S-RR13, observed crews replacing mat bridge Performed SWPP for LDY 28 No damaged ECD's observed during inspection ECD's installed per spec and per E&S plans No signs of sediment outside of LOD or impacting any sensitive resources Proper secondary containment observed					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 10:56 AM	<b>Report #</b>	1608
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+28		<b>Field Station#</b>	+28	
<b>Pic 1 Desc.</b>	ECD's and row conditions @ LDY 28		<b>Pic 2 Desc.</b>	ECD's and row conditions @ LDY 28	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+28		<b>Field Station#</b>	11603+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions @ LDY 28		<b>Pic 4 Desc.</b>	Crews installing new bridge @ S-RR13	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11603+00		<b>Field Station#</b>	11603+00	
<b>Pic 5 Desc.</b>	Crews installing new bridge @ S-RR13		<b>Pic 6 Desc.</b>	Bridge install completed	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 10:56 AM	<b>Report #</b>	1608
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/30/2019 10:56 AM	<b>Report #</b>	1608
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		