



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	101989
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	10/7/2019 7:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10840+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/7/2019 7:56 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	2+34		<b>Field Station#</b>	10820+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10910+00		<b>Field Station#</b>	10855+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10878+00		<b>Field Station#</b>	10865+00	
<b>Pic 5 Desc.</b>	Crews dressing up water bars in preparation for stabilization		<b>Pic 6 Desc.</b>	Crews dressing up travel lane in preparation of stabilization	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/7/2019 7:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	10/7/2019 7:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report



<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	102007
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	10/7/2019 7:34 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11022+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	5.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Broad-Based Dip	Acceptable				
Compost Filter Sock	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Sump Pit	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/7/2019 7:34 AM	<b>Report #</b>	102007
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>SWPPP inspection: 11022+00 to 10930+00. MP- 208.6 to 206.2          The row is very dry and in stable condition.          Perimeter controls, Silt fence, CFS and SSF are in acceptable condition.          Water bars are stable and in good condition.          Sump pits are in acceptable condition as there hasn't been any sediment movement because of the lack of rain fall.          Water bar end treatments are in acceptable condition.          Streams S-IJ18, S-RR5, S-E24, S-E25 - Equipment bridges, Environmental controls, sensitive resource signage, buffers are in acceptable condition. Some streams have dried up due to the drought.          Karst and Karst ECD's and signage are in acceptable condition.          Between sta# 10983+00 and 10964+00, there is damage to the 18" CFS perimeter controls as the landowner has been holding an off road rally, where vehicles are running over the sock, ( see photo log ).          Sta#10947+00- Doe Creek Farms have opened the gate to the row allowing cattle to graze, damaging silt fence at a drainage feature.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	10/7/2019 7:34 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon Oct 07 2019 09:09:29 EDT Position: -037.285137 / -68.164077 Altitude: 2950ft Datum: WGS-84 Azimuth Bearing: 002° N28E 303mils (True) Elevation Angle: +23.9° Horizon Angle: -02.4° Zoom: IX Sta#11015+00 Stream S-IJ18- Equipment bridge, buffers, sensitive resource signage are in acceptable condition.</p>		 <p>Date &amp; Time: Mon Oct 07 2019 09:25:01 EDT Position: -037.322348 / -68.164201 Altitude: 2951ft Datum: WGS-84 Azimuth Bearing: 002° N28W 300mils (True) Elevation Angle: +23.9° Horizon Angle: -02.4° Zoom: IX Sta#11015+00 Stream S-RR5- Equipment bridge, buffers, sensitive resource signage are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11022+00		<b>Field Station#</b>	11016+00	
<b>Pic 1 Desc.</b>	Stream S-IJ18- Environmental controls, sensitive resource signage, equipment bridge, are in acceptable condition.		<b>Pic 2 Desc.</b>	Stream S-RR5- Equipment bridge, Environmental controls, buffers, sensitive resource signage are in acceptable condition.	
 <p>Date &amp; Time: Mon Oct 07 2019 09:51:01 EDT Position: -037.325629 / -68.164312 Altitude: 2960ft Datum: WGS-84 Azimuth Bearing: 002° N28W 303mils (True) Elevation Angle: +15.3° Horizon Angle: -03.7° Zoom: IX Stream S-E25- Sensitive resource signage, ECD's, equipment bridge are in acceptable condition.</p>		 <p>Date &amp; Time: Mon Oct 07 2019 09:51:01 EDT Position: -037.325629 / -68.164312 Altitude: 2960ft Datum: WGS-84 Azimuth Bearing: 002° N28W 303mils (True) Elevation Angle: +15.3° Horizon Angle: -03.7° Zoom: IX Stream S-E24- Sensitive resource signage, environmental controls, equipment bridge, buffers are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10986+00		<b>Field Station#</b>	10985+00	
<b>Pic 3 Desc.</b>	Stream S-E25- Sensitive resource signage, buffers, ECD's, equipment bridge are in acceptable condition.		<b>Pic 4 Desc.</b>	Stream S-E24- Sensitive resource signage, environmental controls, equipment bridge, buffers are in acceptable condition.	
 <p>Date &amp; Time: Mon Oct 07 2019 10:56:51 EDT Position: -037.327880 / -68.164278 Altitude: 2990ft Datum: WGS-84 Azimuth Bearing: 331° N29W 309mils (True) Elevation Angle: +17.5° Horizon Angle: -02.5° Zoom: IX Sta#10986+00 Landowner off road rally- Triple stack perimeter controls damaged.</p>		 <p>Date &amp; Time: Mon Oct 07 2019 10:56:51 EDT Position: -037.327880 / -68.164278 Altitude: 2990ft Datum: WGS-84 Azimuth Bearing: 330° N30W 306mils (True) Elevation Angle: +17.5° Horizon Angle: -02.5° Zoom: IX Sta#10969+00 Landowner off road rally- Triple stack perimeter controls damaged.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10983+00		<b>Field Station#</b>	10969+00	
<b>Pic 5 Desc.</b>	Landowner off road rally has caused damaged to triple stack perimeter controls.		<b>Pic 6 Desc.</b>	Sta#10969+00- Landowner off road rally- CFS perimeter controls pulled back & damaged.	



<b>AFE</b>	124300137	<b>Date/Time</b>	10/7/2019 7:34 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time Mon, Oct 07, 2019, 10:09:48 EDT Position: -107.327959° / -39.030239° Altitude: 24 ft Datum: WGS-84 Azimuth Bearing: 323° N37W 5742mils (true) Declination Angle: +18.7° Horizon Angle: -02.2° Zoom: 1X Size: 10968495 Landowner off road rally - Triple stake perimeter controls damaged</small></p>		 <p><small>Date &amp; Time Mon, Oct 07, 2019, 10:29:01 EDT Position: -107.328009° / -39.037594° Altitude: 2184 ft Datum: WGS-84 Azimuth Bearing: 343° N19W 4042mils (true) Declination Angle: +18.7° Horizon Angle: -00.5° Zoom: 1X Size: 10968495 Doe Creek Farms Landowner has opened gate onto row P1 damaged by cattle</small></p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10968+00	<b>Field Station#</b>	10947+00		
<b>Pic 7 Desc.</b>	Landowner off road rally - Triple stake perimeter controls damaged.	<b>Pic 8 Desc.</b>	Landowner opened gate onto row, cattle have damaged P1 at drainage feature, Doe Creek Farms.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	10/7/2019 7:34 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	102022
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	10/7/2019 3:36 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10835+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/7/2019 3:36 PM	<b>Report #</b>	102022
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>           Conducted VA SWPPP inspection from MP 201.7 to MP 204.6.            Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.            No forward progress has been completed due to FERC shut down.            Right of way has been stabilized using seed, mulch, and natural vegetation.            No deficiencies located during inspection.            After VA SWPPP inspection was completed received call from environmental foreman that hydraulic fluid leak occurred. Upon arrival crew had already clean up spill. Estimated 1 pint of hydraulic fluid was released. Crew removed contaminated soils in heavy duty trash bags from the site.         </p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	10/7/2019 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	10712+50	
<b>Pic 1 Desc.</b>	Compost filter sock checks in place along access road 241.04 bar ditch.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G33.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10698+00		<b>Field Station#</b>	10696+00	
<b>Pic 3 Desc.</b>	Triple stack 18 inch compost filter sock in place at stream bank S-G32.		<b>Pic 4 Desc.</b>	RCE in place at Buffalo Anklets Road to assist with track out prevention.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10686+00		<b>Field Station#</b>	11788+50	
<b>Pic 5 Desc.</b>	Waterbar with triple stack compost filter sock in place as end treatment.		<b>Pic 6 Desc.</b>	Area where spill occurred. Crew has already cleaned spill before EI arrived.	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/7/2019 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	10/7/2019 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		







## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4440
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	10/8/2019 7:25 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11255+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11354+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	56.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 7:25 AM	<b>Report #</b>	4440
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection between MP 213 and MP 214.8. No issues were located. Crews are currently refreshing temporary stabilization as well as repairing or replacing ECDs as needed in this section.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	10/8/2019 7:25 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11258+00	Field Station#	11264+00		
Pic 1 Desc.	Temporary stabilization.	Pic 2 Desc.	Temporary stabilization.		
					
GPS Location	3	GPS Location	4		
Field Station#	11302+00	Field Station#	11323+00		
Pic 3 Desc.	Newly installed CFS.	Pic 4 Desc.	Temporary stabilization.		
					
GPS Location	5	GPS Location	6		
Field Station#	11335+00	Field Station#	11348+00		
Pic 5 Desc.	Temporary stabilization.	Pic 6 Desc.	Temporary stabilization.		

<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 7:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 7:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4447
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	10/8/2019 12:45 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11161+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	56.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



AFE	124300137	Date/Time	10/8/2019 12:45 PM	Report #	
Pictures					
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11225+00		Field Station#	11225+00	
Pic 1 Desc.	Steep slope has been seeded, mulched and crimped, in stable condition.		Pic 2 Desc.	Slope drain, end treatment & rock swale are in acceptable condition.	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11200+00		Field Station#	11191+00	
Pic 3 Desc.	Stabilized row		Pic 4 Desc.	Drainage feature ECD's are in acceptable condition.	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11184+00		Field Station#	11227+00	
Pic 5 Desc.	CWD pipe and plunge pool are in acceptable condition.		Pic 6 Desc.	Winding Way rain gauge reading- 0.60"	

<b>AFE</b>	124300137	<b>Date/Time</b>	10/8/2019 12:45 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p> <small>             Date/Time: Tue Oct 08 2019 11:51:46 EDT              Picture: 0124300137_1153231001              Altitude: 1999ft              Datum: WGS-84              Azimuth/Bearing: 358 (NWP) 358 (NWP) 358              Horizontal Angle: 2.00°              Horizontal Angle: 116.2°              Zoom: 1.0              Catawba rain gauge reading: 0.03           </small> </p>		 <p> <small>             Date/Time: Tue Oct 08 2019 11:55:05 EDT              Picture: 0124300137_1153231002              Altitude: 1999ft              Datum: WGS-84              Azimuth/Bearing: 358 (NWP) 358 (NWP) 358              Horizontal Angle: 2.00°              Horizontal Angle: 116.2°              Zoom: 1.0              Tabor rain gauge reading: 0.20           </small> </p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11988+00	<b>Field Station#</b>	11767+00		
<b>Pic 7 Desc.</b>	Catawba rain gauge reading- 0.03"	<b>Pic 8 Desc.</b>	Tabor rain gauge reading- 0.20".		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			





<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 12:45 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4448
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	10/8/2019 12:49 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11351+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11526+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.10
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Berm	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Broad-Based Dip	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Sensitive Resource Buffer	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 12:49 PM	<b>Report #</b>	4448
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Environmental crew recently completed spreading new seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during inspection. Inspection was conducted during rain event. At time of inspection rain gauge read 0.4". No stormwater was observed being discharged though ECDs. Dry ground was absorbing slow rain fall. Other rain gauges on the spread ranged from 0.2" to 1.1" of rain fall.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	10/8/2019 12:49 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11514+00		Field Station#	11505+00	
Pic 1 Desc.	ROW has been stabilized with seed and mulch. Waterbars in place.		Pic 2 Desc.	Plunge pool in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11502+00		Field Station#	11748+00	
Pic 3 Desc.	Conveyance channel with rock checks and ECB in place at double cut.		Pic 4 Desc.	ECB on two tone with slope drains in place to minimize erosion. Slope drain have rock inlets and outlets in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11471+00		Field Station#	11370+00	
Pic 5 Desc.	Rain gauge at Steele Acres reads 0.4 inches of rain fall.		Pic 6 Desc.	Clean water diversion pipe and clean water diversion berm in place.	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 12:49 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 12:49 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4453
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	10/8/2019 1:40 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11025+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11150+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.70
				<b>Rain Accumulation Time (days)</b>	1.00

- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)  |     |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	10/8/2019 1:40 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	2+34		<b>Field Station#</b>	+1	
<b>Pic 1 Desc.</b>	.7" of rain recorded @ AR 234		<b>Pic 2 Desc.</b>	.7" of rain recorded @ AR Pocahontas	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11025+00		<b>Field Station#</b>	11035+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions S-IJ18		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11130+00		<b>Field Station#</b>	11150+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 1:40 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	10/8/2019 1:40 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		






## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4484
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	10/9/2019 7:01 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11900+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12000+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	69.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Broad-Based Dip	Acceptable				
Compost Filter Sock	Acceptable				
Rock Check Dam	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar Outlet Protection	Acceptable				
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>AFE</b>	124300137	<b>Date/Time</b>	10/9/2019 7:01 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11809+00	<b>Field Station#</b>	11916+40		
<b>Pic 1 Desc.</b>	Loggers have pulled out, CFS perimeter controls are damaged.	<b>Pic 2 Desc.</b>	12" CFS perimeter controls fabric torn.		
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11938+27	<b>Field Station#</b>	11977+00		
<b>Pic 3 Desc.</b>	12" CFS perimeter control fabric torn.	<b>Pic 4 Desc.</b>	Karst and Karst ECD's & signage are in acceptable condition.		
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11942+00	<b>Field Station#</b>	11989+00		
<b>Pic 5 Desc.</b>	Karst and Karst ECD's & sensitive resource signage are in acceptable condition.	<b>Pic 6 Desc.</b>	Catawba rain gauge reading- 0.60"		



<b>AFE</b>	124300137	<b>Date/Time</b>	10/9/2019 7:01 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>             Date &amp; Time: Wed Oct 09 2019 11:49:47 EDT              Position: -017.118019, -80.051359              Altitude: 214.7m              Datum: WGS-84              Azimuth Bearing: 310, Heading: 5511mishus              Elevation Angle: 25.5              Horizon Angle: 12.2              Zoom: 1X              AR-244.00: rain gauge reading: 0.50"           </p>		 <p>             Date &amp; Time: Wed Oct 09 2019 11:49:47 EDT              Position: -017.118019, -80.051359              Altitude: 214.7m              Datum: WGS-84              Azimuth Bearing: 310, Heading: 5511mishus              Elevation Angle: 25.5              Horizon Angle: 12.2              Zoom: 1X              AR-244.00: rain gauge reading: 0.40"           </p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11227+00	<b>Field Station#</b>	11022+00		
<b>Pic 7 Desc.</b>	Winding Way rain gauge reading- 0.50"	<b>Pic 8 Desc.</b>	AR-244.00- 0.40"		
 <p>             Date &amp; Time: Wed Oct 09 2019 11:49:47 EDT              Position: -017.118019, -80.051359              Altitude: 214.7m              Datum: WGS-84              Azimuth Bearing: 310, Heading: 5511mishus              Elevation Angle: 25.5              Horizon Angle: 12.2              Zoom: 1X              Kow Camp rain gauge reading: 0.70"           </p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>			
<b>Field Station#</b>	10888+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Kow Camp rain gauge reading- 0.70"	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 7:01 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4490
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	10/9/2019 7:25 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11789+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11900+00
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00

- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 7:25 AM	<b>Report #</b>	4490
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection between MP 223.3 and 224.3. Assessed access rd 266.03. No issues were located.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 7:25 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time Wed, Oct 09, 2019, 06:45:00 EDT Position: 40°02'01.00"N / -80°11'07.00"W Altitude: 2221 ft Camera: WGS-84 Azimuth/Bearing: 144° 53'E 2200m (0.00) Elevation Angle: -01.8° Horizon Angle: -22.5° Zoom: 1X Restored RoW 11792+00</p>		 <p>Date &amp; Time Wed, Oct 09, 2019, 06:45:00 EDT Position: 40°02'01.00"N / -80°11'07.00"W Altitude: 2221 ft Camera: WGS-84 Azimuth/Bearing: 144° 53'E 2200m (0.00) Elevation Angle: -01.8° Horizon Angle: -22.5° Zoom: 1X Restored RoW 11819+00</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11792+00	<b>Field Station#</b>	11819+00		
<b>Pic 1 Desc.</b>	Restored section of RoW.	<b>Pic 2 Desc.</b>	Restored section of RoW.		
 <p>Date &amp; Time Wed, Oct 09, 2019, 06:45:00 EDT Position: 40°02'01.00"N / -80°11'07.00"W Altitude: 2221 ft Camera: WGS-84 Azimuth/Bearing: 144° 53'E 2200m (0.00) Elevation Angle: -01.8° Horizon Angle: -22.5° Zoom: 1X Restored RoW 11834+00</p>		 <p>Date &amp; Time Wed, Oct 09, 2019, 06:45:00 EDT Position: 40°02'01.00"N / -80°11'07.00"W Altitude: 2221 ft Camera: WGS-84 Azimuth/Bearing: 144° 53'E 2200m (0.00) Elevation Angle: -01.8° Horizon Angle: -22.5° Zoom: 1X Restored RoW 11842+00</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11834+00	<b>Field Station#</b>	11842+00		
<b>Pic 3 Desc.</b>	Restored section of RoW.	<b>Pic 4 Desc.</b>	Restored section of RoW.		
 <p>Date &amp; Time Wed, Oct 09, 2019, 06:45:00 EDT Position: 40°02'01.00"N / -80°11'07.00"W Altitude: 2221 ft Camera: WGS-84 Azimuth/Bearing: 144° 53'E 2200m (0.00) Elevation Angle: -01.8° Horizon Angle: -22.5° Zoom: 1X Restored RoW 11870+00</p>		 <p>Date &amp; Time Wed, Oct 09, 2019, 06:45:00 EDT Position: 40°02'01.00"N / -80°11'07.00"W Altitude: 2221 ft Camera: WGS-84 Azimuth/Bearing: 144° 53'E 2200m (0.00) Elevation Angle: -01.8° Horizon Angle: -22.5° Zoom: 1X Restored RoW 11900+00</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11870+00	<b>Field Station#</b>	11900+00		
<b>Pic 5 Desc.</b>	Restored section of RoW.	<b>Pic 6 Desc.</b>	Restored section of RoW.		

<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 7:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 7:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4506
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	10/9/2019 2:30 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.90
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 2:30 PM	<b>Report #</b>	4506
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Once inspection was completed checked rain gauges at Mount Tabor - 0.4", LDY 37 - 0.5", Pocahontas Road - 0.9", Access Road 234 - 0.9", and Buffalo Anklets Road - 0.5".					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	10/9/2019 2:30 PM	Report #	
Pictures					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11671+00		<b>Field Station#</b>	11687+40	
<b>Pic 1 Desc.</b>	Waterbar, end treatment, and sump pit in place.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-MN21.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.4 inches.		<b>Pic 4 Desc.</b>	Rain gauge at Pocahontas Road reads 0.9 inched.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	Rain gauge at Access Road 234 reads 0.9 inches.		<b>Pic 6 Desc.</b>	Rain gauge at Buffalo Anklets Road reads 0.5 inches.	



<b>AFE</b>	124300137	<b>Date/Time</b>	10/9/2019 2:30 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11761+00	
<b>Pic 7 Desc.</b>	RCE in place at main line valve 26 to assist in the prevention of track out.		<b>Pic 8 Desc.</b>	Reinforced filter fence in place along LOD.	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		









<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 2:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4513
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	10/9/2019 2:46 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11520+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11630+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	63.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Flume Pipe	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar End Treatment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 2:46 PM	<b>Report #</b>	4513
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Collected rain gauge readings .5" @ Steel Acres x and .7" AR Craig's Creek Performed SWPPP from MP 218 - MP 219.5 No damaged ECD's observed during inspection Private portion of section showing good signs of vegetation from helicopter application JNF portion showing minimal signs of vegetation, but adequate application via helicopter ECD's installed per spec and per E&S plans No signs of sediment outside of LOD or impacting any sensitive resources Crews continued to work on stabilizing travel lane @ MP 208 - MP 209.5					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	10/9/2019 2:46 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+1	
<b>Pic 1 Desc.</b>	.5" of rain recorded @ Steel Acres		<b>Pic 2 Desc.</b>	.7" of rain recorded @ Craig's Creek	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11538+00		<b>Field Station#</b>	11553+00	
<b>Pic 3 Desc.</b>	Private section showing good signs of vegetation		<b>Pic 4 Desc.</b>	Private section showing good signs of vegetation	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11567+00		<b>Field Station#</b>	11580+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions on JNF portion		<b>Pic 6 Desc.</b>	JNF portion showing minimal signs of vegetation	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 2:46 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	10/9/2019 2:46 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4538
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	10/10/2019 7:15 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	76.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Culvert	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Waste Management	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 7:15 AM	<b>Report #</b>	4538
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection:LY-29 CFS triple stack perimeter controls are in acceptable condition. House keeping is acceptable. Rock construction surface is maintained in acceptable condition. Culvert and drainage feature are in acceptable condition. AR-238.00 is maintained in acceptable condition. Waste management is acceptable. All mechanical equipment has been removed from the yard.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		10/10/2019 7:15 AM		Report #			
Pictures											
											
<p>Date &amp; Time: Thu Oct 10, 2019, 06:37:29 EDT Position: +40.033011° / -084.679987° Altitude: 1266 ft Datum: WGS-84 Azimuth Bearing: 329° N31W 300ft (true) Elevation Angle: +24.7° Horizon Angle: -04.7° Zoom: IX LY-29 - Arnold's materials storage.</p>				<p>Date &amp; Time: Thu Oct 10, 2019, 06:37:29 EDT Position: +40.033011° / -084.679987° Altitude: 1266 ft Datum: WGS-84 Azimuth Bearing: 329° N31W 300ft (true) Elevation Angle: +24.7° Horizon Angle: -04.7° Zoom: IX LY-29 - Culvert &amp; drainage feature are in acceptable condition.</p>							
GPS Location		See photo GPS						GPS Location		See photo GPS	
Field Station#		12005+00						Field Station#		12005+00	
Pic 1 Desc.		Arnold's materials storage						Pic 2 Desc.		Culvert and drainage feature are in acceptable condition.	
											
<p>Date &amp; Time: Thu Oct 10, 2019, 06:38:00 EDT Position: +40.033011° / -084.679987° Altitude: 1266 ft Datum: WGS-84 Azimuth Bearing: 329° N31W 300ft (true) Elevation Angle: +24.7° Horizon Angle: -04.7° Zoom: IX LY-29 - CFS triple stack perimeter controls are in acceptable condition.</p>				<p>Date &amp; Time: Thu Oct 10, 2019, 06:38:00 EDT Position: +40.033011° / -084.679987° Altitude: 1266 ft Datum: WGS-84 Azimuth Bearing: 329° N31W 300ft (true) Elevation Angle: +24.7° Horizon Angle: -04.7° Zoom: IX LY-29 - PPL materials storage.</p>							
GPS Location		See photo GPS						GPS Location		See photo GPS	
Field Station#		12005+00						Field Station#		12005+00	
Pic 3 Desc.		CFS triple stack perimeter controls are in acceptable condition.						Pic 4 Desc.		PPL Materials storage.	
											
<p>Date &amp; Time: Thu Oct 10, 2019, 06:38:54 EDT Position: +40.033011° / -084.679987° Altitude: 1266 ft Datum: WGS-84 Azimuth Bearing: 329° N31W 300ft (true) Elevation Angle: +24.7° Horizon Angle: -04.7° Zoom: IX LY-29 - Rock construction surface is maintained in acceptable condition.</p>				<p>Date &amp; Time: Thu Oct 10, 2019, 06:41:02 EDT Position: +40.033011° / -084.679987° Altitude: 1266 ft Datum: WGS-84 Azimuth Bearing: 329° N31W 300ft (true) Elevation Angle: +24.7° Horizon Angle: -04.7° Zoom: IX AR-238.00 - Access road into LY-29 is maintained in acceptable condition.</p>							
GPS Location		See photo GPS						GPS Location		See photo GPS	
Field Station#		12005+00						Field Station#		12005+00	
Pic 5 Desc.		LY-29- Rock construction surface is maintained in acceptable condition.						Pic 6 Desc.		AR-238.00 - Access road into LY-29 is maintained in acceptable condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 7:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 7:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4557
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	10/10/2019 2:27 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11025+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	1042+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 2:27 PM	<b>Report #</b>	4557
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for LDY 28 Observed crew loading out equipment from Craig's Creek, stabilized ROW installed curlex No damaged ECD's observed during inspection ECD's installed per spec and per E&S plans No signs of sediment outside of LOD or impacting any sensitive resources Observed crews stabilizing travel lane off AR 244, stabilization complete					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 2:27 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11061+00		<b>Field Station#</b>	11061+00	
<b>Pic 1 Desc.</b>	Crew staging out equipment		<b>Pic 2 Desc.</b>	Crews installing curlex	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+28		<b>Field Station#</b>	+28	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11032+00		<b>Field Station#</b>	11050+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions, travel lane stabilized		<b>Pic 6 Desc.</b>	Crews stabilizing travel lane	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 2:27 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 2:27 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4565
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	10/10/2019 3:11 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Berm	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 3:11 PM	<b>Report #</b>	4565
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during inspection. Conducted VA SWPPP inspection from MP 219.7 to MP 221 During inspection observed perimeter ECDs. All ECDs observed were functional. ROW has been stabilized using hydro mulch applied by helicopter. Minor vegetation growth present in areas. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	10/10/2019 3:11 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Compost filter sock in place along LOD AT LDY 26.		<b>Pic 2 Desc.</b>	Secondary containment in place under fuel cell.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11667+00		<b>Field Station#</b>	11648+00	
<b>Pic 3 Desc.</b>	Waterbar, sump pit, and triple stack compost filter sock end treatment in place.		<b>Pic 4 Desc.</b>	Slope drain with rock inlet and outlet in place over two tone to minimize erosion.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11620+00		<b>Field Station#</b>	11620+00	
<b>Pic 5 Desc.</b>	Vegetation growth present since recent hydro mulching.		<b>Pic 6 Desc.</b>	Clean water diversion pipe and plunge pool in place.	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 3:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	10/10/2019 3:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4594
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	10/11/2019 7:27 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11022+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	2.00


- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | No  |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)   |     |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 7:27 AM	<b>Report #</b>	4594
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11022+00 to 10930+00. MP- 208.6 to 206.2 The row is damp but in stable condition. Sta#11022+00 to 11012+00 - Temporary stabilization has been completed, controls upgraded. Sta#11012+00 to 10930+00- Equipment is staged at Doe Creek RCE, and Temporary stabilization will begin on Monday in this area. Perimeter controls- P1 silt fence, SSF, and CFS are in acceptable condition. Water bars are in stable condition. Sump pits are in acceptable condition. Water bar end treatments are in acceptable condition. Streams S-IJ18, S-RR5, S-E24, S-E25- Environmental controls, buffers, sensitive resource signage, and equipment bridges are in acceptable condition. Karst and Karst ECD's & sensitive resource signage are in acceptable condition. Access road 244.00 and Doe Creek RCE are maintained in acceptable condition. Environmental crew addressed ECD issues					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Oct 11, 2019, 09:09:00 EDT Position: +09.2223297, -080.5311842 Altitude: 2243ft Datum: WGS-84 Azimuth/Bearing: 321° N20W 0142mils (True) Elevation Angle: +17.2° Horizon Angle: -02.8° Zoom: 1X Sta#11022+00- Stream S-1102- AR-244- SSF fabric detached from chain link ending end treatment.</p>		 <p>Date &amp; Time: Fri, Oct 11, 2019, 09:10:46 EDT Position: +09.2223297, -080.531185° Altitude: 2243ft Datum: WGS-84 Azimuth/Bearing: 009° N08E 0142mils (True) Elevation Angle: +18.8° Horizon Angle: -03.0° Zoom: 1X Sta#11022+00- Stream S-1102- AR-244- SSF fabric detached from chain link ending end treatment.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11022+00		<b>Field Station#</b>	11022+00	
<b>Pic 1 Desc.</b>	Row seeded & mulched, new waddles placed at both ends of equipment bridge, ( temporary stabilization).		<b>Pic 2 Desc.</b>	Equipment bridge, ECD's, signage are in acceptable condition.	
 <p>Date &amp; Time: Fri, Oct 11, 2019, 09:04:21 EDT Position: +09.2223297, -080.5311842 Altitude: 2266ft Datum: WGS-84 Azimuth/Bearing: 029° N21W 0340mils (True) Elevation Angle: +17.2° Horizon Angle: -05.8° Zoom: 1X Sta#11022+00- AR-244- SSF fabric detached from chain link ending end treatment.</p>		 <p>Date &amp; Time: Fri, Oct 11, 2019, 09:29:04 EDT Position: +09.2223297, -080.5311842 Altitude: 2266ft Datum: WGS-84 Azimuth/Bearing: 029° N21W 0340mils (True) Elevation Angle: +17.2° Horizon Angle: -05.8° Zoom: 1X Sta#11016+00- Bridge waddles, dirt fence on steep slope, vegetation, stream, travel lane.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11022+00		<b>Field Station#</b>	11016+00	
<b>Pic 3 Desc.</b>	AR-244- SSF fabric detached from chain link behind end treatment.		<b>Pic 4 Desc.</b>	Bridge waddles & steep slope controls replaced, travel lane seeded & mulched.	
 <p>Date &amp; Time: Fri, Oct 11, 2019, 09:51:22 EDT Position: +09.2223297, -080.5311769 Altitude: 2491ft Datum: WGS-84 Azimuth/Bearing: 335° N22W 595mils (True) Elevation Angle: +19.2° Horizon Angle: -02.9° Zoom: 1X Sta#10986+00- Stream S-E25- Equipment bridge, buffers, signage, ECD's are in acceptable condition.</p>		 <p>Date &amp; Time: Fri, Oct 11, 2019, 09:53:21 EDT Position: +09.2223297, -080.5311769 Altitude: 2491ft Datum: WGS-84 Azimuth/Bearing: 338° N22W 600mils (True) Elevation Angle: +22.5° Horizon Angle: -01.9° Zoom: 1X Sta#10985+00- Stream S-E25- Equipment bridge, buffers, signage, ECD's are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10986+00		<b>Field Station#</b>	10985+00	
<b>Pic 5 Desc.</b>	Stream S-E25- Equipment bridge, signage, Buffers, ECD's are in acceptable condition.		<b>Pic 6 Desc.</b>	Stream S-E24- Equipment bridge, buffers, signage, ECD's are in acceptable condition.	

<b>AFE</b>	124300137	<b>Date/Time</b>	10/11/2019 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
		<p>Insert image here</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>			
<b>Field Station#</b>	10929+70	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	P1 silt fence wooden stakes broken off. Contractor notified and made repairs.	<b>Pic 8 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			









<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4605
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	10/11/2019 11:57 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10832+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Flume Pipe	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 11:57 AM	<b>Report #</b>	4605
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 204.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	10/11/2019 11:57 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	10712+50	
<b>Pic 1 Desc.</b>	Compost filter sock checks in place along access road 241.04 in bar ditch.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G33.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10711+50		<b>Field Station#</b>	10710+00	
<b>Pic 3 Desc.</b>	Waterbar across travel lane with end treatment in place.		<b>Pic 4 Desc.</b>	ROW is stabilized with natural vegetation.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10698+00		<b>Field Station#</b>	10696+00	
<b>Pic 5 Desc.</b>	Sensitive resource buffer in place at stream S-G32.		<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road to assist with the prevention of track out.	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 11:57 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 11:57 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread
<b>Contractor</b>	Precision			<b>Report #</b>	4606
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	10/11/2019 2:47 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10830+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 2:47 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	110858+00		<b>Field Station#</b>	11862+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	Water bar and end treatment recently stabilized	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	110862+00		<b>Field Station#</b>	10880+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10920+00		<b>Field Station#</b>	109220+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	Water bar and end treatment	

<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 2:47 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	10/11/2019 2:47 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		