



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 5967 |
| Inspector | Garrett Barclay | | | Date/Time | 11/18/2019 7:28 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11250+00 |
| State | VA | Inspection Area | Partial | Station End | 1+11 |
| County | Giles | Ground | Dry | Temperature (°F) | 40.00 |
| Municipality | N/A | Weather | Sunny | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |




1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|---|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Flume Pipe | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforced Filter Fabric Fence) | Acceptable | | | |
| Waterbar End Treatment | Acceptable | | | |
| Vegetative Stabilization (Temporary) | Acceptable | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| AFE | 124300137 | Date/Time | 11/18/2019 7:28 AM | Report # | 5967 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Arrived at LDY 26 for morning meeting Performed SWPPP from MP 218 - MP 219.5 No damaged ECD's observed during inspection ECD's installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation Crews walked ROW checking ECD's and making minor repairs to ECD's No signs of sediment outside of LOD or impacting any sensitive resources | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|---------------------------------------|--|-----------------------|---------------------------------------|--|
| A/E | 124300137 | Date/Time | 11/18/2019 7:28 AM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11520+00 | | Field Station# | 11530+00 | |
| Pic 1 Desc. | ECD's and row conditions | | Pic 2 Desc. | ECD's and row conditions | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11545+00 | | Field Station# | 11585+00 | |
| Pic 3 Desc. | ECD's and row conditions | | Pic 4 Desc. | ECD's and row conditions | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11587+00 | | Field Station# | 11598+00 | |
| Pic 5 Desc. | ECD's and row conditions | | Pic 6 Desc. | ECD's and row conditions | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/18/2019 7:28 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/18/2019 7:28 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|------------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 5968 |
| Inspector | Chris Burns | | | Date/Time | 11/18/2019 7:43 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11789+00 |
| State | VA | Inspection Area | Partial | Station End | 12005+00 |
| County | Montgomery | Ground | Wet | Temperature (°F) | 47.00 |
| Municipality | N/A | Weather | Light Rain | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 3.00 |

- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|-------------------------------------|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforce Filter Fence) | Acceptable | | | |
| Waterbar | Acceptable | | | |
| Waterbar End Treatment | Acceptable | | | |
| Waterbar Outlet Protection | Acceptable | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/18/2019 7:43 AM | Report # | 5968 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection between MP 223.3 and MP 227.3. No Major issues were located. Four minor locations of wildlife damage were identified, three of which were P-1 located near stations 11843+30, 11938+35 and 11952+58 the fourth item is CFS near 11944+15. Damaged controls located were put on the punch list to be repaired. MBP representatives assessed a portion of this section as well. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|-----------------------|-------------------------------|-----------------------|----------------------------|-----------------|--|
| AFE | 124300137 | Date/Time | 11/18/2019 7:43 AM | Report # | |
| Pictures | | | | | |
| | | | | | |
| GPS Location | 1 | GPS Location | 2 | | |
| Field Station# | 11789+00 | Field Station# | 11827+00 | | |
| Pic 1 Desc. | RCE off of Mt Tabor rd. | Pic 2 Desc. | Restored RoW. | | |
| | | | | | |
| GPS Location | 3 | GPS Location | 4 | | |
| Field Station# | 11863+65 | Field Station# | 11900+00 | | |
| Pic 3 Desc. | P-KL2. | Pic 4 Desc. | Restored RoW. | | |
| | | | | | |
| GPS Location | 5 | GPS Location | 6 | | |
| Field Station# | 11952+00 | Field Station# | 11990+50 | | |
| Pic 5 Desc. | Vegetation on section of RoW. | Pic 6 Desc. | Vegetation on section RoW. | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/18/2019 7:43 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 12 Desc. | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/18/2019 7:43 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|------------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 5986 |
| Inspector | Jared Saunders | | | Date/Time | 11/18/2019 2:22 PM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11670+00 |
| State | VA | Inspection Area | Partial | Station End | 11788+50 |
| County | Montgomery | Ground | Damp | Temperature (°F) | 45.00 |
| Municipality | N/A | Weather | Light Rain | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|----------------------------|------------------|-------------------|-----------------------|---------------|
| Cleanwater Diversion Berm | Acceptable | | | |
| Cleanwater Diversion Pipe | Acceptable | | | |
| Compost Filter Sock | Acceptable | | | |
| Equipment Bridge | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Plunge Pool | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/18/2019 2:22 PM | Report # | 5986 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Conducted VA SWPPP inspection from MP 221 to 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Light rain storm began at 2:00 PM. Rain gauges will be checked 11/18/19. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|---|--|-----------------------|--|--|
| A/E | 124300137 | Date/Time | 11/18/2019 2:22 PM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11670+00 | | Field Station# | 11687+40 | |
| Pic 1 Desc. | ROW stabilized with seed and mulch. Waterbar sump pits and end treatments in place. | | Pic 2 Desc. | Sensitive resource buffer in place at stream S-MN21. | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11760+00 | | Field Station# | 11767+00 | |
| Pic 3 Desc. | Reinforced super silt fence in place along LOD. | | Pic 4 Desc. | RCE in place at main line valve 26 to assist with the prevention of track out. | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11772+00 | | Field Station# | 11772+00 | |
| Pic 5 Desc. | Clean water diversion pipe and plunge pool in place. | | Pic 6 Desc. | Clean water diversion pipe inlet and clean water diversion berm in place. | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/18/2019 2:22 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/18/2019 2:22 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 5999 |
| Inspector | Chris Burns | | | Date/Time | 11/19/2019 7:13 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 12005+00 |
| State | VA | Inspection Area | Partial | Station End | 12005+00 |
| County | Giles | Ground | Damp | Temperature (°F) | 47.00 |
| Municipality | N/A | Weather | Cloudy | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|----------------------------|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

| | |
|---|-----|
| 5. Site Conditions | |
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/19/2019 7:13 AM | Report # | 5999 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection on LDY 29. No issues were located. Little to no daily activity at this site with minimal stored materials. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|---|--|----------------------------------|----------|--|
| A/E | 124300137 | Date/Time | 11/19/2019 7:13 AM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | 1 | GPS Location | 2 | | |
| Field Station# | 12005+00 | Field Station# | 12005+00 | | |
| Pic 1 Desc. | CFS perimeter control in good condition. | Pic 2 Desc. | Main area LDY 29. | | |
|  | |  | | | |
| GPS Location | 3 | GPS Location | 4 | | |
| Field Station# | 12005+00 | Field Station# | 12005+00 | | |
| Pic 3 Desc. | RCE LDY 29. | Pic 4 Desc. | Minimal materials staged LDY 29. | | |
|  | |  | | | |
| GPS Location | 5 | GPS Location | 6 | | |
| Field Station# | 12005+00 | Field Station# | 12005+00 | | |
| Pic 5 Desc. | CFS perimeter controls in good condition. | Pic 6 Desc. | Overview LDY 29. | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/19/2019 7:13 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/19/2019 7:13 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6000 |
| Inspector | Garrett Barclay | | | Date/Time | 11/19/2019 7:15 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11025+00 |
| State | VA | Inspection Area | Partial | Station End | 11055+00 |
| County | Giles | Ground | Wet | Temperature (°F) | 36.00 |
| Municipality | N/A | Weather | Cloudy | Rain Gauge (in) | 0.10 |
| | | | | Rain Accumulation Time (days) | 1.00 |

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|--------------------------------------|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Secondary Containment | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |
| Sensitive Resource Signage | Acceptable | | | |
| Vegetative Stabilization (Temporary) | Acceptable | | | |
| | | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/19/2019 7:15 AM | Report # | 6000 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Arrived at LDY 26 for morning meeting Performed SWPPP for LDY 28 and from MP 220 - MP 221 No damaged ECD's observed during inspection ECD's installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked ROW checking ECD's and row conditions making repairs Recorded .1" of rain @ Craig's creek | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|-----------------------|---------------------------------------|------------------|-----------------------|---------------------------------------|--|
| A/E | 124300137 | Date/Time | 11/19/2019 7:15 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | | | Field Station# | | |
| Pic 1 Desc. | | | Pic 2 Desc. | | |
| Insert image here | | | Insert image here | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | | | Field Station# | | |
| Pic 3 Desc. | | | Pic 4 Desc. | | |
| Insert image here | | | Insert image here | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | | | Field Station# | | |
| Pic 5 Desc. | | | Pic 6 Desc. | | |

| | | | | | |
|---|---------------------------------------|--|-----------------------|---------------------------------------|--|
| AFE | 124300137 | Date/Time | 11/19/2019 7:15 AM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11664+00 | | Field Station# | 11658+00 | |
| Pic 7 Desc. | ECD's and row conditions | | Pic 8 Desc. | ECD's and row conditions | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11643+00 | | Field Station# | +28 | |
| Pic 9 Desc. | ECD's and row conditions | | Pic 10 Desc. | ECD's and row conditions LDY 28 | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | +28 | | Field Station# | +28 | |
| Pic 11 Desc. | ECD's and row conditions LDY 28 | | Pic 12 Desc. | .1" of rain recorded @ Craig's creek | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/19/2019 7:15 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6020 |
| Inspector | Jared Saunders | | | Date/Time | 11/19/2019 3:14 PM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 12005+00 |
| State | VA | Inspection Area | Partial | Station End | 12005+00 |
| County | Giles | Ground | Damp | Temperature (°F) | 47.00 |
| Municipality | N/A | Weather | Cloudy | Rain Gauge (in) | 0.20 |
| | | | | Rain Accumulation Time (days) | 1.00 |







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|----------------------------|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Secondary Containment | Acceptable | | | |
| Waste Management | Acceptable | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/19/2019 3:14 PM | Report # | 6020 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Catawba Road - 0.2 inches, Mount Tabor Road - 0.2 inches, Steele Acres Road - 0.1 inches, Winding Way - 0.1 inches, Access Road 244 - 0.1 inches, Kow Camp Road - Trace, and LDY 37 - 0.0 inches. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|--|--|-----------------------|--|--|
| A/E | 124300137 | Date/Time | 11/19/2019 3:14 PM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11767+00 | | Field Station# | 11990+00 | |
| Pic 1 Desc. | Rain gauge at main line valve 26 reads 0.2 inches. | | Pic 2 Desc. | Rain gauge at Catawba Road reads 0.2 inches. | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11471+00 | | Field Station# | 11118+00 | |
| Pic 3 Desc. | Rain gauge at Steele Acres Road reads 0.1 inches. | | Pic 4 Desc. | Rain gauge at Winding Way reads 0.1 inches. | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11025+00 | | Field Station# | 10883+50 | |
| Pic 5 Desc. | Rain gauge at access road 244 reads 0.1 inches. | | Pic 6 Desc. | Rain gauge Kow Camp Road has trace amount. | |

| | | | | | |
|--|---|---|---|-----------------|--|
| AFE | 124300137 | Date/Time | 11/19/2019 3:14 PM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | GPS Location | See photo for GPS location. | | |
| Field Station# | 12005+00 | Field Station# | 12005+00 | | |
| Pic 7 Desc. | Rain gauge at LDY 37 had no rain water in it. | Pic 8 Desc. | CFS in place along LOD of LDY 26. | | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | GPS Location | See photo for GPS location. | | |
| Field Station# | 12005+00 | Field Station# | 12005+00 | | |
| Pic 9 Desc. | Dumpsters located at LDY 26 for waste management. | Pic 10 Desc. | Secondary containment in place under fuel cell. | | |
| Insert image here | | Insert image here | | | |
| GPS Location | | GPS Location | | | |
| Field Station# | | Field Station# | | | |
| Pic 11 Desc. | | Pic 12 Desc. | | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/19/2019 3:14 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6037 |
| Inspector | Garrett Barclay | | | Date/Time | 11/20/2019 7:43 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11840+00 |
| State | VA | Inspection Area | Partial | Station End | 11940+00 |
| County | Giles | Ground | Dry | Temperature (°F) | 42.00 |
| Municipality | N/A | Weather | Cloudy | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |







- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|---|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforced Filter Fabric Fence) | Acceptable | | | |
| Waterbar End Treatment | Acceptable | | | |
| Vegetative Stabilization (Temporary) | Acceptable | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/20/2019 7:43 AM | Report # | 6037 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Arrived at LDY 26 for morning meeting No damaged ECD's observed during inspection ECD's installed per spec and per E&S plans ROW conditions are stable and shows good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews work on stabilizing ROW off old furnace and checking ROW conditions | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|--|---------------------------------------|---|-----------------------|---------------------------------------|--|
| AFE | 124300137 | Date/Time | 11/20/2019 7:43 AM | Report # | |
| Pictures | | | | | |
|  <p>Date & Time: Wed Nov 20 2019 09:51:52 EST Position: 40°17'21.40"N 76°03'35.40"W Altitude: 2040 ft (621 m) Datum: WGS 84 Azimuth Bearing: 334° N44W 5540mils True (±12) Elevation Grade: -0.2 Horizon Grade: +100 Zoom: 1.0X 10845</p> | |  <p>Date & Time: Wed Nov 20 2019 09:51:52 EST Position: 40°17'21.40"N 76°03'35.40"W Altitude: 2040 ft (621 m) Datum: WGS 84 Azimuth Bearing: 334° N44W 5540mils True (±12) Elevation Grade: -0.2 Horizon Grade: +100 Zoom: 1.0X 10864</p> | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 10845+00 | | Field Station# | 10864+00 | |
| Pic 1 Desc. | ECD's and row conditions | | Pic 2 Desc. | ECD's and row conditions | |
|  <p>Date & Time: Wed Nov 20 2019 09:51:52 EST Position: 40°17'21.40"N 76°03'35.40"W Altitude: 2040 ft (621 m) Datum: WGS 84 Azimuth Bearing: 334° N44W 5540mils True (±12) Elevation Grade: -0.2 Horizon Grade: +100 Zoom: 1.0X 10871</p> | |  <p>Date & Time: Wed Nov 20 2019 09:51:52 EST Position: 40°17'21.40"N 76°03'35.40"W Altitude: 2040 ft (621 m) Datum: WGS 84 Azimuth Bearing: 334° N44W 5540mils True (±12) Elevation Grade: -0.2 Horizon Grade: +100 Zoom: 1.0X 10888</p> | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 10871+00 | | Field Station# | 10888+00 | |
| Pic 3 Desc. | ECD's and row conditions | | Pic 4 Desc. | ECD's and row conditions | |
|  <p>Date & Time: Wed Nov 20 2019 09:51:52 EST Position: 40°17'21.40"N 76°03'35.40"W Altitude: 2040 ft (621 m) Datum: WGS 84 Azimuth Bearing: 334° N44W 5540mils True (±12) Elevation Grade: -0.2 Horizon Grade: +100 Zoom: 1.0X 10920</p> | |  <p>Date & Time: Wed Nov 20 2019 09:51:52 EST Position: 40°17'21.40"N 76°03'35.40"W Altitude: 2040 ft (621 m) Datum: WGS 84 Azimuth Bearing: 334° N44W 5540mils True (±12) Elevation Grade: -0.2 Horizon Grade: +100 Zoom: 1.0X 10929</p> | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 10920+00 | | Field Station# | 10929+00 | |
| Pic 5 Desc. | ECD's and row conditions | | Pic 6 Desc. | ECD's and row conditions | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/20/2019 7:43 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/20/2019 7:43 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report







| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6052 |
| Inspector | Jared Saunders | | | Date/Time | 11/20/2019 3:31 PM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 10670+00 |
| State | VA | Inspection Area | Partial | Station End | 11025+00 |
| County | Giles | Ground | Dry | Temperature (°F) | 48.00 |
| Municipality | N/A | Weather | Cloudy | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|---|------------------|-------------------|-----------------------|---------------|
| Broad-Based Dip | Acceptable | | | |
| Compost Filter Sock | Acceptable | | | |
| Equipment Bridge | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforced Filter Fabric Fence) | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |

| | |
|---|-----|
| 5. Site Conditions | |
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/20/2019 3:31 PM | Report # | 6052 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Conducted VA SWPPP inspection from MP 201.7 to MP 204.6 and from MP 207 to MP 208.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|--|--|-----------------------|--|--|
| A/E | 124300137 | Date/Time | 11/20/2019 3:31 PM | Report # | |
| Pictures | | | | | |
|  <p>Date & Time: Wed Nov 20 2019 10:26:29 EST Position: +037.2083481 / -080.537095 (-22141.0m) Altitude: 2531 ft (-51.2m) Datum: WGS-84 Azimuth/Heading: 297 N43W 5280mils True (-16) Elevation Angle: -22.7 Horizon Angle: +01.3 Zoom: 1.0X 11026+00</p> | |  <p>Date & Time: Wed Nov 20 2019 10:26:29 EST Position: +037.2083481 / -080.537095 (-22141.0m) Altitude: 2531 ft (-51.2m) Datum: WGS-84 Azimuth/Heading: 297 N43W 5280mils True (-16) Elevation Angle: -22.7 Horizon Angle: +01.3 Zoom: 1.0X 11026+00</p> | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11020+00 | | Field Station# | 11008+00 | |
| Pic 1 Desc. | ROW stabilized, waterbars, and end treatments in place. | | Pic 2 Desc. | Reinforced super silt fence in place along LOD. | |
|  <p>Date & Time: Wed Nov 20 2019 10:26:29 EST Position: +037.2083481 / -080.537095 (-22141.0m) Altitude: 2531 ft (-51.2m) Datum: WGS-84 Azimuth/Heading: 297 N43W 5280mils True (-16) Elevation Angle: -22.7 Horizon Angle: +01.3 Zoom: 1.0X 10978+00</p> | |  <p>Date & Time: Wed Nov 20 2019 10:26:29 EST Position: +037.2083481 / -080.537095 (-22141.0m) Altitude: 2531 ft (-51.2m) Datum: WGS-84 Azimuth/Heading: 297 N43W 5280mils True (-16) Elevation Angle: -22.7 Horizon Angle: +01.3 Zoom: 1.0X 10945+00</p> | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 10978+00 | | Field Station# | 10945+00 | |
| Pic 3 Desc. | Triple stack 18 inch compost filter sock in place along LOD. | | Pic 4 Desc. | Waterbars in travel with CFS end treatments and ROW stabilized. | |
|  <p>Date & Time: Wed Nov 20 2019 11:37:05 EST Position: +037.31144 / -080.547095 (-22141.0m) Altitude: 1815 ft (-170.0m) Datum: WGS-84 Azimuth/Heading: 150 S50E 2311mils True (-16) Elevation Angle: -01.3 Horizon Angle: +02.8 Zoom: 1.0X 12005+00</p> | |  <p>Date & Time: Wed Nov 20 2019 11:38:31 EST Position: +037.30689 / -080.52645 (-22141.0m) Altitude: 2214 ft (-102.0m) Datum: WGS-84 Azimuth/Heading: 134 S44E 2418mils True (-16) Elevation Angle: -11.4 Horizon Angle: +02.8 Zoom: 1.0X 10696+00</p> | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 12005+00 | | Field Station# | 10696+00 | |
| Pic 5 Desc. | Compost filter sock checks in place in bar ditch along access road 241.04. | | Pic 6 Desc. | RCE in place Buffalo Anklets Road to assist with track out prevention. | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/20/2019 3:31 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/20/2019 3:31 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6068 |
| Inspector | Chris Burns | | | Date/Time | 11/21/2019 6:53 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11255+00 |
| State | VA | Inspection Area | Partial | Station End | 11354+00 |
| County | Giles | Ground | Damp | Temperature (°F) | 52.00 |
| Municipality | N/A | Weather | Cloudy | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|-------------------------------------|------------------|-------------------|-----------------------|---------------|
| Cleanwater Diversion Berm | Acceptable | | | |
| Cleanwater Diversion Pipe | Acceptable | | | |
| Compost Filter Sock | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Plunge Pool | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforce Filter Fence) | Acceptable | | | |
| Waterbar | Acceptable | | | |

| | |
|---|-----|
| 5. Site Conditions | |
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| AFE | 124300137 | Date/Time | 11/21/2019 6:53 AM | Report # | 6068 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection from MP 213 to MP 214.8. No issues were located in this area. Temporary stabilization or vegetation is sufficient. Asplundh crews were working in close proximity to the RoW LoD near 11331+27. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|--------------------------------|----------------|--|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 6:53 AM | Report # | |
| Pictures | | | | | |
|  | | |  | | |
| GPS Location | 1 | GPS Location | 2 | | |
| Field Station# | 11258+50 | Field Station# | 11265+00 | | |
| Pic 1 Desc. | Temporary vegetation. | | Pic 2 Desc. | Temporary vegetation. | |
|  | | |  | | |
| GPS Location | 3 | GPS Location | 4 | | |
| Field Station# | 11270+00 | Field Station# | 11292+80 | | |
| Pic 3 Desc. | Plunge pool in good condition. | | Pic 4 Desc. | S-MM18. | |
|  | | |  | | |
| GPS Location | 5 | GPS Location | 6 | | |
| Field Station# | 11327+85 | Field Station# | 11352+97 | | |
| Pic 5 Desc. | S-NN12. | | Pic 6 Desc. | S-NN11. | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 6:53 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 6:53 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6069 |
| Inspector | Chris Burns | | | Date/Time | 11/21/2019 7:13 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11161+00 |
| State | VA | Inspection Area | Partial | Station End | 11237+88 |
| County | Giles | Ground | Damp | Temperature (°F) | 52.00 |
| Municipality | N/A | Weather | Cloudy | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|-------------------------------------|------------------|-------------------|-----------------------|---------------|
| Cleanwater Diversion Berm | Acceptable | | | |
| Cleanwater Diversion Pipe | Acceptable | | | |
| Compost Filter Sock | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Plunge Pool | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforce Filter Fence) | Acceptable | | | |
| Waterbar | Acceptable | | | |
| Waterbar End Treatment | Acceptable | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/21/2019 7:13 AM | Report # | 6069 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection from MP 211 to MP 213. No issues were located. Temporary stabilization or vegetation is sufficient. Precision environmental crews and MBP representatives were in this area. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|---|--|---------------------------------------|-----------------|--|
| AFE | 124300137 | Date/Time | 11/21/2019 7:13 AM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | 1 | GPS Location | 2 | | |
| Field Station# | 11229+00 | Field Station# | 11237+00 | | |
| Pic 1 Desc. | Temporary stabilization. | Pic 2 Desc. | Temporary vegetation on topsoil pile. | | |
|  | |  | | | |
| GPS Location | 3 | GPS Location | 4 | | |
| Field Station# | 11222+00 | Field Station# | 11211+00 | | |
| Pic 3 Desc. | Temporary stabilization. | Pic 4 Desc. | Temporary stabilization. | | |
|  | |  | | | |
| GPS Location | 5 | GPS Location | 6 | | |
| Field Station# | 11199+00 | Field Station# | 11184+00 | | |
| Pic 5 Desc. | Reinforced fabric silt fence in good condition. | Pic 6 Desc. | Plunge pool in good condition. | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 7:13 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 7:13 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6072 |
| Inspector | Garrett Barclay | | | Date/Time | 11/21/2019 8:09 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11025+00 |
| State | VA | Inspection Area | Partial | Station End | 11130+00 |
| County | Giles | Ground | Dry | Temperature (°F) | 31.00 |
| Municipality | N/A | Weather | Sunny | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|---|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforced Filter Fabric Fence) | Acceptable | | | |
| Vegetative Stabilization (Temporary) | Acceptable | | | |
| Waterbar End Treatment | Acceptable | | | |

| | |
|---|-----|
| 5. Site Conditions | |
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| AFE | 124300137 | Date/Time | 11/21/2019 8:09 AM | Report # | 6072 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Arrived at LDY 26 for morning meeting Performed SWPPP from MP 208- MP 211.5 No damaged ECD's observed during inspection ECD's installed per spec and per E&S plans ROW conditions are stable and show good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked row checking ECD's and making minor repairs to ECD's | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|-----------------------|---------------------------------------|------------------|-----------------------|---------------------------------------|--|
| AFE | 124300137 | Date/Time | 11/21/2019 8:09 AM | Report # | |
| Pictures | | | | | |
| | | | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11025+00 | | Field Station# | 11320+00 | |
| Pic 1 Desc. | ECD's and row conditions | | Pic 2 Desc. | ECD's and row conditions | |
| | | | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11450+00 | | Field Station# | 11450+00 | |
| Pic 3 Desc. | ECD's and row conditions | | Pic 4 Desc. | ECD's and row conditions | |
| | | | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 1138+00 | | Field Station# | 11140+00 | |
| Pic 5 Desc. | ECD's and row conditions | | Pic 6 Desc. | ECD's and row conditions | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 8:09 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 8:09 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report




| | | | | | |
|---------------------|-------------------------|------------------------|-----------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6091 |
| Inspector | Jared Saunders | | | Date/Time | 11/21/2019 3:08 PM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11351+00 |
| State | VA | Inspection Area | Partial | Station End | 11526+00 |
| County | Giles | Ground | Damp | Temperature (°F) | 55.00 |
| Municipality | N/A | Weather | Cloudy | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|----------------------------|------------------|-------------------|-----------------------|---------------|
| Broad-Based Dip | Acceptable | | | |
| Cleanwater Diversion Berm | Acceptable | | | |
| Cleanwater Diversion Pipe | Acceptable | | | |
| Compost Filter Sock | Acceptable | | | |
| Equipment Bridge | Acceptable | | | |
| Plunge Pool | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |
| Waterbar | Acceptable | | | |

| | |
|---|-----|
| 5. Site Conditions | |
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/21/2019 3:08 PM | Report # | 6091 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Environmental crew recently completed spreading new seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during VA SWPPP inspection. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|---|--|-----------------------|--|--|
| A/E | 124300137 | Date/Time | 11/21/2019 3:08 PM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11506+00 | | Field Station# | 11502+00 | |
| Pic 1 Desc. | Plunge pool and clean water diversion pipe in place. | | Pic 2 Desc. | Conveyance channel with rock checks in place at double cut section of ROW. | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11471+00 | | Field Station# | 11468+00 | |
| Pic 3 Desc. | Compost filter sock checks in place along Steele Acres access road. | | Pic 4 Desc. | Slope drain in place with priority one end treatment. | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11381+00 | | Field Station# | 11429+00 | |
| Pic 5 Desc. | Triple barrier ECDs in place at off ROW karst feature. | | Pic 6 Desc. | ROW recently stabilized with seed and mulch. Waterbar in place. | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 3:08 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/21/2019 3:08 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|------------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6102 |
| Inspector | Chris Burns | | | Date/Time | 11/22/2019 7:21 AM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11789+00 |
| State | VA | Inspection Area | Partial | Station End | 12001+00 |
| County | Montgomery | Ground | Wet | Temperature (°F) | 50.00 |
| Municipality | N/A | Weather | Light Rain | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|-------------------------------------|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforce Filter Fence) | Acceptable | | | |
| Waterbar | Acceptable | | | |
| Waterbar End Treatment | Acceptable | | | |
| Waterbar Outlet Protection | Acceptable | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/22/2019 7:21 AM | Report # | 6102 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| See photos for GPS coordinates. Attended the morning inspection meeting. Attended Precisions weekly safety meeting. Performed SWPPP inspection from MP 223.3 to MP 227.3 as well as assessed AR 266.03. No major issues were located. A hole was identified in P-1, caused by cattle, near 11843+05. Crews repaired the P-1 prior to end of day. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|-----------|-----------|--------------------|----------|--|
| A/E | 124300137 | Date/Time | 11/22/2019 7:21 AM | Report # | |
| Pictures | | | | | |
| <div><div><div><div><div><div></div><div></div></div></div><div><div><div></div><div></div></div></div><div><div><div></div></div></div></div></div><div><div><div><div><div></div><div></div></div></div><div><div><div></div></div></div></div></div><div><div><div><div></div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></div></div></div></div> <div><div><div><div></</div></div></div></div> | | | | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/22/2019 7:21 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 12 Desc. | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/22/2019 7:21 AM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report






| | | | | | |
|---------------------|-------------------------|------------------------|------------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6115 |
| Inspector | Garrett Barclay | | | Date/Time | 11/22/2019 2:40 PM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11520+00 |
| State | VA | Inspection Area | Partial | Station End | 11605+00 |
| County | Giles | Ground | Wet | Temperature (°F) | 48.00 |
| Municipality | N/A | Weather | Light Rain | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|---|------------------|-------------------|-----------------------|---------------|
| Compost Filter Sock | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |
| Silt Fence (Filter Fabric Fence) | Acceptable | | | |
| Silt Fence (Reinforced Filter Fabric Fence) | Acceptable | | | |
| Vegetative Stabilization (Temporary) | Acceptable | | | |
| Waterbar | Acceptable | | | |
| Waterbar End Treatment | Acceptable | | | |

| | |
|---|-----|
| 5. Site Conditions | |
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

| | | | | | |
|---|---------------------------------------|--|-----------------------|---------------------------------------|--|
| AFE | 124300137 | Date/Time | 11/22/2019 2:40 PM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11520+00 | | Field Station# | 11532+00 | |
| Pic 1 Desc. | ECD's and row conditions | | Pic 2 Desc. | ECD's and row conditions | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11548+00 | | Field Station# | 11584+00 | |
| Pic 3 Desc. | ECD's and row conditions | | Pic 4 Desc. | ECD's and row conditions | |
|  | |  | | | |
| GPS Location | See picture above for GPS coordinates | | GPS Location | See picture above for GPS coordinates | |
| Field Station# | 11584+00 | | Field Station# | 11596+00 | |
| Pic 5 Desc. | ECD's and row conditions | | Pic 6 Desc. | ECD's and row conditions | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/22/2019 2:40 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/22/2019 2:40 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |



Visual Site Inspection Report

| | | | | | |
|---------------------|-------------------------|------------------------|------------|--------------------------------------|-------------------------|
| Project Name | H-600 Pipeline Spread G | AFE | 124300137 | Spread | H-600 Pipeline Spread G |
| Contractor | Precision | | | Report # | 6116 |
| Inspector | Jared Saunders | | | Date/Time | 11/22/2019 3:01 PM |
| Permit # | TBD | Inspection Type | VA SWPP | Station Begin | 11670+00 |
| State | VA | Inspection Area | Partial | Station End | 11788+50 |
| County | Montgomery | Ground | Wet | Temperature (°F) | 53.00 |
| Municipality | N/A | Weather | Light Rain | Rain Gauge (in) | 0.00 |
| | | | | Rain Accumulation Time (days) | 1.00 |







- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

| E&S BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired |
|----------------------------|------------------|-------------------|-----------------------|---------------|
| Cleanwater Diversion Berm | Acceptable | | | |
| Cleanwater Diversion Pipe | Acceptable | | | |
| Compost Filter Sock | Acceptable | | | |
| Equipment Bridge | Acceptable | | | |
| Erosion Control Blanket | Acceptable | | | |
| Housekeeping | Acceptable | | | |
| Plunge Pool | Acceptable | | | |
| Rock Construction Entrance | Acceptable | | | |
| Sensitive Resource Buffer | Acceptable | | | |

5. Site Conditions

| | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

| | | | | | |
|---|-------------------------|--------------------------|------------------------------|----------------------|------|
| A/E | 124300137 | Date/Time | 11/22/2019 3:01 PM | Report # | 6116 |
| 6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | |
| PCSM BMPs | Compliance Level | Corrective Action | Corrective Time Frame | Date Repaired | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | |
| | | | | | |
| Comments (Reference above questions as appropriate.) | | | | | |
| Conducted VA SWPPP inspection from MP 221 to 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Light rain storm began at 9:00 AM . Rain gauges will be checked on 11/25/19. | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements. | | | | | |

| | | | | | |
|---|--|--|-----------------------|--|--|
| A/E | 124300137 | Date/Time | 11/22/2019 3:01 PM | Report # | |
| Pictures | | | | | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11669+00 | | Field Station# | 11670+00 | |
| Pic 1 Desc. | Triple stack compost filter sock with priority one silt fence along LOD. | | Pic 2 Desc. | Waterbar, sump pit, and triple stack compost filter sock end treatment in place. | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11681+00 | | Field Station# | 11687+40 | |
| Pic 3 Desc. | ROW stabilized with seed and mulch. Waterbar in place. | | Pic 4 Desc. | Sensitive resource buffer in place at stream S-MN21. | |
|  | |  | | | |
| GPS Location | See photo for GPS location. | | GPS Location | See photo for GPS location. | |
| Field Station# | 11767+00 | | Field Station# | 11776+00 | |
| Pic 5 Desc. | RCE in place at main line valve 26 to prevent track out onto Mount Tabor Road. | | Pic 6 Desc. | Clean water diversion pipe and plunge pool in place. | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/22/2019 3:01 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 7 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 9 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 11 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |

| | | | | | |
|-----------------------|-----------|-----------------------|--------------------|-----------------------|--|
| A/E | 124300137 | Date/Time | 11/22/2019 3:01 PM | Report # | |
| Pictures | | | | | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 13 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 15 Desc. | |
| Insert image here | | | Insert image here | | |
| GPS Location | | GPS Location | | Field Station# | |
| Field Station# | | Field Station# | | Pic 17 Desc. | |
| Insert image here | | | Insert image here | | |
| Insert image here | | | Insert image here | | |