



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6152
Inspector	Garrett Barclay			Date/Time	11/25/2019 7:17 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12500+00
State	VA	Inspection Area	Partial	Station End	12500+00
County	Giles	Ground	Wet	Temperature (°F)	42.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/25/2019 7:17 AM	Report #	6152
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting No damaged ECD's observed during inspection ECD's installed per spec and per E&S plans ROW conditions are stable and show good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked highway 42 section checking ROW conditions and making minor repairs to controls .7" of rain recorded @ Pocahontas AR, .4" of rain @ LDY 37, .7" of rain recorded @ AR 244					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	11/25/2019 7:17 AM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+37	
Pic 1 Desc.	.7" of rain recorded @ Pocahontas AR		Pic 2 Desc.	.4" of rain recorded @ LDY 37	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+28		Field Station#	+28	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+28		Field Station#	+28	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	11/25/2019 7:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/25/2019 7:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6153
Inspector	Chris Burns			Date/Time	11/25/2019 7:18 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	56.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/25/2019 7:18 AM	Report #	6153
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection of LDY 29. No issues were located. No equipment and very little materials stored at this location. Little to no daily activity. Checked rain gauges and assessed adjacent sections of RoW at Buffalo Anklets (.8") and AR 234 (.6").					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	11/25/2019 7:18 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	CFS perimeter control in good condition.	Pic 2 Desc.	CFS perimeter control in good condition.		
					
GPS Location	3	GPS Location	4		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	Stored materials.	Pic 4 Desc.	Overview of LDY 29.		
					
GPS Location	5	GPS Location	6		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	Upper section of LDY 29.	Pic 6 Desc.	Overview of LDY 29.		

A/E	124300137	Date/Time	11/25/2019 7:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/25/2019 7:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6162
Inspector	Rob Robertson			Date/Time	11/25/2019 11:49 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11669+87
County	Giles	Ground	Damp	Temperature (°F)	46.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/25/2019 11:49 AM	Report #	6162
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VADEQ SWPPP inspection for private and JNF lands between Craig Creek Road (11600+01) and the JNF property line at 11669+87. The area received approximately 1.0" of rainfall over the weekend. ROW conditions are currently stable. All perimeter controls are in place and functional. No ECD maintenance needs were identified. Slope breakers are working properly and runoff through end treatments is effectively being filtered. No erosion issues or sediment migration beyond LOD located. Resource crossings are stable with well vegetated buffers and ECDs in place.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	11/25/2019 11:49 AM	Report #	
Pictures					
					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11667+00		Field Station#	11663+00	
Pic 1 Desc.	Perimeter controls in place. ROW stable.		Pic 2 Desc.	Slope breaker end treatment effective	
					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11650+00		Field Station#	11650+00	
Pic 3 Desc.	Perimeter controls in place and working properly		Pic 4 Desc.	End treatments working properly	
					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11639+50		Field Station#	11618+00	
Pic 5 Desc.	Slope breakers working as designed. Grasses adequate to prevent erosion		Pic 6 Desc.	Straw mulch and some annual grasses effectively controlling erosion on private lands	

AFE	124300137	Date/Time	11/25/2019 11:49 AM	Report #	
Pictures					
 <p><small>Date & Time: Mon Nov 25, 2019 10:54:00 EST Position: -83.313676, 41.080103589 Altitude: 1197ft Datum: WGS-84 Azimuth/Bearing: 234, S56W, 41.03mils True Elevation Angle: -34.5 Horizon Angle: +00.2 Zoom: 1X Brush Mtn 11626+04, Private tract stable</small></p>		 <p><small>Date & Time: Mon Nov 25, 2019 10:55:00 EST Position: -83.313676, 41.080103589 Altitude: 1197ft Datum: WGS-84 Azimuth/Bearing: 234, S56W, 41.03mils True Elevation Angle: -34.5 Horizon Angle: +00.2 Zoom: 1X Brush Mtn 11614+20, S-RR14 crossing stable</small></p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11626+04	Field Station#	11614+20		
Pic 7 Desc.	S-HH18 crossing stable	Pic 8 Desc.	S-RR14 crossing stable		
 <p><small>Date & Time: Mon Nov 25, 2019 10:54:00 EST Position: -83.313676, 41.080103589 Altitude: 1197ft Datum: WGS-84 Azimuth/Bearing: 234, S56W, 41.03mils True Elevation Angle: -34.5 Horizon Angle: +00.2 Zoom: 1X Brush Mtn 11608+17, S-006 crossing stable</small></p>		 <p><small>Date & Time: Mon Nov 25, 2019 10:55:00 EST Position: -83.313676, 41.080103589 Altitude: 1197ft Datum: WGS-84 Azimuth/Bearing: 234, S56W, 41.03mils True Elevation Angle: -34.5 Horizon Angle: +00.2 Zoom: 1X Brush Mtn 11607+00, Private tract stable</small></p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11608+17	Field Station#	11607+00		
Pic 9 Desc.	S-006 crossing stable	Pic 10 Desc.	ROW currently stable		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	11/25/2019 11:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6179
Inspector	Jared Saunders			Date/Time	11/25/2019 3:44 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.10
				Rain Accumulation Time (days)	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/25/2019 3:44 PM	Report #	6179
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Catawba Road - 1.2 inches, Mount Tabor Road - 1.1 inches, Steele Acres Road - 1.0 inches, and Winding Way - 1.0 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	11/25/2019 3:44 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11990+00		Field Station#	11767+00	
Pic 1 Desc.	Rain gauge at Catawba Road reads 1.2 inches.		Pic 2 Desc.	Rain gauge at Mount Tabor Road reads 1.1 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11471+00		Field Station#	11125+00	
Pic 3 Desc.	Rain gauge at Steele Acres Road reads 1.0 inches.		Pic 4 Desc.	Rain gauge at Winding Way reads 1.0 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Secondary containment in place under fuel cell.		Pic 6 Desc.	RCE in place at employee parking lot in LDY 26.	

A/E	124300137	Date/Time	11/25/2019 3:44 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/25/2019 3:44 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6190
Inspector	Chris Burns			Date/Time	11/26/2019 7:01 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10929+71
State	VA	Inspection Area	Partial	Station End	11023+80
County	Giles	Ground	Wet	Temperature (°F)	59.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/26/2019 7:01 AM	Report #	6190
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection between MP 207 and MP 208.8. No major issues were located. One hole in CFS, caused by cattle, was identified near 1094+00. Two locations of CFS perimeter control and a section of RoW was impacted by non MVP related vehicle travel from 10970+00 to 10983+00. These issues were repaired by the end of the day.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		Date/Time	11/26/2019 7:01 AM	Report #	
Pictures					
<p>Date & Time: Tue, Nov 26, 2019, 09:15:45 EST Position: +037.208364° / -080.584108° (+16570 ft) Altitude: 2126ft (+27.7m) Datum: WGS-84 Azimuth/Bearing: 304° NSW 500mils True (+22°) Elevation Angle: +22.7° Horizon Angle: +61.3° Zoom: 1.0x 11023+00</p> 		<p>Date & Time: Tue, Nov 26, 2019, 09:16:31 EST Position: +037.211949° / -080.559642° (+17291 ft) Altitude: 2437ft (+73.9m) Datum: WGS-84 Azimuth/Bearing: 64° NNEW 630mils True (+25°) Elevation Angle: +25° Horizon Angle: +37.1° Zoom: 1.0x 11020+00</p> 			
GPS Location 1		GPS Location 2			
Field Station# 11023+00		Field Station# 11020+00			
Pic 1 Desc. Vegetated or stabilized RoW.		Pic 2 Desc. Overview of RoW.			
<p>Date & Time: Tue, Nov 26, 2019, 09:45:28 EST Position: +037.323639° / -080.543013° (+16100 ft) Altitude: 2608ft (+80.3m) Datum: WGS-84 Azimuth/Bearing: 204° SSW 362mils True (+19°) Elevation Angle: +28.3° Horizon Angle: +40.7° Zoom: 1.0x Others enter RoW 10983+00 damaged rock</p> 		<p>Date & Time: Tue, Nov 26, 2019, 10:13:29 EST Position: +037.327549° / -080.571725° (+1738 ft) Altitude: 2517ft (+76.8m) Datum: WGS-84 Azimuth/Bearing: 330° WNW 588mils True (+24°) Elevation Angle: +18° Horizon Angle: +61.1° Zoom: 1.0x 10969+00</p> 			
GPS Location 3		GPS Location 4			
Field Station# 10983+00		Field Station# 10969+00			
Pic 3 Desc. CFS perimeter control damaged by non MVP related vehicle travel.		Pic 4 Desc. Overview of RoW.			
<p>Date & Time: Tue, Nov 26, 2019, 10:30:20 EST Position: +037.329204° / -080.578114° (+26.2ft) Altitude: 1975ft (+60.4m) Datum: WGS-84 Azimuth/Bearing: 295° N65W 524mils True (+20°) Elevation Angle: +10.4° Horizon Angle: +04.1° Zoom: 1.0x 10947+00</p> 		<p>Date & Time: Tue, Nov 26, 2019, 10:39:17 EST Position: +037.318291° / -080.618161° (+1105 ft) Altitude: 2184ft (+66.9m) Datum: WGS-84 Azimuth/Bearing: 345° N14W 615mils True (+20°) Elevation Angle: +06.0° Horizon Angle: +08.6° Zoom: 1.0x 10934+50</p> 			
GPS Location 5		GPS Location 6			
Field Station# 10947+00		Field Station# 10934+50			
Pic 5 Desc. Vegetated RoW.		Pic 6 Desc. Reinforced silt fence perimeter control in good condition.			

A/E	124300137	Date/Time	11/26/2019 7:01 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/26/2019 7:01 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6191
Inspector	Garrett Barclay			Date/Time	11/26/2019 7:01 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10834+00
State	VA	Inspection Area	Partial	Station End	10956+00
County	Giles	Ground	Damp	Temperature (°F)	28.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/26/2019 7:01 AM	Report #	6191
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 205-MP207 No damaged ECD's observed during inspection ECD's are installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked row checking ECD's and making minor repairs to ECD's					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		11/26/2019 7:01 AM		Report #			
Pictures											
											
GPS Location		See picture above for GPS coordinates						GPS Location		See picture above for GPS coordinates	
Field Station#		2+34						Field Station#		10848+00	
Pic 1 Desc.		ECD's and row conditions						Pic 2 Desc.		ECD's and row conditions	
											
GPS Location		See picture above for GPS coordinates						GPS Location		See picture above for GPS coordinates	
Field Station#		10867+00						Field Station#		10875+00	
Pic 3 Desc.		ECD's and row conditions						Pic 4 Desc.		ECD's and row conditions	
											
GPS Location		See picture above for GPS coordinates						GPS Location		See picture above for GPS coordinates	
Field Station#		10888+00						Field Station#		10928+00	
Pic 5 Desc.		ECD's and row conditions						Pic 6 Desc.		ECD's and row conditions	

A/E	124300137	Date/Time	11/26/2019 7:01 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/26/2019 7:01 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6205
Inspector	Jared Saunders			Date/Time	11/26/2019 4:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	10832+00
County	Giles	Ground	Wet	Temperature (°F)	57.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/26/2019 4:22 PM	Report #	6205
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 204.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	11/26/2019 4:22 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location		GPS Location	See photo for GPS location	
Field Station#	10712+50		Field Station#	12005+00	
Pic 1 Desc.	Sensitive resource buffer in place at stream S-G33.		Pic 2 Desc.	Compost filter sock checks in place along AR 241.04 in bar ditch.	
					
GPS Location	See photo for GPS location		GPS Location	See photo for GPS location	
Field Station#	10711+00		Field Station#	10698+00	
Pic 3 Desc.	Waterbar across travel lane with CFS end treatment.		Pic 4 Desc.	Sensitive resource buffer in place at stream S-G32.	
					
GPS Location	See photo for GPS location		GPS Location	See photo for GPS location	
Field Station#	10696+00		Field Station#	1067+00	
Pic 5 Desc.	RCE in place at Buffalo Anklets Road.		Pic 6 Desc.	Reinforced super silt fence in place along LOD.	

A/E	124300137	Date/Time	11/26/2019 4:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/26/2019 4:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6217
Inspector	Chris Burns			Date/Time	11/27/2019 6:59 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11161+00
State	VA	Inspection Area	Partial	Station End	11354+00
County	Giles	Ground	Wet	Temperature (°F)	64.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/27/2019 6:59 AM	Report #	6217
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection from MP 211 to MP 214.8. No issues were located. Temporary stabilization or vegetation is sufficient. All ECDs functional.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	11/27/2019 6:59 AM	Report #	
Pictures					
					
GPS Location	1		GPS Location	2	
Field Station#	11258+00		Field Station#	11283+00	
Pic 1 Desc.	Temporary stabilization.		Pic 2 Desc.	Topsoil pile with temporary stabilization.	
					
GPS Location	3		GPS Location	4	
Field Station#	11292+80		Field Station#	11334+00	
Pic 3 Desc.	S-MM18.		Pic 4 Desc.	Temporary stabilization.	
					
GPS Location	5		GPS Location	6	
Field Station#	11231+00		Field Station#	11206+00	
Pic 5 Desc.	Temporary stabilization.		Pic 6 Desc.	Temporary stabilization.	

A/E	124300137	Date/Time	11/27/2019 6:59 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/27/2019 6:59 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6219
Inspector	Garrett Barclay			Date/Time	11/27/2019 7:17 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11025+00
State	VA	Inspection Area	Partial	Station End	11130+00
County	Giles	Ground	Damp	Temperature (°F)	44.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/27/2019 7:17 AM	Report #	6219
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 208 - MP 211.5 No damaged ECD's observed during SWPPP inspection ECD's are installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked row checking ECD's and making minor repairs to ECD's					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	11/27/2019 7:17 AM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11025+00		Field Station#	11036+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11045+00		Field Station#	11138+00	
Pic 3 Desc.	ECD's and row conditions for		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11138+00		Field Station#	11140+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	11/27/2019 7:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/27/2019 7:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6226
Inspector	Jared Saunders			Date/Time	11/27/2019 3:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11351+00
State	VA	Inspection Area	Partial	Station End	11525+00
County	Giles	Ground	Muddy	Temperature (°F)	64.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/27/2019 3:21 PM	Report #	6226
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Environmental crew recently completed spreading new seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. Deficiencies located during inspection at station number 11455+00 and 11432+00. Both locations stake was broken.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	11/27/2019 3:21 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11506+00		Field Station#	11502+00	
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 2 Desc.	Conveyance channel with rock checks in place at double cut area of ROW.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	11478+00	
Pic 3 Desc.	RCE in place Stevers Gap Road.		Pic 4 Desc.	Slope drain pipe in place over two-tone with rock inlet and outlet.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11455+00		Field Station#	11432+00	
Pic 5 Desc.	Broken priority one silt fence stake along LOD.		Pic 6 Desc.	Broken priority one silt fence stake at earthen ditch location.	

A/E	124300137	Date/Time	11/27/2019 3:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/27/2019 3:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6238
Inspector	Chris Burns			Date/Time	11/29/2019 7:29 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11789+00
State	VA	Inspection Area	Partial	Station End	12001+00
County	Montgomery	Ground	Wet	Temperature (°F)	50.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	2.00

- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	11/29/2019 7:29 AM	Report #	
Pictures					
GPS Location	1	GPS Location	2		
Field Station#	11789+00	Field Station#	11792+00		
Pic 1 Desc.	RCE off of Mt Tabor rd.	Pic 2 Desc.	Restored RoW.		
GPS Location	3	GPS Location	4		
Field Station#	11991+00	Field Station#	11978+00		
Pic 3 Desc.	Restored RoW.	Pic 4 Desc.	Karst.		
GPS Location	5	GPS Location	6		
Field Station#	11929+50	Field Station#	11989+00		
Pic 5 Desc.	Partially restored RoW.	Pic 6 Desc.	Rain gauge at Catawba rd showing .4" accumulation.		

A/E	124300137	Date/Time	11/29/2019 7:29 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/29/2019 7:29 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6242
Inspector	Rob Robertson			Date/Time	11/29/2019 11:28 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11669+87
County	Montgomery	Ground	Damp	Temperature (°F)	44.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.25
				Rain Accumulation Time (days)	3.00







- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/29/2019 11:28 AM	Report #	6242
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VADEQ SWPPP inspection accompanied by Brian Shields LEI of private and JNF properties on Brush Mountain. Deer hunting activity was heavy today. Spoke with several hunters and two hikers with no confrontations. Brush Mountain is currently stable. Environmental controls are in place and working properly. No ECD maintenance needs were discovered. Slope breakers are functional as well as perimeter controls. Grasses are sufficient to prevent erosion. No impact to resources in the area apparent. No housekeeping issues, spills or slips located.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	11/29/2019 11:28 AM	Report #	
Pictures					
 <p>Date & Time: Fri Nov 29, 2019 09:50:52 EST Position: 4397.306N, -7083.192W, 1114.5M Altitude: 2050 ft (625 m) Datum: WGS-84 Azimuth Bearing: 232 S20W 540mils Magnetic (+12) Elevation Angle: -33 Horizon Angle: -90.5 Zoom: 1.0x 11664+00 End treatments in place</p>		 <p>Date & Time: Fri Nov 29, 2019 09:50:52 EST Position: 4397.306N, -7083.192W, 1114.5M Altitude: 2050 ft (625 m) Datum: WGS-84 Azimuth Bearing: 232 S20W 540mils Magnetic (+12) Elevation Angle: -33 Horizon Angle: -90.5 Zoom: 1.0x 11664+00 Slope breakers in place</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11664+00	Field Station#	11661+00		
Pic 1 Desc.	End treatments are in place and functional	Pic 2 Desc.	Slope breakers are working as designed		
 <p>Date & Time: Fri Nov 29, 2019 10:00:00 EST Position: 4397.306N, -7083.192W, 1114.5M Altitude: 2050 ft (625 m) Datum: WGS-84 Azimuth Bearing: 232 S20W 540mils Magnetic (+12) Elevation Angle: -33 Horizon Angle: -90.5 Zoom: 1.0x 11659+00 Perimeter controls in place</p>		 <p>Date & Time: Fri Nov 29, 2019 10:00:00 EST Position: 4397.306N, -7083.192W, 1114.5M Altitude: 2050 ft (625 m) Datum: WGS-84 Azimuth Bearing: 232 S20W 540mils Magnetic (+12) Elevation Angle: -33 Horizon Angle: -90.5 Zoom: 1.0x 11648+00 Perimeter controls in place</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11659+00	Field Station#	11648+00		
Pic 3 Desc.	Perimeter controls are functional	Pic 4 Desc.	Perimeter controls are in place and working properly		
 <p>Date & Time: Fri Nov 29, 2019 10:00:00 EST Position: 4397.306N, -7083.192W, 1114.5M Altitude: 2050 ft (625 m) Datum: WGS-84 Azimuth Bearing: 232 S20W 540mils Magnetic (+12) Elevation Angle: -33 Horizon Angle: -90.5 Zoom: 1.0x 11629+00 End treatments functional</p>		 <p>Date & Time: Fri Nov 29, 2019 10:00:00 EST Position: 4397.306N, -7083.192W, 1114.5M Altitude: 2050 ft (625 m) Datum: WGS-84 Azimuth Bearing: 232 S20W 540mils Magnetic (+12) Elevation Angle: -33 Horizon Angle: -90.5 Zoom: 1.0x 11626+04 S-HH18 crossing stable</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11629+00	Field Station#	11626+04		
Pic 5 Desc.	Slope breakers, sumps and end treatment are working properly	Pic 6 Desc.	S-HH18 crossing is stable		

AFE	124300137	Date/Time	11/29/2019 11:28 AM	Report #	
Pictures					
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11624+00	Field Station#	11614+20		
Pic 7 Desc.	ECDs in place. No movement of soils	Pic 8 Desc.	S-RR14 crossing stable. Flow disappears into ground at edge of bridge.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	11/29/2019 11:28 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6243
Inspector	Jared Saunders			Date/Time	11/29/2019 11:43 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Wet	Temperature (°F)	48.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	2.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	11/29/2019 11:43 AM	Report #	6243
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Checked rain gauge at Access Road 234 - 0.2 inches, Buffalo Anklets Road - 0.2 inches, Winding Way - 0.3 inches, Mount Tabor - 0.3 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	11/29/2019 11:43 AM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10696+00		Field Station#	12005+00	
Pic 1 Desc.	Rain gauge at Buffalo Anklets Road reads 0.2 inches.		Pic 2 Desc.	Rain gauge at Access Road 234 reads 0.2 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11125+00		Field Station#	11672+00	
Pic 3 Desc.	Rain gauge at Winding Way reads 0.3 inches.		Pic 4 Desc.	Waterbar, end treatment, and sump pit in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11767+00	
Pic 5 Desc.	Rain gauge at Mount Tabor Road reads 0.3 inches.		Pic 6 Desc.	RCE in place at Main Line Valve 26.	

A/E	124300137	Date/Time	11/29/2019 11:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	11/29/2019 11:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		