









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H	
<b>Contractor</b>	Precision			<b>Report #</b>	18084	
<b>Inspector</b>	Pat Davis			<b>Date/Time</b>	6/4/2019 2:13 PM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	+0	
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	+0	
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	79.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00	
				<b>Rain Accumulation Time (days)</b>	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Buffer		Acceptable				
Secondary Containment		Acceptable				
Sensitive Resource Signage		Acceptable				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 2:13 PM	<b>Report #</b>	18084
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Crews continue to pickup and remove trash, and preform maintenance on the stone surface					
<b>Comments</b> (Reference above questions as appropriate.) (Summary Spread 9) A check of the rain gauge in the yard MVP-PY-006 and found 0 rainfall in the raingauge. EI preformed SWPPP Inspection on the MVP-PY-006. EI observed no loose trash in the yard. Secondary containment's were in good condition. EI observed no fluid deposits on the stone on the either side of the bulk fuel tanks. The flagging to mark the 100 foot boundary was in place. EI found no leaky parked equipment. The triple stack compost filter sock along the yard boundary was in good condition. No other environmental issues were noted during today's inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	6/4/2019 2:13 PM	Report #	18084		
Pictures							
							
DIRECTION S (T) +37.23544° -080.22963° ACCURACY 16 ft DATUM WGS84			DIRECTION SW (T) +37.23534° -080.22967° ACCURACY 16 ft DATUM WGS84				
MVP-PY-006_060419_PCD Condition of containment 2019-06-04 08:19:06-04:00			MVP-PY-006_060419_PCD Condition of CFS along drive 2019-06-04 08:19:25-04:00				
GPS Location	37.23	Field Station#	+0	GPS Location	37.23	Field Station#	+0
Description	MVP-PY-006_060419 condition of containment under light plant. Looking S. See photo for gps data.			Description	MVP-PY-006_060419 condition of triple stack compost filter along drive. Looking SW. See photo for gps data.		
							
DIRECTION NE (T) +37.23543° -080.22900° ACCURACY 16 ft DATUM WGS84			DIRECTION SE (T) +37.23399° -080.22857° ACCURACY 16 ft DATUM WGS84				
MVP-PY-006_060419_PCD Signage & buffer for feature 2019-06-04 08:21:16-04:00			MVP-PY-006_060419_PCD Condition of CFS along south boundary 2019-06-04 08:23:25-04:00				
GPS Location	37.23	Field Station#	+0	GPS Location	37.23	Field Station#	+0
Description	MVP-PY-006_060419 signage and buffer for feature. Looking NE. See photo for gos data.			Description	MVP-PY-006_060419 condition of triple stack compost filter sock along south boundary. Looking SE. See photo for gps data.		
							
DIRECTION N (T) +37.23502° -080.22582° ACCURACY 16 ft DATUM WGS84			DIRECTION SW (T) +37.23572° -080.22672° ACCURACY 16 ft DATUM WGS84				
MVP-PY-006_060419_PCD Condition of CFS along east boundary 2019-06-04 08:32:34-04:00			MVP-PY-006_060419_PCD No fluid deposits on the north of tanks 2019-06-04 08:34:47-04:00				
GPS Location	37.23	Field Station#	+0	GPS Location	37.23	Field Station#	+0
Description	MVP-PY-006_060419 condition of triple stack compost filter sock along east boundary. Looking N. See photo for gps data.			Description	MVP-PY-006_060419 no fluid deposits on the north side of the bulk fuel tanks. Looking SW. See photo for gps data.		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 2:13 PM	<b>Report #</b>	18084
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 2:13 PM	<b>Report #</b>	18084
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		





## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18148
<b>Inspector</b>	Tyler Cremeens			<b>Date/Time</b>	6/4/2019 7:24 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13262+62
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13342+67
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	81.
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.
				<b>Rain Accumulation Time (days)</b>	1.

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300138	<b>Date/Time</b>	6/4/2019 7:24 AM	<b>Report #</b>	18148
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>After the weekly safety meeting conducted by the contractor as well as the daily, morning meeting in the inspection trailers at the contractor's yard in Elliston; I conducted a SWPP inspection of the ROW between Webster's Corner, Wade's Gap Road &amp; Flanders Road. No issues of sedimentation or erosion were found nor necessary repairs/corrections.</p> <p>The day was clear with little to no winds. Field conditions were dry. Temperatures above are those reported for Callaway, VA from online sources. Rain fall amounts were retrieved from the contractor's rain gauge at the CIS of Wade's Gap Road or from the inspection gauge reported from Cahas Mountain Road.</p> <p>Personnel from John Davis's environmental crew conducted a walk-through between Wade's Gap Road &amp; Flanders Road. Other personnel and vehicles were staged at Webster's &amp; Wade's.</p> <p>No issues arose either at the roads (neither tracking of dirt nor maintenance of RCEs required) nor at the waterbodies S-GH7, S-GH9, S-GH11, S-GH14, &amp; S-GH15.</p> <p>Current vegetative status of the LOD between the road crossings continues to improve with temporary vegetative cover between Flanders Road &amp; Wade's Gap better than that between Wade's &amp; Webster's Corner.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



A/E	124300138	Date/Time	6/4/2019 7:24 AM	Report #	18148		
Pictures							
							
GPS Location	37.09	Field Station#	13267+50	GPS Location	37.09	Field Station#	13274+53
Description	Super saver silt fence & blanketed spoil pile along northern edge of LOD. View: East from northern perimeter of LOD, see photo for GPS data.			Description	Perimeter controls, topsoil piles & timber pile. View: South from western perimeter of LOD, see photo for GPS data.		
							
GPS Location	37.09	Field Station#	13274+63	GPS Location	37.09	Field Station#	13289+24
Description	Waterbar outlet/treatment & fence line. View: North from eastern edge of LOD, see photo for GPS data.			Description	Personnel walking the LOD for monitoring & maintenance issues. View: North from center of LOD, see photo for GPS data.		
							
GPS Location	37.09	Field Station#	13321+47	GPS Location	37.09	Field Station#	13323+43
Description	Downstream of waterway S-GH15 (cows within high water mark) View: South from southern edge of LOD & equipment bridge, see photo for GPS data.			Description	Looking down upon waterway S-GH14. View: East from southern perimeter of LOD, see photo for GPS data.		



<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 7:24 AM	<b>Report #</b>	18148
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 7:24 AM	<b>Report #</b>	18148
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18151
<b>Inspector</b>	Pat Davis			<b>Date/Time</b>	6/4/2019 8:26 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	+0
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	+0
<b>County</b>	Roanoke	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	79.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300138	<b>Date/Time</b>	6/4/2019 8:26 AM	<b>Report #</b>	18151
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Crews have continued to preform maintenance on the stone, safety fence, and compost filter sock along the boundary. Crews have continued to pickup and remove loose trash. Secondary containments have be pumped when needed					
<b>Comments</b> (Reference above questions as appropriate.) (Summary Spread 10) EI preformed SWPPP Inspection on MVP-LY-049. The raingauge was check and found 0 rainfall in the gauge. EI checked the boundary of the LOD and found the triple stack compost filter sock in good condition. EI observed no trash along the boundary safety fence and by the timber mats. Observed the safety fence along the boundary was in good condition. ECD's, signage and buffers at features in good condition and being observed. The rock approaches are in good condition no sediment on the stone. Contractor continues to pick up trash in the yard. No other environmental issues were noted during today's inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300138		Date/Time 6/4/2019 8:26 AM		Report # 18151			
Pictures							
<div>DIRECTION SE (T) +37.27202° -080.12278° ACCURACY 16 ft DATUM WGS84</div>  <div>MVP-LY-049_060419_PCD Condition of rock entrance 2019-06-04 08:48:46-04:00</div>			<div>DIRECTION SE (T) +37.27163° -080.12234° ACCURACY 16 ft DATUM WGS84</div>  <div>MVP-PY-049_060419_PCD CFS &amp; safety fence along drive 2019-06-04 08:49:20-04:00</div>				
GPS Location 37.26		Field Station# +0		GPS Location 37.27		Field Station# +0	
Description		MVP-LY-049_060419 condition of rock entrance on center drive. Looking SE. See photo for gps data.		Description		MVP-LY-049_060419 condition of triple stack compost filter sock along center drive. Looking SE. See photo for gps data.	
<div>DIRECTION N (T) +37.27096° -080.12188° ACCURACY 16 ft DATUM WGS84</div>  <div>MVP-LY-049_060419_PCD Condition of containment 2019-06-04 08:49:49-04:00</div>			<div>DIRECTION NE (T) +37.27119° -080.12155° ACCURACY 16 ft DATUM WGS84</div>  <div>MVP-LY-049_060419_PCD CFS &amp; safety Fence north boundary 2019-06-04 08:50:15-04:00</div>				
GPS Location 37.27		Field Station# +0		GPS Location 37.27		Field Station# +0	
Description		MVP-LY-049_060419 condition of containment under light plant. Looking N. See photo for gps data.		Description		MVP-LY-049_0609419 condition of CFS and safety fence along center drive. Looking NE. See photo for gps data.	
<div>DIRECTION N (T) +37.26999° -080.12359° ACCURACY 16 ft DATUM WGS84</div>  <div>MVP-LY-049_060419_PCD Condition of containment 2019-06-04 08:55:23-04:00</div>			<div>DIRECTION N (T) +37.27165° -080.12306° ACCURACY 16 ft DATUM WGS84</div>  <div>MVP-LY-049_060419_PCD Condition of north rock entrance 2019-06-04 08:57:35-04:00</div>				
GPS Location 37.27		Field Station# +0		GPS Location 37.27		Field Station# +0	
Description		MVP-LY-049_060419 condition of containment under light plant. Looking N. See photo for gps data.		Description		MVP-LY-049_060419 condition of rock entrance on north drive. Looking N. See photo for gps data.	

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 8:26 AM	<b>Report #</b>	18151
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 8:26 AM	<b>Report #</b>	18151
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18152
<b>Inspector</b>	Pat Davis			<b>Date/Time</b>	6/4/2019 8:27 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13342+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13415+51
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	79.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300138	<b>Date/Time</b>	6/4/2019 8:27 AM	<b>Report #</b>	18152
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Crews have completed making corrections to items on the Punchlist between station 13342+67 to station 13415+51. Crews have continued to to pickup, remove trash and preform maintenance on the erosion control devices					
<b>Comments</b> (Reference above questions as appropriate.) (Summary Spread 10) EI preformed SWPPP Inspection between Websters Corner station 13342+67 to Cahas Mt station 13415+51. EI observed 0 rainfall in the raingauge at Cahas Mountain Road. EI observed the installed erosion control blanket on steep slopes was in good condition and secured between station 13334+67 to station 13371+50. Vegetation is growing and getting thicker. The Erosion Control Blanket between station 13403+08 to station 13412+00 was in good condition and secured. Vegetation is growing. The end treatments on the sumps were in good condition and not showing signs of undermining. Several sumps were full of stormwater but no off ROW sediment. EI observed timber mat bridges were clean and closed. The rock approaches at Webster's Corner Road station 13342+67 were in good condition and free of sediment. No sediment was observed off ROW and no features were impacted. No other environmental issues were noted during today's inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	6/4/2019 8:27 AM	Report #	18152	
Pictures						
<div>DIRECTION N (T) <div></div></div> <div>+37.10313° -080.04182° ACCURACY 16 ft DATUM WGS84</div> <div>13348+46_060419_S- RR08_PCD S-RR11 mat bridge clean &amp; closed 2019-06-04 12:50:52-04:00</div>			<div>DIRECTION SE (T) <div></div></div> <div>+37.10254° -080.04114° ACCURACY 16 ft DATUM WGS84</div> <div>13352+23_060419_S- RR09_PCD S-RR09 mat bridge clean &amp; closed 2019-06-04 12:40:15-04:00</div>			
GPS Location	37.27	Field Station#	13348+46	GPS Location	37.27	
Description	13348+46_060419 S-RR08 mat ridge clean and closed. Looking N. See photo for gps data.			Description	13352+23_060419 S-RR09 mat bridge clean and closed. Looking SE. See photo for gps data.	
<div>DIRECTION SW (T) <div></div></div> <div>+37.12287° -080.05936° ACCURACY 1.92 mi DATUM WGS84</div> <div>13355+94_060419_PCD Condition of private drive 2019-06-04 12:32:26-04:00</div>			<div>DIRECTION NW (T) <div></div></div> <div>+37.10096° -080.03924° ACCURACY 16 ft DATUM WGS84</div> <div>13358+64_060419_S- RR11_PCD S-RR11 mat ridge &amp; ROW growth 2019-06-04 12:17:06-04:00</div>			
GPS Location	37.27	Field Station#	13355+94	GPS Location	37.27	
Description	13355+94_040619 condition of private drive crossing. Looking SW. See photo for gps data.			Description	13358+64_060419 S-RR11 mat bridge clean and closed and vegetation growth on ROW. Looking NW. See photo for gps data.	
<div>DIRECTION E (T) <div></div></div> <div>+37.10383° -080.04368° ACCURACY 16 ft DATUM WGS84</div> <div>13342+67_060419_PCD Webster's Corner East rock entrance 2019-06-04 13:20:17-04:00</div>			<div>DIRECTION NW (T) <div></div></div> <div>+37.09296° -080.02756° ACCURACY 16 ft DATUM WGS84</div> <div>13413+05_060419_S- IJ1_PCD Mat bridge clean &amp; closed 2019-06-04 13:30:30-04:00</div>			
GPS Location	37.27	Field Station#	13342+67	GPS Location	37.27	
Description	13342+67_060419 Webster's Corner east rock entrance. Looking E. See photo for gps data.			Description	13413+05_060419 S-IJ1 mat bridge clean and closed. Looking NW. See photo for gps data.	

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 8:27 AM	<b>Report #</b>	18152
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 8:27 AM	<b>Report #</b>	18152
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18155
<b>Inspector</b>	Jason Nielsen			<b>Date/Time</b>	6/4/2019 9:17 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12445+30
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12449+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 9:17 AM	<b>Report #</b>	18155
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Since the last inspection of the area there has been no PPL activity.					
<b>Comments</b> (Reference above questions as appropriate.) Went to Cove Hollow Road to perform a SWPPP inspection. While performing my inspection I checked for any damaged ECDs, RCEs, and stabilization issues. Everything was in good condition and there was no need for maintenance at the time.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	6/4/2019 9:17 AM	Report #	18155		
Pictures							
							
GPS Location	37.23	Field Station#	12448+12	GPS Location	37.23	Field Station#	12448+50
Description	RCE. Looking E. See picture for GPS data.			Description	Stabilized ROW. Looking SW. See picture for GPS data.		
							
GPS Location	37.23	Field Station#	12447+50	GPS Location	37.23	Field Station#	12445+50
Description	P1 and safety fence perimeter controls. Looking W. See picture for GPS data.			Description	End cap covering well point system. Looking N. See picture for GPS data.		
							
GPS Location	37.23	Field Station#	12445+86	GPS Location	37.23	Field Station#	12445+87
Description	Curlexed drain crossing the ROW. Looking S. See picture for GPS data.			Description	Stabilized ROW. Looking SE. See picture for GPS data.		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 9:17 AM	<b>Report #</b>	18155
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		









<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 9:17 AM	<b>Report #</b>	18155
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18160
<b>Inspector</b>	Joe Scott			<b>Date/Time</b>	6/4/2019 9:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12686+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13143+00
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Broad-Based Dip	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Rock Construction Entrance	Acceptable				
Erosion Control Blanket	Acceptable				
Equipment Bridge	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300138	<b>Date/Time</b>	6/4/2019 9:31 AM	<b>Report #</b>	18160
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Attended the MVP Inspectors morning meeting at the MVP-PY-006 along with the PPL weekly safety meeting. Attended the morning meeting with PPL management afterwards. Met with lead EI and fellow EI's and discussed activities for the day.</p> <p>Traveled to FR-292 and inspected the access road and installed ECD's along the access road for possible deficiencies or impacts. No construction activities have taken place at this part of the ROW, only the access road. No issues were found. Traveled to FR-291 and walked the ROW from 13120+17 back to US-221, 12993+00. All observed ECD's, BMP's and temporary stabilization remained in compliance. Traveled to RO-288, RO-287, Bottom Creek Road, and Honeysuckle Road. No issues or impacts were observed throughout these areas.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300138		Date/Time		6/4/2019 9:31 AM		Report #		18160					
Pictures															
															
GPS Location		37.12		Field Station#		13143+00		GPS Location		37.12		Field Station#		13116+50	
Description		No issues or impacts observed at FR-292.										Description		ROW has been temporarily stabilized with Curlex and Vegetation. No compliance issues observed throughout the area.	
															
GPS Location		37.12		Field Station#		13036+00		GPS Location		37.12		Field Station#		13040+00	
Description		Environmental crew recently performed maintenance to sump and end treatment.										Description		No issues or impacts found in the area near S-H1.	
															
GPS Location		37.12		Field Station#		13018+00		GPS Location		37.12		Field Station#		12994+00	
Description		No issues or impacts found throughout the area today.										Description		ECD's, BMP's and stabilization were adequate. No compliance issues found. Ssss	

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 9:31 AM	<b>Report #</b>	18160
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 9:31 AM	<b>Report #</b>	18160
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18165
<b>Inspector</b>	Dustin Lyons			<b>Date/Time</b>	6/4/2019 5:17 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12072+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300138	<b>Date/Time</b>	6/4/2019 5:17 PM	<b>Report #</b>	18165
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Since the last SWPPP inspection, the contractor performed mitigation measures in this area which included repairing minor holes in the CFS and maintaining the water bar sumps.					
<b>Comments</b> (Reference above questions as appropriate.) I met with the inspection team at the main yard this morning at 7:00 am and attended the contractor's weekly safety meeting. After the safety meeting I traveled to the ROW. No measurable rainfall was recorded at Catawba Road within the last 24 hours.  I performed a SWPPP inspection of the ROW from station 12005+00 to 12072+00. The ROW throughout this area has been temporarily stabilized with combinations of Earthguard, seed, mulch and erosion control blanket. I observed the conditions of ECDs, stream crossings, access roads (MVP-MN-268, 268.01 and 270) and general conditions of the ROW. No environmental issues, off-ROW sediment or stream impacts were observed in this area during today's SWPPP inspection.  Precision's crews did not work in this section today.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	6/4/2019 5:17 PM	Report #	18165		
Pictures							
							
GPS Location	37.27	Field Station#	12007+00	GPS Location	37.27	Field Station#	12062+00
Description	See photo for gps data. Triangular silt dike along ATWS-1159 allows the landowner to access the adjacent field, installed 5/28/19.			Description	See photo for gps data. Photo shows the ROW condition from about 12062+00 to 12072+00.		
							
GPS Location	37.27	Field Station#	12061+00	GPS Location	37.27	Field Station#	12054+00
Description	See photo for gps data. Photo shows the ROW condition from about 12056+00 to 12061+00.			Description	See photo for gps data. Photo shows the ROW condition from about 12038+00 to 12054+00.		
							
GPS Location	37.27	Field Station#	12037+75	GPS Location	37.27	Field Station#	12035+00
Description	See photo for gps data. Photo shows the plunge pool outlet at about 12037+75.			Description	See photo for gps data. Photo shows the ROW condition from about 12033+00 to 12035+00.		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 5:17 PM	<b>Report #</b>	18165
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 5:17 PM	<b>Report #</b>	18165
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18175
<b>Inspector</b>	John Brcic			<b>Date/Time</b>	6/4/2019 9:54 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12071+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12195+50
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Erosion Control Blanket	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sump Pit	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Slope Drain Pipe	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	Yes
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	No
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	Yes

<b>AFE</b>	124300138	<b>Date/Time</b>	6/4/2019 9:54 AM	<b>Report #</b>	18175
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
Station 12071+00 to 12195+50.....Activities since last SWPPP inspection. Other than minor maintenance, there has been no activity in this inspection area since the previous SWPPP inspection.					
<b>Comments</b> (Reference above questions as appropriate.)					
At the beginning of the day, I attended the Spread H safety meeting in the Precision Pipeline yard and then the inspection meeting at the MVP trailer after that. I then performed a SWPPP inspection on the right-of-way (ROW) between stations 12071+00 and 12195+50. There were no problems observed with any ECDs or sensitive resources throughout this inspection area. There was also no work being performed by Precision Pipeline in this stretch of ROW. AEP's contractor was working on their substation where they were pouring concrete into the hole they bored yesterday for a pier. They were cleaning the concrete trucks into a wheelbarrow and collecting the remains so nothing went on the ground anywhere on MVP ROW.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	6/4/2019 9:54 AM	Report #	18175		
Pictures							
							
GPS Location	37.25	Field Station#	12076+96	GPS Location	37.25	Field Station#	12082+00
Description	Stream S-MM15, facing north, upstream.			Description	Sumps are in good condition and functioning properly.		
							
GPS Location	37.25	Field Station#	12108+41	GPS Location	37.25	Field Station#	12112+13
Description	Stream S-F15, facing northwest, upstream.			Description	Stream S-F16A/B, facing northeast, upstream.		
							
GPS Location	37.25	Field Station#	12185+00	GPS Location	37.25	Field Station#	12170+00
Description	AEP contractor preparing to pour a cement pier next to the MVP ROW.			Description	Fill slope drain in satisfactory condition and performing as needed.		



<b>AFE</b>	124300138	<b>Date/Time</b>	6/4/2019 9:54 AM	<b>Report #</b>	18175
<b>Pictures</b>					
		<p>Insert image here</p>			
<b>GPS Location</b>	37.25	<b>Field Station#</b>	12185+00	<b>GPS Location</b>	
<b>Description</b>	The AEP contractor poured the concrete pier that was bored for yesterday.			<b>Description</b>	
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>				<b>Description</b>	
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>				<b>Description</b>	
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>				<b>Description</b>	









<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 9:54 AM	<b>Report #</b>	18175
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18179
<b>Inspector</b>	Dawn McCullough			<b>Date/Time</b>	6/4/2019 5:48 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13188+66
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13262+58
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	79.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Berm	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Sump Pit	Acceptable				
Waterbar	Acceptable				
Waterbar Outlet Protection	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 5:48 PM	<b>Report #</b>	18179
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended morning Spread H safety meeting. Attended morning inspection and contractor meeting. Performed routine SWPPP inspection of ROW and access roads between Sta. No. 13188+66 to Sta. No. 13262+58. MVP-MLV-AR-29, Dillons Mill Road, and Flanders Road road crossings were maintained, with no environmental issues noted. Cattle were observed in first field at MVP-MLV-AR-29 on the access road. Channelized flow noted in off ROW wetland W-II4, saturated soil and standing water observed ATWS-1055 from W-II4 drainage; off ROW channel entering stream S-II4 within the limits of disturbance; water was clear entering stream S-II4. ECDs were functioning acceptably at stream crossings and ROW perimeters. All equipment bridges were in acceptable condition. Soil piles were observed to be stabilized with acceptable vegetative cover and curlex on piles. Temporary vegetative cover noted to be moderate on ROW. PPL did not walk this inspection area today. No additional environmental issues noted during this inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	6/4/2019 5:48 PM	Report #	18179		
Pictures							
							
GPS Location	37.32	Field Station#	13216+00	GPS Location	37.32	Field Station#	13219+00
Description	Please see photo for accurate coordinates. ROW, soil piles stabilized, waterbars and end treatments functioning acceptably.			Description	Please see photo for accurate coordinates. ROW, temporary vegetative cover acceptable, no environmental issues noted.		
							
GPS Location	37.32	Field Station#	13250+50	GPS Location	37.32	Field Station#	13260+60
Description	Please see photo for accurate coordinates. ROW, waterbars and end treatments functioning acceptably.			Description	Please see photo for accurate coordinates. S-II4, looking upstream at resource crossing, no environmental issues noted.		
							
GPS Location	37.32	Field Station#	13262+00	GPS Location	37.32	Field Station#	13262+00
Description	Please see photo for accurate coordinates. ATWS-1055, clean water conveyance mostly dry, ECDs functioning acceptably.			Description	Please see photo for accurate coordinates. ATWS-1055, topsoil stable, perimeter controls maintained, no environmental issues present.		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 5:48 PM	<b>Report #</b>	18179
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 5:48 PM	<b>Report #</b>	18179
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18206
<b>Inspector</b>	Jason Nielsen			<b>Date/Time</b>	6/4/2019 7:06 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12290+85
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12440+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300138	<b>Date/Time</b>	6/4/2019 7:06 PM	<b>Report #</b>	18206
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Since the last inspection the crews have walked and repaired any damaged ECDS.					
<b>Comments</b> (Reference above questions as appropriate.) Went to access road MVP-MN-276.03 to begin a SWPPP of the access road and ROW. During the inspection I checked for any ECDs, RCE, or stabilization that needs maintenance performed. There was no issues in the area and no need for maintenance. Went to access road MVP-MN-279.02 where myself and the environmental crew was walking the ROW checking all ECDs for damages. Everything looked good and there was no need for maintenance. Also while at access MVP-MN-279.02 I marked up an over head photo to show the actual edge of LOD.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	6/4/2019 7:06 PM	Report #	18206		
Pictures							
							
GPS Location	37.23	Field Station#	12378+84	GPS Location	37.23	Field Station#	12383+00
Description	Stabilized ROW. Looking SE. See picture for GPS data.			Description	Bridge crossing the clear water crossing. Looking W. See picture for GPS data.		
							
GPS Location	37.23	Field Station#	12373+76	GPS Location	37.23	Field Station#	12234+77
Description	Felled trees on the GAS of I-81. Looking NE. See picture for GPS data.			Description	RCE. Looking W. See picture for GPS data.		
							
GPS Location	37.23	Field Station#	12283+00	GPS Location	37.23	Field Station#	12234+00
Description	Stabilized hill side. Looking NW. See picture for GPS data.			Description	CFS perimeter control along access road MVP-MN-276.03		

<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 7:06 PM	<b>Report #</b>	18206
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



<b>A/E</b>	124300138	<b>Date/Time</b>	6/4/2019 7:06 PM	<b>Report #</b>	18206
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



## Visual Site Inspection Report


<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	18216
<b>Inspector</b>	Charles Head			<b>Date/Time</b>	6/5/2019 9:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13415+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	13670+00
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sump Pit	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300138	<b>Date/Time</b>	6/5/2019 9:31 AM	<b>Report #</b>	18216
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP inspection of spread H section of ROW. All LOD and resource boundary ECDs inspected. No issues observed at time of inspection. All streams flowing clean and clear of sediment at time of inspection. RCEs inspected and are in good condition. Contractor has addressed any maintenance issues in this area.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300138	<b>Date/Time</b>	6/5/2019 9:31 AM	<b>Report #</b>	18216
<b>Pictures</b>					
					
<b>GPS Location</b>	37.08	<b>Field Station#</b>	13420+00	<b>GPS Location</b>	37.08
<b>Field Station#</b>	13419+21	<b>Description</b>		Approximately 13420+00. ROW temporarily seeded and stabilized in this area.	
					
<b>GPS Location</b>	37.08	<b>Field Station#</b>	13415+91	<b>GPS Location</b>	37.08
<b>Field Station#</b>	13417+52	<b>Description</b>		Approximately 13415+91. Sump pit and CFS end treatment. ECDs installed and appear to be functioning correctly at time of inspection.	
					
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Description</b>			

<b>A/E</b>	124300138	<b>Date/Time</b>	6/5/2019 9:31 AM	<b>Report #</b>	18216
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



<b>A/E</b>	124300138	<b>Date/Time</b>	6/5/2019 9:31 AM	<b>Report #</b>	18216
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		