



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6859
<b>Inspector</b>	Brian Shields			<b>Date/Time</b>	12/23/2019 7:51 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11599+91
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11668+00		<b>Field Station#</b>	11660+00	
<b>Pic 1 Desc.</b>	waterbar and end treatment		<b>Pic 2 Desc.</b>	installed perimeter controls	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11656+00		<b>Field Station#</b>	11630+00	
<b>Pic 3 Desc.</b>	installed super silt fence		<b>Pic 4 Desc.</b>	waterbar and end treatment	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11626+04		<b>Field Station#</b>	11607+00	
<b>Pic 5 Desc.</b>	stream s-hh18		<b>Pic 6 Desc.</b>	stabilized ROW	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6868
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/23/2019 9:20 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	Stormwater Event	<b>Station Begin</b>	12005+00
<b>State</b>	WV	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Monroe	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	35.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? WV: Exceeding 7 days if to be left inactive for more than 21 days	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 9:20 AM	<b>Report #</b>	6868
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Storm water report for LY37. The rock surface of the yard is maintained in acceptable condition. P1 silt fence, CFS perimeter controls are in acceptable condition throughout the yard. Wetland ECD's and sensitive resource signage are in acceptable condition. Culvert and bar ditch environmental controls are in acceptable condition. Rock channel is in acceptable condition. Waste oil totes are in containment. Mechanical equipment stored in the yard- no fluid leaks were observed at the time of inspection. House keeping is acceptable. Waste management is acceptable. No PPL personnel were present, security was present.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	12/23/2019 9:20 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Dec 23, 2019, 09:44:38 EST  Position: +407.416472° / -800.741024° (±16.4m)  Altitude: 18559 (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 210° 530W 3753mils True (±25°)  Elevation Angle: -03.2°  Horizon Angle: +02.5°  Zoom: 1.0X  LY-37- Materials storage and rock surface of the yard is acceptable.</p> 		<p>Date &amp; Time: Mon, Dec 23, 2019, 09:11:30 EST  Position: +407.416472° / -800.741024° (±16.4m)  Altitude: 18559 (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 210° 530W 3753mils True (±25°)  Elevation Angle: -10.7°  Horizon Angle: -00.2°  Zoom: 1.0X  LY-37- Equipment stored in yard-Did not observe any fluid leaks at the time of inspection.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	LY-37- Materials storage and rock surface of the yard are acceptable.	<b>Pic 2 Desc.</b>	LY-37- Equipment stored in the yard does not have any fluid leaks observed at the time of inspection.		
<p>Date &amp; Time: Mon, Dec 23, 2019, 09:47:41 EST  Position: +407.416472° / -800.741024° (±16.4m)  Altitude: 18510 (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 29° 161W 494mils True (±25°)  Elevation Angle: -05.1°  Horizon Angle: -00.2°  Zoom: 1.0X  LY-37- P1 perimeter controls are in acceptable condition.</p> 		<p>Date &amp; Time: Mon, Dec 23, 2019, 10:00:45 EST  Position: +407.416472° / -800.741024° (±16.4m)  Altitude: 1863H (±9.8m)  Datum: WGS-84  Azimuth/Bearing: 141° 539E 2507mils True (±25°)  Elevation Angle: -11.1°  Horizon Angle: +02.7°  Zoom: 1.0X  LY-37- Waste oil containment in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	P1 perimeter controls are in acceptable condition	<b>Pic 4 Desc.</b>	LY-37- waste oil containment is in acceptable condition.		
<p>Date &amp; Time: Mon, Dec 23, 2019, 10:04:38 EST  Position: +407.416472° / -800.741024° (±16.4m)  Altitude: 1871H (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 214° 534W 3804mils True (±25°)  Elevation Angle: -15.0°  Horizon Angle: -01.4°  Zoom: 1.0X  LY-37- Wetland controls &amp; sensitive resource signage are in acceptable condition.</p> 		<p>Date &amp; Time: Mon, Dec 23, 2019, 10:07:42 EST  Position: +407.416472° / -800.741024° (±16.4m)  Altitude: 1855H (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 234° 534W 4183mils True (±25°)  Elevation Angle: -16.6°  Horizon Angle: +01.9°  Zoom: 1.0X  LY-37- Culvert, bar ditch controls are in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	LY-37- Wetland controls & sensitive resource signage are in acceptable condition.	<b>Pic 6 Desc.</b>	Culvert, bar ditch controls are in acceptable condition.		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 9:20 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 9:20 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6878
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/23/2019 2:22 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11607+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 2:22 PM	<b>Report #</b>	6878
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11524+00 to 11607+00 Temporary stabilization is in good condition with good vegetative growth, the row is muddy but in stable condition. Perimeter controls, silt fence, SSF, CFS are in good condition. Water bars and water bar end treatments and sump pits are in acceptable condition. Slope drain pipes are in acceptable condition. CWD pipes and plunge pools are in acceptable condition. Streams, equipment bridges, buffers, sensitive resource signage, stream ECD's are in acceptable condition. RCE and access road 258.02 are maintained in acceptable condition. Staged pipe appears stable.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Dec 23, 2019, 11:55:49 EST  Position: -037.329705 / -080.415275 (-32.9705, -80.415275)  Altitude: 214ft (-65.0m)  Datum: WGS-84  Azimuth/Bearing: 252.520W, 4280mils True (-25.25)  Elevation Angle: -27.3  Horizon Angle: -01.0  Zoom: 1.0x  Sta#11527+00- Temporary stabilization, slope drains &amp; ECD's are in good condition</p> 		<p>Date &amp; Time: Mon, Dec 23, 2019, 11:57:00 EST  Position: -037.329705 / -080.415275 (-32.9705, -80.415275)  Altitude: 214ft (-65.0m)  Datum: WGS-84  Azimuth/Bearing: 330.180W, 4820mils True (-30.18)  Elevation Angle: -25.0  Horizon Angle: -00.2  Zoom: 1.0x  Sta#11549+00- Slope drains, Environmental controls, water bars, sump pits &amp; end treatments are in acceptable condition</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11527+00		<b>Field Station#</b>	11549+00	
<b>Pic 1 Desc.</b>	Temporary stabilization, slope drains, & ECD's are in acceptable condition.		<b>Pic 2 Desc.</b>	Slope drains, environmental controls, water bars, end treatments are in acceptable condition.	
<p>Date &amp; Time: Mon, Dec 23, 2019, 12:02:04 EST  Position: -037.324391 / -080.415497 (-32.8011, -80.415497)  Altitude: 3019ft (-92.7m)  Datum: WGS-84  Azimuth/Bearing: 165.515E, 2933mils True (-25.15)  Elevation Angle: -26.3  Horizon Angle: -02.1  Zoom: 1.0x  Top of Sinking Creek mountain, JNF down to Craig Creek</p> 		<p>Date &amp; Time: Mon, Dec 23, 2019, 12:05:27 EST  Position: -037.321117 / -080.412973 (-32.8011, -80.412973)  Altitude: 2513ft (-76.6m)  Datum: WGS-84  Azimuth/Bearing: 162.518E, 2890mils True (-25.18)  Elevation Angle: -22.6  Horizon Angle: -02.5  Zoom: 1.0x  Stream S-PP22- bridge sensitive resource signage, stream ECD's are in acceptable condition</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11558+00		<b>Field Station#</b>	11668+00	
<b>Pic 3 Desc.</b>	Top of Sinking Creek mountain, JNF, looking towards Craig Creek.		<b>Pic 4 Desc.</b>	Stream S-PP22- Stream bridge, ECD's, sensitive resource signage, buffers are in acceptable condition.	
<p>Date &amp; Time: Mon, Dec 23, 2019, 12:29:09 EST  Position: -037.317865 / -080.409376 (-32.9841, -80.409376)  Altitude: 2064ft (-629.0m)  Datum: WGS-84  Azimuth/Bearing: 160.520E, 2844mils True (-25.15)  Elevation Angle: -18.0  Horizon Angle: -04.7  Zoom: 1.0x  Stream S-PP21 - Sta#11585 bridge sensitive resource signage, stream ECD's are in acceptable condition</p> 		<p>Date &amp; Time: Mon, Dec 23, 2019, 12:30:03 EST  Position: -037.317571 / -080.408648 (-32.9841, -80.408648)  Altitude: 1214ft (-369.0m)  Datum: WGS-84  Azimuth/Bearing: 159.521E, 2827mils True (-25.15)  Elevation Angle: -13.9  Horizon Angle: -00.8  Zoom: 1.0x  Stream S-PP20- Sta#11588+00, bridge sensitive resource signage, stream ECD's are in acceptable condition</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11585+00		<b>Field Station#</b>	11588+00	
<b>Pic 5 Desc.</b>	Stream S-PP21- Bridge, sensitive resource signage, buffers, stream ECD's are in acceptable condition.		<b>Pic 6 Desc.</b>	Stream S-PP20- Equipment bridge, buffers, ECD's, sensitive resource signage are in acceptable condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6904
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/26/2019 8:14 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	28.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 8:14 AM	<b>Report #</b>	6904
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
PPL crews are off during holidays. SWPPP inspection: LY-29 AR-238.00 is maintained in acceptable condition. The rock surface of the yard is maintained in acceptable condition. House keeping is acceptable. Waste management is acceptable. Overhead flagging for utility protection is maintained in acceptable condition. Triple stack CFS perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 8:14 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Dec 26, 2019, 08:21:30 EST  Position: +037.262287° / -080.677912° (+16.4ft)  Altitude: 1221ft (+37.9ft)  Datum: WGS-84  Azimuth/Bearing: 238.558W 4231mils True (+25°)  Elevation Angle: -09.5°  Horizon Angle: +01.8°  Zoom: 1.0X  LY-29- Materials storage is acceptable.</p> 		<p>Date &amp; Time: Thu, Dec 26, 2019, 08:24:40 EST  Position: +037.262287° / -080.677912° (+16.4ft)  Altitude: 1221ft (+37.9ft)  Datum: WGS-84  Azimuth/Bearing: 337° 50W 443mils True (+25°)  Elevation Angle: -02.1°  Horizon Angle: +03.2°  Zoom: 1.0X  LY-29- Overhead flagging for utility protection is maintained in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	LY-29- Materials storage is acceptable.		<b>Pic 2 Desc.</b>	LY-29- Overhead flagging for utility protection is maintained in acceptable condition.	
<p>Date &amp; Time: Thu, Dec 26, 2019, 08:25:11 EST  Position: +037.262287° / -080.676561° (+32.9ft)  Altitude: 1659ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 264° 54W 498mils True (+25°)  Elevation Angle: -13.0°  Horizon Angle: -00.3°  Zoom: 1.0X  LY-29- Rock surface of the yard is maintained in acceptable condition.</p> 		<p>Date &amp; Time: Thu, Dec 26, 2019, 08:26:14 EST  Position: +037.262287° / -080.676561° (+32.9ft)  Altitude: 1669ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 192° 51W 3413mils True (+26°)  Elevation Angle: -10.1°  Horizon Angle: -00.2°  Zoom: 1.0X  LY-29- CFS 18" Triple stack perimeter controls are in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	LY-29- The rock surface of the yard is maintained in acceptable condition.		<b>Pic 4 Desc.</b>	LY-29- CFS 18" Triple stack perimeter controls are in acceptable condition.	
<p>Date &amp; Time: Thu, Dec 26, 2019, 08:30:54 EST  Position: +037.262287° / -080.677912° (+16.4ft)  Altitude: 1695ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 192° 51W 3413mils True (+26°)  Elevation Angle: -10.1°  Horizon Angle: -00.2°  Zoom: 1.0X  LY-29- Arnold's materials storage area.</p> 		<p>Date &amp; Time: Thu, Dec 26, 2019, 08:31:07 EST  Position: +037.262287° / -080.677912° (+16.4ft)  Altitude: 1695ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 137° 53W 2791mils True (+25°)  Elevation Angle: -07.0°  Horizon Angle: -00.2°  Zoom: 1.0X  LY-29- Culvert and drainage feature are in good condition.</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	LY-29- Arnold's materials storage area.		<b>Pic 6 Desc.</b>	Culvert and drainage feature are in good condition.	



<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 8:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 8:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6914
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/23/2019 2:04 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	12/23/2019 2:04 PM	<b>Report #</b>	6914
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 227.4 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 2:04 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, Dec 23, 2019, 09:24:34 EST Position: +037.294722° / -080.391549° (±163.4ft) Altitude: 2230ft (±12.4ft) Datum: WGS-84 Azimuth/Bearing: 058° N58E 233mils True (±17°) Elevation Angle: -15° Horizon Angle: -10.3° Zoom: 1.0X 11687+00</p>		 <p>Date &amp; Time: Mon, Dec 23, 2019, 11:25:00 EST Position: +037.294933° / -080.378282° (±139.4ft) Altitude: 2230ft (±12.4ft) Datum: WGS-84 Azimuth/Bearing: 058° N58E 1031mils True (±13°) Elevation Angle: -17.5° Horizon Angle: -00.3° Zoom: 1.0X 11730+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11687+40		<b>Field Station#</b>	11730+00	
<b>Pic 1 Desc.</b>	Sensitive resource buffer in place at stream S-MN21		<b>Pic 2 Desc.</b>	Waterbar in place and ROW is stabilized with seed and mulch.	
 <p>Date &amp; Time: Mon, Dec 23, 2019, 10:47:45 EST Position: +037.297161° / -080.391549° (±1071.6ft) Altitude: 2200ft (±12.4ft) Datum: WGS-84 Azimuth/Bearing: 120° S54E 2340mils True (±13°) Elevation Angle: -09.4° Horizon Angle: -01.6° Zoom: 1.0X 11767+00</p>		 <p>Date &amp; Time: Mon, Dec 23, 2019, 11:25:00 EST Position: +037.294722° / -080.373156° (±139.1ft) Altitude: 2104ft (±12.7ft) Datum: WGS-84 Azimuth/Bearing: 215° S35W 3822mils True (±13°) Elevation Angle: -22.4° Horizon Angle: -04.7° Zoom: 1.0X 11751+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11751+00	
<b>Pic 3 Desc.</b>	RCE in place Main Line Valve 26 access point.		<b>Pic 4 Desc.</b>	Waterbar, sump pit, and waterbar end treatment in place.	
 <p>Date &amp; Time: Mon, Dec 23, 2019, 10:47:45 EST Position: +037.297161° / -080.391549° (±1071.6ft) Altitude: 2017ft (±13.5ft) Datum: WGS-84 Azimuth/Bearing: 211° S31W 3751mils True (±13.1°) Elevation Angle: -21.6° Horizon Angle: -02.4° Zoom: 1.0X 11774+00</p>		 <p>Date &amp; Time: Mon, Dec 23, 2019, 11:25:00 EST Position: +037.295000° / -080.369400° (±139.6ft) Altitude: 2200ft (±12.4ft) Datum: WGS-84 Azimuth/Bearing: 040° S32W 401mils True (±13°) Elevation Angle: -02.2° Horizon Angle: -06.1° Zoom: 1.0X 11898+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11774+00		<b>Field Station#</b>	11898+00	
<b>Pic 5 Desc.</b>	Clean water diversion pipe and plunge pool in place.		<b>Pic 6 Desc.</b>	ROW has been restored to original grade and permanent vegetation growth present.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 2:04 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	12/23/2019 2:04 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6915
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/26/2019 5:16 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 5:16 PM	<b>Report #</b>	6915
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection of LDY 28. All perimeter controls in place and functional. No leak observed under staged equipment. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 5:16 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Dec 26, 2019, 09:39:51 EST Position: +49° 23' 42.1" / -80° 50' 32.1" (±10.3m) Altitude: 1555ft (±11.4m) Datum: WGS-84 Azimuth/Bearing: 174.506E 3093mils True (±10°) Elevation Angle: +09.7° Horizon Angle: -03.8° Zoom: 4.0X LDY 28</p>		 <p>Date &amp; Time: Thu, Dec 26, 2019, 09:41:19 EST Position: +49° 23' 42.1" / -80° 50' 32.1" (±10.3m) Altitude: 1555ft (±11.4m) Datum: WGS-84 Azimuth/Bearing: 174.506E 3093mils True (±10°) Elevation Angle: +09.7° Horizon Angle: -03.8° Zoom: 4.0X LDY 28</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Port-a-potties in secondary containment.		<b>Pic 2 Desc.</b>	CFS along LOD.	
 <p>Date &amp; Time: Thu, Dec 26, 2019, 09:46:40 EST Position: +49° 23' 42.1" / -80° 50' 32.1" (±10.3m) Altitude: 1555ft (±11.4m) Datum: WGS-84 Azimuth/Bearing: 174.506E 3093mils True (±10°) Elevation Angle: +09.7° Horizon Angle: -03.8° Zoom: 1.0X LDY 28</p>		 <p>Date &amp; Time: Thu, Dec 26, 2019, 09:46:40 EST Position: +49° 23' 42.1" / -80° 50' 32.1" (±10.3m) Altitude: 1555ft (±11.4m) Datum: WGS-84 Azimuth/Bearing: 174.506E 3093mils True (±10°) Elevation Angle: +09.7° Horizon Angle: -03.8° Zoom: 1.0X LDY 28</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	No leaks under staged vehicles.		<b>Pic 4 Desc.</b>	Yard covered with geotextile fabric and stone.	
 <p>Date &amp; Time: Thu, Dec 26, 2019, 09:49:45 EST Position: +49° 23' 42.1" / -80° 50' 32.1" (±10.3m) Altitude: 1555ft (±11.4m) Datum: WGS-84 Azimuth/Bearing: 058.533E 1659mils True (±10°) Elevation Angle: -13.6° Horizon Angle: -03.8° Zoom: 1.0X LDY 28</p>		 <p>Date &amp; Time: Thu, Dec 26, 2019, 09:50:45 EST Position: +49° 23' 42.1" / -80° 50' 32.1" (±10.3m) Altitude: 1555ft (±11.4m) Datum: WGS-84 Azimuth/Bearing: 058.533E 1659mils True (±10°) Elevation Angle: -03.2° Horizon Angle: -11.2° Zoom: 1.0X LDY 28</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	CFS along LOD.		<b>Pic 6 Desc.</b>	Access road to LDY has is covered in stone.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 5:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 5:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6916
<b>Inspector</b>	Brian Shields			<b>Date/Time</b>	12/26/2019 5:35 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)   |     |







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 5:35 PM	<b>Report #</b>	6916
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
VA SWPPP inspection at LY 26 All installed erosion control devices are in good working condition with no maintenance needed Rock construction entrance is functioning as designed Staged equipment inspected for leaks, none observed All secondary containment's are empty and in adequate condition  Wetland solutions on site performing ODCP inspection Precision crews not on site, no activity at yard.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 5:35 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Installed perimeter controls		<b>Pic 2 Desc.</b>	Staged materials	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Staged materials		<b>Pic 4 Desc.</b>	Fuel tank secondary containment	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	Installed perimeter controls		<b>Pic 6 Desc.</b>	Fuel tank secondary containment. Tanks are empty	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 5:35 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	12/26/2019 5:35 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6924
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/27/2019 8:22 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11024+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	5.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 8:22 AM	<b>Report #</b>	6924
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: Sta#11024+00 to 10930+00 MP-208.6 to 206.2 The row is in stable condition, temporary stabilization and vegetation is acceptable. The perimeter controls, Silt fence, CFS, & SSF are in acceptable condition. Water bars are in stable condition. Sump pits and end treatments are in acceptable condition. Karst's and Karst ECD's and sensitive resource signage are in acceptable condition. Streams S-IJ18, S-RR5, S-E24, S-E25 are in good condition along with ECD's, equipment bridges, buffers,& sensitive resource signage. AR-244 and Doe Creek RCE are maintained in acceptable condition. PPL sent out an environmental crew to repair P1 damaged by others not associated with the pipeline.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	12/27/2019 8:22 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Dec 27, 2019, 10:09:29 EST  Position: +037.321814° / +080.552970° (+32.8ft)  Altitude: 2342ft (+59.4ft)  Datum: WGS-84  Azimuth/Bearing: 342° N18W 6080mils True (+25°)  Elevation Angle: -09.8°  Horizon Angle: +01.8°  Zoom: 1.0X  Star#11018-00 Stream S-IJ18-AR-244- Stream bridge environmental.com site in acceptable condition</p> 		<p>Date &amp; Time: Fri, Dec 27, 2019, 10:15:02 EST  Position: +037.323300° / +080.552189° (+16.4ft)  Altitude: 2342ft (+59.4ft)  Datum: WGS-84  Azimuth/Bearing: 284° N24W 5049mils True (+25°)  Elevation Angle: -13.4°  Horizon Angle: +04.3°  Zoom: 1.0X  Star#11018-00 Stream S-RR5- Bridge, buffers, signage ECD's are in acceptable condition</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11018+00		
<b>Pic 1 Desc.</b>	Stream bridge at AR-244, S-IJ18	<b>Pic 2 Desc.</b>	Row and stream S-RR5		
<p>Date &amp; Time: Fri, Dec 27, 2019, 10:15:02 EST  Position: +037.325528° / +080.554427° (+32.8ft)  Altitude: 2378ft (+78.7ft)  Datum: WGS-84  Azimuth/Bearing: 101° S79E 1173mils True (+10°)  Elevation Angle: -15.0°  Horizon Angle: +00.9°  Zoom: 1.0X  Star#10985+00 Stream S-E25 Bridge, buffers, signage ECD's are in acceptable condition</p> 		<p>Date &amp; Time: Fri, Dec 27, 2019, 10:30:14 EST  Position: +037.325528° / +080.554427° (+32.8ft)  Altitude: 2378ft (+78.7ft)  Datum: WGS-84  Azimuth/Bearing: 290° N80W 6627mils True (+14°)  Elevation Angle: -10.1°  Horizon Angle: +03.9°  Zoom: 1.0X  Star#10985+00 Stream S-E24 Bridge, buffers, signage ECD's are in acceptable condition</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10986+00	<b>Field Station#</b>	10985+00		
<b>Pic 3 Desc.</b>	Stream S-E25, bridge, buffers, ECD's.	<b>Pic 4 Desc.</b>	Stream S-E24, bridge, buffers, ECD's		
<p>Date &amp; Time: Fri, Dec 27, 2019, 10:46:44 EST  Position: +037.327744° / +080.571153° (+98.0ft)  Altitude: 2317ft (+59.4ft)  Datum: WGS-84  Azimuth/Bearing: 347° N13W 6149mils True (+10°)  Elevation Angle: -15.9°  Horizon Angle: +01.9°  Zoom: 1.0X  Star#10965+00 Karst ECD's &amp; signage are in acceptable condition</p> 		<p>Date &amp; Time: Fri, Dec 27, 2019, 10:50:28 EST  Position: +037.328900° / +080.569650° (+94.4ft)  Altitude: 2289ft (+59.4ft)  Datum: WGS-84  Azimuth/Bearing: 290° N80W 6242mils True (+10°)  Elevation Angle: -12.7°  Horizon Angle: +02.9°  Zoom: 1.0X  Star#10964+00 Drainage feature and ECD's are in acceptable condition</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10965+00	<b>Field Station#</b>	10964+00		
<b>Pic 5 Desc.</b>	Karst and Karst ECD's	<b>Pic 6 Desc.</b>	Drainage feature and ECD's.		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 8:22 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 8:22 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6928
<b>Inspector</b>	Brian Shields			<b>Date/Time</b>	12/27/2019 9:23 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 9:23 AM	<b>Report #</b>	6928
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
VA SWPPP inspection MP 208.78 to 209.56 Accompanied on inspection by MBP inspector Josh Hale installed perimeter controls are in good worn condition with no maintenance needed area has been temporarily stabilized with majority of section with minimal disturbance as grade has not been through area sumps are dry throughout area installed waterbars are functioning as designed					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 9:23 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11029+00	<b>Field Station#</b>	11032+00		
<b>Pic 1 Desc.</b>	installed perimeter controls	<b>Pic 2 Desc.</b>	installed waterbar and sump		
					
<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11033+00	<b>Field Station#</b>	11043+00		
<b>Pic 3 Desc.</b>	stabilized ROW conditions	<b>Pic 4 Desc.</b>	stabilized ROW conditions		
					
<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11058+00	<b>Field Station#</b>	11061+00		
<b>Pic 5 Desc.</b>	installed perimeter controls	<b>Pic 6 Desc.</b>	stabilized ROW conditions		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 9:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 9:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6999
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/27/2019 11:16 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 11:16 AM	<b>Report #</b>	6999
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 207. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	12/27/2019 11:16 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	10698+00	
<b>Pic 1 Desc.</b>	CFS checks in place along access road 241.04 in bar ditch.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G32.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10696+00		<b>Field Station#</b>	10862+00	
<b>Pic 3 Desc.</b>	RCE in place at Buffalo Anklets Road.		<b>Pic 4 Desc.</b>	Waterbar, sump pit, and waterbar end treatment in place.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10901+00		<b>Field Station#</b>	10917+00	
<b>Pic 5 Desc.</b>	Priority one silt fence in place along LOD.		<b>Pic 6 Desc.</b>	ROW stabilized with seed, mulch, and natural vegetation.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 11:16 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/27/2019 11:16 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		