



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9426
Inspector	Garrett Barclay			Date/Time	3/23/2020 3:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+00
County	Giles	Ground	Wet	Temperature (°F)	47.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/23/2020 3:22 PM	Report #	9426
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 205-MP207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	3/23/2020 3:22 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+1	
Pic 1 Desc.	.7" of rain recorded @ Kow Camp		Pic 2 Desc.	.4" of rain recorded @ Catawba	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	10872+00	
Pic 3 Desc.	.6" of rain recorded @ Mt Tabor		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10863+00		Field Station#	10889+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	3/23/2020 3:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/23/2020 3:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9427
Inspector	Jared Saunders			Date/Time	3/23/2020 3:26 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	11025+00
County	Giles	Ground	Muddy	Temperature (°F)	50.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.90
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/23/2020 3:26 PM	Report #	9427
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6 and from MP 207 to MP 208.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. Checked rain gauges at AR 234 - 0.9 inches, Buffalo Anklets Road - 0.8 inches, AR 244 - 0.7 inches, Winding Way - 0.8 inches, and Stevers Gap Road - 0.8 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	3/23/2020 3:26 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11025+00		Field Station#	10966+00	
Pic 1 Desc.	Rain gauge at Access Road 244 reads 0.7 inches.		Pic 2 Desc.	Triple barrier ECDs in place at open throat karst feature.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	10696+00	
Pic 3 Desc.	Rain gauge at Access Road 234 reads 0.9 inches.		Pic 4 Desc.	Rain gauge at Buffalo Anklets Road reads 0.8 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	10696+00	
Pic 5 Desc.	Rain gauge at Stevers Gap Road reads 0.8 inches.		Pic 6 Desc.	RCE in place at Buffalo Anklets Road.	

A/E	124300137	Date/Time	3/23/2020 3:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/23/2020 3:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9428
Inspector	Chris Burns			Date/Time	3/23/2020 3:00 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11064+53
County	Giles	Ground	Wet	Temperature (°F)	52.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	Yes
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/23/2020 3:00 PM	Report #	9428
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245.01. Inspection performed during ongoing rain event. No issues were located. All perimeter controls, ECDs and BMPs functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/23/2020 3:00 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11027+00	Field Station#	11033+00		
Pic 1 Desc.	Functional perimeter controls.	Pic 2 Desc.	Water bar, sump and end treatment.		
					
GPS Location	3	GPS Location	4		
Field Station#	11037+00	Field Station#	11048+00		
Pic 3 Desc.	RoW conditions and controls.	Pic 4 Desc.	Water bars and end treatments.		
					
GPS Location	5	GPS Location	6		
Field Station#	11055+00	Field Station#	11055+00		
Pic 5 Desc.	Karst protection controls.	Pic 6 Desc.	Row conditions and controls.		

A/E	124300137	Date/Time	3/23/2020 3:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/23/2020 3:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9454
Inspector	Brian Shields			Date/Time	3/24/2020 12:42 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Full	Station End	11158+77
County	Giles	Ground	Wet	Temperature (°F)	55.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/24/2020 12:42 PM	Report #	9454
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPPP inspection MP 211.33 to 213.16 ATWS and Rock construction entrance are functioning as designed perimeter controls throughout the area are maintenance free and functioning as designed clean water diversion berms are beginning to experience new growth no water is currently flowing through pipes or plunge pools area is temporarily stabilized with little to no sediment movement observed throughout the area all waterbars are functioning as designed, little to no erosion has been observed with the throats of the waterbars all sumps and end treatments are functioning as designed. no environmental issues identified during swppp inspection MBP inspectors on site during inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/24/2020 12:42 PM	Report #	
Pictures					
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	11222+00		Field Station#	11215+00	
Pic 1 Desc.	stabilized row conditions		Pic 2 Desc.	installed perimeter controls	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	11208+00		Field Station#	11203+00	
Pic 3 Desc.	stabilized row conditions		Pic 4 Desc.	installed perimeter controls	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	11189+00		Field Station#	11179+00	
Pic 5 Desc.	stabilized row conditions		Pic 6 Desc.	stabilized row conditions	

A/E	124300137	Date/Time	3/24/2020 12:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/24/2020 12:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9460
Inspector	Garrett Barclay			Date/Time	3/25/2020 3:05 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+00
State	VA	Inspection Area	Partial	Station End	11600+00
County	Giles	Ground	Damp	Temperature (°F)	56.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	3/25/2020 3:05 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11545+00		Field Station#	11530+00	
Pic 1 Desc.	CFS undermined		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11551+00		Field Station#	11580+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+1	
Pic 5 Desc.	1\" of rain recorded @ AR 244		Pic 6 Desc.	1.1\" of rain recorded @ Craig's creek	

A/E	124300137	Date/Time	3/25/2020 3:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/25/2020 3:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9462
Inspector	Chris Burns			Date/Time	3/24/2020 3:17 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Wet	Temperature (°F)	56.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Housekeeping	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/24/2020 3:17 PM	Report #	9462
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Performed SWPPP inspection from MP 213 to MP 214.8 as well as assessed At 256.02. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/24/2020 3:17 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11259+00	Field Station#	11262+70		
Pic 1 Desc.	Slope drain into water bar.	Pic 2 Desc.	Water bar end treatment.		
					
GPS Location	3	GPS Location	4		
Field Station#	11267+00	Field Station#	11270+00		
Pic 3 Desc.	RoW conditions and controls.	Pic 4 Desc.	Slope drain and sump.		
					
GPS Location	5	GPS Location	6		
Field Station#	11316+00	Field Station#	11331+00		
Pic 5 Desc.	RoW conditions and controls.	Pic 6 Desc.	RoW conditions and controls including S-NN12.		

A/E	124300137	Date/Time	3/24/2020 3:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/24/2020 3:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9496
Inspector	Rob Robertson			Date/Time	3/25/2020 3:09 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11700+00
County	Montgomery	Ground	Wet	Temperature (°F)	48.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/25/2020 3:09 PM	Report #	9496
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
A routine scheduled VADEQ SWPPP inspection was completed today on private and JNF property on Brush Mountain. The area received 1.1" of rainfall in the past 24 hours. ECDs are in place and functioning as designed. No erosion issues or sediment deposits beyond LOD were located. Slope breakers and end treatments are working properly. No impact noted at the resource crossings located in the area. The contractor is maintaining ECDs as needed. No slips have occurred and vegetation or mulch is adequate to prevent sediment movement. No environmental concerns were identified.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/25/2020 3:09 PM	Report #	
Pictures					
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11665+00	Field Station#	11659+00		
Pic 1 Desc.	Slope breakers effective	Pic 2 Desc.	Perimeter controls in place and functioning.		
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11648+00	Field Station#	11645+00		
Pic 3 Desc.	ROW currently stable with controls in place	Pic 4 Desc.	Perimeter ECDs in place and functional		
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11632+00	Field Station#	11620+75		
Pic 5 Desc.	End treatments and perimeter controls effective	Pic 6 Desc.	Runoff properly filtered before leaving ROW. No sediment deposits off ROW		

AFE	124300137	Date/Time	3/25/2020 3:09 PM	Report #	
Pictures					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11619+00	Field Station#	11614+20		
Pic 7 Desc.	Plunge pool in place	Pic 8 Desc.	Conditions at the S-RR14 crossing are stable		
GPS Location	On photo	GPS Location	On photo		
Field Station#	11607+81	Field Station#	11601+50		
Pic 9 Desc.	S-006 crossing is stable	Pic 10 Desc.	ROW conditions stable		
<div>Insert image here</div>		<div>Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	3/25/2020 3:09 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9498
Inspector	Garrett Barclay			Date/Time	3/24/2020 3:15 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+00
State	VA	Inspection Area	Partial	Station End	11158+00
County	Giles	Ground	Damp	Temperature (°F)	47.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/24/2020 3:15 PM	Report #	9498
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 209 - MP 211.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		3/24/2020 3:15 PM		Report #							
Pictures															
															
GPS Location				See picture above for GPS coordinates				GPS Location				See picture above for GPS coordinates			
Field Station#				+1				Field Station#				11085+00			
Pic 1 Desc.				.2" of rain recorded @ Kow Camp				Pic 2 Desc.				ECD's and row conditions			
															
GPS Location				See picture above for GPS coordinates				GPS Location				See picture above for GPS coordinates			
Field Station#				11086+00				Field Station#				11119+00			
Pic 3 Desc.				ECD's and row conditions				Pic 4 Desc.				ECD's and row conditions			
															
GPS Location				See picture above for GPS coordinates				GPS Location				See picture above for GPS coordinates			
Field Station#				11119+00				Field Station#				11130+00			
Pic 5 Desc.				ECD's and row conditions				Pic 6 Desc.				ECD's and row conditions			

A/E	124300137	Date/Time	3/24/2020 3:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/24/2020 3:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9499
Inspector	Chris Burns			Date/Time	3/25/2020 2:35 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+99
State	VA	Inspection Area	Partial	Station End	12005+00
County	Montgomery	Ground	Wet	Temperature (°F)	57.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.05
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Roadside Ditch	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	3/25/2020 2:35 PM	Report #	9499
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>See photos for GPS coordinates. Performed SWPPP inspection from MP 225.3 to MP 227.37 as well as assessed AR 266. No major issues were located. Three locations of weather impact to controls were identified, two of which were punch listed including an undercut end treatment near 11901+00 and multiple undercut end treatments on the hill between 11918+00 and 11924+00. Crews began making repairs. The weather impacted location not put on the punch list is W-NN6 near 12001+00 as it is currently submerged and inaccessible following recent rain events, an assessment of this area will be made once waters recede. All other perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Participated in the Spread G conference call.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	3/25/2020 2:35 PM	Report #	
Pictures					
<p>Date & Time: Wed, Mar 25, 2020, 10:43:09 EDT Position: +487.247670° / -900.326594° (+312.87) Altitude: 1997ft (+312.87) Datum: WGS-84 Azimuth/Bearing: 157.523E 2791mils True (±12°) Elevation Angle: -10.2° Horizon Angle: -03.2° Zoom: 1.0X Catawba rd 1.05'</p> 		<p>Date & Time: Wed, Mar 25, 2020, 11:44:56 EDT Position: +487.247670° / -900.326594° (+312.87) Altitude: 1997ft (+312.87) Datum: WGS-84 Azimuth/Bearing: 131° S41E 2600mils True (±13°) Elevation Angle: -13.6° Horizon Angle: 100.6° Zoom: 1.0X 11991+00</p> 			
GPS Location	1	GPS Location	2		
Field Station#	11989+00	Field Station#	11991+00		
Pic 1 Desc.	Rain gauge from Catawba rd indicating 1.05" of accumulation.		Pic 2 Desc.	Section of restored RoW and controls.	
<p>Date & Time: Wed, Mar 25, 2020, 11:43:59 EDT Position: +487.247670° / -900.326594° (+312.87) Altitude: 2312ft (+45.94) Datum: WGS-84 Azimuth/Bearing: 135° S13W 2493mils True (±11°) Elevation Angle: -12.0° Horizon Angle: -00.2° Zoom: 1.0X 11993+00</p> 		<p>Date & Time: Wed, Mar 25, 2020, 11:41:01 EDT Position: +487.247670° / -900.326594° (+312.87) Altitude: 2312ft (+45.94) Datum: WGS-84 Azimuth/Bearing: 207° S67W 4391mils True (±53°) Elevation Angle: -13.0° Horizon Angle: -00.2° Zoom: 1.0X 11993+00</p> 			
GPS Location	3	GPS Location	4		
Field Station#	11906+00	Field Station#	11939+00		
Pic 3 Desc.	Section of semi restored RoW and controls.		Pic 4 Desc.	Section of semi restored RoW and controls.	
<p>Date & Time: Wed, Mar 25, 2020, 12:04:19 EDT Position: +487.247670° / -900.326594° (+312.87) Altitude: 1733ft (+32.89) Datum: WGS-84 Azimuth/Bearing: 135° S45E 2700mils True (±24°) Elevation Angle: -11.7° Horizon Angle: +00.0° Zoom: 1.0X 11970+50</p> 		<p>Date & Time: Wed, Mar 25, 2020, 12:11:39 EDT Position: +487.247670° / -900.326594° (+312.87) Altitude: 1733ft (+32.89) Datum: WGS-84 Azimuth/Bearing: 140° S40E 2489mils True (±17°) Elevation Angle: -11.7° Horizon Angle: +02.0° Zoom: 1.0X 11977+00</p> 			
GPS Location	5	GPS Location	6		
Field Station#	11970+50	Field Station#	11977+00		
Pic 5 Desc.	Section of semi restored RoW and controls.		Pic 6 Desc.	Karst controls functional.	

A/E	124300137	Date/Time	3/25/2020 2:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/25/2020 2:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9502
Inspector	Jared Saunders			Date/Time	3/25/2020 4:11 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Muddy	Temperature (°F)	50.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.30
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	3/25/2020 4:11 PM	Report #	
Pictures					
 <p><small>Date & Time: Wed, Mar 25, 2020 08:32:55 EDT Position: +089.54188° / +38.97319° (+100.2M) Altitude: 2720M (+83.0M) Datum: WGS-84 Azimuth/Bearing: 088° N08E 1067mils True (+13.1) Elevation Angle: -02.8 Horizon Angle: -00.4 Zoom: 1.0X AR 234</small></p>		 <p><small>Date & Time: Wed, Mar 25, 2020 08:46:18 EDT Position: +089.54188° / +38.97319° (+100.2M) Altitude: 2664M (+83.0M) Datum: WGS-84 Azimuth/Bearing: 133° S07W 3681mils True (+13.1) Elevation Angle: -04.1 Horizon Angle: -00.5 Zoom: 1.0X Buffalo</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	10696+00	
Pic 1 Desc.	Rain gauge at Access Road 234 reads 1 inch.		Pic 2 Desc.	Rain gauge at Buffalo Anklets Road reads 1 inch.	
 <p><small>Date & Time: Wed, Mar 25, 2020 11:05:08 EDT Position: +089.54188° / +38.97319° (+100.2M) Altitude: 2133M (+68.1M) Datum: WGS-84 Azimuth/Bearing: 296° N64W 5262mils True (+13.1) Elevation Angle: -02.7 Horizon Angle: -00.3 Zoom: 1.0X Kow Camp</small></p>		 <p><small>Date & Time: Wed, Mar 25, 2020 10:48:13 EDT Position: +089.54188° / +38.97319° (+100.2M) Altitude: 2768M (+75.1M) Datum: WGS-84 Azimuth/Bearing: 277° N83W 4924mils True (+13.1) Elevation Angle: -07.8 Horizon Angle: -01.1 Zoom: 1.0X 11687+40 S-MN21</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10883+50		Field Station#	11687+40	
Pic 3 Desc.	Rain gauge at Kow Camp Road reads 1.2 inches.		Pic 4 Desc.	Sensitive resource buffer in place at stream S-MN21.	
 <p><small>Date & Time: Wed, Mar 25, 2020 11:05:43 EDT Position: +089.54188° / +38.97319° (+100.2M) Altitude: 2017M (+61.1M) Datum: WGS-84 Azimuth/Bearing: 133° S69E 3737mils True (+14.1) Elevation Angle: -03.1 Horizon Angle: -00.4 Zoom: 1.0X 11767+00</small></p>		 <p><small>Date & Time: Wed, Mar 25, 2020 11:40:18 EDT Position: +089.54188° / +38.97319° (+100.2M) Altitude: 2013M (+60.6M) Datum: WGS-84 Azimuth/Bearing: 085° N85E 1511mils True (+13.1) Elevation Angle: -03.7 Horizon Angle: -00.5 Zoom: 1.0X 11767+00</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11676+00	
Pic 5 Desc.	RCE in place at Main Line Valve 26.		Pic 6 Desc.	Rain gauge at Mount Tabor Road reads 1.3 inches.	

A/E	124300137	Date/Time	3/25/2020 4:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/25/2020 4:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9508
Inspector	Jared Saunders			Date/Time	3/24/2020 10:30 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11525+00
State	VA	Inspection Area	Partial	Station End	11351+00
County	Giles	Ground	Muddy	Temperature (°F)	55.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00




1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/24/2020 10:30 AM	Report #	9508
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/24/2020 10:30 AM	Report #	
Pictures					
<p>Date & Time: Tue, Mar 24, 2020, 09:11:29 EDT Position: +037 326147 / -080 425880 (+14031.9ft) Altitude: 2224ft (+35.9ft) Datum: WGS-84 Azimuth/Bearing: 330° N30W 5867mils True (+13°) Elevation Angle: -17.1° Horizon Angle: -02.2° Zoom: 1.0x 11507+00</p> 		<p>Date & Time: Tue, Mar 24, 2020, 09:12:26 EDT Position: +037 326147 / -080 425880 (+14031.9ft) Altitude: 2211ft (+34.3ft) Datum: WGS-84 Azimuth/Bearing: 174° S06E 3093mils True (+13°) Elevation Angle: -02.6° Horizon Angle: +01.0° Zoom: 1.0x 11505+00</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11507+00		Field Station#	11506+00	
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 2 Desc.	Clean water diversion pipe and clean water diversion berm in place.	
<p>Date & Time: Tue, Mar 24, 2020, 09:12:56 EDT Position: +037 326007 / -080 426977 (+18.5ft) Altitude: 2224ft (+35.9ft) Datum: WGS-84 Azimuth/Bearing: 224° S44W 3982mils True (+13°) Elevation Angle: -02.8° Horizon Angle: -00.6° Zoom: 1.0x 11503+00</p> 		<p>Date & Time: Tue, Mar 24, 2020, 09:19:11 EDT Position: +037 326147 / -080 430482 (+1713.0ft) Altitude: 2224ft (+35.9ft) Datum: WGS-84 Azimuth/Bearing: 101° S51W 4284mils True (+12°) Elevation Angle: -11.0° Horizon Angle: -00.3° Zoom: 1.0x 11489+00</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11503+00		Field Station#	11489+00	
Pic 3 Desc.	Conveyance channel with rock checks in place at double cut section of ROW.		Pic 4 Desc.	RCE in place at Stevers Gap Road.	
<p>Date & Time: Tue, Mar 24, 2020, 09:26:06 EDT Position: +037 326776 / -080 473623 (+13904.6ft) Altitude: 2162ft (+82.8ft) Datum: WGS-84 Azimuth/Bearing: 272° N88W 4836mils True (+13°) Elevation Angle: -02.6° Horizon Angle: -00.7° Zoom: 1.0x 11477+00</p> 		<p>Date & Time: Tue, Mar 24, 2020, 09:26:06 EDT Position: +037 326776 / -080 473623 (+13904.6ft) Altitude: 2082ft (+63.1ft) Datum: WGS-84 Azimuth/Bearing: 304° S04W 5106mils True (+13°) Elevation Angle: -08.2° Horizon Angle: +00.0° Zoom: 1.0x 11380+00</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11477+00		Field Station#	11380+00	
Pic 5 Desc.	Two tone stabilized with ECB and slope drains in place to minimize erosion.		Pic 6 Desc.	Triple barrier ECDs in place at off ROW karst feature.	

A/E	124300137	Date/Time	3/24/2020 10:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/24/2020 10:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9521
Inspector	Brian Shields			Date/Time	3/25/2020 7:51 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Full	Station End	11899+99
County	Montgomery	Ground	Wet	Temperature (°F)	55.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.30
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/25/2020 7:51 AM	Report #	9521
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPPP inspection MP 223.26 to 225.38 1.3 inches of rain recieved across area overnight area has been permanently restored vegetation growth is becoming heavy throughout area as the growing season begins installed rock construction entrance is in good working condition all installed perimeter controls are functioning as designed with no maintenance needed permanent waterbars and weir sections appear to be functioning as designed no environmental issues identified during course of inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/25/2020 7:51 AM	Report #	
Pictures					
	<div>3090 Mount Tabor Road, Blacksburg, Virginia, 24060</div> <div>● 37.296, -80.360141 ±6m</div>  <div>11792+00 row conditions</div> <div>Spread G</div> <div>25 Mar 2020, 11:10 AM</div>			<div>Checking street address ...</div> <div>● 37.296072, -80.358047 ±7m</div>  <div>11798+00 permanent weir</div> <div>Spread G</div> <div>25 Mar 2020, 11:32 AM</div>	
GPS Location	see photo		GPS Location	see photo	
Field Station#	11792+00		Field Station#	11798+00	
Pic 1 Desc.	stabilized row conditions		Pic 2 Desc.	permanent waterbar and end treatment	
	<div>Checking street address ...</div> <div>● 37.295979, -80.356862 ±6m</div>  <div>11802+00 row conditions</div> <div>Spread G</div> <div>25 Mar 2020, 11:15 AM</div>			<div>Checking street address ...</div> <div>● 37.294371, -80.351709 ±5m</div>  <div>11835+00 installed controls</div> <div>Spread G</div> <div>25 Mar 2020, 11:35 AM</div>	
GPS Location	see photo		GPS Location	see photo	
Field Station#	11802+00		Field Station#	11835+00	
Pic 3 Desc.	stabilized row conditions		Pic 4 Desc.	installed controls	
	<div>Checking street address ...</div> <div>● 37.286704, -80.348618 ±9m</div>  <div>11852+00 installed controls</div> <div>Spread G</div> <div>25 Mar 2020, 11:46 AM</div>			<div>Checking street address ...</div> <div>● 37.286254, -80.34475 ±19m</div>  <div>11871+00 row conditions</div> <div>Spread G</div> <div>25 Mar 2020, 11:56 AM</div>	
GPS Location	see photo		GPS Location	see photo	
Field Station#	11852+00		Field Station#	11871+00	
Pic 5 Desc.	installed perimeter controls		Pic 6 Desc.	stabilized row conditions	

A/E	124300137	Date/Time	3/25/2020 7:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/25/2020 7:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9576
Inspector	Chris Burns			Date/Time	3/27/2020 2:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11064+53
County	Giles	Ground	Wet	Temperature (°F)	80.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/27/2020 2:36 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11025+50	Field Station#	11035+00		
Pic 1 Desc.	S-IJ18.	Pic 2 Desc.	RoW conditions and controls.		
					
GPS Location	3	GPS Location	4		
Field Station#	11039+00	Field Station#	11050+10		
Pic 3 Desc.	Perimeter controls functional.	Pic 4 Desc.	S-IJ16B and S-IJ17.		
					
GPS Location	5	GPS Location	6		
Field Station#	11055+00	Field Station#	11064+50		
Pic 5 Desc.	RoW conditions and controls.	Pic 6 Desc.	RoW conditions and controls.		

A/E	124300137	Date/Time	3/27/2020 2:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/27/2020 2:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9577
Inspector	Brian Shields			Date/Time	3/27/2020 3:52 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Full	Station End	10929+62
County	Giles	Ground	Damp	Temperature (°F)	60.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/27/2020 3:52 PM	Report #	9577
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPPP Inspection MP 208.79 to 207 installed rock construction entrance is in good working condition all installed perimeter controls appear to be functioning as designed with no maintenance needed sumps are dry and free of water waterbars are functioning as designed vegetation growth is becoming heavy throughout certain areas of the section, other areas throughout have recently been over seeded all end treatments are maintenance free. no issues observed during inspection, conditions are wet due to recent rains.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/27/2020 3:52 PM	Report #	
Pictures					
GPS Location	see photo	GPS Location	see photo		
Field Station#	11016+50	Field Station#	10992+50		
Pic 1 Desc.	s-rr5 upstream	Pic 2 Desc.	Installed perimeter controls		
GPS Location	see photo	GPS Location	see photo		
Field Station#	10978+00	Field Station#	10976+96		
Pic 3 Desc.	stabilized row conditions	Pic 4 Desc.	buffer installed around possible stream		
GPS Location	see photo	GPS Location	see photo		
Field Station#	10937+90	Field Station#	10934+00		
Pic 5 Desc.	stabilized row conditions	Pic 6 Desc.	installed perimeter controls		

A/E	124300137	Date/Time	3/27/2020 3:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/27/2020 3:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9598
Inspector	Jared Saunders			Date/Time	3/26/2020 2:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	45.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/26/2020 2:36 PM	Report #	9598
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/26/2020 2:36 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack compost filter sock in place around drainage.		Pic 2 Desc.	Checked staged equipment for leaks.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	18 inch compost filter sock in place along LOD of LDY.		Pic 4 Desc.	Secondary containment in place under fuel cell.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Dumpsters being utilized for trash management.		Pic 6 Desc.	Port-a-potties and light plant in secondary containment.	

A/E	124300137	Date/Time	3/26/2020 2:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/26/2020 2:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9599
Inspector	Jared Saunders			Date/Time	3/27/2020 2:39 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	10750+00
County	Giles	Ground	Damp	Temperature (°F)	85.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Erosion Control Blanket	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/27/2020 2:39 PM	Report #	9599
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		3/27/2020 2:39 PM		Report #			
Pictures											
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		10712+50						Field Station#		10711+00	
Pic 1 Desc.		Sensitive resource buffer in place at stream S-G33.						Pic 2 Desc.		ROW stabilized with natural vegetation.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		10698+00						Field Station#		10696+00	
Pic 3 Desc.		Sensitive resource buffer in place at stream S-G32.						Pic 4 Desc.		RCE in place at Buffalo Anklets Road.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		10732+50						Field Station#		10710+00	
Pic 5 Desc.		Sensitive resource buffer in place at Wetland W-Z11.						Pic 6 Desc.		Compost filter sock checks in place along access road 241.04.	

A/E	124300137	Date/Time	3/27/2020 2:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/27/2020 2:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9606
Inspector	Garrett Barclay			Date/Time	3/26/2020 3:16 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Damp	Temperature (°F)	46.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Secondary Containment	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/26/2020 3:16 PM	Report #	9606
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for LDY 28 & LDY 29 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/26/2020 3:16 PM	Report #	
Pictures					
<p>Date & Time Thu, Mar 26, 2020, 05:56:17 EDT Position: +39°51'55.87" / -85°47'35.37" (+16.3m) Altitude: 1710 ft (+51.3m) Datum: WGS-84 Azimuth/Bearing: 324° 53'35" 500m Error (Error) Elevation Grade: -00% Horizon Grade: -00% Zoom: 1.0X 29</p> 		<p>Date & Time Thu, Mar 26, 2020, 05:56:18 EDT Position: +39°51'55.87" / -85°47'35.37" (+16.3m) Altitude: 1710 ft (+51.3m) Datum: WGS-84 Azimuth/Bearing: 137° 50'18" 500m Error (Error) Elevation Grade: -00% Horizon Grade: -00% Zoom: 1.0X 29</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+29		Field Station#	+29	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
<p>Date & Time Thu, Mar 26, 2020, 09:03:09 EDT Position: +39°52'02.45" / -85°48'10.72" (+15.6m) Altitude: 1630 ft (+50.0m) Datum: WGS-84 Azimuth/Bearing: 120° 55'48" 500m Error (Error) Elevation Grade: -00% Horizon Grade: -00% Zoom: 1.0X 28</p> 		<p>Date & Time Thu, Mar 26, 2020, 09:03:09 EDT Position: +39°52'02.45" / -85°48'10.72" (+15.6m) Altitude: 1630 ft (+50.0m) Datum: WGS-84 Azimuth/Bearing: 120° 55'48" 500m Error (Error) Elevation Grade: -00% Horizon Grade: -00% Zoom: 1.0X 28</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+28		Field Station#	+28	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
<p>Date & Time Thu, Mar 26, 2020, 09:03:26 EDT Position: +39°52'02.45" / -85°48'11.12" (+15.6m) Altitude: 1630 ft (+50.0m) Datum: WGS-84 Azimuth/Bearing: 273° 14'57" 500m Error (Error) Elevation Grade: -010% Horizon Grade: -001% Zoom: 1.0X 28</p> 		<p>Date & Time Thu, Mar 26, 2020, 09:03:26 EDT Position: +39°52'02.45" / -85°48'11.12" (+15.6m) Altitude: 1630 ft (+50.0m) Datum: WGS-84 Azimuth/Bearing: 273° 14'57" 500m Error (Error) Elevation Grade: -010% Horizon Grade: -001% Zoom: 1.0X 28</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+28		Field Station#	+28	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	3/26/2020 3:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/26/2020 3:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9607
Inspector	Garrett Barclay			Date/Time	3/27/2020 3:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+62
County	Giles	Ground	Damp	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/27/2020 3:21 PM	Report #	9607
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 205 - MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	3/27/2020 3:21 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10862+00		Field Station#	10869+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10873+00		Field Station#	10891+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10898+00		Field Station#	10915+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	3/27/2020 3:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/27/2020 3:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		