



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10224
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	4/20/2020 8:13 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11024+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	51.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			



## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





<b>AFE</b>	124300137	<b>Date/Time</b>	4/20/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, Apr 20, 2020, 09:29:01 EDT Position: +037 325412 / +005 552872 (+2799.99) Altitude: +3254 ft (+991 m) Datum: WGS 84 Azimuth/Bearing: 305° NSW 5426mils True (±10°) Elevation Angle: -13° Horizon Angle: +03.3° Zoom: 1.0x Star 11024-00- P1 perimeter has been repaired.</p>		 <p>Date &amp; Time: Mon, Apr 20, 2020, 09:30:37 EDT Position: +037 325412 / +005 552872 (+2799.99) Altitude: +3254 ft (+991 m) Datum: WGS 84 Azimuth/Bearing: 227° S47W 4036mils True (±10°) Elevation Angle: -16.6° Horizon Angle: +03.3° Zoom: 1.0x Star 11017-00- P1 perimeter controls have been replaced.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11017+00		
<b>Pic 1 Desc.</b>	Contractor has repaired damaged P1 silt fence.	<b>Pic 2 Desc.</b>	Damaged silt fence has been replaced.		
 <p>Date &amp; Time: Mon, Apr 20, 2020, 09:32:01 EDT Position: +037 325412 / +005 552872 (+2799.99) Altitude: +3254 ft (+991 m) Datum: WGS 84 Azimuth/Bearing: 204° NSW 5006mils True (±10°) Elevation Angle: -05.3° Horizon Angle: +02.1° Zoom: 1.0x Stream S-RR5 Stream &amp; stream controls are in acceptable condition.</p>		 <p>Date &amp; Time: Mon, Apr 20, 2020, 09:33:48 EDT Position: +037 325412 / +005 552872 (+2799.99) Altitude: +304 ft (+92.5 ft) Datum: WGS 84 Azimuth/Bearing: 080° N80E 1329mils True (±10°) Elevation Angle: -04.2° Horizon Angle: +00.7° Zoom: 1.0x Stream S-E25 Stream &amp; stream controls are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11017+00	<b>Field Station#</b>	10986+00		
<b>Pic 3 Desc.</b>	Stream S- RR5 bridge and ECD's	<b>Pic 4 Desc.</b>	Stream S-E25 bridge and ECD's.		
 <p>Date &amp; Time: Mon, Apr 20, 2020, 09:35:48 EDT Position: +037 325412 / +005 552872 (+2799.99) Altitude: +2726 ft (+831 m) Datum: WGS 84 Azimuth/Bearing: 309° NSW 5956mils True (±10°) Elevation Angle: -12.8° Horizon Angle: +03.3° Zoom: 1.0x Stream S-E24- Stream &amp; stream controls are in acceptable condition.</p>		 <p>Date &amp; Time: Mon, Apr 20, 2020, 10:10:02 EDT Position: +037 325412 / +005 552872 (+2799.99) Altitude: +2324 ft (+707.4 m) Datum: WGS 84 Azimuth/Bearing: 335° N25W 5956mils True (±10°) Elevation Angle: -21.3° Horizon Angle: +02.7° Zoom: 1.0x Star 10965-00- Karst &amp; Karst ECD's are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10985+00	<b>Field Station#</b>	10965+00		
<b>Pic 5 Desc.</b>	Stream S-E24 bridge and ECD's.	<b>Pic 6 Desc.</b>	Karst and Karst ECD's.		

<b>AFE</b>	124300137	<b>Date/Time</b>	4/20/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
<small>Date &amp; Time: Mon, Apr 20, 2020 11:02:23 EDT  Position: +037 318019 / +080 553536 / +16.44h  Altitude: 2162ft (+19.7h)  Datum: WGS-84  Azimuth/Bearing: 288° N22W 5120mils True (+10°)  Elevation Angle: +18.0  Horizon Angle: +04.9  Zoom: 1.0X  AR-244 rain gauge reading: 0.60</small> 		<small>Date &amp; Time: Mon, Apr 20, 2020 11:16:56 EDT  Position: +037 300445 / +080 503493 / +16.44h  Altitude: 1957ft (+26.2h)  Datum: WGS-84  Azimuth/Bearing: 177° S03E 3147mils True (+10°)  Elevation Angle: +18.0  Horizon Angle: +02.6  Zoom: 1.0X  Winding Way rain gauge reading: 0.55</small> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11227+00		
<b>Pic 7 Desc.</b>	AR-244 rain gauge reading- 0.60"	<b>Pic 8 Desc.</b>	Winding Way rain gauge reading - 0.55"		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	4/20/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10242
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	4/20/2020 3:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	4/20/2020 3:12 PM	<b>Report #</b>	10242
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. Checked rain gauges at Buffalo Anklets Road - 0.5 inches, Access Road 234 - 0.6 inches, Mount Tabor Road - 0.5 inches and Catawba Road - 0.5 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	4/20/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10696+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Rain gauge at Buffalo Anklets Road reads 0.5 inches.		<b>Pic 2 Desc.</b>	Rain gauge at Access Road 234 reads 0.6 inches.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10767+00		<b>Field Station#</b>	11990+00	
<b>Pic 3 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.5 inches.		<b>Pic 4 Desc.</b>	Rain gauge at Catawba Road reads 0.5 inches.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00		<b>Field Station#</b>	10696+00	
<b>Pic 5 Desc.</b>	ROW stabilized with natural vegetation growth.		<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/20/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	4/20/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10244
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	4/20/2020 3:47 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Equipment Bridge	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/20/2020 3:47 PM	<b>Report #</b>	10244
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245.01. No Issues we're located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		Date/Time		Report #	
124300137		4/20/2020 3:47 PM			
Pictures					
<div><div><div>Date &amp; Time: Mon, Apr 20, 2020, 10:27:00 EDT</div><div>Position: +037.31118° / -80.56284° (±28.1m)</div><div>Altitude: 2545 (±11.4m)</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 18° 307° 330mils True (±26°)</div><div>Elevation Angle: -33.4°</div><div>Horizon Angle: -0.0°</div><div>Zoom: 1.0x</div><div>S-IJ18</div></div><div></div></div>		<div><div><div>Date &amp; Time: Mon, Apr 20, 2020, 10:29:07 EDT</div><div>Position: +037.22118° / -80.56362° (±28.1m)</div><div>Altitude: 2545 (±11.4m)</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 18° 307° 330mils True (±26°)</div><div>Elevation Angle: -33.4°</div><div>Horizon Angle: -0.0°</div><div>Zoom: 1.0x</div><div>S-IJ18</div></div><div></div></div>			
GPS Location		1		GPS Location	
Field Station#		11025+50		2	
Field Station#		11025+50		Field Station#	
Field Station#		11025+50		11034+00	
Pic 1 Desc.		S-IJ18 and controls.		Pic 2 Desc.	
Pic 2 Desc.		RoW conditions and controls.			
<div><div><div>Date &amp; Time: Mon, Apr 20, 2020, 10:31:00 EDT</div><div>Position: +037.31523° / -80.54595° (±28.1m)</div><div>Altitude: 2295ft (±10.4m)</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 360° 000° 640mils True (±25°)</div><div>Elevation Angle: -39.6°</div><div>Horizon Angle: -0.7°</div><div>Zoom: 1.0x</div><div>S-IJ16B and S-IJ17</div></div><div></div></div>		<div><div><div>Date &amp; Time: Mon, Apr 20, 2020, 10:37:55 EDT</div><div>Position: +037.31523° / -80.54595° (±28.1m)</div><div>Altitude: 2106ft (±10.4m)</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 055° 056° 627mils True (±26°)</div><div>Elevation Angle: -11.1°</div><div>Horizon Angle: -0.6°</div><div>Zoom: 1.0x</div><div>S-IJ16B and S-IJ17</div></div><div></div></div>			
GPS Location		3		GPS Location	
Field Station#		11039+00		4	
Field Station#		11039+00		Field Station#	
Field Station#		11039+00		11050+10	
Pic 3 Desc.		Perimeter controls functional.		Pic 4 Desc.	
Pic 4 Desc.		S-IJ16B and S-IJ17 buffers.			
<div><div><div>Date &amp; Time: Mon, Apr 20, 2020, 10:39:55 EDT</div><div>Position: +037.31523° / -80.54711° (±28.1m)</div><div>Altitude: 2295ft (±10.4m)</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 050° 050° 639mils True (±27°)</div><div>Elevation Angle: -14.3°</div><div>Horizon Angle: -0.1°</div><div>Zoom: 1.0x</div><div>S-IJ16B and S-IJ17</div></div><div></div></div>		<div><div><div>Date &amp; Time: Mon, Apr 20, 2020, 10:44:50 EDT</div><div>Position: +037.31523° / -80.54595° (±28.1m)</div><div>Altitude: 2209ft (±10.4m)</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 107° 050° 640mils True (±26°)</div><div>Elevation Angle: -03.9°</div><div>Horizon Angle: -0.6°</div><div>Zoom: 1.0x</div><div>11057+50</div></div><div></div></div>			
GPS Location		5		GPS Location	
Field Station#		11050+10		6	
Field Station#		11050+10		Field Station#	
Field Station#		11050+10		11057+50	
Pic 5 Desc.		S-IJ16B and S-IJ17.		Pic 6 Desc.	
Pic 6 Desc.		RoW conditions and controls.			

<b>A/E</b>	124300137	<b>Date/Time</b>	4/20/2020 3:47 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	4/20/2020 3:47 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10267
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	4/21/2020 8:47 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11161+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 8:47 AM	<b>Report #</b>	10267
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at Winding Way. SWPPP inspection: Sta#11254+88 to 11161+00. MP- 213 to 211 The row is wet but in stable condition, no sediment movement observed. Temporary stabilization is acceptable. Perimeter controls, Silt fence, CFS, SSF are in acceptable condition. Slope drains are in acceptable condition. CWD pipe and plunge pool are in good condition. Water bars are stable. Water bar sump pits and end treatments are in acceptable condition. Sensitive resource, drainage feature are in acceptable condition, ECD's are in acceptable condition. Access roads, Winding Way, AR- 249.02, AR- 249.01 are maintained in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/21/2020 8:47 AM	Report #	
Pictures					
<div><div><div>Date &amp; Time: Tue, Apr 21, 2020, 08:45:10 EDT Position: +037.3003487° N +000.0000797° W (+16.400) Altitude: 2067ft (+59.400) Datum: WGS-84 Azimuth/Bearing: 330° S10W 3378mils True (±10°) Elevation Angle: +15.0° Horizon Angle: +01.2° Zoom: 1.0x Sta#11232+00 to 11225+00- Perimeter controls, water bars row in acceptable condition.</div></div></div>		<div><div><div>Date &amp; Time: Tue, Apr 21, 2020, 09:29:03 EDT Position: +037.301518° N +000.002539° W (+32.8m) Altitude: 2067ft (+59.6m) Datum: WGS-84 Azimuth/Bearing: 190° S10W 3378mils True (±10°) Elevation Angle: +29.0° Horizon Angle: +06.1° Zoom: 1.0x Sta#11225+00 to 11222+00- Sloped drain, end treatment, rock channel are in acceptable condition.</div></div></div>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11232+00		Field Station#	11225+00	
Pic 1 Desc.	Perimeter controls, water bars, row in acceptable condition.		Pic 2 Desc.	Slope drain, end treatment, rock channel are in acceptable condition.	
<div><div><div>Date &amp; Time: Tue, Apr 21, 2020, 09:45:14 EDT Position: +037.308012° N +000.500902° W (+105.8m) Altitude: 2021ft (+61.8m) Datum: WGS-84 Azimuth/Bearing: 169° S11E 3004mils True (±10°) Elevation Angle: +19.2° Horizon Angle: +00.9° Zoom: 1.0x Sta#11200+00 to 11204+00- Water bars on steep slope are in stable condition.</div></div></div>		<div><div><div>Date &amp; Time: Tue, Apr 21, 2020, 09:48:56 EDT Position: +037.305110° N +000.507534° W (+164.1m) Altitude: 2060ft (+63.0m) Datum: WGS-84 Azimuth/Bearing: 184° S06W 3671mils True (±10°) Elevation Angle: +25.0° Horizon Angle: +00.5° Zoom: 1.0x Sta#11200+00 to 11204+00- CFS perimeter controls and CFS triple stack and treatments are in acceptable condition.</div></div></div>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11200+00		Field Station#	11200+00	
Pic 3 Desc.	Water bars on steep slope are stable.		Pic 4 Desc.	CFS perimeter controls and CFS triple stack end treatment's are in acceptable condition.	
<div><div><div>Date &amp; Time: Tue, Apr 21, 2020, 09:55:08 EDT Position: +037.305192° N +000.508203° W (+141.4m) Altitude: 2020ft (+61.8m) Datum: WGS-84 Azimuth/Bearing: 233° N45W 3244mils True (±10°) Elevation Angle: +23.0° Horizon Angle: +07.0° Zoom: 1.0x Sta#11195+00 to 11191+00- SSF &amp; CFS perimeter controls are in acceptable condition.</div></div></div>		<div><div><div>Date &amp; Time: Tue, Apr 21, 2020, 10:01:14 EDT Position: +037.305192° N +000.509652° W (+16.0m) Altitude: 1950ft (+59.4m) Datum: WGS-84 Azimuth/Bearing: 035° N45W 5583mils True (±10°) Elevation Angle: +1.0° Horizon Angle: +05.4° Zoom: 1.0x Sta#11191+00- Sensitive resource, drainage feature, ECD's are in acceptable condition.</div></div></div>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11195+00		Field Station#	11191+00	
Pic 5 Desc.	SSF & CFS perimeter controls are in acceptable condition.		Pic 6 Desc.	Sensitive resource, drainage feature, ECD's are in acceptable condition.	



<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 8:47 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 8:47 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10277
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	4/21/2020 1:48 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 1:48 PM	<b>Report #</b>	10277
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at Winding Way access for morning meeting Performed SWPPP from MP 209 - MP 211.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	4/21/2020 1:48 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue Apr 21, 2020 09:11:01 EDT  Position: +38°14'54.17" / -80°22'19.88" (+448.9ft)  Altitude: 2323ft (+11085ft)  Datum: WGS 84  Azimuth/Bearing: 045° N45E 0800mils Error (Error)  Elevation Grade: -01%  Horizon Grade: +001  Zoom: 1.0X  11080</p> 		<p>Date &amp; Time: Tue Apr 21, 2020 09:14:49 EDT  Position: +38°14'54.17" / -80°22'19.88" (+448.9ft)  Altitude: 2323ft (+11085ft)  Datum: WGS 84  Azimuth/Bearing: 045° N45E 0800mils Error (Error)  Elevation Grade: -01%  Horizon Grade: +001  Zoom: 1.0X  11085</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11080+00		<b>Field Station#</b>	11085+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Tue Apr 21, 2020 09:19:11 EDT  Position: +38°16'22.33" / -80°22'12.34" (+14493.7ft)  Altitude: 2323ft (+11093ft)  Datum: WGS 84  Azimuth/Bearing: 092° N92E 1071mils Error (Error)  Elevation Grade: -001%  Horizon Grade: -012  Zoom: 1.0X  11093</p> 		<p>Date &amp; Time: Tue Apr 21, 2020 09:25:00 EDT  Position: +38°16'42.00" / -80°18'22.88" (+45092.1ft)  Altitude: 1771ft (+8851ft)  Datum: WGS 84  Azimuth/Bearing: 042° N42E 0747mils Error (Error)  Elevation Grade: -02%  Horizon Grade: +000  Zoom: 1.0X  11101</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11093+00		<b>Field Station#</b>	111101+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Tue Apr 21, 2020 09:26:29 EDT  Position: +38°16'54.47" / -80°21'41.27" (+15230ft)  Altitude: 2323ft (+11119ft)  Datum: WGS 84  Azimuth/Bearing: 042° N42E 0801mils Error (Error)  Elevation Grade: -001%  Horizon Grade: +001  Zoom: 1.0X  11119</p> 		<p>Date &amp; Time: Tue Apr 21, 2020 09:26:38 EDT  Position: +38°16'54.47" / -80°21'41.27" (+15230ft)  Altitude: 2323ft (+11135ft)  Datum: WGS 84  Azimuth/Bearing: 042° N42E 0920mils Error (Error)  Elevation Grade: -001%  Horizon Grade: +001%  Zoom: 1.0X  11135</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11119+00		<b>Field Station#</b>	11135+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 1:48 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 1:48 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10278
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	4/20/2020 12:59 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	48.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	4/20/2020 12:59 PM	<b>Report #</b>	10278
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 205 - MP 207 Observed damaged ECD's during inspection Notified environmental foreman of damaged ECDs, items fixed the same day ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	4/20/2020 12:59 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+1	
<b>Pic 1 Desc.</b>	.6" of rain recorded @ Kow Camp		<b>Pic 2 Desc.</b>	.5" of rain recorded @ Craig Creek	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10862+00		<b>Field Station#</b>	10875+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10890+00		<b>Field Station#</b>	10925+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	Damaged P1	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/20/2020 12:59 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	4/20/2020 12:59 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10282
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	4/21/2020 3:39 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	63.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





AFE		124300137		Date/Time		4/21/2020 3:39 PM		Report #							
Pictures															
															
GPS Location				1				GPS Location				2			
Field Station#				11265+25				Field Station#				11286+00			
Pic 1 Desc.				Perimeter controls functional.				Pic 2 Desc.				Perimeter controls functional.			
															
GPS Location				3				GPS Location				4			
Field Station#				11292+80				Field Station#				11327+40			
Pic 3 Desc.				S-MM18 and controls.				Pic 4 Desc.				Turkey nest containing eggs within the buffer of S-NN12.			
															
GPS Location				5				GPS Location				6			
Field Station#				11327+85				Field Station#				11352+97			
Pic 5 Desc.				S-NN12 and controls.				Pic 6 Desc.				S-NN11 and controls.			

<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 3:39 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 3:39 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



# Visual Site Inspection Report





<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10300
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	4/22/2020 8:02 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	63.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 8:02 AM	<b>Report #</b>	10300
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Performed SWPPP inspection from MP 223.3 to MP 225.3 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	4/22/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed Apr 22, 2020 08:48:45 EDT  Position: +037.23722 / -080.359247 (+213.5ft)  Altitude: 2152ft (+32.8ft)  Datum: WGS-84  Azimuth/Bearing: 072° N72E 1280mils True (±23°)  Elevation Angle: -01°  Horizon Angle: -03.0  Zoom: 1.0X  11792+00</p> 		<p>Date &amp; Time: Wed Apr 22, 2020 08:57:27 EDT  Position: +037.239216 / -080.352623 (+19.7ft)  Altitude: 2251ft (+3.8ft)  Datum: WGS-84  Azimuth/Bearing: 102° S42W 4402mils True (±17°)  Elevation Angle: -02°  Horizon Angle: -03.0  Zoom: 1.0X  11818+00</p> 			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11792+00	<b>Field Station#</b>	11818+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.	
<p>Date &amp; Time: Wed Apr 22, 2020 09:03:19 EDT  Position: +037.288696 / -080.348510 (+13.7ft)  Altitude: 2261ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 131° S45E 3389mils True (±15°)  Elevation Angle: -01°  Horizon Angle: -05.1°  Zoom: 1.0X  11835+00</p> 		<p>Date &amp; Time: Wed Apr 22, 2020 09:07:51 EDT  Position: +037.288696 / -080.348522 (+13.1ft)  Altitude: 2126ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 050° N50E 0889mils True (±14°)  Elevation Angle: -02.0  Horizon Angle: -03.8  Zoom: 1.0X  11844+00</p> 			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11835+00	<b>Field Station#</b>	11844+00		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	Perimeter controls functional.	
<p>Date &amp; Time: Wed Apr 22, 2020 09:26:59 EDT  Position: +037.23777 / -080.339294 (+13.1ft)  Altitude: 2189ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 099° S81E 1740mils True (±15°)  Elevation Angle: -02.2  Horizon Angle: -00.5  Zoom: 1.0X  11886+00</p> 		<p>Date &amp; Time: Wed Apr 22, 2020 09:32:20 EDT  Position: +037.237321 / -080.334748 (+19.7ft)  Altitude: 2241ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 279° N81W 4960mils True (±51°)  Elevation Angle: -02.9°  Horizon Angle: -01.4  Zoom: 1.0X  11899+00</p> 			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11886+00	<b>Field Station#</b>	11899+00		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10302
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	4/22/2020 9:09 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	47.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 9:09 AM	<b>Report #</b>	10302
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11899+00 to 12005+00. MP- 225.3 to 227.3 Dry Run road is still closed to through traffic. Access roads AR-266.03 and AR-266.00 are in acceptable condition. The row is dry and in stable condition. Permanent restoration is acceptable condition with perineal vegetation filling in. Perimeter controls, Silt fence, CFS, & SSF are in acceptable condition. Karst and Karst ECD's are in acceptable condition. Water bars and level spreaders are in good condition. Wetland ECD's are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 9:09 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Apr 22, 2020, 09:14:30 EDT Position: +037.282827° N +080.325511° W (+90.40) Altitude: 2357ft (+37.4m) Datum: WGS-84 Azimuth/Bearing: 227° SSW 410mils True (+10°) Elevation Angle: -05.6° Horizon Angle: +03.6° Zoom: 1.0x AR-266.03 is in acceptable condition.</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 09:25:01 EDT Position: +037.282827° N +080.325511° W (+90.40) Altitude: 2357ft (+37.4m) Datum: WGS-84 Azimuth/Bearing: 101° SWS 283mils True (+10°) Elevation Angle: -05.6° Horizon Angle: +02.4° Zoom: 1.0x Sta#11919+00- ECD in this area is in acceptable condition. row is stable.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11900+00		<b>Field Station#</b>	11919+00	
<b>Pic 1 Desc.</b>	AR-266.03 is in acceptable condition		<b>Pic 2 Desc.</b>	Row stable, ECD's in acceptable condition.	
 <p>Date &amp; Time: Wed, Apr 22, 2020, 09:36:00 EDT Position: +037.282827° N +080.325511° W (+90.40) Altitude: 2375ft (+37.4m) Datum: WGS-84 Azimuth/Bearing: 147° SSW 330mils True (+10°) Elevation Angle: -23.7° Horizon Angle: +03.2° Zoom: 1.0x Sta#11936+00- Row vegetation is good.</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 09:42:54 EDT Position: +037.278803° N +080.327235° W (+90.40) Altitude: 2310ft (+37.5m) Datum: WGS-84 Azimuth/Bearing: 165° SWS 293mils True (+25°) Elevation Angle: -16.9° Horizon Angle: +01.3° Zoom: 1.0x Sta#11942+00- Karst ECD's are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11936+00		<b>Field Station#</b>	11942+00	
<b>Pic 3 Desc.</b>	Row vegetation looks good.		<b>Pic 4 Desc.</b>	Karst and Karst ECD's are in acceptable condition.	
 <p>Date &amp; Time: Wed, Apr 22, 2020, 09:58:57 EDT Position: +037.273771° N +080.325511° W (+90.40) Altitude: 1739ft (+210.0m) Datum: WGS-84 Azimuth/Bearing: 232° SSW 416mils True (+25°) Elevation Angle: -13.5° Horizon Angle: +02.8° Zoom: 1.0x Sta#11962+00- Contractor has cut up fallen tree &amp; removed it from ECD's.</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:21:04 EDT Position: +037.268345° N +080.316619° W (+84.1m) Altitude: 1443ft (+315.0m) Datum: WGS-84 Azimuth/Bearing: 126° SWS 224mils True (+10°) Elevation Angle: -15.0° Horizon Angle: +01.3° Zoom: 1.0x Sta#12001+00- Wetland ECD's</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11962+00		<b>Field Station#</b>	12001+00	
<b>Pic 5 Desc.</b>	Contractor has removed fallen tree from controls.		<b>Pic 6 Desc.</b>	Wetland ECD's are in acceptable condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 9:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 9:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10317
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	4/22/2020 2:08 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	43.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 2:08 PM	<b>Report #</b>	10317
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
A routine VADEQ SWPPP inspection was completed on private and JNF lands on Brush Mountain. The ROW is currently stable. No erosion is found on the ROW surface. There has not been any sediment movement beyond the approved LOD. ECDs are in place and being maintained along perimeter of LOD. Slope breakers and end treatments are functioning as designed. Resource crossings are stable with no impact from recent rain events. No vandalism or housekeeping issues were identified.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	4/22/2020 2:08 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed Apr 22, 2020, 10:20:50 EDT  Position: +037.333385 / -080.393884 (-32.81n)  Altitude: 2938ft (-39.4n)  Datum: WGS-84  Azimuth/Bearing: 300° N65W 5333mils Magnetic (-12.6)  Elevation Angle: -02.6  Horizon Angle: -01.3  Zoom: 1.0X  Brush Min. Perimeter controls in place. ROW stable. 11669+00</p> 		<p>Date &amp; Time: Wed Apr 22, 2020, 10:20:50 EDT  Position: +037.333385 / -080.393884 (-32.81n)  Altitude: 2938ft (-39.4n)  Datum: WGS-84  Azimuth/Bearing: 300° N65W 5333mils Magnetic (-12.6)  Elevation Angle: -02.6  Horizon Angle: -01.3  Zoom: 1.0X  Brush Min. Perimeter controls in place. End treatments functional. 11661+00</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11669+70	<b>Field Station#</b>	11661+00		
<b>Pic 1 Desc.</b>	Topsoil piles stable. Perimeter controls in place.	<b>Pic 2 Desc.</b>	End treatments and perimeter controls functional.		
<p>Date &amp; Time: Wed Apr 22, 2020, 10:48:39 EDT  Position: +037.333385 / -080.397461 (-32.81n)  Altitude: 2859ft (-39.4n)  Datum: WGS-84  Azimuth/Bearing: 199° S19W 5533mils Magnetic (-12.6)  Elevation Angle: -00.6  Horizon Angle: -02.6  Zoom: 1.0X  Brush Min. Perimeter controls in place. ROW stable. 11644+00</p> 		<p>Date &amp; Time: Wed Apr 22, 2020, 10:57:16 EDT  Position: +037.333385 / -080.397461 (-32.81n)  Altitude: 2859ft (-39.4n)  Datum: WGS-84  Azimuth/Bearing: 240° S40W 5533mils Magnetic (-12.6)  Elevation Angle: -02.6  Horizon Angle: -03.4  Zoom: 1.0X  Brush Min. Perimeter controls in place. ROW stable. 11634+00</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11644+00	<b>Field Station#</b>	11634+00		
<b>Pic 3 Desc.</b>	Perimeter controls in place. ROW stable.	<b>Pic 4 Desc.</b>	Perimeter controls are in place and effective.		
<p>Date &amp; Time: Wed Apr 22, 2020, 11:08:21 EDT  Position: +037.313626 / -080.398620 (-32.81n)  Altitude: 1918ft (-32.8n)  Datum: WGS-84  Azimuth/Bearing: 273° N87W 4853mils Magnetic (-12.6)  Elevation Angle: -02.6  Horizon Angle: -01.0  Zoom: 1.0X  Brush Min. S-HH18 crossing stable. 11626+04</p> 		<p>Date &amp; Time: Wed Apr 22, 2020, 11:32:16 EDT  Position: +037.313626 / -080.398620 (-32.81n)  Altitude: 1940ft (-32.5n)  Datum: WGS-84  Azimuth/Bearing: 179° S01E 3182mils Magnetic (-12.6)  Elevation Angle: -06.6  Horizon Angle: -00.6  Zoom: 2.0X  Brush Min. S-006 crossing stable m.</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11607+81		
<b>Pic 5 Desc.</b>	Buffers at S-HH18 crossing stable with ECDs in place.	<b>Pic 6 Desc.</b>	S-006 crossing is stable.		

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 2:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 2:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10334
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	4/21/2020 8:13 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11351+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11526+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	58.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 8:13 AM	<b>Report #</b>	10334
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	4/21/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Apr 21, 2020 08:41:38 EDT Position: +031.231747 / -080.459387 (+12129.00) Altitude: 2017ft (+151.5m) Datum: WGS-84 Azimuth/Bearing: 289° N71W 5138mils True (+14°) Elevation Angle: -18.5° Horizon Angle: -01.5° Zoom: 1.0X 11507+00</p>		 <p>Date &amp; Time: Tue, Apr 21, 2020 08:28:53 EDT Position: +031.231747 / -080.459387 (+12129.00) Altitude: 2000ft (+152.4m) Datum: WGS-84 Azimuth/Bearing: 240° S30W 4200mils True (+13°) Elevation Angle: -01° Horizon Angle: -00.5° Zoom: 1.0X 11503+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11507+00		<b>Field Station#</b>	11503+00	
<b>Pic 1 Desc.</b>	Clean water diversion pipe and plunge pool in place.		<b>Pic 2 Desc.</b>	Conveyance channel with rock checks in place at double cut section of ROW.	
 <p>Date &amp; Time: Tue, Apr 21, 2020 10:09:16 EDT Position: +031.231747 / -080.431677 (+108.9m) Altitude: 2084ft (+126.1m) Datum: WGS-84 Azimuth/Bearing: 300° S60W 3000mils True (+12°) Elevation Angle: -03.5° Horizon Angle: +01.6° Zoom: 1.0X 11488+00</p>		 <p>Date &amp; Time: Tue, Apr 21, 2020 11:12:41 EDT Position: +031.231747 / -080.459433 (+1728.0m) Altitude: 2143ft (+126.4m) Datum: WGS-84 Azimuth/Bearing: 330° S30W 3000mils True (+12°) Elevation Angle: -07.0° Horizon Angle: +00.4° Zoom: 1.0X 11380+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11488+00		<b>Field Station#</b>	11380+00	
<b>Pic 3 Desc.</b>	Rock lined channel in place.		<b>Pic 4 Desc.</b>	Triple barrier ECDs in place at off ROW karst feature.	
 <p>Date &amp; Time: Tue, Apr 21, 2020 10:57:52 EDT Position: +031.231747 / -080.433999 (+17362.2m) Altitude: 2143ft (+126.4m) Datum: WGS-84 Azimuth/Bearing: 310° N50W 5911mils True (+12°) Elevation Angle: -28.3° Horizon Angle: -06.5° Zoom: 1.0X 11428+00</p>		 <p>Date &amp; Time: Tue, Apr 21, 2020 11:35:42 EDT Position: +031.229677 / -080.459387 (+2010.2m) Altitude: 2084ft (+126.4m) Datum: WGS-84 Azimuth/Bearing: 226° S64W 4018mils True (+13°) Elevation Angle: -08.8° Horizon Angle: -02.1° Zoom: 1.0X 11351+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11428+00		<b>Field Station#</b>	11351+00	
<b>Pic 5 Desc.</b>	Rock lined channel in place over fill slope to prevent erosion.		<b>Pic 6 Desc.</b>	RCE in place at Old Furnace Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/21/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10335
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	4/23/2020 8:21 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	51.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 8:21 AM	<b>Report #</b>	10335
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with EI's at the work trailer          SWPPP inspection: LY28          LY28- This portion of the yard houses transport buses, five of the eight buses stored have secondary containment under them. I did not observe any fluid leaks at the time of inspection.          There are twenty nine Porta- Johns stored in the yard. Twenty three units are on trailers, six units are on the ground with containment under them.          The RCE is maintained in acceptable condition.</p> <p>LY - 28- Truck storage portion of the yard.          There are fifteen trucks in the yard, seven trucks have secondary containment under them. I did not observe any fluid leaks at the time of inspection.          Overhead utility protection is in place, flagging is wind tattered.          RCE is acceptable.          CFS perimeter controls are in acceptable condition.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 8:21 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	LY-28- Transport buses stored, secondary containment is acceptable.		<b>Pic 2 Desc.</b>	LY-28 - RCE is maintained in acceptable condition.	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	LY-28- CFS perimeter controls.		<b>Pic 4 Desc.</b>	LY-28- Truck storage, containment under trucks.	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	CFS perimeter controls, LY28		<b>Pic 6 Desc.</b>	LY-28- Pipe fittings stored in the yard.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 8:21 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 8:21 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10336
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	4/22/2020 8:33 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 8:33 AM	<b>Report #</b>	10336
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	4/22/2020 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Apr 22, 2020, 10:43:58 EDT Position: +037.23522° / -080.49580° (-118.57N) Altitude: 2028ft (-624.9m) Datum: WGS-84 Azimuth/Bearing: 125.584E 2220mils True (±12°) Elevation Angle: +14.1° Horizon Angle: +00.1° Zoom: 1.0X 11670+00</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 10:43:58 EDT Position: +037.23522° / -080.49580° (-118.57N) Altitude: 2028ft (-624.9m) Datum: WGS-84 Azimuth/Bearing: 096.584E 1707mils True (±12°) Elevation Angle: +10.3° Horizon Angle: +02.1° Zoom: 1.0X 11670+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11670+00		<b>Field Station#</b>	11740+50	
<b>Pic 1 Desc.</b>	Triple stack compost filter sock and priority one silt along LOD.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-EF65.	
 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:09:43 EDT Position: +037.248560° / -080.404269° (-10292.2N) Altitude: 2200ft (-670.3m) Datum: WGS-84 Azimuth/Bearing: 153.527E 2720mils True (±12°) Elevation Angle: +21.8° Horizon Angle: +00.6° Zoom: 1.0X 11761+00</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:09:43 EDT Position: +037.248560° / -080.404269° (-10292.2N) Altitude: 2200ft (-670.3m) Datum: WGS-84 Azimuth/Bearing: 117.543E 2080mils True (±13°) Elevation Angle: +11.1° Horizon Angle: +01.8° Zoom: 1.0X 11767+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11761+00		<b>Field Station#</b>	11767+00	
<b>Pic 3 Desc.</b>	Waterbar, sump pit and waterbar end treatment in place.		<b>Pic 4 Desc.</b>	RCE in place Main Line Valve 26.	
 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:15:19 EDT Position: +037.248560° / -080.404269° (-10292.2N) Altitude: 2010ft (-612.8m) Datum: WGS-84 Azimuth/Bearing: 011.111E 0190mils True (±13°) Elevation Angle: +10.6° Horizon Angle: +03.1° Zoom: 1.0X 11770+00</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:18:10 EDT Position: +037.248560° / -080.404269° (-10292.2N) Altitude: 2010ft (-612.8m) Datum: WGS-84 Azimuth/Bearing: 221.541W 3929mils True (±13°) Elevation Angle: +23.4° Horizon Angle: +01.2° Zoom: 1.0X 11775+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11770+00		<b>Field Station#</b>	11775+00	
<b>Pic 5 Desc.</b>	Clean water diversion pipe inlet and clean water diversion berm in place.		<b>Pic 6 Desc.</b>	Clean water diversion pipe and and plunge pool in place.	



<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10359
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	4/23/2020 3:10 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	48.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 3:10 PM	<b>Report #</b>	10359
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for LDY 28 Observed damaged ECD's during inspection of AR 234 Notified environmental foreman of damaged ECDs, items fixed the same day ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/23/2020 3:10 PM	Report #	
Pictures					
		<p>Date &amp; Time: Thu Apr 23 2020 09:27:25 EDT  Position: -037°21'42.88" / -080°40'39.44" (-15.9M)  Altitude: 1210ft (-11.0M)  Datum: WGS-84  Azimuth: Bearing: 082° N28E 1173mils Error: Error  Elevation Grade: -000%  Horizon Grade: -000%  Zoom: 1.00X  234</p> 		<p>Date &amp; Time: Thu Apr 23 2020 09:27:53 EDT  Position: -037°21'42.10" / -080°40'37.29" (-15.9M)  Altitude: 1210ft (-11.0M)  Datum: WGS-84  Azimuth: Bearing: 082° N28E 1238mils Error: Error  Elevation Grade: -000%  Horizon Grade: -000%  Zoom: 1.00X  234</p> 	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
		<p>Date &amp; Time: Thu Apr 23 2020 09:45:00 EDT  Position: -037°22'36.39" / -080°40'44.38" (-15.9M)  Altitude: 2120ft (-11.5M)  Datum: WGS-84  Azimuth: Bearing: 222° S22W 222mils Error: Error  Elevation Grade: -03%  Horizon Grade: -01%  Zoom: 1.00X  234</p> 		<p>Date &amp; Time: Thu Apr 23 2020 09:45:00 EDT  Position: -037°22'36.39" / -080°40'44.38" (-15.9M)  Altitude: 2030ft (-11.4M)  Datum: WGS-84  Azimuth: Bearing: 129° S56E 222mils Error: Error  Elevation Grade: -03%  Horizon Grade: -00%  Zoom: 1.00X  234</p> 	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	2+34		Field Station#	2+34	
Pic 3 Desc.	Damaged P1		Pic 4 Desc.	Damaged P1	
		<p>Date &amp; Time: Thu Apr 23 2020 09:45:00 EDT  Position: -037°21'42.88" / -080°40'39.44" (-15.9M)  Altitude: 1630ft (-11.1M)  Datum: WGS-84  Azimuth: Bearing: 082° N28E 1434mils Error: Error  Elevation Grade: -000%  Horizon Grade: -000%  Zoom: 1.00X  234</p> 		<p>Date &amp; Time: Thu Apr 23 2020 09:45:00 EDT  Position: -037°21'42.88" / -080°40'39.44" (-15.9M)  Altitude: 2030ft (-11.4M)  Datum: WGS-84  Azimuth: Bearing: 082° N28E 1434mils Error: Error  Elevation Grade: -000%  Horizon Grade: -000%  Zoom: 1.00X  234</p> 	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	2+34	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 3:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 3:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10395
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	4/24/2020 3:08 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11024+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.70
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Broad-Based Dip	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	4/24/2020 3:08 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Apr 24, 2020 11:53:33 EDT Position: +037 23272° / -080 56619° (±16.4ft) Altitude: 2265ft (±39.6ft) Datum: WGS-84 Azimuth/Bearing: 099° S81E 1760mils True (±10°) Elevation Angle: -34.5° Horizon Angle: -109.8° Zoom: 1.0X Stream S-RR-5 Sta#11016+00 - Stream &amp; controls are in acceptable condition.</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 12:14:41 EDT Position: +037 232605° / -080 566827° (±16.4ft) Altitude: 2265ft (±39.6ft) Datum: WGS-84 Azimuth/Bearing: 079° N49E 1494mils True (±10°) Elevation Angle: -11.5° Horizon Angle: -108.3° Zoom: 1.0X Stream E25 - Sta#10986+00 - Stream &amp; controls are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11016+00		<b>Field Station#</b>	10986+00	
<b>Pic 1 Desc.</b>	Stream S-RR-5		<b>Pic 2 Desc.</b>	Stream S-E25	
 <p>Date &amp; Time: Fri, Apr 24, 2020 12:15:39 EDT Position: +037 232505° / -080 554822° (±16.4ft) Altitude: 2267ft (±39.6ft) Datum: WGS-84 Azimuth/Bearing: 308° N51W 563mils True (±10°) Elevation Angle: -15.7° Horizon Angle: -103.3° Zoom: 1.0X Stream E24 - Sta#10985+00 - Stream &amp; controls are in acceptable condition.</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 12:11:03 EDT Position: +037 232619° / -080 571797° (±16.4ft) Altitude: 2327ft (±39.6ft) Datum: WGS-84 Azimuth/Bearing: 092° S92E 1653mils True (±10°) Elevation Angle: -02.2° Horizon Angle: -02.4° Zoom: 2.0X Sta#10965+00 - MP 207.5 - Sensitive resource, bat habitat, ECD's.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10985+00		<b>Field Station#</b>	10965+00	
<b>Pic 3 Desc.</b>	Stream S-E24		<b>Pic 4 Desc.</b>	Sensitive resource ECD's	
 <p>Date &amp; Time: Fri, Apr 24, 2020 12:37:01 EDT Position: +037 232599° / -080 575096° (±16.4ft) Altitude: 2239ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 200° N40W 5333mils True (±10°) Elevation Angle: -15.0° Horizon Angle: -100.6° Zoom: 2.0X Sta#10950+00 to 10956+00 - ECD's damaged by cattle have been replaced at Doe Creek Farms.</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 12:40:42 EDT Position: +037 232599° / -080 575096° (±16.4ft) Altitude: 2239ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 114° S46E 2027mils True (±10°) Elevation Angle: -26.2° Horizon Angle: -101.8° Zoom: 2.0X Sta#10950+00 - gates to row have been padlocked.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10956+00		<b>Field Station#</b>	10950+00	
<b>Pic 5 Desc.</b>	Contractor has replaced damaged ECD's from sta#10950+00 to 10956+00		<b>Pic 6 Desc.</b>	Cattle crossing gate padlocked, Doe Creek Farms.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 3:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 3:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10396
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	4/24/2020 7:22 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	110023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Temporary Diversion Berm	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 7:22 AM	<b>Report #</b>	10396
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245. No issues were located. Vegetation or stabilization sufficient. All perimeter controls, ECDs and BMPs are functional. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		Date/Time	Report #
124300137		4/24/2020 7:22 AM	
Pictures			
			
GPS Location		GPS Location	
1		2	
Field Station#		Field Station#	
11025+50		11034+00	
Pic 1 Desc.		Pic 2 Desc.	
S-IJ18 and controls.		RoW conditions and controls.	
			
GPS Location		GPS Location	
3		4	
Field Station#		Field Station#	
11048+00		11050+14	
Pic 3 Desc.		Pic 4 Desc.	
RoW conditions and controls.		S-IJ16B and S-IJ17 and controls.	
			
GPS Location		GPS Location	
5		6	
Field Station#		Field Station#	
11055+00		11064+50	
Pic 5 Desc.		Pic 6 Desc.	
RoW conditions and controls.		RoW conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 7:22 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 7:22 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10397
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	4/24/2020 4:05 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 4:05 PM	<b>Report #</b>	10397
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 205 - MP 207 Observed no damaged ECD's during inspection Recorded video footage of streams for future bore information ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	4/24/2020 4:05 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Apr 24, 2020 11:25:31 EDT Position: +037°12'22.23" / -080°39'15.33" (+7881.4m) Altitude: 1791ft (+70.7m) Datum: WGS-84 Azimuth/Bearing: 360° N00W 6400mils Error/ Error Elevation Grade: +036° Horizon Grade: +001° Zoom: 1.0X 10858</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 11:25:38 EDT Position: +037°12'23.23" / -080°39'15.33" (+7881.4m) Altitude: 1791ft (+70.7m) Datum: WGS-84 Azimuth/Bearing: 360° N00W 6400mils Error/ Error Elevation Grade: +036° Horizon Grade: +001° Zoom: 1.0X 10862</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10858+00		<b>Field Station#</b>	10862+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
 <p>Date &amp; Time: Fri, Apr 24, 2020 11:36:44 EDT Position: +037°20'13.86" / -080°39'09.14" (+8147m) Altitude: 2349ft (+71.2m) Datum: WGS-84 Azimuth/Bearing: 312° N47W 5564mils Error/ Error Elevation Grade: +040° Horizon Grade: +008° Zoom: 1.0X 10872</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 11:49:10 EDT Position: +037°20'13.77" / -080°39'09.14" (+8147m) Altitude: 2349ft (+71.2m) Datum: WGS-84 Azimuth/Bearing: 312° N47W 5564mils Error/ Error Elevation Grade: +040° Horizon Grade: +008° Zoom: 1.0X 11890</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10872+00		<b>Field Station#</b>	11890+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
 <p>Date &amp; Time: Fri, Apr 24, 2020 15:07:13 EDT Position: +037°16'4.93" / -080°15'13.67" (+822.5m) Altitude: 1612ft (+492.0m) Datum: WGS-84 Azimuth/Bearing: 355° N35W 5044mils Error/ Error Elevation Grade: +003° Horizon Grade: +003° Zoom: 1.0X 8" cal</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 11:42:38 EDT Position: +037°20'5.74" / -080°09'48.32" (+21.2m) Altitude: 2146ft (+65.7m) Datum: WGS-84 Azimuth/Bearing: 307° S30W 6142mils Error/ Error Elevation Grade: +003° Horizon Grade: +003° Zoom: 1.0X 50</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+1	
<b>Pic 5 Desc.</b>	.8" of rain recorded @ Catawba		<b>Pic 6 Desc.</b>	.5" of rain recorded @ Kow Camp	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 4:05 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 4:05 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10521
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	4/24/2020 3:22 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	4/24/2020 3:22 PM	<b>Report #</b>	10521
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. Checked rain gauges at Access Road 234 - 0.6 inches, Buffalo Anklets Road - 0.5 inches and Mount Tabor Road - 0.8 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 4/24/2020 3:22 PM		Report #	
Pictures					
 <p>Date &amp; Time: Fri, Apr 24, 2020 12:21:23 EDT Position: +037 296113 / -080 367825 (+49.1ft) Altitude: 2015ft (+97.7ft) Datum: WGS-84 Azimuth/Bearing: 079 N 79E 1004mils True (+10) Elevation Angle: -01.4 Horizon Angle: -00.6 Zoom: 1.0X 10696+00</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 13:00:43 EDT Position: +037 349238 / -080 652884 (+15.4ft) Altitude: 2056ft (+11.2ft) Datum: WGS-84 Azimuth/Bearing: 103 S 72E 1920mils True (+10) Elevation Angle: -11.2 Horizon Angle: -03.0 Zoom: 1.0X 10696+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	10696+00	
Pic 1 Desc.	Rain gauge at Access Road 234 reads 0.6 inches.		Pic 2 Desc.	Rain gauge at Buffalo Anklets Road reads 0.5 inches.	
 <p>Date &amp; Time: Fri, Apr 24, 2020 14:47:58 EDT Position: +037 296113 / -080 367825 (+49.1ft) Altitude: 2015ft (+97.7ft) Datum: WGS-84 Azimuth/Bearing: 079 N 79E 1004mils True (+10) Elevation Angle: -02.3 Horizon Angle: -00.0 Zoom: 1.0X 10696+00</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 13:00:43 EDT Position: +037 349238 / -080 652884 (+15.4ft) Altitude: 2056ft (+11.2ft) Datum: WGS-84 Azimuth/Bearing: 103 S 72E 1920mils True (+10) Elevation Angle: -11.2 Horizon Angle: -03.0 Zoom: 1.0X 10696+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	10696+00	
Pic 3 Desc.	Rain gauge at Mount Tabor Road reads 0.8 inches.		Pic 4 Desc.	RCE in place at Buffalo Anklets Road.	
 <p>Date &amp; Time: Fri, Apr 24, 2020 12:50:38 EDT Position: +037 346157 / -080 652269 (+16.1ft) Altitude: 2268ft (+38.4ft) Datum: WGS-84 Azimuth/Bearing: 111 S 49E 1973mils True (+10) Elevation Angle: -05.6 Horizon Angle: -04.2 Zoom: 1.0X 10698+00 S-G32</p>		 <p>Date &amp; Time: Fri, Apr 24, 2020 12:55:53 EDT Position: +037 346452 / -080 647451 (+86.9ft) Altitude: 2278ft (+38.7ft) Datum: WGS-84 Azimuth/Bearing: 100 S 80E 1778mils True (+14) Elevation Angle: -12.7 Horizon Angle: -11.9 Zoom: 1.0X 10712+50 S-G33</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10698+00		Field Station#	10712+50	
Pic 5 Desc.	Sensitive resource buffer in place at stream S-G32.		Pic 6 Desc.	Sensitive resource buffer in place at stream S-G33.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 3:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/24/2020 3:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10731
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	4/23/2020 9:47 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Secondary Containment	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 9:47 AM	<b>Report #</b>	10731
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 4/23/2020 9:47 AM		Report #	
Pictures					
<p>Date &amp; Time Thu, Apr 23, 2020, 10:44:38 EDT Position: +38.216287° / -88.885877° (+12.37) Altitude: 1794' (+11.37) Datum: WGS-84 Azimuth/Heading: 231° 30'W 310mils True (+10°) Elevation Angle: +32.2° Horizon Angle: +01.8° Zoom: 1.0X LIDY 26</p> 		<p>Date &amp; Time Thu, Apr 23, 2020, 10:44:38 EDT Position: +38.216287° / -88.885877° (+12.37) Altitude: 1794' (+11.37) Datum: WGS-84 Azimuth/Heading: 231° 30'W 310mils True (+10°) Elevation Angle: +32.2° Horizon Angle: +01.8° Zoom: 1.0X LIDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Dumpsters being utilized for trash management.		Pic 2 Desc.	18 inch compost filter sock in place along LOD.	
<p>Date &amp; Time Thu, Apr 23, 2020, 10:45:11 EDT Position: +38.216287° / -88.885877° (+12.37) Altitude: 1800' (+11.40) Datum: WGS-84 Azimuth/Heading: 231° 59'W 306mils True (+10°) Elevation Angle: +32.2° Horizon Angle: +01.8° Zoom: 1.0X LIDY 26</p> 		<p>Date &amp; Time Thu, Apr 23, 2020, 10:45:04 EDT Position: +38.216287° / -88.885877° (+12.37) Altitude: 1800' (+11.40) Datum: WGS-84 Azimuth/Heading: 100° 29'W 180mils True (+10°) Elevation Angle: +30.8° Horizon Angle: +00.8° Zoom: 1.0X LIDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Checked staged equipment for leaks.		Pic 4 Desc.	Secondary containment in place under fuel cell.	
<p>Date &amp; Time Thu, Apr 23, 2020, 10:45:35 EDT Position: +38.216287° / -88.885877° (+12.37) Altitude: 1794' (+11.37) Datum: WGS-84 Azimuth/Heading: 133° 53'E 278mils True (+10°) Elevation Angle: +32.2° Horizon Angle: +01.8° Zoom: 1.0X LIDY 26</p> 		<p>Date &amp; Time Thu, Apr 23, 2020, 10:45:35 EDT Position: +38.216287° / -88.885877° (+12.37) Altitude: 1794' (+11.37) Datum: WGS-84 Azimuth/Heading: 133° N33E 180mils True (+10°) Elevation Angle: +32.2° Horizon Angle: +00.8° Zoom: 1.0X LIDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Checked staged equipment for leaks.		Pic 6 Desc.	RCE in place at Lay Down Yard 26 entrance.	

<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 9:47 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	4/23/2020 9:47 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10733
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	4/22/2020 9:54 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 9:54 AM	<b>Report #</b>	10733
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 9:54 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Apr 22, 2020, 10:43:53 EDT Position: +037.23522° / -080.49580° (-116.57N) Altitude: 2202ft (+166.3ft) Datum: WGS-84 Azimuth/Bearing: 125.58SE 2202mils True (+12) Elevation Angle: +14.1 Horizon Angle: +02.1 Zoom: 1.0X 11669+00</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 10:43:53 EDT Position: +037.23522° / -080.49580° (-116.57N) Altitude: 2202ft (+166.3ft) Datum: WGS-84 Azimuth/Bearing: 096.58SE 1707mils True (+12) Elevation Angle: +10.3 Horizon Angle: +02.1 Zoom: 1.0X 11740+43</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11669+00	<b>Field Station#</b>	11740+43	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 1 Desc.</b>	Triple stack compost filter sock and priority one silt fence in place along LOD.	<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-EF65.	<b>GPS Location</b>	See photo for GPS location.
 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:06:43 EDT Position: +037.24856° / -080.40426° (-116.29N) Altitude: 2200ft (+166.3ft) Datum: WGS-84 Azimuth/Bearing: 153.527E 2720mils True (+12) Elevation Angle: +21.8 Horizon Angle: +00.6 Zoom: 1.0X 11761+00</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:07:53 EDT Position: +037.25031° / -080.35632° (-116.17N) Altitude: 2188ft (+166.3ft) Datum: WGS-84 Azimuth/Bearing: 117.54SE 2080mils True (+13) Elevation Angle: +11.1 Horizon Angle: +01.8 Zoom: 1.0X 11767+00</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11761+00	<b>Field Station#</b>	11767+00	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 3 Desc.</b>	Waterbar, sump pit, and waterbar end treatment in place.	<b>Pic 4 Desc.</b>	RCE in place Main Line Valve 26.	<b>GPS Location</b>	See photo for GPS location.
 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:15:15 EDT Position: +037.24772° / -080.36523° (-116.44N) Altitude: 2010ft (+154.9ft) Datum: WGS-84 Azimuth/Bearing: 011.11E 0196mils True (+13) Elevation Angle: +10.6 Horizon Angle: +03.1 Zoom: 1.0X 11770+00</p>		 <p>Date &amp; Time: Wed, Apr 22, 2020, 11:18:10 EDT Position: +037.24772° / -080.36523° (-116.44N) Altitude: 2010ft (+154.9ft) Datum: WGS-84 Azimuth/Bearing: 221.54W 3929mils True (+13) Elevation Angle: +23.4 Horizon Angle: +01.2 Zoom: 1.0X 11775+00</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11770+00	<b>Field Station#</b>	11775+00	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 5 Desc.</b>	Clean water diversion pipe and clean water diversion berm in place.	<b>Pic 6 Desc.</b>	Clean water diversion pipe and plunge pool in place.	<b>GPS Location</b>	See photo for GPS location.



<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 9:54 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	4/22/2020 9:54 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		