



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11036
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/18/2020 12:21 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 12:21 PM	<b>Report #</b>	11036
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300137		Date/Time		5/18/2020 12:21 PM		Report #							
Pictures															
				<p>Date &amp; Time: Mon May 18, 2020 10:58:50 EDT Position: -637.351062, -680.649218, (+53.3N) Altitude: 2262ft (+22.6m) Datum: WGS-84 Azimuth/Bearing: 162.518E 2880mils True (+14.1) Elevation Angle: -07.6 Horizon Angle: -02.9 Zoom: 1.0X 10710+00</p>								<p>Date &amp; Time: Mon May 18, 2020 11:02:17 EDT Position: -637.351062, -680.649218, (+53.3N) Altitude: 2262ft (+22.6m) Datum: WGS-84 Azimuth/Bearing: 119.561E 2116mils True (+6.7) Elevation Angle: -12.2 Horizon Angle: -07.4 Zoom: 1.0X 10712+50 S-G33</p>			
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				10710+00				Field Station#				10712+50			
Pic 1 Desc.				CFS checks in place along access road 241,04.				Pic 2 Desc.				Sensitive resource buffer in place at stream S-G33.			
				<p>Date &amp; Time: Mon May 18, 2020 11:06:03 EDT Position: -637.342175, -680.650027, (+53.3N) Altitude: 2105ft (+21.1m) Datum: WGS-84 Azimuth/Bearing: 108.572E 1920mils True (+18.1) Elevation Angle: -02.0 Horizon Angle: -02.5 Zoom: 1.0X 10698+00 S-G32</p>								<p>Date &amp; Time: Mon May 18, 2020 11:06:45 EDT Position: -637.342175, -680.650027, (+53.3N) Altitude: 2105ft (+21.1m) Datum: WGS-84 Azimuth/Bearing: 109.588E 1920mils True (+18.1) Elevation Angle: -14.2 Horizon Angle: -01.5 Zoom: 1.0X 10700+00</p>			
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				10698+00				Field Station#				10700+00			
Pic 3 Desc.				Sensitive resource buffer in place at stream S-G32.				Pic 4 Desc.				Travel lane stabilized with ECB and waterbar in place.			
				<p>Date &amp; Time: Mon May 18, 2020 11:11:42 EDT Position: -637.349237, -680.652884, (+53.3N) Altitude: 2074ft (+20.7m) Datum: WGS-84 Azimuth/Bearing: 091.589E 1618mils True (+10.1) Elevation Angle: -08.1 Horizon Angle: -04.1 Zoom: 1.0X 10695+00</p>								<p>Date &amp; Time: Mon May 18, 2020 11:15:47 EDT Position: -637.351728, -680.665493, (+53.3N) Altitude: 2217ft (+22.2m) Datum: WGS-84 Azimuth/Bearing: 300.000W 5333mils True (+10.0) Elevation Angle: -1.8 Horizon Angle: -15.3 Zoom: 1.0X 10670+00</p>			
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				10696+00				Field Station#				10670+00			
Pic 5 Desc.				RCE in place at Buffalo Anklets Road.				Pic 6 Desc.				Reinforced super silt fence in place along LOD.			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 12:21 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 12:21 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11047
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/18/2020 8:02 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	74.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, May 18, 2020 08:30:00 EDT  Position: +037.322477 / -080.547934 / (+19.7m)  Altitude: 2405ft (+10.3m)  Datum: WGS-84  Azimuth/Bearing: 344° N16°W 16.16mils True (+13°)  Elevation Angle: -05.1°  Horizon Angle: -00.0°  Zoom: 1.0x  11025+00</p> 		<p>Date &amp; Time: Mon, May 18, 2020 09:02:26 EDT  Position: +037.320458 / -080.541625 / (+4909.3m)  Altitude: 2420ft (+32.2m)  Datum: WGS-84  Azimuth/Bearing: 180° S01E 00.00mils True (+0°)  Elevation Angle: -00.0°  Horizon Angle: -00.0°  Zoom: 1.0x  11034+00</p> 			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11025+50	<b>Field Station#</b>	11034+00		
<b>Pic 1 Desc.</b>	S-IJ18 and controls.	<b>Pic 2 Desc.</b>	RoW conditions and controls.		
<p>Date &amp; Time: Mon, May 18, 2020 09:10:31 EDT  Position: +037.318049 / -080.547958 / (+157.9m)  Altitude: 1936ft (+10.4m)  Datum: WGS-84  Azimuth/Bearing: 284° N97W 499mils True (+12.4°)  Elevation Angle: +13.7°  Horizon Angle: -00.1°  Zoom: 1.0x  11049+00</p> 		<p>Date &amp; Time: Mon, May 18, 2020 09:11:00 EDT  Position: +037.318582 / -080.547643 / (+19.7m)  Altitude: 2077ft (+10.4m)  Datum: WGS-84  Azimuth/Bearing: 353° N87W 622mils True (+12.4°)  Elevation Angle: +21.5°  Horizon Angle: -00.0°  Zoom: 1.0x  11050+00</p> 			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11049+00	<b>Field Station#</b>	11050+10		
<b>Pic 3 Desc.</b>	RoW conditions and controls.	<b>Pic 4 Desc.</b>	S-IJ16B and S-IJ17 and controls.		
<p>Date &amp; Time: Mon, May 18, 2020 09:10:16 EDT  Position: +037.318070 / -080.546070 / (+105.0m)  Altitude: 2070ft (+12.3m)  Datum: WGS-84  Azimuth/Bearing: 161° S19E 262mils True (+13.4°)  Elevation Angle: -02.9°  Horizon Angle: -00.5°  Zoom: 1.0x  11055+00</p> 		<p>Date &amp; Time: Mon, May 18, 2020 09:19:29 EDT  Position: +037.318221 / -080.546049 / (+19.7m)  Altitude: 2069ft (+10.0m)  Datum: WGS-84  Azimuth/Bearing: 315° N45W 560mils True (+12.4°)  Elevation Angle: +17.1°  Horizon Angle: -00.0°  Zoom: 1.0x  11064+50</p> 			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11055+00	<b>Field Station#</b>	11064+50		
<b>Pic 5 Desc.</b>	RoW conditions and controls.	<b>Pic 6 Desc.</b>	RoW conditions and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11049
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	5/18/2020 8:26 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/18/2020 8:26 AM	<b>Report #</b>	11049
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
EI meeting at the work trailer. SWPPP inspection: Sta#11023+80 to 10930+00. MP- 208.6 to 206.2 The row is dry and in stable condition. Temporary stabilization is acceptable. Water bars are stable. Water bar sumps and end treatments are in acceptable condition. Perimeter controls, P1 silt fence, CFS, & SSF are in acceptable condition. Streams-S-IJ18, S-RR5, S-E24, S-E25 - equipment bridges, buffers, signage and ECD's are in acceptable condition, no sediment impact to streams. Sensitive resource area is in acceptable condition. ( Sta# 10965+00 ). Doe Creek Farms- The landowner has cut the chain on the paddocked gates and allowed cattle back onto the row. AR-244.00 and Doe Creek RCE are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 5/18/2020 8:26 AM		Report #	
Pictures					
 <p>Date &amp; Time: Mon, May 18, 2020 09:29:02 EDT Position: +037 32701° / -080 55279° (+16.4ft) Altitude: 2330ft (+39.2ft) Datum: WGS-84 Azimuth/Bearing: 316° N42W 5453mils True (+10°) Elevation Angle: -15° Horizon Angle: +01.7° Zoom: 1.0x Start 1024+00 - AB Slope into Stream S-IJ18</p>		 <p>Date &amp; Time: Mon, May 18, 2020 09:28:19 EDT Position: +037 32721° / -080 55021° (+16.4ft) Altitude: 2330ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 226° N42W 4900mils True (+10°) Elevation Angle: -22° Horizon Angle: +02.7° Zoom: 1.0x Start 11014+00 - Slope into stream S-RR5 is stable</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11024+00		Field Station#	11017+00	
Pic 1 Desc.	Stream S-IJ18		Pic 2 Desc.	Stream S- RR5	
 <p>Date &amp; Time: Mon, May 18, 2020 10:05:31 EDT Position: +037 32587° / -080 55003° (+16.4ft) Altitude: 2340ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 201° N39W 4676mils True (+05°) Elevation Angle: +00.4° Horizon Angle: +00.7° Zoom: 1.0x Start 10993+00 - Perimeter controls on steep slope</p>		 <p>Date &amp; Time: Mon, May 18, 2020 10:05:32 EDT Position: +037 32587° / -080 55003° (+16.4ft) Altitude: 2340ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 281° N79W 4676mils True (+05°) Elevation Angle: +00.1° Horizon Angle: +00.7° Zoom: 1.0x Start 10986+00 - Stream S-E25</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	10993+00		Field Station#	10986+00	
Pic 3 Desc.	P1 perimeter controls on steep slope.		Pic 4 Desc.	Stream S-E25	
 <p>Date &amp; Time: Mon, May 18, 2020 10:04:06 EDT Position: +037 32447° / -080 56052° (+16.4ft) Altitude: 2401ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 288° N45W 5016mils True (+10°) Elevation Angle: -07.3° Horizon Angle: +01.8° Zoom: 1.0x Start 10985+00 - Stream S-E24</p>		 <p>Date &amp; Time: Mon, May 18, 2020 10:14:24 EDT Position: +037 32447° / -080 56052° (+16.4ft) Altitude: 2401ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 250° N59W 4446mils True (+25°) Elevation Angle: -18.6° Horizon Angle: -00.6° Zoom: 1.0x Start 10976+00 - 18\"</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	10985+00		Field Station#	10976+00	
Pic 5 Desc.	Stream S- E24		Pic 6 Desc.	18" CFS triple stack perimeter controls.	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/18/2020 8:26 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10966+00	<b>Field Station#</b>	10953+00		
<b>Pic 7 Desc.</b>	Row on Doe Creek Farms	<b>Pic 8 Desc.</b>	Cattle grazing on row, Landowner cut chain on gates to row.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 8:26 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11062
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	5/18/2020 3:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/18/2020 3:14 PM	<b>Report #</b>	11062
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 205 -MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 3:14 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10858+00		<b>Field Station#</b>	10876+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10889+00		<b>Field Station#</b>	10898+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10916+00		<b>Field Station#</b>	10920+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	



<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 3:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/18/2020 3:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11081
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	5/19/2020 8:05 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	51.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			



## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/19/2020 8:05 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, May 19, 2020, 09:46:41 EDT  Position: +402.2029161° N -080.9002225° W (+32.200)  Altitude: 2107ft (+639.40)  Datum: WGS-84  Azimuth/Bearing: 198° S18W, 3520mils True (+25)  Elevation Angle: -13.6  Horizon Angle: +00.9  Zoom: 1.0x  Staff: 11223+00 - P1 perimeter controls.</p> 		<p>Date &amp; Time: Tue, May 19, 2020, 09:11:07 EDT  Position: +402.201474° N -080.902535° W (+32.80)  Altitude: 2080ft (+634.00)  Datum: WGS-84  Azimuth/Bearing: 198° S18W, 3520mils True (+25)  Elevation Angle: -11.6  Horizon Angle: +02.9  Zoom: 1.0x  Staff: 11225+00 - Slope drain pipe, end treatment, rock channel.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11232+00	<b>Field Station#</b>	11225+00		
<b>Pic 1 Desc.</b>	P1 perimeter controls are in acceptable condition.	<b>Pic 2 Desc.</b>	Slope drain pipe, end treatment, rock channel.		
<p>Date &amp; Time: Tue, May 19, 2020, 09:45:00 EDT  Position: +402.2000000° N -080.9000000° W (+32.0000000)  Altitude: 2067ft (+630.00)  Datum: WGS-84  Azimuth/Bearing: 198° S18W, 3520mils True (+25)  Elevation Angle: -13.6  Horizon Angle: +00.9  Zoom: 1.0x  Staff: 11202+00 - CFS perimeter controls.</p> 		<p>Date &amp; Time: Tue, May 19, 2020, 09:45:00 EDT  Position: +402.2000000° N -080.9000000° W (+32.0000000)  Altitude: 2067ft (+630.00)  Datum: WGS-84  Azimuth/Bearing: 198° S18W, 3520mils True (+25)  Elevation Angle: -13.6  Horizon Angle: +00.9  Zoom: 1.0x  Staff: 11195+00 - SSF perimeter controls.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11202+00	<b>Field Station#</b>	11195+00		
<b>Pic 3 Desc.</b>	CFS perimeter controls are in acceptable condition.	<b>Pic 4 Desc.</b>	SSF perimeter controls are in acceptable condition.		
<p>Date &amp; Time: Tue, May 19, 2020, 09:37:03 EDT  Position: +402.201474° N -080.902535° W (+32.80)  Altitude: 2080ft (+634.00)  Datum: WGS-84  Azimuth/Bearing: 198° S18W, 3520mils True (+25)  Elevation Angle: -11.6  Horizon Angle: +02.9  Zoom: 1.0x  Staff: 11184+00 - CWD pipe &amp; plunge pool.</p> 		<p>Date &amp; Time: Tue, May 19, 2020, 09:37:03 EDT  Position: +402.201474° N -080.902535° W (+32.80)  Altitude: 2080ft (+634.00)  Datum: WGS-84  Azimuth/Bearing: 198° S18W, 3520mils True (+25)  Elevation Angle: -11.6  Horizon Angle: +02.9  Zoom: 1.0x  Staff: 11184+00 - CWD pipe &amp; plunge pool.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11191+00	<b>Field Station#</b>	11184+00		
<b>Pic 5 Desc.</b>	Drainage feature and ECD's are in acceptable condition.	<b>Pic 6 Desc.</b>	CWD pipe and plunge pool are in good condition.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/19/2020 8:05 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p> <small> Date &amp; Time: Tue May 19, 2020, 10:05:34 EDT  Position: +037.317288° N +080.520380° W (s=12.42)  Altitude: 2120ft (+131ft)  Datum: WGS-84  Azimuth/Bearing: 288° N77W 533inile True (s=5)  Elevation Angle: +15.5  Horizon Angle: +04.2  Zoom: 1.0X  AR-244.00 rain gauge reading: 0.60" </small> </p>		 <p> <small> Date &amp; Time: Tue May 19, 2020, 10:06:10 EDT  Position: +037.335163° N +080.522711° W (s=12.42)  Altitude: 2128ft (+197ft)  Datum: WGS-84  Azimuth/Bearing: 300° N65W 638inile True (s=10)  Elevation Angle: +07.3  Horizon Angle: +01.2  Zoom: 1.0X  Kow Camp rain gauge reading: 0.50" </small> </p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	10888+00		
<b>Pic 7 Desc.</b>	AR-244.00 rain gauge reading- 0.60"	<b>Pic 8 Desc.</b>	Kow Camp rain gauge reading- 0.50"		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 8:05 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11095
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/19/2020 1:03 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+16
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	1.50
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Broad-Based Dip	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 1:03 PM	<b>Report #</b>	11095
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. Deficiencies located at station numbers; 11438+00 - cattle damaged priority one silt fence. 11430+00 - Holes in priority one silt fence. 11418+00 - Priority one silt fence stake broke. Checked rain gauges at Stevers Gap Road - 1.0 inches, Mount Tabor Road - 1.2 inches, and Catawba Road - 1.5 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/19/2020 1:03 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11489+00		<b>Field Station#</b>	11767+00	
<b>Pic 1 Desc.</b>	Rain gauge at Stevers Gap Road reads 1 inch.		<b>Pic 2 Desc.</b>	Rain gauge at Mount Tabor Road 1.2 inches.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11990+00		<b>Field Station#</b>	11489+00	
<b>Pic 3 Desc.</b>	Rain gauge at Catawba Road reads 1.5 inches.		<b>Pic 4 Desc.</b>	RCE in place Stevers Gap Road.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11418+00		<b>Field Station#</b>	11380+00	
<b>Pic 5 Desc.</b>	Broken priority one silt fence stake.		<b>Pic 6 Desc.</b>	Triple barrier ECDs in place at off ROW karst feature.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 1:03 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 1:03 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11098
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/19/2020 2:22 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 2:22 PM	<b>Report #</b>	11098
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Gathered rain gauge data from LDY 37 (0.45") and Pocahontas rd (0.4"). Performed SWPPP inspection from MP 213 to MP 214.8. Inspection performed during ongoing rain event. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/19/2020 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11265+00	<b>Field Station#</b>	11286+00		
<b>Pic 1 Desc.</b>	Perimeter controls functional.	<b>Pic 2 Desc.</b>	Perimeter controls functional.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11292+80	<b>Field Station#</b>	11303+00		
<b>Pic 3 Desc.</b>	S-MM18 and controls.	<b>Pic 4 Desc.</b>	Perimeter controls functional.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11327+85	<b>Field Station#</b>	11352+97		
<b>Pic 5 Desc.</b>	S-NN12 and controls.	<b>Pic 6 Desc.</b>	S-NN11.		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11104
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	5/19/2020 3:03 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	51.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 3:03 PM	<b>Report #</b>	11104
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 209 - MP 211.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/19/2020 3:03 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11068+00		<b>Field Station#</b>	11085+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11101+00		<b>Field Station#</b>	111139+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+1	
<b>Pic 5 Desc.</b>	.3" of rain recorded @ AR 234		<b>Pic 6 Desc.</b>	.3" of rain recorded @ Buffalo Anklets AR	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 3:03 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/19/2020 3:03 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11114
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	5/20/2020 7:59 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 7:59 AM	<b>Report #</b>	11114
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met at Winding Way with EI's SWPPP inspection: Sta#11899+99 to 12005+00 Rain over night and continued throughout the day, this inspection area received 1.60" & 1.50" yesterday. The row is saturated but stable, with no sediment movement. Permanent stabilization is acceptable with very good vegetation. Perimeter controls, silt fence, CFS, & SSF are in acceptable condition. Karst's and Karst ECD's are in acceptable condition. Wetland at sta#12001+00- Silt fence has been replaced with CFS. AR-266.03 and AR-266.00 are in acceptable condition. PPL environmental crew were checking access roads.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/20/2020 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed May 20, 2020 10:30:05 EDT Position: +037°28'30N / -080°31'25W (+6581.7ft) Altitude: 2181ft (+124.7m) Datum: WGS-84 Azimuth/Bearing: 288° N72W 5120mils True (+10°) Elevation Angle: -20.7° Horizon Angle: +03.2° Zoom: 1.0X AR-266.03-</p>		 <p>Date &amp; Time: Wed May 20, 2020 10:34:55 EDT Position: +037°28'30N / -080°31'25W (+6581.7ft) Altitude: 2181ft (+124.7m) Datum: WGS-84 Azimuth/Bearing: 209° S29W 3718mils True (+10°) Elevation Angle: -17.3° Horizon Angle: +02.4° Zoom: 1.0X Karst</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11900+00	<b>Field Station#</b>	11942+00		
<b>Pic 1 Desc.</b>	AR-266.03	<b>Pic 2 Desc.</b>	Karst and Karst ECD's		
 <p>Date &amp; Time: Wed May 20, 2020 11:05:43 EDT Position: +037°27'45N / -080°31'21W (+6581.7ft) Altitude: 1964ft (+196.3m) Datum: WGS-84 Azimuth/Bearing: 189° S29W 3340mils True (+10°) Elevation Angle: -17.4° Horizon Angle: +01.5° Zoom: 1.0X s</p>		 <p>Date &amp; Time: Wed May 20, 2020 11:15:54 EDT Position: +037°27'28N / -080°31'21W (+6581.7ft) Altitude: 1964ft (+196.3m) Datum: WGS-84 Azimuth/Bearing: 163° S17E 2898mils True (+10°) Elevation Angle: -18.5° Horizon Angle: +03.1° Zoom: 1.0X skaret</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11955+00	<b>Field Station#</b>	11977+00		
<b>Pic 3 Desc.</b>	Row vegetation	<b>Pic 4 Desc.</b>	Karst and Karst ECD's		
 <p>Date &amp; Time: Wed May 20, 2020 11:49:00 EDT Position: +037°27'45N / -080°31'21W (+6581.7ft) Altitude: 1489ft (+107.4m) Datum: WGS-84 Azimuth/Bearing: 091° S89E 1618mils True (+10°) Elevation Angle: +01.4° Horizon Angle: +00.7° Zoom: 1.0X wetland</p>		 <p>Date &amp; Time: Wed May 20, 2020 11:49:00 EDT Position: +037°27'45N / -080°31'21W (+6581.7ft) Altitude: 1489ft (+107.4m) Datum: WGS-84 Azimuth/Bearing: 091° S89E 1618mils True (+10°) Elevation Angle: +01.4° Horizon Angle: +00.7° Zoom: 1.0X wetland</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11989+00	<b>Field Station#</b>	12001+00		
<b>Pic 5 Desc.</b>	AR-266.00- Rock check dam in ditch line.	<b>Pic 6 Desc.</b>	Wetland ECD's- Silt fence has been replaced with CFS.		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11120
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	5/20/2020 9:09 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	1.75
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions





Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 9:09 AM	<b>Report #</b>	11120
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a regular scheduled VADEQ SWPPP inspection. Heavy rains are occurring throughout the project area. The ROW is currently stable. ECDs are in place and functioning as designed. No slips or erosion issues were located. Slope breakers are working to control runoff. The sumps end treatments are filtering runoff. No sediment deposits beyond LOD were found. Resource buffers are stable. No issues from swollen creeks identified today. Stream S-RR13 at access road MN-258.04 is very high and was washing over the equipment bridge during times of heavy rainfall. The bridge remains in place with cable and dead man anchor should it break free. Perimeter controls are in place and surface stable.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 9:09 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed, May 20, 2020, 11:27:23 EDT  Position: +037.314003° / -080.398488° (±16.4ft)  Altitude: 1935ft (±6.2m)  Datum: WGS-84  Azimuth/Bearing: 125° S35E 222mils Magnetic (±10°)  Elevation Angle: -02.6°  Horizon Angle: -02.6°  Zoom: 1.0x  Brush Min 11669+50 FS188 crossing</p> 		<p>Date &amp; Time: Wed, May 20, 2020, 11:29:14 EDT  Position: +037.314003° / -080.398488° (±16.4ft)  Altitude: 1935ft (±6.2m)  Datum: WGS-84  Azimuth/Bearing: 125° S35E 222mils Magnetic (±10°)  Elevation Angle: -01.1°  Horizon Angle: -05.0°  Zoom: 1.0x  Brush Min 11666+25 ROW stable</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11669+50	<b>Field Station#</b>	11666+25		
<b>Pic 1 Desc.</b>	FS188 and ROW stable.	<b>Pic 2 Desc.</b>	ROW stable with ECDs in place.		
<p>Date &amp; Time: Wed, May 20, 2020, 13:43:58 EDT  Position: +037.314003° / -080.398488° (±16.4ft)  Altitude: 1935ft (±6.2m)  Datum: WGS-84  Azimuth/Bearing: 125° S35E 221mils Magnetic (±10°)  Elevation Angle: -07.1°  Horizon Angle: -00.2°  Zoom: 1.0x  Brush Min: ECDs and slope breakers functional, 11627+00</p> 		<p>Date &amp; Time: Wed, May 20, 2020, 13:41:47 EDT  Position: +037.314003° / -080.398488° (±16.4ft)  Altitude: 1935ft (±6.2m)  Datum: WGS-84  Azimuth/Bearing: 125° S35E 224mils Magnetic (±12°)  Elevation Angle: -01.0°  Horizon Angle: -01.0°  Zoom: 1.0x  Brush Min: S-HH18 crossing stable 11626+04</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11627+00	<b>Field Station#</b>	11626+04		
<b>Pic 3 Desc.</b>	Steep slope and 2-tone stable.	<b>Pic 4 Desc.</b>	S-HH18 crossing is stable.		
<p>Date &amp; Time: Wed, May 20, 2020, 13:31:57 EDT  Position: +037.312742° / -080.402628° (±16.4ft)  Altitude: 1835ft (±6.2m)  Datum: WGS-84  Azimuth/Bearing: 127° S31E 223mils Magnetic (±12°)  Elevation Angle: -13.5°  Horizon Angle: -03.5°  Zoom: 1.0x  Brush Min: S-HH18 crossing</p> 		<p>Date &amp; Time: Wed, May 20, 2020, 13:35:06 EDT  Position: +037.312742° / -080.401278° (±16.4ft)  Altitude: 1985ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 342° N18W 608mils Magnetic (±12°)  Elevation Angle: -25.0°  Horizon Angle: -00.0°  Zoom: 1.0x  Brush Min: ECDs effective 11618+50</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11614+20	<b>Field Station#</b>	11618+50		
<b>Pic 5 Desc.</b>	S-RR14 crossing stable.	<b>Pic 6 Desc.</b>	Drain pipe at edge of travel lane working properly.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/20/2020 9:09 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Wed, May 20, 2020, 13:36:32 EDT Position: +037.314234° / -080.400404° (±32.8ft) Altitude: 2057ft (±78.7ft) Datum: WGS-84 Azimuth/Bearing: 046° N44E 0782mils Magnetic (±12°) Elevation Angle: -36.0° Horizon Angle: +00.2° Zoom: 1.0X Brush Mtn. ECDs effective during heavy runoff 11622+00</small></p>		 <p><small>Date &amp; Time: Wed, May 20, 2020, 11:02:34 EDT Position: +037.314552° / -080.402632° (±16.4ft) Altitude: 1935ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 176° S04E 3129mils Magnetic (±14°) Elevation Angle: -06.2° Horizon Angle: +01.1° Zoom: 1.0X Access road 258.04 S-RR13</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11622+00	<b>Field Station#</b>	11613+69		
<b>Pic 7 Desc.</b>	Heavy runoff controlled by ECDs. No sediment lost from limits of disturbance.	<b>Pic 8 Desc.</b>	Craig Creek washes over equipment bridge at access road 258.04.		
 <p><small>Date &amp; Time: Wed, May 20, 2020, 13:39:54 EDT Position: +037.313214° / -080.401982° (±32.8ft) Altitude: 1926ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 325° N35W 5778mils Magnetic (±12°) Elevation Angle: -14.8° Horizon Angle: +01.8° Zoom: 1.0X Brush Mtn. ECDs effective</small></p>		 <p><small>Date &amp; Time: Wed, May 20, 2020, 13:40:16 EDT Position: +037.313475° / -080.404745° (±16.4ft) Altitude: 1918ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 081° N81E 1440mils Magnetic (±12°) Elevation Angle: -14.4° Horizon Angle: -00.4° Zoom: 1.0X Brush Mtn S-004 crossing flooding</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11614+75	<b>Field Station#</b>	11607+81		
<b>Pic 9 Desc.</b>	Slope breakers, sumps and end treatments working properly.	<b>Pic 10 Desc.</b>	Craig Creek is swollen from recent rainfall. Damages to ECDs will be assessed again after water resides.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 9:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11134
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/20/2020 12:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	49.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.70
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 12:14 PM	<b>Report #</b>	11134
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.3 to MP 225.3 as well as assessed AR 266.03. Inspection performed during ongoing rain event. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 12:14 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11793+00	<b>Field Station#</b>	11806+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11837+00	<b>Field Station#</b>	11863+65		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	P-KL2.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11878+00	<b>Field Station#</b>	11899+99		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 12:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 12:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11142
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/20/2020 2:42 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	1.70
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 2:42 PM	<b>Report #</b>	11142
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. Deficiencies located at station numbers; 11711+00 - Priority one silt fence undermined. 11715+00 - Priority one silt fence undermined and needs to be extended. Water is bypassing. 11740+00 - Priority one silt fence needs to be extended, water is bypassing. 11767+00 - Priority one silt fence stake broke. Rain gauge at Mount Tabor read 1.7 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/20/2020 2:42 PM	Report #	
Pictures					
 <p>Date &amp; Time: Wed, May 20, 2020, 10:30:45 EDT Position: +489.894828° / +880.594613° (+19.2m) Altitude: 2792ft (+13.5ft) Datum: WGS-84 Azimuth/Bearing: 143° S37E 2542mils True (+17°) Elevation Angle: +27.1° Horizon Angle: -04.2° Zoom: 1.0X 11669+00</p>		 <p>Date &amp; Time: Wed, May 20, 2020, 10:30:45 EDT Position: +489.894828° / +880.594613° (+19.2m) Altitude: 2792ft (+13.5ft) Datum: WGS-84 Azimuth/Bearing: 143° S37E 2542mils True (+17°) Elevation Angle: +27.1° Horizon Angle: -04.2° Zoom: 1.0X 11672+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11669+00		Field Station#	11672+00	
Pic 1 Desc.	Triple stack compost filter sock and priority one silt fence in place along LOD.		Pic 2 Desc.	Waterbar, sump pit, and waterbar end treatment in place.	
 <p>Date &amp; Time: Wed, May 20, 2020, 11:34:41 EDT Position: +489.277828° / +880.594613° (+19.2m) Altitude: 2628ft (+143.9ft) Datum: WGS-84 Azimuth/Bearing: 289° N42W 5298mils True (+13°) Elevation Angle: -04.5° Horizon Angle: -04.5° Zoom: 1.0X 11704+10</p>		 <p>Date &amp; Time: Wed, May 20, 2020, 11:37:46 EDT Position: +489.277828° / +880.594613° (+19.2m) Altitude: 2600ft (+139.3ft) Datum: WGS-84 Azimuth/Bearing: 27° S43E 2089mils True (+18°) Elevation Angle: -15.2° Horizon Angle: +04.2° Zoom: 1.0X 11761+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11704+10		Field Station#	11761+00	
Pic 3 Desc.	Sensitive resource buffer in place at stream S-MN22.		Pic 4 Desc.	Priority one silt fence check in place where rilling commonly occurs.	
 <p>Date &amp; Time: Wed, May 20, 2020, 11:37:41 EDT Position: +489.277828° / +880.594613° (+19.2m) Altitude: 2183ft (+117.8ft) Datum: WGS-84 Azimuth/Bearing: 114° S43E 2027mils True (+14°) Elevation Angle: -37.2° Horizon Angle: +04.2° Zoom: 1.0X 11767+00</p>		 <p>Date &amp; Time: Wed, May 20, 2020, 11:40:06 EDT Position: +489.277828° / +880.594613° (+19.2m) Altitude: 2070ft (+175.5ft) Datum: WGS-84 Azimuth/Bearing: 130° S46E 2044mils True (+14°) Elevation Angle: -46.7° Horizon Angle: -04.7° Zoom: 1.0X 11774+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11776+00	
Pic 5 Desc.	RCE in place at main line valve 26.		Pic 6 Desc.	Reinforced super silt fence in place along LOD.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 2:42 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 2:42 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11146
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	5/20/2020 2:11 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	38.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 2:11 PM	<b>Report #</b>	11146
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 218 - MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch 1.4" of rain recorded @ AR 234, 1.1" of rain recorded @ Buffalo Anklets					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/20/2020 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, May 20, 2020, 08:56:37 EDT Position: +037 22 10.31' / -080 40 40.72' (+27.24) Altitude: 1771ft (+53.2m) Datum: WGS-84 Azimuth/Bearing: 045° N65E 1173mils True (+53°) Elevation Grade: -001° Horizon Grade: -002° Zoom: 1.0x 1.4" 234</p>		 <p>Date &amp; Time: Wed, May 20, 2020, 08:48:00 EDT Position: +037 20 57.07' / -080 39 10.31' (+27.24) Altitude: 2066ft (+630.2m) Datum: WGS-84 Azimuth/Bearing: 222° S42W 3940mils True (+52°) Elevation Grade: -007° Horizon Grade: -002° Zoom: 1.0x 1.1" buffalo</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+1	
<b>Pic 1 Desc.</b>	1.4" of rain recorded @ AR 234		<b>Pic 2 Desc.</b>	1.1" of rain recorded @ Buffalo Anklets	
 <p>Date &amp; Time: Wed, May 20, 2020, 10:47:26 EDT Position: +037 19 3.24' / -080 24 33.82' (+15.2m) Altitude: 2095ft (+638.6m) Datum: WGS-84 Azimuth/Bearing: 85° S62E 6924mils True (+17°) Elevation Grade: -041° Horizon Grade: -006° Zoom: 1.0x 11550</p>		 <p>Date &amp; Time: Wed, May 20, 2020, 10:40:20 EDT Position: +037 18 13.51' / -080 24 44.20' (+15.1m) Altitude: 2466ft (+751.7m) Datum: WGS-84 Azimuth/Bearing: 253° S73W 4498mils True (+19°) Elevation Grade: -054° Horizon Grade: -022° Zoom: 1.0x 11575 fpp2x</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11550+00		<b>Field Station#</b>	11584+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
 <p>Date &amp; Time: Wed, May 20, 2020, 10:40:20 EDT Position: +037 18 13.51' / -080 24 44.20' (+15.1m) Altitude: 2466ft (+751.7m) Datum: WGS-84 Azimuth/Bearing: 253° S73W 4498mils True (+19°) Elevation Grade: -054° Horizon Grade: -022° Zoom: 1.0x 11575 fpp2x</p>		 <p>Date &amp; Time: Wed, May 20, 2020, 10:40:20 EDT Position: +037 18 13.51' / -080 24 44.20' (+15.1m) Altitude: 2466ft (+751.7m) Datum: WGS-84 Azimuth/Bearing: 253° S73W 4498mils True (+19°) Elevation Grade: -054° Horizon Grade: -022° Zoom: 1.0x 11575 fpp2x</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11584+00		<b>Field Station#</b>	11575+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/20/2020 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11168
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	5/21/2020 8:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	53.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	1.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 8:40 AM	<b>Report #</b>	11168
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at the work trailer SWPPP inspection:LY-29 Twenty four hour rain fall- 1.80", rain is forecasted to continue. AR-238.00 servicing LY-29 is in acceptable condition. Perimeter controls for the yard are 18" triple stack CFS- controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. Rock surface of the yard is maintained in acceptable condition. Waste management is acceptable. Materials storage is acceptable. No mechanical equipment stored in the yard. Rain gauge readings: Buffalo Anklets-1.60" AR-234.00- 1.80"  Checked row and access road conditions.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, May 21, 2020, 09:40:48 EDT  Position: +407.345200° / -080.677942° (±16.4m)  Altitude: 1789.0 (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 225.536W 419.6mils True (±21°)  Elevation Angle: -05.3°  Horizon Angle: +00.2°  Zoom: 1.0x  LY-29- PPL materials storage.</p> 		<p>Date &amp; Time: Thu, May 21, 2020, 09:44:33 EDT  Position: +407.345200° / -080.677942° (±16.4m)  Altitude: 1707.0 (±19.6m)  Datum: WGS-84  Azimuth/Bearing: 275.845W 488.9mils True (±26°)  Elevation Angle: -10.6°  Horizon Angle: +01.0°  Zoom: 1.0x  LY-29- 18" CFS triple stack perimeter controls.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	LY29- PPL Materials storage	<b>Pic 2 Desc.</b>	LY 29- 18" CFS triple stack perimeter controls.		
<p>Date &amp; Time: Thu, May 21, 2020, 09:47:50 EDT  Position: +407.345200° / -080.677198° (±16.4m)  Altitude: 1794.0 (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 285° N35W 520.6mils True (±21°)  Elevation Angle: -13.5°  Horizon Angle: +01.0°  Zoom: 1.0x  LY-29- Culvert and drainage feature.</p> 		<p>Date &amp; Time: Thu, May 21, 2020, 09:48:47 EDT  Position: +407.345200° / -080.677942° (±16.4m)  Altitude: 1789.0 (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 202.522W 559.1mils True (±26°)  Elevation Angle: -08.5°  Horizon Angle: +02.6°  Zoom: 1.0x  AR-238.00</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY29- Culvert and drainage feature.	<b>Pic 4 Desc.</b>	AR- 238.00		
<p>Date &amp; Time: Thu, May 21, 2020, 09:16:53 EDT  Position: +407.345200° / -080.652837° (±16.4m)  Altitude: 2046ft (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 216.536W 384.0mils True (±10°)  Elevation Angle: -14.6°  Horizon Angle: +03.2°  Zoom: 1.0x  Buffalo Anklets rain gauge- 1.60"</p> 		<p>Date &amp; Time: Thu, May 21, 2020, 09:33:15 EDT  Position: +407.345200° / -080.677942° (±16.4m)  Altitude: 1789.0 (±19.7m)  Datum: WGS-84  Azimuth/Bearing: 112° S38E 169.1mils True (±16°)  Elevation Angle: -17.2°  Horizon Angle: +08.8°  Zoom: 1.0x  AR- 234.00 rain gauge reading- 1.80"</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10676+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	Buffalo Anklets rain gauge reading- 1.60"	<b>Pic 6 Desc.</b>	AR-234.00 rain gauge reading- 1.80"		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11179
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/21/2020 1:24 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	2.60
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 1:24 PM	<b>Report #</b>	11179
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Winding Way Road - 2.6 inches, Mount Tabor Road - 2.6 inches, and Catawba Road - 2.0 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/21/2020 1:24 PM	Report #	
Pictures					
<p>Date &amp; Time: Thu, May 21, 2020, 10:45:46 EDT  Position: +397.21660° / +080.503471° (+73.11)  Altitude: 1940' (+61.30)  Datum: WGS-84  Azimuth/Bearing: 331° 30'W 304°mils True (+10°)  Elevation Angle: -02.5°  Horizon Angle: -00.7°  Zoom: 1.0X  LDY: 26</p> 		<p>Date &amp; Time: Thu, May 21, 2020, 10:45:46 EDT  Position: +397.21660° / +080.503471° (+73.11)  Altitude: 1940' (+61.30)  Datum: WGS-84  Azimuth/Bearing: 331° 30'W 304°mils True (+10°)  Elevation Angle: -02.5°  Horizon Angle: -00.7°  Zoom: 1.0X  LDY: 26</p> 			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		RCE in place Lay Down Yard 26 entrance.		<b>Pic 2 Desc.</b>	
				18 inch compost filter sock in place along LOD.	
<p>Date &amp; Time: Thu, May 21, 2020, 10:45:46 EDT  Position: +397.21660° / +080.503471° (+73.11)  Altitude: 1940' (+61.30)  Datum: WGS-84  Azimuth/Bearing: 331° 30'W 304°mils True (+10°)  Elevation Angle: -02.5°  Horizon Angle: -00.7°  Zoom: 1.0X  LDY: 26</p> 		<p>Date &amp; Time: Thu, May 21, 2020, 10:45:46 EDT  Position: +397.21660° / +080.503471° (+73.11)  Altitude: 1940' (+61.30)  Datum: WGS-84  Azimuth/Bearing: 331° 30'W 304°mils True (+10°)  Elevation Angle: -02.5°  Horizon Angle: -00.7°  Zoom: 1.0X  LDY: 26</p> 			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Secondary containment in place under fuel cell.		<b>Pic 4 Desc.</b>	
				Rain gauge at Winding Way reads 2.6 inches.	
<p>Date &amp; Time: Thu, May 21, 2020, 11:36:26 EDT  Position: +397.22110° / +080.51789° (+74.70)  Altitude: 2015' (+62.60)  Datum: WGS-84  Azimuth/Bearing: 025° N25E 044°mils True (+10°)  Elevation Angle: -02.7°  Horizon Angle: -00.8°  Zoom: 1.0X  LDY: 00</p> 		<p>Date &amp; Time: Thu, May 21, 2020, 11:36:26 EDT  Position: +397.22110° / +080.51789° (+74.70)  Altitude: 2015' (+62.60)  Datum: WGS-84  Azimuth/Bearing: 025° N25E 044°mils True (+10°)  Elevation Angle: -02.7°  Horizon Angle: -00.8°  Zoom: 1.0X  LDY: 00</p> 			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11767+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Rain gauge at Mount Tabor Road reads 2.6 inches.		<b>Pic 6 Desc.</b>	
				Rain gauge at Catawba Road reads 2.0 inches.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 1:24 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 1:24 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11191
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	5/21/2020 2:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	49.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	2.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 2:18 PM	<b>Report #</b>	11191
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for LDY 28 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch 2.4" of rain recorded @ Stevens Gap, 1.3" @ Kow Camp, 1.2" @ AR 244 Observed ru;n on from off ROW and running down Stevens gap, eroding some of the road, water is not from ROW					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/21/2020 2:18 PM	Report #	
Pictures					
 <p>Date &amp; Time: Thu, May 21, 2020 10:23:41 EDT Position: +48°17'29.28" N / -80°25'53.05" W (-11.53N) Altitude: 21400 ft (11.3N) Datum: WGS-84 Azimuth/Bearing: 228° 55' 0" 1/2 mile True (-12°) Elevation Grade: -0.2% Horizon Grade: -0.03% Zoom: 1.0X Stevens Gap 2.4"</p>		 <p>Date &amp; Time: Thu, May 21, 2020 10:24:44 EDT Position: +48°17'29.28" N / -80°25'53.05" W (-11.53N) Altitude: 21390 ft (11.3N) Datum: WGS-84 Azimuth/Bearing: 273° 18' 0" 1/2 mile True (-12°) Elevation Grade: -0.04% Horizon Grade: -0.04% Zoom: 1.0X 1.3"</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+1	
Pic 1 Desc.	2.4" of rain recorded @ Stevens Gap		Pic 2 Desc.	1.3" @ Kow Camp	
 <p>Date &amp; Time: Thu, May 21, 2020 14:05:45 EDT Position: +48°17'29.28" N / -80°25'53.05" W (-11.53N) Altitude: 10700 ft (11.3N) Datum: WGS-84 Azimuth/Bearing: 302° 55' 0" 1/2 mile True (-12°) Elevation Grade: -0.02% Horizon Grade: -0.02% Zoom: 1.0X 28</p>		 <p>Date &amp; Time: Thu, May 21, 2020 14:05:55 EDT Position: +48°17'29.28" N / -80°25'53.05" W (-11.53N) Altitude: 21390 ft (11.3N) Datum: WGS-84 Azimuth/Bearing: 310° 55' 0" 1/2 mile True (-12°) Elevation Grade: -0.11% Horizon Grade: -0.00% Zoom: 1.0X Stevens Gap 2.4"</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	11489+70	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	See picture above for GPS coordinates	
 <p>Date &amp; Time: Thu, May 21, 2020 14:07:33 EDT Position: +48°17'29.28" N / -80°25'53.05" W (-11.53N) Altitude: 21510 ft (11.3N) Datum: WGS-84 Azimuth/Bearing: 302° 55' 0" 1/2 mile True (-12°) Elevation Grade: -0.28% Horizon Grade: -0.02% Zoom: 1.0X Stevens Gap 2.4"</p>		 <p>Date &amp; Time: Thu, May 21, 2020 10:27:17 EDT Position: +48°17'29.28" N / -80°25'53.05" W (-11.53N) Altitude: 21540 ft (11.3N) Datum: WGS-84 Azimuth/Bearing: 142° 53' 0" 1/2 mile True (-12°) Elevation Grade: -0.04% Horizon Grade: -0.00% Zoom: 1.0X Stevens Gap 2.4"</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11489+70		Field Station#	11489+70	
Pic 5 Desc.	Water washed out state maintained road		Pic 6 Desc.	Run on from off row, stream flooded and braided	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 2:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/21/2020 2:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11208
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	5/22/2020 8:22 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	57.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/22/2020 8:22 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri, May 22, 2020, 09:40:30 EDT Position: +037323616 / -000555317 (424200) Altitude: 2445ft (1374m) Datum: WGS-84 Azimuth Bearing: 080 N80E 1422mils True (±10°) Elevation Angle: -15.2° Horizon Angle: +05.1° Zoom: 1.0x Start 11024+00 Stream S-IJ18 Bridge &amp; ECDS</p>		<p>Date &amp; Time: Fri, May 22, 2020, 09:44:29 EDT Position: +037323616 / -000555317 (424200) Altitude: 2435ft (1197m) Datum: WGS-84 Azimuth Bearing: 312° N48W 5547mils True (±10°) Elevation Angle: -15.2° Horizon Angle: +05.1° Zoom: 1.0x Stream S-IJ18- Bridge &amp; ECDS</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11024+00		
<b>Pic 1 Desc.</b>	AR-244 rain gauge reading- 0.80"	<b>Pic 2 Desc.</b>	Stream S- IJ18		
<p>Date &amp; Time: Fri, May 22, 2020, 10:00:31 EDT Position: +037323616 / -000555317 (424200) Altitude: 2445ft (1374m) Datum: WGS-84 Azimuth Bearing: 080 N80E 1422mils True (±10°) Elevation Angle: -15.2° Horizon Angle: +05.1° Zoom: 1.0x Start 11016+00 Stream S-RR5 Bridge ECDS</p>		<p>Date &amp; Time: Fri, May 22, 2020, 10:30:31 EDT Position: +037325795 / -000560063 (560200) Altitude: 2379ft (1374m) Datum: WGS-84 Azimuth Bearing: 101° S79E 1786mils True (±10°) Elevation Angle: -13.2° Horizon Angle: -00.0° Zoom: 1.0x Start 10986+00 Stream S-E25 bridge &amp; controls</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11016+00	<b>Field Station#</b>	10986+00		
<b>Pic 3 Desc.</b>	Stream S-RR5	<b>Pic 4 Desc.</b>	Stream S- E25		
<p>Date &amp; Time: Fri, May 22, 2020, 10:39:31 EDT Position: +037325795 / -000560063 (560200) Altitude: 2379ft (1374m) Datum: WGS-84 Azimuth Bearing: 080° N89E 1582mils True (±10°) Elevation Angle: -13.2° Horizon Angle: +03.2° Zoom: 1.0x Start 10977+00 P1 protecting sensitive resource in good condition</p>		<p>Date &amp; Time: Fri, May 22, 2020, 10:39:31 EDT Position: +037325795 / -000560063 (560200) Altitude: 2379ft (1374m) Datum: WGS-84 Azimuth Bearing: 080° N89E 1582mils True (±10°) Elevation Angle: -13.2° Horizon Angle: +03.2° Zoom: 1.0x Start 10977+00 P1 protecting sensitive resource in good condition</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10985+00	<b>Field Station#</b>	10977+00		
<b>Pic 5 Desc.</b>	Stream S- E24	<b>Pic 6 Desc.</b>	P1 sensitive resource controls		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/22/2020 8:22 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/22/2020 8:22 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11223
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/22/2020 2:44 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/22/2020 2:44 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11489+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Rain gauge At Stevers Gap Road reads 0.8 inches.		<b>Pic 2 Desc.</b>	Rain gauge at Access Road 234 reads 0.5 inches.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10748+00		<b>Field Station#</b>	10696+00	
<b>Pic 3 Desc.</b>	ROW stabilized with natural vegetation growth.		<b>Pic 4 Desc.</b>	Rain gauge at Buffalo Anklets Road reads 0.5 inches.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	110696+00	
<b>Pic 5 Desc.</b>	Rain gauge at Mount Tabor Road reads 1.0 inches.		<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/22/2020 2:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/22/2020 2:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11230
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	5/22/2020 3:09 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	1.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/22/2020 3:09 PM	<b>Report #</b>	11230
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 205 - MP 207 Observed damaged ECD's during inspection Notified environmental foreman of issues. Crews repaired items same day ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Damaged ECD's added to punch list Walked row for post storm inspection from 208.5 - MP 211.2					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/22/2020 3:09 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	10892+00	
<b>Pic 1 Desc.</b>	1.1" of rain recorded @ Catawba		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10918+00		<b>Field Station#</b>	11057+00	
<b>Pic 3 Desc.</b>	Damaged P1		<b>Pic 4 Desc.</b>	Damaged P1	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10916+00		<b>Field Station#</b>	11370+00	
<b>Pic 5 Desc.</b>	Damaged SSF		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/22/2020 3:09 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/22/2020 3:09 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		