Y Mour	Ntain Valley	r -	Visu	al S	Site	e Ins	specti	on Re	epc	ort			
Project Nar	ne H-600 Pip	eline Spread I		A	FE	124300	0139	Spre	ead	H-600	Pipelin	e Spread I	
Contract	or Precision							Repor	rt #	9274			
Inspect	or Ben Dav	enport						Date/Ti	me	3/19/2	020 5:0	0 PM	
Permit #	TBD		Inspection T	уре	VA	SWPP		Station	Beg	in 14	928+52		
State	VA		Inspection /	Area	Par	tial		Statio	n Er	1 d 15	296+00)	
County	Franklin/Pitts	ylvania	Gro	ound	Dar	np		Те	emp	eratur	re (ºF)	78.00	
Municipality	Chatham		Wea	ther	Sur	nny		F	Rain	Gaug	ge (in)	0.00	
							Rain Ac	cumulati	ion 1	Гime (days)	1.00	
1. Are the appro	I. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes					
2. Are there act (If yes, notify			f the limits of dis Permitting Coord						ngs?)		No	
followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes						
 E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a pick is required.) 									, a picture				
E٤	&S BMPs		Compliance Level		Co	rrectiv	e Action			rective Fram	-	Date Repaired	
Equipment Bridge	9	Ac	cceptable										
Compost Filter So	ock	Ac	cceptable										
Silt Fence (Filter	Fabric Fence)	Ac	cceptable										
Sediment Filter Lo	og	Ac	cceptable										
5. Site Conditi	ons											T	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.								No					
Have inactive di	sturbed area	s (stockpiles,	final grade) bee	en sta	abiliz	zed pe	r state req	uirements	s?			Yes	
Are slopes 3:1 a	ind greater s	tabilized with	appropriate BM	Ps as	s pei	r E&S	plans?					Yes	
Has a new slip/s	lide been ob	served? (If y	es, complete Sl	ide R	еро	rt Forn	n)					No	

AFE 124300139	Date/Ti	me 3/19/2020 5:00 PM	Report # 927	74						
 PCSM BMPs (List BMPs and note if picture is required.) 	and note if installed and maintained as per the plan. If corrective action is needed, a									
PCSM BMPs	Compliance	Corrective Action	Corrective	Date						
	Level		Time Frame	Repaired						
7. Identify all remedial measures that h	nave been taken s	since the previous inspection was	s conducted.							
Comments (Reference above question	s as appropriate.)								
-Performed SWPPP inspection of portion of -Multiple rain events occurred during inspec	f Spread I section	in log for totals in all sections								
-Sunny with damp ground conditions during -Perimeter controls and ECD's were inspec	inspection	-	tor for repair							
 -Inspection observed condition of water bar -Continue to monitor ROW for signs of eros 	s, sumps, and end	treatments along ROW								
-Environmental crews continue to perform e -Multiple environmental issues observed an	environmental main id items added to e	nvironmental punch list								
-Issues identified in previous SWPPP Repo -EI team continues to travel ROW to identify	y environmental ma	ated and continue to be addressed b aintenance and compliance issues. A	y contractor All issues identified	will continue						
to be communicated to contractor for comp	letion									
Note: It is a condition of National Pollut	ant Discharge Eli	mination System and Erosion an	d Sediment perm	its that a						
maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or										
replacement are needed or have been	made for BMPs a	is a result of the inspection. Faile	ure to conduct the	e required						
inspection may result in permit suspens as part of a permit condition this form n			-	s required						

AFE 12430013	9 Date/Time	3/19/2020 5:00 P	M Report #
	Pict	ures	
GPS Location	1	GPS Location	2
Field Station#	15072+86	Field Station#	15092+95
Pic 1 Desc.	View of stream S-G11. Equipment crossing and surrounding ECD's in good condition.	Pic 2 Desc.	View of stream S-G9. Equipment crossing and surrounding ECD's in good condition.
GPS Location	3	GPS Location	4
Field Station#		Field Station#	
Pic 3 Desc.	View of stream S-A6. Equipment crossing and surrounding ECD's in good condition.	Pic 4 Desc.	View of stream S-C7. Equipment crossing and surrounding ECD's in good condition.
GPS Location	5	GPS Location	6
Field Station#		Field Station#	
Pic 5 Desc.	View of stream S-D3. Equipment crossing and surrounding ECD's in good condition.	Pic 6 Desc.	View of stream S-G13. Equipment crossing and surrounding ECD's in good condition.

AFE 1	24300139		Date/Time	3/19/2020 5:00 PN	N	Report #				
			Pict	ures						
		Insert image here		Insert image here GPS Location						
GPS Lo	ocation									
Field S	Station#			Field Station#						
Pic 7	Desc.			Pic 8 Desc.						
		Insert image here			Insert im	age here				
GPS Lo	ocation			GPS Location						
Field S	Station#			Field Station#						
Pic 9	Desc.			Pic 10 Desc.						
		Insert image here			Insert im	age here				
GPS Lo	ocation			GPS Location						
Field S	Station#			Field Station#						
Pic 11	Desc.			Pic 12 Desc.						

AFE 1	124300139		Date/Time	3/19/2020 5:00 PM	N	Report #			
			Pict	ures					
		Insert image here		Insert image here GPS Location					
GPS L	ocation								
Field S	Station#			Field Station#					
Pic 13	3 Desc.			Pic 14 Desc.					
		Insert image here			Insert im	age here			
GPS L	ocation			GPS Location					
Field S	Station#			Field Station#					
Pic 15	5 Desc.			Pic 16 Desc.					
		Insert image here			Insert im	age here			
GPS L	ocation			GPS Location					
Field S	Station#			Field Station#					
Pic 17	7 Desc.			Pic 18 Desc.					

Moun		Visu	al S	Site	e Ins	specti	on Re	epo	ort		
Project Nan	ne H-600 Pipeline Sprea	ad I	AF	ΞE	124300)139	Spre	ad	H-600 Pipe	line	Spread I
Contract	or Precision						Repor	rt #	9300		
Inspect	or Justin Burch						Date/Tir	me	3/19/2020	10:4	I8 AM
Permit #	TBD	Inspection ⁻	Гуре	VA	SWPP		Station	Begi	i n 14171+	-36	
State	VA	Inspection	Area	Full			Statio	n En	d 14546+	-75	
County	Franklin	Gro	ound	Dar	mp		Τe	emp	erature (º	F)	77.00
Municipality	N/A	Wea	ather	Sur	nny		F	Rain	Gauge (i	n)	0.10
						Rain Ac	cumulati	ion T	ime (day	s)	6.00
1. Are the appro	oved (stamped) E&S P	lan and PCSM Pla	in pres	sent	t on sit	e?					Yes
	ivities occurring outsid the MVP Environment							ngs?			No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)								Yes			
 E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picturis required.) 										a picture	
E&S BMPs Corrective Action							ective Frame	R	Date epaired		
Waterbar End Tre	eatment	Communication									
Waterbar End Tre	eatment	Communication									
Waterbar		Communication									
Waterbar End Tre	eatment	Communication									
Silt Fence (Reinfo	orce Filter Fence)	Acceptable									
Plunge Pool		Acceptable									
5. Site Conditions											
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.									No		
Have inactive di	sturbed areas (stockpil	es, final grade) be	en sta	biliz	zed pei	r state req	uirements	s?			Yes
Are slopes 3:1 a	nd greater stabilized w	ith appropriate BN	IPs as	ре	r E&S	plans?					Yes
Has a new slip/s	lide been observed? (If yes, complete S	lide Re	epo	rt Form	<u></u> ו)					No

AFE 124300139	Date/Ti	me 3/19/2020 10:48 AM	Report # 930	00				
 PCSM BMPs (List BMPs and note picture is required.) 	e if installed and ma	intained as per the plan. If corr	ective action is ne	eded, a				
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired				
			_					
			-					
7. Identify all remedial measures that	it have been taken s	since the previous inspection wa	as conducted.	·				
Comments (Reference above question		-						
 Inspector performed a SWPPP inspective Several issues were added to the puncontractor. Other ECDs were observed 	nch list since the last S ed to be in compliance	SWPPP inspection which have bee e at the time of inspection.	-	essed by the				
 Inspector checked rain gauges at Tim 	iber Ridge Road and	Farm View Road. See the rain log	or details					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a								
maintenance program be conducted t weekly basis and after each stormwa			-					
replacement are needed or have bee	en made for BMPs a	as a result of the inspection. Fai	ilure to conduct the	e required				
nspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.								

AFE 124300139	9	Date/Time	3/19/2020 10:48 <i>F</i>	АM	Report #	
		Pict	ures			
240 270 1 - 1 - 1 - 2 240 270 270 270 270 270 270 270 27	• 37°0'29"N, 79°45'16"W ±164ft ▲ 994ft		S TEB TEB TEB TEB TEB TEB TEB TEB	SW 240 • 37°0'30"N, 79°45" • 0 100 100 100 100 100 100 100 100 100		N. 14534-25 2020, 0945:11
GPS Location	0		GPS Location	0		
Field Station#			Field Station#			
Pic 1 Desc.	Rock Flume at waterbar end trea repaired	atment needs	Pic 2 Desc.	Rock Flume at repaired	waterbar end t	reatment needs
Second se	SW 20 NV 30 37°0'31"N, 79°45"15"W ±16ft ▲ 1077ft	14533-50 0.0949:51	MVP Sprand 1	SE 100 ST 37°0'32"N, 79°45"		¥227.
GPS Location	0		GPS Location	0		
Field Station#			Field Station#			
Pic 3 Desc.	Flow line of waterbar is eroding; control blanket needs installed	erosion	Pic 4 Desc.	Erosion occurri clean water div control blanket	ing where wate version pipe; ne installed past (rbar flows over eds erosion CWD pipe
MVP Spread I	NE 6 2 2 5 50 37'3'4''N, 79'49'19''W ±32ft & 1009ft	S 1. 1 1.	NE 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	E 12	45"W±16ft ▲ 862ft	20 1 1 1 2 20 1 1 2 20 1 1 2 20 1 1 2 20 1 1 2 20 1 1 20 1 1 1 20 1 1 1 1
GPS Location	0		GPS Location	0		
Field Station#			Field Station#			
Pic 5 Desc.	P1 silt fence in acceptable condit	tion	Pic 6 Desc.	Plunge pool in	acceptable cor	ndition

AFE	124300139		Date/Time	3/19/2020 10:48 A	M	Report #				
			Pict	ures						
		Insert image here		Insert image here GPS Location						
	ocation									
Field	Station#			Field Station#						
Pic 7	7 Desc.			Pic 8 Desc.						
		Insert image here			Insert im	age here				
GPS L	ocation			GPS Location						
Field	Station#			Field Station#						
Pic 9) Desc.			Pic 10 Desc.						
		Insert image here			Insert im	age here				
	ocation			GPS Location						
Field	Station#			Field Station#						
Pic 1	1 Desc.			Pic 12 Desc.						

AFE	124300139)	Date/Time	3/19/2020 10:48 A	M	Report #				
			Pict	ures						
		Insert image here		Insert image here GPS Location						
	ocation									
Field	Station#			Field Station#						
Pic 13	3 Desc.			Pic 14 Desc.						
		Insert image here			Insert im	age here				
GPS L	ocation			GPS Location						
Field	Station#			Field Station#						
Pic 1	5 Desc.			Pic 16 Desc.						
		Insert image here			Insert im	age here				
GPS L	ocation			GPS Location						
Field	Station#			Field Station#						
Pic 17	7 Desc.			Pic 18 Desc.						

🎝 Mour	Ntain Valley		Visu	al S	Site In	specti	on Rej	oor	t		
Project Nar	ne H-600 Pipe	eline Spread I		Α	FE 12430	0139	Sprea	d H-	600 Pipelir	e Spread I	
Contract	t or Precision				•		Report	# 93	04		
Inspect	t or Charles He	ead					Date/Tim	e 3/1	9/2020 11	:41 AM	
Permit #	TBD		Inspection	Туре	VA SWPF)	Station B	egin	13784+3	5	
State	VA		Inspection	Area	Partial		Station	End	14171+36	3	
County	Franklin		Gro	ound	Damp		Tei	npera	ature (ºF)	70.00	
Municipality	N/A		Wea	ather	Sunny		R	ain G	auge (in)	0.10	
						Rain Ac	cumulatio	n Tin	ne (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes				
2. Are there act (If yes, notify		•	the limits of di ermitting Coor				•	gs?		No	
followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes				
4. E&S BMPs (is required.)	(List BMPs and	d note if insta	alled and main	tained	as per th	e plan. If c	corrective a	ction	is needec	l, a picture	
E٤	&S BMPs	C	Compliance Level		Correcti	ve Action	-	orreo me F		Date Repaired	
Compost Filter So	ock	Co	mmunication								
Equipment Bridge	e	Ac	ceptable								
Erosion Control E	Blanket	Co	mmunication								
Rock Constructio	n Entrance	Ac	ceptable								
Sensitive Resour	ce Signage	Ac	ceptable								
Silt Fence (Filter	Fabric Fence)	Co	mmunication								
Silt Fence (Reinfo	orce Filter Fenc	ce) Ac	ceptable								
Waterbar		Co	mmunication								
Vegetative Stabil	ization (Tempo	rary) Ac	ceptable								
5. Site Conditi	ons										
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.											
Have inactive di	sturbed areas	s (stockpiles,	final grade) be	en sta	abilized pe	er state req	uirements?	•		Yes	
Are slopes 3:1 a	and greater sta	abilized with a	appropriate BN	/IPs as	s per E&S	plans?				Yes	
Has a new slip/s	slide been obs	served? (If ye	es, complete S	lide R	eport Fori	n)				No	

AFE 124300139	Date/Ti	me 3/19/2020 11:41 AM	Report # 930)4						
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)										
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired						
7. Identify all remedial measures that h	ave been taken s	since the previous inspection was	conducted.							
Comments (Reference above questions	s as appropriate.)								
SWPPP inspection of Spread I. Inspection vater bars, sumps, end treatments, CWDs,	was conducted of L	OD and resource boundary ECDs, r	esources, road cro	ssings, RCEs,						
Seeding and stabilization practices are prog Streams running clean and clear of sedimen	pressing. Contracto	r has addressed and continues to ad	ddress maintenance	e issues.						
Note: It is a condition of National Pollut	ant Discharge Eli	mination System and Erosion an	d Sediment perm	its that a						
maintenance program be conducted to weekly basis and after each stormwate	provide for the op	peration and maintenance of all E	BMPs to be inspe	cted on a						
replacement are needed or have been i	made for BMPs a	s a result of the inspection. Faile	ure to conduct the	e required						
inspection may result in permit suspens as part of a permit condition this form m				siequileu						

AFE 124300139) D	ate/Time 3/19/2020 11:41	me 3/19/2020 11:41 AM Report #					
		Pictures		·				
GPS Location	0	GPS Location	0					
Field Station#		Field Station#						
Pic 1 Desc.	Approximately 13998+15. Overview or crossing, equipment bridge and ECD stream S-KL36.	of stream Is at Pic 2 Desc.	Approximately installed and f inspection.	v 14131+50. RC unctioning corre	E appears to be actly at time of			
GPS Location	0	GPS Location	0					
Field Station#		Field Station#						
Dia 2 Dasa	Approximately 14163+50. Overview of ROW temporarily stabilized and has and permanent vegetation growing.	winter Pic 4 Desc.	Approximately crossing, equi stream S-C8.	/ 14141+62. Ov pment bridge a	erview of stream nd ECDs at			
	Insert image here		Insert im	age here				
GPS Location		GPS Location						
Field Station#		Field Station#						
Pic 5 Desc.		Pic 6 Desc.						

AFE	124300139		Date/Time	3/19/2020 11:41 A	M	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 7	' Desc.			Pic 8 Desc.			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 9	Desc.			Pic 10 Desc.			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 1 ⁴	1 Desc.			Pic 12 Desc.			

AFE	124300139)	Date/Time	3/19/2020 11:41 A	M	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 1	3 Desc.			Pic 14 Desc.			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 1	5 Desc.			Pic 16 Desc.			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 1	7 Desc.			Pic 18 Desc.			

Mour		<mark>وک</mark>	Visu	ial S	Sit	e In	specti	on Re	epc	ort			
Project Nar	ne H-600	Pipeline Sprea	d I	A	ΞE	12430	0139	Spre	ead	H-600 Pipe	eline	e Spread I	
Contract	t or Precis	ion						Repo	ort #	9308			
Inspect	t or John \	White						Date/Ti	ime	3/19/2020	12:3	32 PM	
Permit #	TBD		Inspection	Туре	VA	SWPP		Station	Beg	in 15678-	+57		
State	VA		Inspection	Area	Ful	I		Static	on Er	nd 16027-	+46	6	
County	Pittsylvan	ia	Gr	ound	Dry	,		Т	emp	erature (^o	PF)	74.00	
Municipality	Chatham		We	ather	Sur	nny			Rain	Gauge (i	in)	0.00	
	•			Rain Accumulation Time (days)						vs)	4.00		
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes							
	e of the limits of d al Permitting Coor				•		ings?)		No			
 Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a 						Yes							
4. E&S BMPs (is required.)	(List BMPs	and note if ir	nstalled and main	tained	as	per the	e plan. If c	corrective	e actio	on is need	led,	a picture	
E&S BMPs			Compliance Level	Corrective Action					Corrective Time Frame		R	Date epaired	
Compost Filter So	ock		Acceptable										
Equipment Bridge	Э		Acceptable										
Housekeeping			Acceptable										
Sump Pit			Acceptable										
Waterbar End Tre	eatment		Acceptable										
Erosion Control E	Blanket		Acceptable										
5. Site Conditi	ons												
beyond defined	limits of d	sediment, gravel, sulting from earth Environmental Pe	distur	ban	ce acti	vity or inef	-				No		
Have inactive di	sturbed a	reas (stockpile	es, final grade) been stabilized per state requirements?							Yes			
Are slopes 3:1 a	and greate	er stabilized wi	th appropriate BN	/IPs as	pe	r E&S	plans?					Yes	
Has a new slip/s	slide been	observed? (f yes, complete S	lide R	epo	rt Forr	n)					No	

AFE 124300139	Date/Tim	e 3/19/2020 12:32 PM	Report # 9308					
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)								
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired				
7. Identify all remedial measures that	t have been taken si	nce the previous inspection w	as conducted.					
Comments (Reference above questic	ons as appropriate.)							
Performed SWPPP Inspection on this sec repaired the identified issues. Other than	ction. There were issue	is identified and added to the pure punch list there were no issues	nch list. The Contract to report at the time of	or has of Inspection.				
Note: It is a condition of National Pollmaintenance program be conducted tweekly basis and after each stormwat	to provide for the ope ter event. Please list	eration and maintenance of al	I BMPs to be inspected ents to note if repair	cted on a irs or				
replacement are needed or have been inspection may result in permit suspen as part of a permit condition this form	nsion or the imposition	on of civil penalties. If supple	mental monitoring i					

AFE 124300139	9	Date/Time	3/19/2020 12:32 F	PM	Report #	
		Pict	ures			
GPS Location	0		GPS Location	0		
Field Station#			Field Station#			
Pic 1 Desc.	Observing equipment crossing a performing as they should.	nd ECD's	Pic 2 Desc.	Observing cfs	check performi	ng as it should.
GPS Location	0		GPS Location	0		
Field Station#	2+00		Field Station#	15779+00		
Pic 3 Desc.	Observing sensitive resource fen required maintenance.	ncing that	Pic 4 Desc.	Observing sun	np and end trea	atment.
	Insert image here			Insert im	age here	
GPS Location			GPS Location			
Field Station#			Field Station#			
Pic 5 Desc.			Pic 6 Desc.			

AFE	124300139)	Date/Time	3/19/2020 12:32 F	ΡM	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 7	7 Desc.			Pic 8 Desc.			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 9) Desc.			Pic 10 Desc.			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 1	1 Desc.			Pic 12 Desc.			

AFE	124300139)	Date/Time	3/19/2020 12:32 F	ΡM	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 13	3 Desc.			Pic 14 Desc.			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 1	5 Desc.			Pic 16 Desc.			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field	Station#			Field Station#			
Pic 17	7 Desc.			Pic 18 Desc.			

Mour	Ntain Valley		Visu	al S	Site Ir	ns	specti	on R	ерс	ort			
Project Nar	ne H-600 Pipel	ine Spread I		A	FE 1243	300	139	Spi	read	H-6	00 Pipe	eline	Spread I
Contract	t or Precision							Repo	ort #	931	4		
Inspect	t or Glenn Mike	Renfro						Date/T	Time	3/19	9/2020	1:54	PM
Permit #	TBD		Inspection T	уре	VA SWF	Р		Station	ו Beg	jin	0000+0)0	
State	VA		Inspection /	Area	Partial			Stati	on Ei	nd	0000+0	00	
County	Franklin		Gro	und	Dry				Temp	era	ture (º	F)	72.00
Municipality	N/A		Wea	eather Cloudy Rain Gauge (in)							n)	0.60	
				Rain Accumulation Time (days)							s)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes						
2. Are there act (If yes, notify	tivities occurrin the MVP Envi	-							-	?			No
 Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a plan and plan an							Yes						
4. E&S BMPs (is required.)	(List BMPs and	note if insta	lled and maint	ained	as per t	the	plan. If c	orrective	e acti	on i	s need	ed,	a picture
Εł	&S BMPs	С	ompliance Level		Correc	tiv	e Action		Cor Time			R	Date epaired
Compost Filter So	ock	Aco	ceptable										
Housekeeping		Aco	ceptable										
Rock Constructio	n Entrance	Aco	ceptable										
Secondary Conta	inment	Aco	ceptable										
Roadside Ditch		Aco	ceptable										
5. Site Conditi	ons												
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.								No					
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?								N/A					
Are slopes 3:1 a	and greater stal	bilized with a	ppropriate BM	Ps as	per E&	Sp	olans?						N/A
Has a new slip/s	slide been obse	erved? (If ye	s, complete SI	ide R	eport Fo	orm	ı) <u> </u>						No

AFE 124300139	Date/Tim	e 3/19/2020 1:54 PM	Report # 9314					
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)								
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired				
				•				
			_					
	ļ		_					
7. Identify all remedial measures that h	lave been taken sir	nce the previous inspection w	as conducted.					
Comments (Reference above question Performed SWPPP inspection of Spread In issues were found during the inspection. Th	main laydown yard in ne inlet protection for	the parking lot drains in the pave	ed yard were found to	be in				
issues were found during the inspection. The inlet protection for the parking lot drains in the paved yard were found to be in acceptable condition. All secondary containment structures were found to be in compliance at the time of inspection. The RCE at the gravel yard was found to be in good condition. The General Construction permits and contact information are posted at the main entrance of the paved yard as required. There were no issues found during todays inspection.								
Note: It is a condition of National Pollut maintenance program be conducted to weekly basis and after each stormwate replacement are needed or have been inspection may result in permit suspens as part of a permit condition this form n	provide for the ope r event. Please list made for BMPs as sion or the impositio	eration and maintenance of all t in the space provided comm a result of the inspection. Fa on of civil penalties. If supple	I BMPs to be inspected ents to note if repain allure to conduct the mental monitoring it	cted on a irs or e required				

AFE 124300139	9	Date/Time	3/19/2020 1:54 PI	M	Report #	
		Pict	ures			
GPS Location	000000000		GPS Location	0000000000		
Field Station#			Field Station#			
Pic 1 Desc.	RCE at gravel yard in good cond	ition.	Pic 2 Desc.	Perimeter ECE acceptable cor	D's on west sid ndition.	e of gravel yard in
GPS Location			GPS Location	0000000000		
Field Station#			Field Station#			
Pic 3 Desc.	Perimeter ECD's on north end of good condition.	paved yard in	Pic 4 Desc.	Secondary cor protection and of paved yard	ntainment struc perimeter ECI in good conditi	cture, inlet D's on west side on.
	Insert image here			Insert im	age here	
GPS Location			GPS Location			
Field Station#			Field Station#			
Pic 5 Desc.			Pic 6 Desc.			

AFE 12	24300139		Date/Time	3/19/2020 1:54 PN	N	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 7	Desc.			Pic 8 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 9	Desc.			Pic 10 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 11	Desc.			Pic 12 Desc.			

AFE 1	24300139		Date/Time	3/19/2020 1:54 PN	N	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 13	Desc.			Pic 14 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 15	Desc.			Pic 16 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 17	' Desc.			Pic 18 Desc.			

Mour	Ntain Val	ey NE LLC		V	'isual	S	Site	Ins	specti	on R	epo	ort			
Project Nar	ne H-60	00 Pipe	line Spread			AF	E 12	4300	0139	Sp	read	H-6	00 Pipe	line	Spread I
Contract	t or Prec	ision								Rep	ort #	932	25		
Inspect	t or Ran	dall Gr	ey							Date/	Time	3/1	9/2020 4	4:50	PM
Permit #	TBD			Inspec	tion Typ	be	VA SV	NPP		Statio	n Beç	gin	14546+	-75	
State	VA			Inspec	ction Are	ea	Partia	I		Stat	ion E	nd	14928+	-52	
County	Franklin	1			Groun	nd	Dry				Temp	bera	ture (º	F)	76.00
Municipality	N/A				Weath	er	Cloud	у			Rair	ו Ga	auge (i	n)	0.40
				I					Rain Ac	cumula	ation	Tim	ne (day	s)	4.00
1. Are the appr	oved (st	ampe	d) E&S Pla	an and PCS	M Plan p	ores	sent o	n sit	e?						Yes
2. Are there act (If yes, notify			-						•		-	?			No
3. Is Constructi followed? (If									•				et being	3	Yes
 E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a is required.) 								a picture							
E٤	Complian Level	ice	Corrective Action				Corrective Time Frame			Date epaired					
Equipment Bridge A				Acceptable											
Sump Pit				Acceptable											
Compost Filter So	ock			Acceptable											
5. Site Conditi	ons														
Is an unauthoriz beyond defined a photo and imn	limits of	distur	bance res	ulting from e	earth dist	turk	bance	acti	vity or ine	-					No
Have inactive di	sturbed	areas	(stockpile	s, final grad	le) been	sta	bilized	d pe	r state req	uiremer	nts?				Yes
Are slopes 3:1 a	and grea	iter sta	abilized wit	h appropria	te BMPs	as	per E	&S	plans?						Yes
Has a new slip/s	slide bee	en obs	erved? (If	yes, compl	ete Slide	Re	eport	Forn	n)					T	No

AFE 124300139	Date/Ti	me 3/19/2020 4:50 PM	Report # 9325						
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is nee picture is required.)									
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired					
				Repaired					
7. Identify all remedial measures that	have been taken s	since the previous inspection was	s conducted.						
Comments (Reference above questio	ns as appropriate.)							
Performed SWPPP inspection on portion of Spread I. Rain total since Friday 3/13/20 equals 0.4". Perimeter controls and ECDs were inspected and any issues found were forwarded to the contractor for repair. Sections of right of way will continuously be monitored checking water bars, sumps, temporary stabilization, and ECDs to update the punch list.									
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.									

AFE 124300139	9	Date/Time 3/19/2020 4:50 P	M Report #
		Pictures	
	E 120 SE 120 S (17) LAT: 36.982557 LON: -79.688178 ±16ft ▲ S	55ft © 170°S	S 10 10 10 10 10 10 10 10 10 10
GPS Location	0	GPS Location	0
Field Station#		Field Station#	14781+00
Pic 1 Desc.	Equipment bridge clean at strean	Pic 2 Desc.	Sump pit functioning as intended
	SE 10 SW 400 10 LAT: 37.003735 LON: -79.767721 ±16421ft ▲	₩0 20 SW 210 -1 -1 957ft © 294*NM © 957ft © 294*NM	240 W2 300 N 370 LAT: 36.978406 LON: -79.682054 ±16ft ▲ 883ft 100 LAT: 36.978406 LON: -79.682054 ±16ft ▲ 883ft
GPS Location	0	GPS Location	0
Field Station#		Field Station#	
Pic 3 Desc.	Third party logging company cros of way	Pic 4 Desc.	Equipment bridge clean at stream S-H25
1 • 1 • 1 • 1	3W 240 W 270 W 300	No. 1. 1311t • 432°N	Ne e0 120 150 120 120 150 150 (T) LAT: 36.970987 LON: -79.657987 ±98ft ▲ 840ft
GPS Location	0	GPS Location	0
Field Station#		Field Station#	
Pic 5 Desc.	Equipment bridge clean at strean	Pic 6 Desc.	Sump pit functioning as intended

AFE 1:	24300139		Date/Time	3/19/2020 4:50 PN	N	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 7	Desc.			Pic 8 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 9	Desc.			Pic 10 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 11	Desc.			Pic 12 Desc.			

AFE 1	24300139		Date/Time	3/19/2020 4:50 PN	N	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 13	B Desc.			Pic 14 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 15	5 Desc.			Pic 16 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 17	' Desc.			Pic 18 Desc.			

Visual Site Inspection Report												
Project Nar	ne H-600 Pip	eline Spread I		Α	FE 1:	24300	139	Spre	ad ⊦	I-600 Pipeli	ne Spread I	
Contract	or Precision							Repor	t # 9	329		
Inspect	or Logan Bo	x						Date/Tir	ne 3	8/19/2020 6	:42 PM	
Permit #	TBD		Inspection 7	Гуре	VA S	WPP		Station I	Begiı	n 13670+0	0	
State	VA		Inspection	Area	Partia	al		Statio	n Ene	d 13784+3	35	
County	Franklin		Gro	ound	Dam	C		Те	empe	erature (°F) 70.00	
Municipality	N/A		Wea	ther	Sunn	у		F	Rain	Gauge (in) 0.80	
							Rain Ac	cumulati	on Ti	ime (days) 6.00	
1. Are the appre	oved (stampe	ed) E&S Plan	and PCSM Pla	nd PCSM Plan present on site?								
2. Are there act (If yes, notify			the limits of dis						ngs?		No	
3. Is Constructi followed? (If			e construction ental Permitting							set being	Yes	
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a								d, a picture				
is required.)	&S BMPs	C	Compliance Level		Corr	ectiv	e Action			ective Frame	Date Repaired	
3rd Party Damag	Co	ommunication							Ropanou			
Compost Filter So	ock	Ac	ceptable									
Equipment Bridge	Э	Ac	ceptable									
5. Site Conditi	ons											
Is an unauthoriz beyond defined a photo and imn	limits of distu	rbance result	ing from earth	distur	bance	e activ	ity or inef	-				
lave inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? Yes								Yes				
Are slopes 3:1 a	and greater st	abilized with a	appropriate BM	IPs as	s per l	E&S p	olans?				Yes	
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? Has a new slip/slide been observed? (If yes, complete Slide Report Form)										No		

AFE 124300139 Date/Time 3/19/2020 6:42 PM Report # 9329									
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed picture is required.)									
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired					
 Identify all remedial measures that hat 	ave been taken s	since the previous inspection was	conducted.						
Comments (Reference above questions	as appropriate.)							
Traveled and inspected all ECDs throughout	the row, monitore	ed vegetation growth throughout.							
Inspected all stream and wetland crossings,	checked equipme	ent bridges and protection.							
Documented land owner damages to ECDs a	and will continue t	o monitor the area to make repairs a	s needed.						
Talked with environmental crews as they wor installed correctly.	rked to make repa	irs to punch list items and inspected	ECDs to be sure the	hey were					
Total measurable rainfall for this period is 0.8	8" Row conditions	were accessible for the contractor to	complete mainten	ance repairs.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.									

AFE 124300139	9	Date/Time	3/19/2020 6:42 PM	Л	Report #	
		Pict	ures			
GPS Location	0000		GPS Location	0000		
Field Station#			Field Station#			
Pic 1 Desc.	Land owner damaged/removed E access the row.	ECDs to	Pic 2 Desc.	Land owner dat access the row	maged/remove '.	ed ECDs to
GPS Location	0000		GPS Location	0000		
Field Station#			Field Station#			
Pic 3 Desc.	Checked ECDs along the LOD		Pic 4 Desc.	Monitored equi	pment bridge o	crossings.
	Insert image here			Insert ima	age here	
GPS Location			GPS Location			
Field Station#			Field Station#			
Pic 5 Desc.			Pic 6 Desc.			

AFE 1:	24300139		Date/Time	3/19/2020 6:42 PM	N	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 7	Desc.			Pic 8 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 9	Desc.			Pic 10 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 11	Desc.			Pic 12 Desc.			

AFE 1	124300139		Date/Time	3/19/2020 6:42 PM	N	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 13	B Desc.			Pic 14 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 15	5 Desc.			Pic 16 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 17	' Desc.			Pic 18 Desc.			

Y Mour		Y _{uc}	Visu	ual S	Site In	specti	on Rep	or	t	
Project Nar	ne H-600	Pipeline Sprea	d I	A	FE 12430	0139	Sprea	а н-	600 Pipelin	e Spread I
Contract	t or Precisi	on					Report	# 93	47	
Inspect	t or Casey	McGaha					Date/Tim	e 3/1	9/2020 5:0	0 PM
Permit #	TBD		Inspection	Туре	VA SWPP)	Station B	egin	15296+00)
State	VA		Inspection	Area	Full		Station	End	15678+57	7
County	Pittsylvani	а	Gr	ound	Dry		Ten	npera	ture (ºF)	78.00
Municipality	Chatham		We	ather	Sunny		Ra	in G	auge (in)	0.00
						Rain Ac	cumulatio	n Tin	ne (days)	0.00
1. Are the appr	oved (star	nped) E&S Pl	an and PCSM Pla	an pre	sent on si	te?				Yes
			of the limits of d Permitting Coo					s?		No
followed? (If	No, notify	MVP Environ	the construction mental Permitting	g Coor	dinator an	id explain i	n comment	s.)	U	Yes
4. E&S BMPs (is required.)	(List BMPs	and note if ir	stalled and main	tained	as per th	e plan. If o	corrective a	tion	is needed	, a picture
E٤	&S BMPs		Compliance Level		Correcti	ve Action			ctive rame F	Date Repaired
Silt Fence (Filter	Silt Fence (Filter Fabric Fence)									
Erosion Control E	Blanket		Communication							
5 044 0 IV										
5. Site Conditi		···· / ···· ! ··				t =) = = =			41	
beyond defined	limits of di	sturbance res	sediment, gravel, sulting from earth Environmental Pe	distur	bance act	ivity or ine	-			
Have inactive di	lave inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? Yes							Yes		
Are slopes 3:1 a	and greate	r stabilized wi	th appropriate BN	MPs as	s per E&S	plans?				Yes
Has a new slip/s	slide been	observed? (I	f yes, complete S	Slide R	eport Forr	n)				No

AFE 12	24300139	Date/Ti	me 3/19/2020 5:00 PM	Report # 9347					
 PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) 									
precur	PCSM BMPs	Compliance	Corrective Action	Corrective	Date				
		Level		Time Frame	Repaired				
	7 H P I A A A								
7. Identi	ty all remedial measures that h	ave been taken s	since the previous inspection wa	as conducted.					
Comme	nts (Reference above questions	s as appropriate.)						
the punch	list so repairs can be made.	-	nce, and compliance issues. Any is	sue discovered will l	be added to				
The envir	onmental crew continues to perfor	m maintenance on that all maintenand	all punchlist items. ce issues are being repaired correc	tly.					
Note: It i	s a condition of National Polluta	ant Discharge Eli	mination System and Erosion a	nd Sediment perm	its that a				
maintena	ance program be conducted to	provide for the op	peration and maintenance of all st in the space provided comme	BMPs to be inspec	cted on a				
replacem	nent are needed or have been r	made for BMPs a	is a result of the inspection. Fai	lure to conduct the	e required				
			tion of civil penalties. If suppler eet those monitoring requirement		s required				

AFE 124300139		Date/Time	3/19/2020 5:00 PI	1 Rep	oort #
		Pict	ures		
GPS Location	0		GPS Location	0	
Field Station#			Field Station#		
Pic 1 Desc.	Replace damaged P1 fence.		Pic 2 Desc.	Bank of sump is sloug	hing off.
GPS Location	0		GPS Location	0	
Field Station#			Field Station#		
Pic 3 Desc.	New curlex and CFS installed alc drainage feature during maintena	ong natural ance process.	Pic 4 Desc.	Undermining occurring	g along P1 fence.
				Insert image he	re
GPS Location	0		GPS Location		
Field Station#	15610+00		Field Station#		
Pic 5 Desc.	No vegetation along row.		Pic 6 Desc.		

AFE 1	24300139		Date/Time	3/19/2020 5:00 PN	N	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 7	Desc.			Pic 8 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 9	Desc.			Pic 10 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 11	Desc.			Pic 12 Desc.			

AFE 1	124300139		Date/Time	3/19/2020 5:00 PM	N	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 13	3 Desc.			Pic 14 Desc.			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 15	5 Desc.			Pic 16 Desc.			
		Insert image here			Insert im	age here	
GPS L	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 17	7 Desc.			Pic 18 Desc.			

Mour		Visu	ual S	Site Ins	specti	on Re	oor	t	
Project Nar	me Transco Interconnec	t Station	A	FE 124300	0113	Sprea	d Tra	ansco Inte	rconnect Sta
Contract	t or Kanahwa			•		Report	# 93	06	
Inspect					Date/Tim	e 3/*	19/2020 12	::18 PM	
Permit #	TBD	Inspection	Туре	VA SWPP		Station E	egin	00+00	
State	VA	Inspection	Inspection Area Full			Station End 00+00			
County	Pittsylvania	Gr	round Dry Te		Те	mper	ature (°F)	74.00	
Municipality	Chatham	We	ather	Sunny		R	ain G	auge (in)	0.00
				•	Rain Ac	cumulatio	n Tir	ne (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?								Yes	
 Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) 									No
 Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) 								Yes	
 E&S BMPs (is required.) 	(List BMPs and note if i	nstalled and main	itained	as per the	e plan. If c	corrective a	ction	is needed	l, a picture
. ,		Compliance	Corrective Action			Corr		ctive	Date
Ed	&S BMPs	Level		Correctiv	ve Action	Ti	me F	rame	Repaired
Compost Filter Se	ock	Acceptable							
Rock Check Dam	1	Acceptable							
Silt Fence (Filter	Fabric Fence)	Acceptable							
5. Site Conditi	ons								
beyond defined	ed discharge (such as limits of disturbance re nediately contact MVP	sulting from earth	distur	bance acti	vity or ine	-			
Have inactive di	sturbed areas (stockpil	es, final grade) be	een sta	abilized pe	r state req	uirements	2		Yes
Are slopes 3:1 a	and greater stabilized w	vith appropriate BN	MPs as	s per E&S	plans?				Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No

AFE 124300113	Date/Time	e 3/19/2020 12:18 PM	Report # 9306		
6. PCSM BMPs (List BMPs and note picture is required.)	if installed and main	tained as per the plan. If cor	rrective action is ne	eded, a	
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
	+ +				
	++				
	╡───┤				
	1 1				
	++				
7. Identify all remedial measures that	t have been taken sir	the providue inspection w	ica conducted		
Comments (Reference above questic	ons as appropriate.)				
Performed SWPPP Inspection on the Tra	insco Facility and Lay d	own yard. There were no issues	s to report at the time	of Inspection.	
Notes It is a condition of National Poll	utant Discharge Elim	ination System and Eracion	and Sadimant norm	its that a	
Note: It is a condition of National Poll maintenance program be conducted t	to provide for the ope	ration and maintenance of a	II BMPs to be inspe	cted on a	
weekly basis and after each stormwat replacement are needed or have bee					
inspection may result in permit suspe	nsion or the imposition		emental monitoring i		

AFE 124300113	AFE 124300113 Date/Time		3/19/2020 12:18 F	PM Report #
		Pict	ures	
GPS Location	0		GPS Location	0
Field Station#			Field Station#	
Pic 1 Desc.	Observing ECD's performing as t	they should.	Pic 2 Desc.	Observing ECD's performing as they should.
GPS Location	0		GPS Location	0
Field Station#			Field Station#	
Pic 3 Desc.	Observing storm water pond.		Pic 4 Desc.	Observing ECD's performing as they should.
	Insert image here			Insert image here
GPS Location			GPS Location	
Field Station#			Field Station#	
Pic 5 Desc.			Pic 6 Desc.	

AFE 12	24300113	5	Date/Time	3/19/2020 12:18 F	ΡM	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
GPS Lo				GPS Location			
Field S	Station#			Field Station#			
Pic 7	Desc.			Pic 8 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 9	Desc.			Pic 10 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 11	Desc.			Pic 12 Desc.			

AFE 1	24300113	5	Date/Time	3/19/2020 12:18 F	PM	Report #	
			Pict	ures			
		Insert image here			Insert im	age here	
	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 13	Desc.			Pic 14 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 15	Desc.			Pic 16 Desc.			
		Insert image here			Insert im	age here	
GPS Lo	ocation			GPS Location			
Field S	Station#			Field Station#			
Pic 17	Desc.			Pic 18 Desc.			