



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11860
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/15/2020 2:41 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 2:41 PM	<b>Report #</b>	11860
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauge at Craig Creek Road - 1.1 inches, Mount Tabor Road - 0.7 inches, and Catawba Road - 1.2 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	6/15/2020 2:41 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack compost filter sock in place around drainage.		Pic 2 Desc.	Dumpsters being utilized for trash management.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Secondary containment in place under fuel cell.		Pic 4 Desc.	Rain gauge at Craig Creek Road reads 1.1 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Rain gauge at Mount Tabor Road reads 0.7 inches.		Pic 6 Desc.	Rain gauge at Catawba Road reads 1.2 inches.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 2:41 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 2:41 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11861
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/15/2020 3:29 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	57.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	2.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 3:29 PM	<b>Report #</b>	11861
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Performed SWPPP inspection of LDY 29. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Little to no daily activities at this locations.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/15/2020 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Overview of the lower section of LDY 29 (1).		<b>Pic 2 Desc.</b>	Overview of the lower section of LDY 29 (2).	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	Perimeter controls in the lower section of LDY 29 functional.		<b>Pic 4 Desc.</b>	Perimeter controls in the lower section of LDY 29 functional.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	Perimeter controls in the upper portion of LDY 29 functional.		<b>Pic 6 Desc.</b>	Main entrance to LDY 29.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11864
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	6/15/2020 1:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.10
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Secondary Containment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 1:18 PM	<b>Report #</b>	11864
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 Gathered rain gauge amounts Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/15/2020 1:18 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+2	
<b>Pic 1 Desc.</b>	1.1" of rain recorded @ Kow Camp		<b>Pic 2 Desc.</b>	.8" of rain recorded @ AR 244	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+3		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	1" of rain recorded @ Winding Way		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 1:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2020 1:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11884
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/16/2020 8:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	61.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 8:31 AM	<b>Report #</b>	11884
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Performed SWPPP inspection from MP 206.2 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 8:31 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Jun 16, 2020 11:45:00 EDT  Position: +037.33887° / +00.55925° (+16.47)  Altitude: 2228ft (+109m)  Datum: WGS 84  Azimuth/Bearing: 025° N25E 044mils True (+12°)  Elevation Angle: +0.7  Horizon Angle: +0.7  Zoom: 0.5X  S-IJ16B</p> 		<p>Date &amp; Time: Tue, Jun 16, 2020 11:45:10 EDT  Position: +037.33887° / +00.55925° (+16.47)  Altitude: 2228ft (+109m)  Datum: WGS 84  Azimuth/Bearing: 025° N25E 044mils True (+12°)  Elevation Angle: +0.7  Horizon Angle: +0.7  Zoom: 0.5X  S-IJ16B</p> 			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	10960+00	<b>Field Station#</b>	10986+04		
<b>Pic 1 Desc.</b>	Section of RoW and controls.	<b>Pic 2 Desc.</b>	S-E24.		
<p>Date &amp; Time: Tue, Jun 16, 2020 10:45:00 EDT  Position: +037.33887° / +00.55925° (+16.47)  Altitude: 2228ft (+109m)  Datum: WGS 84  Azimuth/Bearing: 025° N25E 044mils True (+12°)  Elevation Angle: +0.7  Horizon Angle: +0.7  Zoom: 0.5X  10986+00</p> 		<p>Date &amp; Time: Tue, Jun 16, 2020 10:45:00 EDT  Position: +037.33887° / +00.55925° (+16.47)  Altitude: 2228ft (+109m)  Datum: WGS 84  Azimuth/Bearing: 025° N25E 044mils True (+12°)  Elevation Angle: +0.7  Horizon Angle: +0.7  Zoom: 0.5X  10986+00</p> 			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	10989+00	<b>Field Station#</b>	11015+47		
<b>Pic 3 Desc.</b>	Perimeter controls functional.	<b>Pic 4 Desc.</b>	S-RR5.		
<p>Date &amp; Time: Tue, Jun 16, 2020 09:42:00 EDT  Position: +037.33887° / +00.55925° (+16.47)  Altitude: 2228ft (+109m)  Datum: WGS 84  Azimuth/Bearing: 027° N27E 048mils True (+12°)  Elevation Angle: +0.1  Horizon Angle: +0.7  Zoom: 0.5X  S-IJ17</p> 		<p>Date &amp; Time: Tue, Jun 16, 2020 09:42:00 EDT  Position: +037.33887° / +00.55925° (+16.47)  Altitude: 2228ft (+109m)  Datum: WGS 84  Azimuth/Bearing: 027° N27E 048mils True (+12°)  Elevation Angle: +0.1  Horizon Angle: +0.7  Zoom: 0.5X  S-IJ17</p> 			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11025+50	<b>Field Station#</b>	11050+10		
<b>Pic 5 Desc.</b>	S-IJ18 and controls.	<b>Pic 6 Desc.</b>	S-IJ16B/S-IJ17 and controls.		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 8:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 8:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11898
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/16/2020 2:51 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 2:51 PM	<b>Report #</b>	11898
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. Checked rain gauges at Buffalo Anklets Road - 0.3 inches, Access Road 234 - 0.3 inches and at Tabor Road - 0.2 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/16/2020 2:51 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Jun 16, 2020, 10:47:49 EDT Position: +037 342134 / -080 447541 (+15.4ft) Altitude: 2280ft (+69.3ft) Datum: WGS-84 Azimuth/Bearing: 082° N89E 1582mils True (+15.1°) Elevation Angle: -09.1° Horizon Angle: -05.3° Zoom: 1.0X 10712+50</p>		 <p>Date &amp; Time: Tue, Jun 16, 2020, 10:47:01 EDT Position: +037 342697 / -080 446427 (+14.3ft) Altitude: 2270ft (+69.2ft) Datum: WGS-84 Azimuth/Bearing: 082° S83W 2036mils True (+14.2°) Elevation Angle: -03.2° Horizon Angle: -00.8° Zoom: 1.0X 10710+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10712+50		<b>Field Station#</b>	10710+00	
<b>Pic 1 Desc.</b>	Sensitive resource buffer in place at stream S-G33.		<b>Pic 2 Desc.</b>	Environmental crew redoing the rock on access road 241.01.	
 <p>Date &amp; Time: Tue, Jun 16, 2020, 11:13:22 EDT Position: +037 342134 / -080 447541 (+15.4ft) Altitude: 2280ft (+69.3ft) Datum: WGS-84 Azimuth/Bearing: 082° N89E 1582mils True (+15.1°) Elevation Angle: -09.1° Horizon Angle: -05.3° Zoom: 1.0X 10696+00</p>		 <p>Date &amp; Time: Tue, Jun 16, 2020, 12:02:01 EDT Position: +037 296179 / -080 367882 (+12.2ft) Altitude: 2016ft (+61.5ft) Datum: WGS-84 Azimuth/Bearing: 022° N22E 0391mils True (+12.1°) Elevation Angle: -03.2° Horizon Angle: -00.8° Zoom: 1.0X 11767+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10696+00		<b>Field Station#</b>	11767+00	
<b>Pic 3 Desc.</b>	Rain gauge at Buffalo Anklets Road reads 0.3 inches.		<b>Pic 4 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.2 inches.	
 <p>Date &amp; Time: Tue, Jun 16, 2020, 09:45:58 EDT Position: +037 342542 / -080 472200 (+16.2ft) Altitude: 1750ft (+53.5ft) Datum: WGS-84 Azimuth/Bearing: 080° N80E 1422mils True (+16.1°) Elevation Angle: -00.6° Horizon Angle: -00.1° Zoom: 1.0X AR 234</p>		 <p>Date &amp; Time: Tue, Jun 16, 2020, 10:14:14 EDT Position: +037 342640 / -080 446427 (+14.3ft) Altitude: 2061ft (+62.8ft) Datum: WGS-84 Azimuth/Bearing: 116° S44E 2062mils True (+10.1°) Elevation Angle: -07.5° Horizon Angle: -03.5° Zoom: 1.0X 10696+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	11696+00	
<b>Pic 5 Desc.</b>	Rain gauge at Access Road 234 reads 0.3 inches.		<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 2:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 2:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11901
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	6/16/2020 1:06 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.25
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 1:06 PM	<b>Report #</b>	11901
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 205 - MP 207 Gathered rain gauge amounts Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/16/2020 1:06 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+1	
<b>Pic 1 Desc.</b>	.2" of rain recorded @ Kow Camp		<b>Pic 2 Desc.</b>	.25" of rain recorded @ Catawba	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10858+00		<b>Field Station#</b>	10875+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10888+00		<b>Field Station#</b>	10898+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 1:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2020 1:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11923
<b>Inspector</b>	Brian Shields			<b>Date/Time</b>	6/17/2020 8:25 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	56.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	1.05
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 8:25 AM	<b>Report #</b>	11923
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
VA SWPPP inspection MP 211.33 to 213.16 Heavy rain during time of inspection; thunderstorms forecasted for this afternoon. Site has accrued 2.25 inches and counting over 72 hours.  installed rock construction entrance is functioning as designed installed perimeter controls are in good working condition with no maintenance needed temporary stabilization throughout the area is sufficient, little to no sediment movement has been observed. diversion berms are functioning as designed slope drain pipe at 11215 has come apart and is functioning at half capacity installed waterbars are functioning as designed. sump pits are holding water as designed with end treatments filtering the release. orange safety fence is down at two locations.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 8:25 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11217+00		<b>Field Station#</b>	11215+50	
<b>Pic 1 Desc.</b>	Row conditions		<b>Pic 2 Desc.</b>	slope drain pipe disconnected	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11215+00		<b>Field Station#</b>	11208+00	
<b>Pic 3 Desc.</b>	slope drain pipe into sump		<b>Pic 4 Desc.</b>	stabilized row conditions	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11207+50		<b>Field Station#</b>	11173+50	
<b>Pic 5 Desc.</b>	safety fence down		<b>Pic 6 Desc.</b>	safety fence down.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 8:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 8:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11939
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/17/2020 3:16 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+25
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11534+50
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	1.75
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



AFE	124300137	Date/Time	6/17/2020 3:16 PM	Report #	
Pictures					
 <p>Date &amp; Time: Wed, Jun 17, 2020, 08:57:41 EDT Position: +037.297281° / -080.43494° (±6632.0ft) Altitude: 2241ft (±683.2ft) Datum: WGS-84 Azimuth/Bearing: 335° N45°W 500mils True (±16°) Elevation Angle: -12.0° Horizon Angle: -01.3° Zoom: 1.0X 11507+00</p>		 <p>Date &amp; Time: Wed, Jun 17, 2020, 08:58:00 EDT Position: +037.297281° / -080.43494° (±6632.0ft) Altitude: 2241ft (±683.2ft) Datum: WGS-84 Azimuth/Bearing: 335° N45°W 500mils True (±16°) Elevation Angle: -12.0° Horizon Angle: -01.3° Zoom: 1.0X 11489+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11507+00		Field Station#	11489+00	
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 2 Desc.	RCE in place at Stevers Gap Road in place.	
 <p>Date &amp; Time: Wed, Jun 17, 2020, 09:08:43 EDT Position: +037.324927° / -080.431419° (±15.7ft) Altitude: 2150ft (±10.9ft) Datum: WGS-84 Azimuth/Bearing: 315° N45°W 5600mils True (±14°) Elevation Angle: -03.1° Horizon Angle: +01.0° Zoom: 1.0X 11489+00</p>		 <p>Date &amp; Time: Wed, Jun 17, 2020, 09:43:00 EDT Position: +037.333252° / -080.432534° (±7812.1ft) Altitude: 2173ft (±93.1ft) Datum: WGS-84 Azimuth/Bearing: 340° N20°W 6044mils True (±16°) Elevation Angle: -22.2° Horizon Angle: -03.0° Zoom: 1.0X 11428+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	11428+00	
Pic 3 Desc.	Rain gauge at Stevers Gap Road reads 1.5 inches.		Pic 4 Desc.	Priority one silt fence stake broken at end treatment.	
 <p>Date &amp; Time: Wed, Jun 17, 2020, 09:46:38 EDT Position: +037.309148° / -080.463773° (±68632.0ft) Altitude: 2324ft (±68.2ft) Datum: WGS-84 Azimuth/Bearing: 316° N44°W 5618mils True (±16°) Elevation Angle: -21.5° Horizon Angle: +00.8° Zoom: 1.0X 11420+00</p>		 <p>Date &amp; Time: Wed, Jun 17, 2020, 10:51:40 EDT Position: +037.294025° / -080.367703° (±458.2ft) Altitude: 2011ft (±53.5ft) Datum: WGS-84 Azimuth/Bearing: 020° N02°E 3356mils True (±16°) Elevation Angle: -01.5° Horizon Angle: +00.5° Zoom: 1.0X Tabor</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11420+00		Field Station#	11767+00	
Pic 5 Desc.	Priority one silt fence stake broken at end treatment.		Pic 6 Desc.	Rain gauge at Mount Tabor Road reads 1.7 inches.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 3:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 3:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11940
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/17/2020 3:44 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	1.05
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 3:44 PM	<b>Report #</b>	11940
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213 to MP 214.8 as well as assessed AR 256.02. Inspection completed during ongoing rain event. No issues were located within the pipeline RoW. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Continuous rainfall and high water levels restricted views of some controls. During the assessment of AR 256.02 it was discovered that construction activities, conducted by VDOT, within the MVP RoW of AR 256.02. Multiple environmental controls have been impacted due to the VDOT construction and has created the potential for runoff and/or erosion issues.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/17/2020 3:44 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11265+00	<b>Field Station#</b>	11286+00		
<b>Pic 1 Desc.</b>	Perimeter controls functional.		<b>Pic 2 Desc.</b>	Perimeter controls functional.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11292+80	<b>Field Station#</b>	11327+85		
<b>Pic 3 Desc.</b>	S-MM18 and controls.		<b>Pic 4 Desc.</b>	S-NN12 and controls.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11352+97	<b>Field Station#</b>	11331+00		
<b>Pic 5 Desc.</b>	S-NN11 and controls.		<b>Pic 6 Desc.</b>	VDOT road construction on and off RoW disturbance along AR 256.02.	



<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 3:44 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	11331+00	<b>Field Station#</b>	11331+00		
<b>Pic 7 Desc.</b>	VDOT damaged controls on AR 256.02.		<b>Pic 8 Desc.</b>	VDOT road construction on and off RoW disturbance along AR 256.02. (Branch location of new road from AR 256.02).	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 3:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11967
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	6/18/2020 1:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions



Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 1:14 PM	<b>Report #</b>	11967
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted a routine VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The area received 1.6" of rainfall in the past 24 hours. No rilling or other form of erosion was located. Environmental controls were found in place, in good condition and functioning as designed. Slope breakers and end treatments are effective at control of runoff. Resource crossings are stable with ECDs in place. No impact to streams. RCEs are in good condition. No ECD maintenance needs were identified.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/18/2020 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11666+50	<b>Field Station#</b>	11663+00		
<b>Pic 1 Desc.</b>	End treatments in place and effective	<b>Pic 2 Desc.</b>	End treatments and perimeter controls functional		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11661+00	<b>Field Station#</b>	11646+00		
<b>Pic 3 Desc.</b>	End treatments and perimeter controls are in place and effective	<b>Pic 4 Desc.</b>	ROW stable. Slope breakers in place and functioning		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+20		
<b>Pic 5 Desc.</b>	S-HH18 crossing stable with environmental controls in place	<b>Pic 6 Desc.</b>	S-RR14 crossing stable with environmental controls in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	6/18/2020 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, Jun 18, 2020, 11:46:30 EDT Position: +037.314500° / -080.402671° (±14.4ft) Altitude: 1935ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 159° S27E 2720mils Magnetic (±13°) Elevation Angle: -15.2° Horizon Angle: +00.1° Zoom: 1.0X S-RR13 crossing stable</small></p>		 <p><small>Date &amp; Time: Thu, Jun 18, 2020, 11:49:00 EDT Position: +037.313530° / -080.404971° (±14.4ft) Altitude: 1908ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 158° S27E 1970mils Magnetic (±12°) Elevation Angle: -16.3° Horizon Angle: +00.3° Zoom: 1.0X S-006 crossing stable</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11613+69	<b>Field Station#</b>	11607+81		
<b>Pic 7 Desc.</b>	S-RR13 crossing stable with environmental controls in place	<b>Pic 8 Desc.</b>	S-006 crossing stable with environmental controls in place		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11973
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/18/2020 2:56 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 2:56 PM	<b>Report #</b>	11973
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Catawba Road - 0.8 inches and Mount Tabor Road - 0.7 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/18/2020 2:56 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11990+00		<b>Field Station#</b>	11670+00	
<b>Pic 1 Desc.</b>	Rain gauge at Catawba Road reads 0.8 inches.		<b>Pic 2 Desc.</b>	Triple stack compost filter sock and priority one silt fence in place along LOD.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11687+40		<b>Field Station#</b>	11767+00	
<b>Pic 3 Desc.</b>	Sensitive resource buffer in place at stream S-MN21.		<b>Pic 4 Desc.</b>	RCE in place at Main Line Valve 26.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11772+00	
<b>Pic 5 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.7 inches.		<b>Pic 6 Desc.</b>	Clean water diversion pipe inlet and clean water diversion berm in place.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 2:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 2:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11978
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	6/18/2020 1:55 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 1:55 PM	<b>Report #</b>	11978
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218 - MP 219.5 Gathered rain gauge amounts Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 1:55 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11532+00		<b>Field Station#</b>	11551+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11568+00		<b>Field Station#</b>	11555+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11585+00		<b>Field Station#</b>	11589+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 1:55 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 1:55 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11979
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/18/2020 3:56 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 3:56 PM	<b>Report #</b>	11979
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.3 to MP 227.37 as well as assessed AR 266. PPL crews were working between AR 266.03 and Catawba Rd repairing or replacing ECDs as needed. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	6/18/2020 3:56 PM	Report #	
Pictures					
<div><div><div>Date &amp; Time: Thu, Jun 18, 2020, 05:45:44 EDT Position: +45° 29' 59.57" / -80.29999° (-801.47) Altitude: 21531 (+22.87) Datum: WGS-84 Adm/Br/Bearing: 30° 330W 330mils True (+12°) Elevation Angle: -0.3° Horizon Angle: -0.3° Zoom: 1.0X 11789+00</div></div></div>		<div><div><div>Date &amp; Time: Thu, Jun 18, 2020, 05:16:01 EDT Position: +45° 29' 59.45" / -80.29999° (-801.47) Altitude: 21531 (+22.87) Datum: WGS-84 Adm/Br/Bearing: 30° 330W 330mils True (+12°) Elevation Angle: -0.3° Horizon Angle: -0.3° Zoom: 1.0X 11792+00</div></div></div>			
GPS Location	1	GPS Location	2		
Field Station#	11789+00	Field Station#	11792+00		
Pic 1 Desc.	RCE on the South side of Mt Tabor Rd.		Pic 2 Desc.	Section of restored RoW showing conditions and controls.	
<div><div><div>Date &amp; Time: Thu, Jun 18, 2020, 05:45:44 EDT Position: +45° 29' 59.57" / -80.29999° (-801.47) Altitude: 22231 (+22.87) Datum: WGS-84 Adm/Br/Bearing: 161° 330W 330mils True (+12°) Elevation Angle: -0.3° Horizon Angle: -0.3° Zoom: 1.0X 11828+00</div></div></div>		<div><div><div>Date &amp; Time: Thu, Jun 18, 2020, 05:41:47 EDT Position: +45° 29' 59.51" / -80.29999° (-801.47) Altitude: 21831 (+22.87) Datum: WGS-84 Adm/Br/Bearing: 288° N72W 5120 mils True (+12°) Elevation Angle: -0.3° Horizon Angle: -0.3° Zoom: 1.0X 11863+65</div></div></div>			
GPS Location	3	GPS Location	4		
Field Station#	11828+00	Field Station#	11863+65		
Pic 3 Desc.	Section of restored RoW showing conditions and controls.		Pic 4 Desc.	P-KL2 and controls.	
<div><div><div>Date &amp; Time: Thu, Jun 18, 2020, 10:16:12 EDT Position: +45° 29' 59.67" / -80.29999° (-801.47) Altitude: 22231 (+22.87) Datum: WGS-84 Adm/Br/Bearing: 161° 330W 330mils True (+12°) Elevation Angle: -0.3° Horizon Angle: -0.3° Zoom: 1.0X 11905+50</div></div></div>		<div><div><div>Date &amp; Time: Thu, Jun 18, 2020, 11:06:29 EDT Position: +45° 29' 59.69" / -80.29999° (-801.47) Altitude: 19431 (+22.87) Datum: WGS-84 Adm/Br/Bearing: 172° N72E 1951mils True (+12°) Elevation Angle: -0.3° Horizon Angle: -0.3° Zoom: 1.0X 11991+00</div></div></div>			
GPS Location	5	GPS Location	6		
Field Station#	11905+50	Field Station#	11991+00		
Pic 5 Desc.	Section of partially restored RoW showing conditions and controls.		Pic 6 Desc.	Section of restored RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 3:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2020 3:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	11982
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	6/17/2020 3:03 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+28
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.90
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 3:03 PM	<b>Report #</b>	11982
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 209- MP 211.5 Gathered rain gauge amounts Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/17/2020 3:03 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed, Jun 17, 2020, 08:30:01 EDT  Position: +037°18'55.44" / -080°52'37.54" (+29°11N)  Altitude: 2102ft (+640ft)  Datum: WGS-84  Azimuth/Bearing: 268° N72W 5120mils True (+12°)  Elevation Grade: -031%  Horizon Grade: -00%  Zoom: 1.0X  10862</p> 		<p>Date &amp; Time: Wed, Jun 17, 2020, 08:43:19 EDT  Position: +037°18'55.03" / -080°52'14.31" (+17°00N)  Altitude: 2144ft (+340ft)  Datum: WGS-84  Azimuth/Bearing: 148° S26E 2070mils True (+13°)  Elevation Grade: -022%  Horizon Grade: -00%  Zoom: 1.0X  11085</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10862+00		<b>Field Station#</b>	11085+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Wed, Jun 17, 2020, 09:07:06 EDT  Position: +037°18'58.96" / -080°52'36.66" (+29°11N)  Altitude: 2080ft (+640ft)  Datum: WGS-84  Azimuth/Bearing: 271° S26W 4000mils True (+12°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 1.0X  11096</p> 		<p>Date &amp; Time: Wed, Jun 17, 2020, 09:07:44 EDT  Position: +037°18'57.57" / -080°52'10.06" (+17°00N)  Altitude: 2131ft (+329.6ft)  Datum: WGS-84  Azimuth/Bearing: 270° S26W 4000mils True (+12°)  Elevation Grade: -010%  Horizon Grade: -00%  Zoom: 1.0X  11110</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11096+00		<b>Field Station#</b>	11110+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Wed, Jun 17, 2020, 09:11:46 EDT  Position: +037°18'59.17" / -080°51'34.77" (+24°44.5N)  Altitude: 1930ft (+621ft)  Datum: WGS-84  Azimuth/Bearing: 274° N86W 4871mils True (+12°)  Elevation Grade: -031%  Horizon Grade: +00%  Zoom: 1.0X  11140</p> 		<p>Date &amp; Time: Wed, Jun 17, 2020, 10:17:55 EDT  Position: +037°18'55.04" / -080°14'12.25" (+13°7N)  Altitude: 1425ft (+10.8ft)  Datum: WGS-84  Azimuth/Bearing: 154° S26E 2738mils True (+12°)  Elevation Grade: -007%  Horizon Grade: -002%  Zoom: 1.0X  1.9" cal</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11140+00		<b>Field Station#</b>	+1	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	1.9" of rain recorded @ Catawba	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 3:03 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2020 3:03 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12025
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/19/2020 3:22 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/19/2020 3:22 PM	<b>Report #</b>	12025
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	6/19/2020 3:22 PM	Report #	
Pictures					
 <p>Date &amp; Time: Fri, Jun 19, 2020, 09:21:57 EDT Position: +097°21'31.74" / +030°55'38.41" (NAD83) Altitude: 1787ft (±11.3m) Datum: WGS-84 Azimuth Bearing: 134.543° (562mils True (±10.1)) Elevation Angle: +31.6° Horizon Angle: -09.2° Zoom: 1.0X LDY 26</p>		 <p>Date &amp; Time: Fri, Jun 19, 2020, 09:28:09 EDT Position: +097°21'31.74" / +030°55'38.41" (NAD83) Altitude: 1787ft (±11.3m) Datum: WGS-84 Azimuth Bearing: 101.1° (SW) (172mils True (±10.1)) Elevation Angle: +31.6° Horizon Angle: -09.2° Zoom: 1.0X LDY 26</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Dumpsters being utilized for trash management.		Pic 2 Desc.	18 inch compost filter sock in place along LOD.	
 <p>Date &amp; Time: Fri, Jun 19, 2020, 09:40:19 EDT Position: +097°21'31.74" / +030°55'38.41" (NAD83) Altitude: 1787ft (±11.3m) Datum: WGS-84 Azimuth Bearing: 134.543° (562mils True (±10.1)) Elevation Angle: +31.6° Horizon Angle: -09.2° Zoom: 1.0X LDY 26</p>		 <p>Date &amp; Time: Fri, Jun 19, 2020, 09:40:19 EDT Position: +097°21'31.74" / +030°55'38.41" (NAD83) Altitude: 1787ft (±11.3m) Datum: WGS-84 Azimuth Bearing: 101.1° (SW) (172mils True (±10.1)) Elevation Angle: +31.6° Horizon Angle: -09.2° Zoom: 1.0X LDY 26</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	RCE in place at LDY 26 entrance.		Pic 4 Desc.	Triple stack 12 inch compost filter sock in place along LOD.	
 <p>Date &amp; Time: Fri, Jun 19, 2020, 09:40:19 EDT Position: +097°21'31.74" / +030°55'38.41" (NAD83) Altitude: 1787ft (±11.3m) Datum: WGS-84 Azimuth Bearing: 134.543° (562mils True (±10.1)) Elevation Angle: +31.6° Horizon Angle: -09.2° Zoom: 1.0X LDY 26</p>		 <p>Date &amp; Time: Fri, Jun 19, 2020, 09:40:19 EDT Position: +097°21'31.74" / +030°55'38.41" (NAD83) Altitude: 1787ft (±11.3m) Datum: WGS-84 Azimuth Bearing: 101.1° (SW) (172mils True (±10.1)) Elevation Angle: +31.6° Horizon Angle: -09.2° Zoom: 1.0X LDY 26</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Checked staged equipment for leaks.		Pic 6 Desc.	Secondary containment in place under fuel cell.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/19/2020 3:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/19/2020 3:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12029
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	6/19/2020 1:21 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Secondary Containment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	Yes

<b>A/E</b>	124300137	<b>Date/Time</b>	6/19/2020 1:21 PM	<b>Report #</b>	12029
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 & 29 Gathered rain gauge amounts Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	6/19/2020 1:21 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri Jun 19 2020 09:11:07 EDT  Position: +037°20'54.77" N -080°33'19.93" W (501.81ft)  Altitude: 2092ft (+42.5m)  Datum: WGS-84  Azimuth/Bearing: 209° S30W 3733mils True (±5°)  Elevation Grade: -013%  Horizon Grade: -001%  Zoom: 1.0X  1" = 1ft</p> 		<p>Date &amp; Time: Fri Jun 19 2020 09:18:20 EDT  Position: +037°22'14.42" N -080°40'51.27" W (163.1ft)  Altitude: 1899ft (+58.0ft)  Datum: WGS-84  Azimuth/Bearing: 069° N49E 12270mils True (±5°)  Elevation Grade: -004%  Horizon Grade: -092%  Zoom: 1.0X  1" = 234"</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+2	
<b>Pic 1 Desc.</b>	.1" of rain recorded @ Buffalo Anklets		<b>Pic 2 Desc.</b>	.1" of rain recorded @ AR 234	
<p>Date &amp; Time: Fri Jun 19 2020 09:45:07 EDT  Position: +037°17'46.85" N -081°02'24.75" W (520.80ft)  Altitude: 2014ft (+62.1ft)  Datum: WGS-84  Azimuth/Bearing: 264° S84W 4723mils True (±5°)  Elevation Grade: +003%  Horizon Grade: -002%  Zoom: 1.0X  1" = 1ft</p> 		<p>Date &amp; Time: Fri Jun 19 2020 09:50:41 EDT  Position: +036°01'42.01" N -080°40'58.97" W (226.4ft)  Altitude: 1711ft (+51.4ft)  Datum: WGS-84  Azimuth/Bearing: 305° S85W 4020mils True (±5°)  Elevation Grade: -002%  Horizon Grade: -001%  Zoom: 1.0X  1" = 234"</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+3		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	.1" of rain recorded @ Tabor		<b>Pic 4 Desc.</b>	ECD's and row conditions LDY 29	
<p>Date &amp; Time: Fri Jun 19 2020 09:45:07 EDT  Position: +037°20'54.77" N -080°33'19.93" W (501.81ft)  Altitude: 1500ft (+45.7m)  Datum: WGS-84  Azimuth/Bearing: 264° S84W 5038mils True (±5°)  Elevation Grade: -004%  Horizon Grade: -001%  Zoom: 1.0X  1" = 1ft</p> 		<p>Date &amp; Time: Fri Jun 19 2020 09:48:39 EDT  Position: +037°20'54.77" N -080°40'51.27" W (163.1ft)  Altitude: 1520ft (+45.7m)  Datum: WGS-84  Azimuth/Bearing: 306° N84W 5400mils True (±5°)  Elevation Grade: -013%  Horizon Grade: -001%  Zoom: 1.0X  1" = 234"</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions LDY 28		<b>Pic 6 Desc.</b>	ECD's and row conditions @ LDY 28	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/19/2020 1:21 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/19/2020 1:21 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		