



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11653
Inspector	Rob Robertson			Date/Time	6/8/2020 12:46 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Dry	Temperature (°F)	74.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/8/2020 12:46 PM	Report #	11653
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
A routine VADEQ SWPPP inspection was completed today on private and JNF tracts at Brush Mountain. ROW conditions are currently stable. ECDs are in place with no maintenance needs identified. Resource crossings and access points are in good condition. No erosion or sediment movement of any kind located. Protesters painted graffiti on the pipe at FS188 access point. No other evidence of vandalism found.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/8/2020 12:46 PM	Report #	
Pictures					
<p>Date & Time: Mon, Jun 08, 2020, 09:53:54 EDT Position: +037.303390, -080.594785 (+16.4ft) Altitude: 2822ft (+157.7ft) Datum: WGS-84 Azimuth/Bearing: 248° S48W 4409mils Magnetic (+13°) Elevation Angle: -21.7° Horizon Angle: +01.6° Zoom: 1.0X Brush Min: 11669+87</p> 		<p>Date & Time: Mon, Jun 08, 2020, 10:13:07 EDT Position: +037.305227, -080.594785 (+16.4ft) Altitude: 2822ft (+157.7ft) Datum: WGS-84 Azimuth/Bearing: 219° S39W 3893mils Magnetic (+13°) Elevation Angle: -02.3° Horizon Angle: -02.4° Zoom: 1.0X Brush Min: 11669+50</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11669+87	Field Station#	11669+50		
Pic 1 Desc.	Graffiti painted on pipe over weekend.	Pic 2 Desc.	Graffiti painted on pipe over weekend.		
<p>Date & Time: Mon, Jun 08, 2020, 10:03:29 EDT Position: +037.309770, -080.594902 (+16.4ft) Altitude: 2822ft (+157.7ft) Datum: WGS-84 Azimuth/Bearing: 289° S40W 3911mils Magnetic (+13°) Elevation Angle: -02.3° Horizon Angle: +01.6° Zoom: 1.0X Brush Min: 11669+50</p> 		<p>Date & Time: Mon, Jun 08, 2020, 10:11:14 EDT Position: +037.305227, -080.594785 (+16.4ft) Altitude: 2822ft (+157.7ft) Datum: WGS-84 Azimuth/Bearing: 209° S40W 4288mils Magnetic (+12°) Elevation Angle: -02.3° Horizon Angle: +00.3° Zoom: 1.0X Brush Min: 11669+00. End treatments functional</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11669+50	Field Station#	11659+00		
Pic 3 Desc.	Graffiti painted on pipe over weekend.	Pic 4 Desc.	End treatments are in place and functional.		
<p>Date & Time: Mon, Jun 08, 2020, 10:44:11 EDT Position: +037.311470, -080.597372 (+16.4ft) Altitude: 2004ft (+157.7ft) Datum: WGS-84 Azimuth/Bearing: 229° N51W 5316mils Magnetic (+13°) Elevation Angle: +01.5° Horizon Angle: -00.5° Zoom: 1.0X Brush Min: ROW stable 11629+00</p> 		<p>Date & Time: Mon, Jun 08, 2020, 10:44:11 EDT Position: +037.311470, -080.597372 (+16.4ft) Altitude: 1954ft (+157.7ft) Datum: WGS-84 Azimuth/Bearing: 165° S15E 2933mils Magnetic (+13°) Elevation Angle: +01.8° Horizon Angle: -01.2° Zoom: 1.0X Brush Min: Right of way crossing is stable 11626+04</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11629+00	Field Station#	11626+04		
Pic 5 Desc.	ROW stable. Slope breakers functional. ECDs in place.	Pic 6 Desc.	S-HH18 crossing stable.		

AFE	124300137	Date/Time	6/8/2020 12:46 PM	Report #	
Pictures					
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11614+20	Field Station#	11607+81		
Pic 7 Desc.	S-RR14 crossing is stable.	Pic 8 Desc.	S-006 crossing is stable.		
					
GPS Location	On photo	GPS Location			
Field Station#	11602+50	Field Station#			
Pic 9 Desc.	ROW currently stable.	Pic 10 Desc.			
					
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	6/8/2020 12:46 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report


Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11659
Inspector	Len Kruizenga			Date/Time	6/8/2020 2:17 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+99
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	71.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/8/2020 2:17 PM	Report #	11659
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with EI's at Winding Way. SWPPP inspection: Sta#11899+99 to 12005+00. MP-225.3 to 227.3 Catawba rain gauge reading- 0.80" The row is dry and in stable condition. The vegetation in the inspection area is good. P1 silt fence, SSF and CFS perimeter controls are in acceptable condition. Water bars and level spreaders are in good condition. Karst's ECD's are in acceptable condition. AR-266.03 and AR-266.00 are maintained in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/8/2020 2:17 PM	Report #	
Pictures					
 <p>Date & Time: Mon Jun 08 2020 09:32:12 EDT Position: +037.297412, -080.333714 (+32.8ft) Altitude: 2310ft (+69.2ft) Datum: WGS-84 Azimuth/Bearing: 305° N55W 342mils True (+10°) Elevation Angle: -18.6° Horizon Angle: -101.5° Zoom: 1.0x Star: 11949-00- Access road & controls</p>		 <p>Date & Time: Mon Jun 08 2020 09:57:15 EDT Position: +037.275055, -080.316858 (+7.6ft 3ft) Altitude: 2263ft (+12.4ft) Datum: WGS-84 Azimuth/Bearing: 189° S09W 334mils True (+10°) Elevation Angle: -19.5° Horizon Angle: -102.2° Zoom: 1.0x Star: 11942-00- Karst ECD's</p>		GPS Location	See photo GPS
Field Station#	11900+00	Field Station#	11942+00	GPS Location	See photo GPS
Pic 1 Desc.	AR-266.03	Pic 2 Desc.	Karst ECD's	Field Station#	11949+00
 <p>Date & Time: Mon Jun 08 2020 10:05:05 EDT Position: +037.277928, -080.326170 (+10.0ft) Altitude: 2180ft (+66.9ft) Datum: WGS-84 Azimuth/Bearing: 359° S01W 338mils True (+25°) Elevation Angle: -100.8° Horizon Angle: -102.9° Zoom: 1.0x Star: 11949-00- Row vegetation</p>		 <p>Date & Time: Mon Jun 08 2020 10:07:27 EDT Position: +037.275808, -080.326170 (+9.8ft) Altitude: 1922ft (+315.1ft) Datum: WGS-84 Azimuth/Bearing: 217° S37W 385mils True (+18°) Elevation Angle: -100.6° Horizon Angle: -100.2° Zoom: 1.0x Star: 11954-00- Level spreader</p>		GPS Location	See photo GPS
Field Station#	11949+00	Field Station#	11954+00	GPS Location	See photo GPS
Pic 3 Desc.	Permanent restoration vegetation.	Pic 4 Desc.	Level spreader	Field Station#	11989+00
 <p>Date & Time: Mon Jun 08 2020 10:27:13 EDT Position: +037.248113, -080.333714 (+26.2ft) Altitude: 1611ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 093° S87E 1833mils True (+10°) Elevation Angle: -27.5° Horizon Angle: -100.8° Zoom: 1.0x AR-266.00- Access road culvert inlet</p>		 <p>Date & Time: Mon Jun 08 2020 10:28:27 EDT Position: +037.248972, -080.320073 (+16.4ft) Altitude: 1627ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 127° S53E 2258mils True (+10°) Elevation Angle: -13.7° Horizon Angle: -101.5° Zoom: 1.0x Catawba rain gauge feeding 0.80"</p>		GPS Location	See photo GPS
Field Station#	11989+00	Field Station#	11990+00	GPS Location	See photo GPS
Pic 5 Desc.	AR-266.00- Access road culvert inlet.	Pic 6 Desc.	Catawba rain gauge reading- 0.80"	Field Station#	

A/E	124300137	Date/Time	6/8/2020 2:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/8/2020 2:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11664
Inspector	Jared Saunders			Date/Time	6/8/2020 3:33 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.15
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/8/2020 3:33 PM	Report #	11664
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 219.6 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Rain gauge at Mount Tabor Road reads 0.15 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/8/2020 3:33 PM	Report #	
Pictures					
<p>Date & Time: Mon, Jun 08, 2020, 11:20:15 EDT Position: +037.224881° / +080.427119° (+1623.00) Altitude: 2825ft (+110.3m) Datum: WGS-84 Azimuth/Bearing: 156° S24E 2773mils True (+13°) Elevation Angle: -22.0° Horizon Angle: +01.8° Zoom: 1.0X 11671+00</p>					
<p>Date & Time: Mon, Jun 08, 2020, 10:14:29 EDT Position: +037.299265° / +080.511352° (+16427.4ft) Altitude: 2838ft (+107.5ft) Datum: WGS-84 Azimuth/Bearing: 1157° S21E 2791mils True (+13°) Elevation Angle: -11.5° Horizon Angle: +00.3° Zoom: 1.0X 11687+40</p>					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11671+00		Field Station#	11687+40	
Pic 1 Desc.	Waterbars in place and ROW stabilized with seed, mulch, and minor vegetation growth.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-MN21.	
<p>Date & Time: Mon, Jun 08, 2020, 11:20:15 EDT Position: +037.224881° / +080.427119° (+1623.00) Altitude: 2059ft (+125.7m) Datum: WGS-84 Azimuth/Bearing: 100° S80E 1278mils True (+13°) Elevation Angle: -07.3° Horizon Angle: +00.3° Zoom: 1.0X 11767+00</p>					
<p>Date & Time: Mon, Jun 08, 2020, 11:32:21 EDT Position: +037.678104° / +080.367963° (+63.3ft) Altitude: 2029ft (+62.4m) Datum: WGS-84 Azimuth/Bearing: 061° N61E 1084mils True (+13°) Elevation Angle: -00.2° Horizon Angle: +00.5° Zoom: 1.0X 11767+00</p>					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11767+00	
Pic 3 Desc.	RCE in place at main line valve 26.		Pic 4 Desc.	Rain gauge at Mount Tabor Road reads 0.15 inches.	
<p>Date & Time: Mon, Jun 08, 2020, 11:35:33 EDT Position: +037.224716° / +080.350446° (+31494.3ft) Altitude: 2613ft (+144.9m) Datum: WGS-84 Azimuth/Bearing: 095° N55E 0978mils True (+13°) Elevation Angle: +03.7° Horizon Angle: +03.2° Zoom: 1.0X 11772+00</p>					
<p>Date & Time: Mon, Jun 08, 2020, 11:38:53 EDT Position: +037.224410° / +080.344936° (+316.4ft) Altitude: 2088ft (+268.2m) Datum: WGS-84 Azimuth/Bearing: -181° S01W 3218mils True (+13°) Elevation Angle: -13.5° Horizon Angle: +04.3° Zoom: 1.0X 11775+00</p>					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11772+00		Field Station#	11775+00	
Pic 5 Desc.	Clean water diversion pipe and clean water diversion berm in place.		Pic 6 Desc.	Clean water diversion pipe and plunge pool in place.	

A/E	124300137	Date/Time	6/8/2020 3:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/8/2020 3:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11670
Inspector	Chris Burns			Date/Time	6/8/2020 4:10 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+99
County	Montgomery	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/8/2020 4:10 PM	Report #	11670
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Performed SWPPP inspection from MP 223.3 to MP 225.3 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		6/8/2020 4:10 PM		Report #					
Pictures													
													
GPS Location				1		GPS Location				2			
Field Station#				11789+00		Field Station#				11798+00			
Pic 1 Desc.				RCE on this South side of Mt Tabor rd.				Pic 2 Desc.				Section of restored RoW showing conditions and controls.	
													
GPS Location				3		GPS Location				4			
Field Station#				11818+00		Field Station#				11845+00			
Pic 3 Desc.				Section of restored RoW showing conditions and controls.				Pic 4 Desc.				Section of restored RoW showing conditions and controls.	
													
GPS Location				5		GPS Location				6			
Field Station#				11863+65		Field Station#				11899+00			
Pic 5 Desc.				P-KL2 and controls.				Pic 6 Desc.				Section of restored RoW showing conditions and controls.	

A/E	124300137	Date/Time	6/8/2020 4:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/8/2020 4:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11688
Inspector	Len Kruizenga			Date/Time	6/9/2020 8:26 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	71.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/9/2020 8:26 AM	Report #	11688
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
EI meeting at the work trailer. SWPPP inspection: LY-29 AR-238.00- Access road serving LY-29 is in acceptable condition. The rock surface of the yard is maintained in acceptable condition. Materials storage is acceptable. Waste management is acceptable. House keeping is acceptable. CSF triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. There are no mechanical equipment stored in the yard.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/9/2020 8:26 AM	Report #	
Pictures					
 <p>Date & Time: Tue, Jun 09, 2020, 09:41:31 EDT Position: +037.363179° / -080.672129° (-16.6ft) Altitude: 1801ft (-59.4ft) Datum: WGS-84 Azimuth/Bearing: 229° S46W 4071mils True (+25°) Elevation Angle: -04.8° Horizon Angle: -00.7° Zoom: 1.0X LY-29- Access road to LY-29.</p>		 <p>Date & Time: Tue, Jun 09, 2020, 09:46:01 EDT Position: +037.363186° / -080.672627° (-16.5ft) Altitude: 1800ft (-59.4ft) Datum: WGS-84 Azimuth/Bearing: 239° S60W 4216mils True (+26°) Elevation Angle: -05.2° Horizon Angle: -00.6° Zoom: 1.0X LY-29- Overhead view of the yard.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	AR-238.00- Access road to LY-29.	Pic 2 Desc.	LY-29- Over view of the yard.		
 <p>Date & Time: Tue, Jun 09, 2020, 09:48:27 EDT Position: +037.363227° / -080.677334° (-19.8ft) Altitude: 1711ft (-59.4ft) Datum: WGS-84 Azimuth/Bearing: 249° S68W 4409mils True (+30°) Elevation Angle: -11.6° Horizon Angle: -00.7° Zoom: 1.0X LY-29- PPL materials storage.</p>		 <p>Date & Time: Tue, Jun 09, 2020, 09:50:21 EDT Position: +037.363186° / -080.676725° (-132.8ft) Altitude: 1694ft (-58.7ft) Datum: WGS-84 Azimuth/Bearing: 339° N61W 5183mils True (+31°) Elevation Angle: -19.8° Horizon Angle: -00.6° Zoom: 1.0X LY-29- Rock surface of the yard is maintained in acceptable condition.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	LY-29- PPL materials storage.	Pic 4 Desc.	LY-29- Rock surface of the yard is maintained in acceptable condition.		
 <p>Date & Time: Tue, Jun 09, 2020, 09:52:01 EDT Position: +037.363254° / -080.676636° (-132.8ft) Altitude: 1690ft (-59.4ft) Datum: WGS-84 Azimuth/Bearing: 284° N76W 5049mils True (+25°) Elevation Angle: -12.4° Horizon Angle: -00.7° Zoom: 1.0X LY-29- CFS triple stack perimeter controls.</p>		 <p>Date & Time: Tue, Jun 09, 2020, 09:55:12 EDT Position: +037.363611° / -080.677247° (-49.8ft) Altitude: 1721ft (-59.4ft) Datum: WGS-84 Azimuth/Bearing: 011° N11E 0156mils True (+31°) Elevation Angle: -18.3° Horizon Angle: -00.2° Zoom: 1.0X LY-29- Culvert and drainage feature.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	LY-29- CFS triple stack perimeter controls.	Pic 6 Desc.	LY-29- Culvert and drainage feature.		

A/E	124300137	Date/Time	6/9/2020 8:26 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	6/9/2020 8:26 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11703
Inspector	Garrett Barclay			Date/Time	6/9/2020 2:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	84.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/9/2020 2:13 PM	Report #	11703
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Observed crews replacing CFS for LDY 28					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/9/2020 2:13 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Secondary containment		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	Secondary containment	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Crew replacing CFS		Pic 6 Desc.	Removed CFS	

A/E	124300137	Date/Time	6/9/2020 2:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/9/2020 2:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11705
Inspector	Jared Saunders			Date/Time	6/9/2020 5:40 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/9/2020 5:40 PM	Report #	11705
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 6/9/2020 5:40 PM		Report #	
Pictures					
<p>Date & Time: Tue Jun 09 2020 09:59:24 EDT Position: +037.31978° / -080.65771° (-213.5h) Altitude: 1795ft (-32.8h) Datum: WGS-84 Azimuth/Bearing: 001° N01E 0018mils True (-13°) Elevation Angle: -11.3 Horizon Angle: -04.2 Zoom: 1.0x LDY 26</p> 		<p>Date & Time: Tue Jun 09 2020 10:00:00 EDT Position: +037.31978° / -080.65801° (-213.5h) Altitude: 1795ft (-32.8h) Datum: WGS-84 Azimuth/Bearing: 091° S89E 1618mils True (-20°) Elevation Angle: -01.4 Horizon Angle: -03.9 Zoom: 1.0x LDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack compost filter sock in place around drainage.		Pic 2 Desc.	Checked staged equipment for leaks.	
<p>Date & Time: Tue Jun 09 2020 10:18:52 EDT Position: +037.319289° / -080.657560° (-213.5h) Altitude: 1795ft (-32.8h) Datum: WGS-84 Azimuth/Bearing: 009° N09E 0160mils True (-12°) Elevation Angle: -01.1 Horizon Angle: -01.1 Zoom: 1.0x LDY 26</p> 		<p>Date & Time: Tue Jun 09 2020 10:22:00 EDT Position: +037.31933° / -080.65831° (-213.5h) Altitude: 1807ft (-33.1h) Datum: WGS-84 Azimuth/Bearing: 089° N89E 1690mils True (-15°) Elevation Angle: -1.4° Horizon Angle: -00.3° Zoom: 1.0x LDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Secondary containment in place under fuel cell.		Pic 4 Desc.	RCE in place at employee parking lot entrance.	
<p>Date & Time: Tue Jun 09 2020 10:24:50 EDT Position: +037.31942° / -080.65836° (-213.5h) Altitude: 1795ft (-32.8h) Datum: WGS-84 Azimuth/Bearing: 270° S90W 3500mils True (-22.1°) Elevation Angle: +05.9 Horizon Angle: +00.2 Zoom: 1.0x LDY 26</p> 		<p>Date & Time: Tue Jun 09 2020 10:26:10 EDT Position: +037.31974° / -080.65886° (-213.5h) Altitude: 1795ft (-32.8h) Datum: WGS-84 Azimuth/Bearing: 251° S71W 4442mils True (-10.1°) Elevation Angle: -02.4° Horizon Angle: -01.4° Zoom: 1.0x LDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Dumpsters being utilized for trash management.		Pic 6 Desc.	18 inch compost filter sock in place along LOD.	

A/E	124300137	Date/Time	6/9/2020 5:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/9/2020 5:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11736
Inspector	Len Kruizenga			Date/Time	6/10/2020 8:05 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+88
State	VA	Inspection Area	Full	Station End	10930+00
County	Giles	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/10/2020 8:05 AM	Report #	11736
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met at the work trailer for EI meeting. SWPPP inspection: Sta#11023+88 to 10930+00. MP-208.6 to 206.2 The row is dry and in stable condition. Temporary stabilization is acceptable, vegetation is good. Water bars, sump pits, end treatments are in acceptable condition. Silt fence, CFS, & SSF perimeter controls are in acceptable condition. Stream S-IJ18, S-RR5, S-E24, S-E25 are in good condition, ECD's, Bridges, buffers & signage are in acceptable condition. Sta#10965+00- Bat habitat ECD's are in good condition. AR-244.00 and Doe Creek RCE are in acceptable condition. Sta#10956+00 to 10950+00- The contractor has removed ECD's because the landowner continues to graze the row and cattle continue to damage controls.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/10/2020 8:05 AM	Report #	
Pictures					
<p>Date & Time: Wed, Jun 10, 2020, 09:22:22 EDT Position: +037.32323° / -080.55551° (±16.4m) Altitude: 2390ft (±19.7m) Datum: WGS-84 Azimuth/Bearing: 006° N06E 0107mils True (±15.1) Elevation Angle: -12.2 Horizon Angle: -100.8 Zoom: 1.0X Sta#11018+00- Stream S- IJ18- Stream bridge & controls.</p> 		<p>Date & Time: Wed, Jun 10, 2020, 09:31:17 EDT Position: +037.32323° / -080.55551° (±16.4m) Altitude: 2390ft (±19.7m) Datum: WGS-84 Azimuth/Bearing: 106° S74E 1886mils True (±10.1) Elevation Angle: 21.6 Horizon Angle: -102.1 Zoom: 1.0X Sta#11016+00- Stream RR5- Bridge controls.</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11024+00		Field Station#	11016+00	
Pic 1 Desc.	AR-244.00, stream S-IJ18 bridge & controls.		Pic 2 Desc.	Stream S- RR5, bridge & controls.	
<p>Date & Time: Wed, Jun 10, 2020, 09:31:18 EDT Position: +037.32527° / -080.56257° (±16.4m) Altitude: 2566ft (±52.5ft) Datum: WGS-84 Azimuth/Bearing: 094° S84E 1707mils True (±10.1) Elevation Angle: -01.1 Horizon Angle: -01.0 Zoom: 1.0X Sta#10995+00- Row vegetation is good, clover thick on steep slope.</p> 		<p>Date & Time: Wed, Jun 10, 2020, 09:52:15 EDT Position: +037.325358° / -080.565217° (±16.4m) Altitude: 2702ft (±839.7m) Datum: WGS-84 Azimuth/Bearing: 094° S86E 1671mils True (±25.1) Elevation Angle: 38.5 Horizon Angle: -101.4 Zoom: 1.0X Sta#10986+00- Stream S- E25- Bridge & controls.</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	10995+00		Field Station#	10986+00	
Pic 3 Desc.	Row vegetation is acceptable.		Pic 4 Desc.	Stream S- E25- Bridge & controls.	
<p>Date & Time: Wed, Jun 10, 2020, 09:52:59 EDT Position: +037.32532° / -080.564902° (±16.4m) Altitude: 2403ft (±19.7m) Datum: WGS-84 Azimuth/Bearing: 299° N61W 3316mils True (±10.1) Elevation Angle: -12.9 Horizon Angle: -102.3 Zoom: 1.0X Sta#10985+00- Stream S-E24- Bridge & controls.</p> 		<p>Date & Time: Wed, Jun 10, 2020, 10:06:59 EDT Position: +037.325397° / -080.57113° (±16.4m) Altitude: 2565ft (±52.4m) Datum: WGS-84 Azimuth/Bearing: 314° N26W 3326mils True (±10.1) Elevation Angle: -07.2 Horizon Angle: -001.2 Zoom: 1.0X Sta#10965+00- Bat habitat trees.</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	10985+00		Field Station#	10965+00	
Pic 5 Desc.	Stream S-E24- Stream & controls		Pic 6 Desc.	Bat habitat and ECD's	

A/E	124300137	Date/Time	6/10/2020 8:05 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/10/2020 8:05 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11748
Inspector	Garrett Barclay			Date/Time	6/10/2020 3:18 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+62
County	Giles	Ground	Dry	Temperature (°F)	81.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/10/2020 3:18 PM	Report #	11748
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 205 - MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/10/2020 3:18 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10854+00		Field Station#	10854+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10858+00		Field Station#	10869+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10891+00		Field Station#	10873+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	6/10/2020 3:18 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/10/2020 3:18 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11753
Inspector	Chris Burns			Date/Time	6/10/2020 4:06 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11064+53
County	Giles	Ground	Dry	Temperature (°F)	77.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/10/2020 4:06 PM	Report #	11753
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDS and are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. PPL crews were currently working in this section repairing/replacing ECDs as needed. PM showers.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/10/2020 4:06 PM	Report #	
Pictures					
<p>Date & Time Wed, Jun 10, 2020, 09:29:51 EDT Position: +037.209217° / +080.553133° (+2390' 11") Altitude: 1857ft (+37.44' / 080.553133° (+2390' 11") Datum: WGS-84 Azimuth/Bearing: 029° N29E 0516mils True (+1.4) Elevation Angle: -08.8 Horizon Angle: +01.1 Zoom: 0.5X S-IJ18</p> 		<p>Date & Time Wed, Jun 10, 2020, 09:08:05 EDT Position: +037.209217° / +080.553133° (+2390' 11") Altitude: 1857ft (+37.44' / 080.553133° (+2390' 11") Datum: WGS-84 Azimuth/Bearing: 139° S01E 074mils True (+1.2) Elevation Angle: +00.7 Horizon Angle: +01.2 Zoom: 0.5X S-IJ18</p> 			
GPS Location	1	GPS Location	2		
Field Station#	11025+50	Field Station#	11034+00		
Pic 1 Desc.	S-IJ18 and controls.	Pic 2 Desc.	Section of RoW showing conditions and controls.		
<p>Date & Time Wed, Jun 10, 2020, 09:39:34 EDT Position: +037.216306° / +080.55752° (+2710' 04") Altitude: 2040ft (+41.5133) Datum: WGS-84 Azimuth/Bearing: 302° W08W 500mils True (+1.2) Elevation Angle: +00.4 Horizon Angle: +00.5 Zoom: 0.5X 11049+00</p> 		<p>Date & Time Wed, Jun 10, 2020, 09:41:32 EDT Position: +037.216311° / +080.55772° (+2710' 04") Altitude: 2040ft (+41.5133) Datum: WGS-84 Azimuth/Bearing: 006° N06E 0107mils True (+1.2) Elevation Angle: +00.5 Horizon Angle: +00.5 Zoom: 0.5X S-IJ16B/S-IJ7</p> 			
GPS Location	3	GPS Location	4		
Field Station#	11049+00	Field Station#	11050+10		
Pic 3 Desc.	Section of RoW showing conditions and controls.	Pic 4 Desc.	S-IJ16B/S-IJ7 and controls.		
<p>Date & Time Wed, Jun 10, 2020, 09:41:58 EDT Position: +037.217447° / +080.54677° (+2681' 57") Altitude: 2170ft (+43.57) Datum: WGS-84 Azimuth/Bearing: 149° S11E 300mils True (+1.2) Elevation Angle: -02.9 Horizon Angle: +00.9 Zoom: 0.5X 11054+50</p> 		<p>Date & Time Wed, Jun 10, 2020, 09:46:24 EDT Position: +037.218229° / +080.54697° (+2681' 57") Altitude: 2074ft (+43.77) Datum: WGS-84 Azimuth/Bearing: 312° N04W 300mils True (+1.2) Elevation Angle: +00.9 Horizon Angle: +00.9 Zoom: 0.5X 11064+50</p> 			
GPS Location	5	GPS Location	6		
Field Station#	11054+50	Field Station#	11064+50		
Pic 5 Desc.	Perimeter controls functional.	Pic 6 Desc.	Section of RoW showing conditions and controls.		

A/E	124300137	Date/Time	6/10/2020 4:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/10/2020 4:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11764
Inspector	Len Kruizenga			Date/Time	6/11/2020 8:41 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Full	Station End	11158+27
County	Giles	Ground	Dry	Temperature (°F)	66.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Problem Area			
Rock Check Dam	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/11/2020 8:41 AM	Report #	11764
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection:Sta#11254+99 to 11158+27. MP- 211 to 213 Winding Way rain gauge reading- 0.00" Access rods Winding Way, AR-249.02, AR- 249.01 are in acceptable condition Temporary stabilization is acceptable. Row is dry and in stable condition. Perimeter controls are in acceptable condition. Water bars and sump pits & end treatment's are in acceptable condition. Slope drains are in acceptable condition. CWD pipe and plunge pool are in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/11/2020 8:41 AM	Report #	
Pictures					
 <p>Date & Time: Thu, Jun 11, 2020 13:27:24 EDT Position: +037.309559° / -080.509583° (-541.4ft) Altitude: 0ft (Error) Datum: WGS-84 Azimuth/Bearing: 183° 503W 3253mils True (±10°) Elevation Angle: -04.4° Horizon Angle: +00.5° Zoom: 1.0X Winding Way rain gauge reading- 0.00"</p>		 <p>Date & Time: Thu, Jun 11, 2020 08:41 EDT Position: +037.309559° / -080.509583° (-541.4ft) Altitude: 0ft (Error) Datum: WGS-84 Azimuth/Bearing: 183° 503W 3253mils True (±10°) Elevation Angle: -04.4° Horizon Angle: +00.5° Zoom: 1.0X Sta#11227+00 to 11237+00- Row vegetation.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11227+00	Field Station#	11227+00		
Pic 1 Desc.	Winding Way rain gauge reading- 0.00"	Pic 2 Desc.	Row vegetation		
 <p>Date & Time: Thu, Jun 11, 2020 04:24:38 EDT Position: +037.309559° / -080.509583° (-224896.2ft) Altitude: 0ft (Error) Datum: WGS-84 Azimuth/Bearing: 338° N22W 4009mils True (±10°) Elevation Angle: -03.7° Horizon Angle: +03.7° Zoom: 1.0X Sta#11225+00- Rock channel</p>		 <p>Date & Time: Wed, Jun 10, 2020 19:55:06 EDT Position: +037.306544° / -080.510420° (-2076.0ft) Altitude: 1955ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 112° S48E 1991mils True (±10°) Elevation Angle: -08.9° Horizon Angle: -02.4° Zoom: 1.0X Sta#11190+00- Sensitive resource drainage feature, row ECD's on slope</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11225+00	Field Station#	11190+00		
Pic 3 Desc.	Rock channel & ECD's	Pic 4 Desc.	Drainage feature and ECD's		
 <p>Date & Time: Wed, Jun 10, 2020 10:47:14 EDT Position: +037.313522° / -080.4984° (-316.4ft) Altitude: 94ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 315° N45W 3400mils True (±10°) Elevation Angle: -09.0° Horizon Angle: +05.6° Zoom: 1.0X Sta#11184+00- CWD pipe and plunge pool</p>		 <p>Date & Time: Wed, Jun 10, 2020 10:44:16 EDT Position: +037.313522° / -080.4984° (-316.4ft) Altitude: 855ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 253° S23W 2428mils True (±10°) Elevation Angle: -25.7° Horizon Angle: -00.9° Zoom: 1.0X Sta#11172+70- Slope drain, CSF checks, sumps, & end treatment</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11184+00	Field Station#	11172+70		
Pic 5 Desc.	CWD pipe and plunge pool are in good condition	Pic 6 Desc.	Slope drain, checks, sump and end treatment		

A/E	124300137	Date/Time	6/11/2020 8:41 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/11/2020 8:41 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11778
Inspector	Chris Burns			Date/Time	6/11/2020 12:24 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Dry	Temperature (°F)	77.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/11/2020 12:24 PM	Report #	11778
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213 to MP 214.8. No issues were located. PPL crews were currently assessing controls and repairing/replacing as needed within this section during the inspection. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/11/2020 12:24 PM	Report #	
Pictures					
					
GPS Location	1		GPS Location	2	
Field Station#	11265+00		Field Station#	11286+00	
Pic 1 Desc.	Perimeter controls functional.		Pic 2 Desc.	Perimeter controls functional.	
					
GPS Location	3		GPS Location	4	
Field Station#	11292+80		Field Station#	11301+00	
Pic 3 Desc.	S-MM18 and controls.		Pic 4 Desc.	Section of RoW showing conditions and controls.	
					
GPS Location	5		GPS Location	6	
Field Station#	11327+85		Field Station#	11352+97	
Pic 5 Desc.	S-NN12 overview.		Pic 6 Desc.	W-NN11 and controls.	

A/E	124300137	Date/Time	6/11/2020 12:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/11/2020 12:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11783
Inspector	Jared Saunders			Date/Time	6/11/2020 2:42 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+67
State	VA	Inspection Area	Partial	Station End	11525+25
County	Giles	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Broad-Based Dip	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/11/2020 2:42 PM	Report #	11783
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. Checked rain gauges at Stevers Gap Road - 0.0, Catawba Road - 0.0, and Mount Tabor Road - 0.0.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/11/2020 2:42 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11507+00		Field Station#	11505+00	
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 2 Desc.	Clean water diversion pipe and clean water diversion berm in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	11489+00	
Pic 3 Desc.	RCE in place at Stevers Gap Road.		Pic 4 Desc.	Rain gauge at Stevers Gap Road reads 0.0.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11990+00	
Pic 5 Desc.	Rain gauge at Mount Tabor Road reads 0.0 inches.		Pic 6 Desc.	Rain gauge at Catawba Road reads 0.0 inches.	

A/E	124300137	Date/Time	6/11/2020 2:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/11/2020 2:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11785
Inspector	Garrett Barclay			Date/Time	6/11/2020 2:19 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+53
State	VA	Inspection Area	Partial	Station End	111582+00
County	Giles	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/11/2020 2:19 PM	Report #	11785
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 209 - MP 211 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/11/2020 2:19 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+1	
Pic 1 Desc.	.6" of rain recorded @ Buffalo Anklets		Pic 2 Desc.	.7" of rain recorded @ AR 234	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11081+00		Field Station#	11127+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11132+00		Field Station#	11136+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	6/11/2020 2:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/11/2020 2:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11803
Inspector	Chris Burns			Date/Time	6/12/2020 7:11 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+99
County	Montgomery	Ground	Dry	Temperature (°F)	79.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar Outlet Protection	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/12/2020 7:11 AM	Report #	11803
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.3 to MP 225.3. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/12/2020 7:11 AM	Report #	
Pictures					
<p>Date & Time: Fri Jun 12, 2020 08:22:11 EDT Position: +037 237052 / -080 359947 (+213.3ft) Altitude: 2099ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 151° S29E 2686mils True (+12.1) Elevation Angle: +02.3° Horizon Angle: +00.0° Zoom: 0.5x 11789+00</p> 		<p>Date & Time: Fri Jun 12, 2020 08:30:44 EDT Position: +037 237076 / -080 355361 (+149.3ft) Altitude: 2180ft (+45.6ft) Datum: WGS-84 Azimuth/Bearing: 072° N22E 1280mils True (+12.1) Elevation Angle: +02.7° Horizon Angle: +01.8° Zoom: 0.5x 11806+00</p> 			
GPS Location	1	GPS Location	2		
Field Station#	11789+00	Field Station#	11806+00		
Pic 1 Desc.	Section of restored RoW showing conditions and controls.		Pic 2 Desc.	Section of restored RoW showing conditions and controls.	
<p>Date & Time: Fri Jun 12, 2020 08:39:34 EDT Position: +037 294768 / -080 351824 (+10796.4ft) Altitude: 2221ft (+104.7ft) Datum: WGS-84 Azimuth/Bearing: 172° S04E 3093mils True (+12.1) Elevation Angle: +03.3° Horizon Angle: +01° Zoom: 0.5x 11826+00</p> 		<p>Date & Time: Fri Jun 12, 2020 08:50:01 EDT Position: +037 287613 / -080 348805 (+40.3ft) Altitude: 2109ft (+36.4ft) Datum: WGS-84 Azimuth/Bearing: 189° S09W 3360mils True (+12.1) Elevation Angle: +07.0° Horizon Angle: +02.9° Zoom: 0.5x 11849+00</p> 			
GPS Location	3	GPS Location	4		
Field Station#	11826+00	Field Station#	11849+00		
Pic 3 Desc.	Section of restored RoW showing conditions and controls.		Pic 4 Desc.	Section of restored RoW showing conditions and controls.	
<p>Date & Time: Fri Jun 12, 2020 08:55:29 EDT Position: +037 237051 / -080 346398 (+550.1ft) Altitude: 2185ft (+33.8ft) Datum: WGS-84 Azimuth/Bearing: 082° N38E 0676mils True (+12.1) Elevation Angle: +04.1° Horizon Angle: +03.8° Zoom: 1.5x P-KL2</p> 		<p>Date & Time: Fri Jun 12, 2020 09:10:07 EDT Position: +037 237483 / -080 336874 (+36.8ft) Altitude: 2222ft (+33.8ft) Datum: WGS-84 Azimuth/Bearing: 085° N85E 1511mils True (+12.1) Elevation Angle: +03.7° Horizon Angle: +03.5° Zoom: 0.5x 11891+00</p> 			
GPS Location	5	GPS Location	6		
Field Station#	11863+65	Field Station#	11891+00		
Pic 5 Desc.	Section of restored RoW showing conditions and controls.		Pic 6 Desc.	Section of restored RoW showing conditions and controls.	

A/E	124300137	Date/Time	6/12/2020 7:11 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/12/2020 7:11 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11812
Inspector	Rob Robertson			Date/Time	6/12/2020 12:51 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Dry	Temperature (°F)	74.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/12/2020 12:51 PM	Report #	11812
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a routine VADEQ SWPPP inspection on private and JNF properties at Brush Mountain. The ROW in the area is currently stable with dry conditions. No rilling or other forms of erosion were located. No slips or movement of soils were found. Erosion controls are in place and in good condition. Resource buffers are stable with adequate controls in place to prevent impact. Runoff is being controlled with slope breakers and end treatments. No environmental concerns were identified.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/12/2020 12:51 PM	Report #	
Pictures					
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11663+00	Field Station#	11663+00		
Pic 1 Desc.	ROW is currently stable.	Pic 2 Desc.	End treatments were checked and found functional and in good condition.		
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11650+00	Field Station#	11636+00		
Pic 3 Desc.	ROW is currently stable. ECDs are in place and functioning as designed.	Pic 4 Desc.	Sumps and end treatments have worked to control runoff and sediment transport.		
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11628+00	Field Station#	11626+04		
Pic 5 Desc.	Perimeter controls in place and in good condition.	Pic 6 Desc.	Resource crossing S-HH18 is stable. ECDs in place. No impact.		

AFE	124300137	Date/Time	6/12/2020 12:51 PM	Report #	
Pictures					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11614+20	Field Station#	11607+81		
Pic 7 Desc.	Resource crossing S-RR14 crossing stable. ECDs in place and in good condition.	Pic 8 Desc.	Resource crossing S-006 is stable with ECDs in place.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	6/12/2020 12:51 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11814
Inspector	Garrett Barclay			Date/Time	6/12/2020 1:19 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/12/2020 1:19 PM	Report #	11814
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 218 - MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/12/2020 1:19 PM	Report #	
Pictures					
 <p>Date & Time: Fri, Jun 12, 2020, 09:18:20 EDT Position: +037.310227° / -080.411935° (±3269.2ft) Altitude: 2605ft (±58.5ft) Datum: WGS-84 Azimuth/Bearing: 154° 52'4E 2773mils True (±10°) Elevation Angle: -34.8° Horizon Angle: +03.4° Zoom: 1.0X 11532</p>		 <p>Date & Time: Fri, Jun 12, 2020, 09:58:19 EDT Position: +037.310227° / -080.411935° (±3269.2ft) Altitude: 2605ft (±58.5ft) Datum: WGS-84 Azimuth/Bearing: 154° 52'4E 2773mils True (±10°) Elevation Angle: -34.8° Horizon Angle: +03.4° Zoom: 1.0X 11552</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11532+00		Field Station#	11552+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
 <p>Date & Time: Fri, Jun 12, 2020, 09:53:57 EDT Position: +037.310227° / -080.411935° (±3269.2ft) Altitude: 2605ft (±58.5ft) Datum: WGS-84 Azimuth/Bearing: 154° 52'4E 2773mils True (±10°) Elevation Angle: -34.8° Horizon Angle: +03.4° Zoom: 1.0X 11569pp22</p>		 <p>Date & Time: Fri, Jun 12, 2020, 09:54:28 EDT Position: +037.310227° / -080.411935° (±3269.2ft) Altitude: 2605ft (±58.5ft) Datum: WGS-84 Azimuth/Bearing: 154° 52'4E 2773mils True (±10°) Elevation Angle: -34.8° Horizon Angle: +03.4° Zoom: 1.0X 11569pp22</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11569+00		Field Station#	11569+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
 <p>Date & Time: Fri, Jun 12, 2020, 10:07:29 EDT Position: +037.310227° / -080.411935° (±3269.2ft) Altitude: 2605ft (±58.5ft) Datum: WGS-84 Azimuth/Bearing: 172° 50'8E 3358mils True (±10°) Elevation Angle: -25.1° Horizon Angle: +03.9° Zoom: 1.0X 11584</p>		 <p>Date & Time: Fri, Jun 12, 2020, 10:09:43 EDT Position: +037.310227° / -080.411935° (±3269.2ft) Altitude: 2605ft (±58.5ft) Datum: WGS-84 Azimuth/Bearing: 225° 52'4W 5244mils True (±10°) Elevation Angle: -10.1° Horizon Angle: +05.0° Zoom: 1.0X 11588</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11584+00		Field Station#	11588+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	6/12/2020 1:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/12/2020 1:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11816
Inspector	Len Kruizenga			Date/Time	6/12/2020 1:20 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	67.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Broad-Based Dip	Acceptable			
Rock Check Dam	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/12/2020 1:20 PM	Report #	11816
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11999+00 to 12005+00. MP-225.3 to 227.3 The row is dry and in stable condition. The perimeter controls, Silt fence, CFS, SSF are in acceptable condition. Water bars and level spreaders are in good condition. Karst ECD's are in acceptable condition. Wetland is in acceptable condition. AR-266.03 and AR-266.00 are maintained in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/12/2020 1:20 PM	Report #	
Pictures					
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11971+00	Field Station#	11957+00		
Pic 1 Desc.	Row vegetation	Pic 2 Desc.	Row vegetation		
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11938+00	Field Station#	11904+00		
Pic 3 Desc.	Row vegetation	Pic 4 Desc.	P1 perimeter controls		
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11951+25	Field Station#	12001+00		
Pic 5 Desc.	Row vegetation and controls.	Pic 6 Desc.	Wetland ECD's		

A/E	124300137	Date/Time	6/12/2020 1:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/12/2020 1:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11818
Inspector	Jared Saunders			Date/Time	6/12/2020 3:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/12/2020 3:25 PM	Report #	11818
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/12/2020 3:25 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11687+40		Field Station#	11704+00	
Pic 1 Desc.	Sensitive resource buffer in place at stream S-MN21.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-MN22.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11718+00		Field Station#	11767+00	
Pic 3 Desc.	ROW stabilized with mulch. Waterbars in place.		Pic 4 Desc.	RCE in place at Main Line Valve 26.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11776+00		Field Station#	11778+00	
Pic 5 Desc.	Reinforced super silt fence in place along LOD.		Pic 6 Desc.	Clean water diversion pipe and plunge pool in place.	

A/E	124300137	Date/Time	6/12/2020 3:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/12/2020 3:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		