



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12821
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	7/20/2020 8:14 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	92.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 8:14 AM	<b>Report #</b>	12821
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.78 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300137		Date/Time		7/20/2020 8:14 AM		Report #							
Pictures															
<p>Date &amp; Time: Mon Jul 20, 2020 08:48:59 EDT Position: +037.06484° / -080.550459° (-13385.00) Altitude: 1858ft (+165.5ft) Datum: WGS-84 Azimuth/Bearing: 011° N11E 0.96mils True (+13) Elevation Angle: -02.5° Horizon Angle: -00.0° Zoom: 0.5X S-IJ18</p> 								<p>Date &amp; Time: Mon Jul 20, 2020 08:53:07 EDT Position: +037.121224° / -080.550980° (-1336.1th) Altitude: 2374ft (+113.7th) Datum: WGS-84 Azimuth/Bearing: 153° S27E 2720mils True (+12) Elevation Angle: -00.5° Horizon Angle: -00.2° Zoom: 0.5X 11034+00</p> 							
GPS Location				1				GPS Location				2			
Field Station#				11025+50				Field Station#				11034+00			
Pic 1 Desc.				S-IJ18.				Pic 2 Desc.				Section of RoW showing conditions and controls.			
<p>Date &amp; Time: Mon Jul 20, 2020 09:02:40 EDT Position: +037.110139° / -080.540086° (-137.1th) Altitude: 2124ft (+9.4ft) Datum: WGS-84 Azimuth/Bearing: 285° N74W 508mils True (+12.1) Elevation Angle: +03.2° Horizon Angle: -00.9° Zoom: 0.5X 11049+00</p> 								<p>Date &amp; Time: Mon Jul 20, 2020 09:10:16:40 EDT Position: +037.318106° / -080.540107° (-12154.00) Altitude: 2118ft (+5.1ft) Datum: WGS-84 Azimuth/Bearing: 033° N04E 860mils True (+11.7) Elevation Angle: +03.1° Horizon Angle: -02.9° Zoom: 0.5X S-IJ16B/S-IJ17</p> 							
GPS Location				3				GPS Location				4			
Field Station#				11049+00				Field Station#				11050+10			
Pic 3 Desc.				Section of RoW showing conditions and controls.				Pic 4 Desc.				S-IJ16B/S-IJ17 showing conditions and controls.			
<p>Date &amp; Time: Mon Jul 20, 2020 09:05:50 EDT Position: +037.308772° / -080.550502° (-13337.00) Altitude: 2092ft (+135.8ft) Datum: WGS-84 Azimuth/Bearing: 165° S14E 3531mils True (+12.1) Elevation Angle: +01.3° Horizon Angle: -00.1° Zoom: 0.5X 11055+00</p> 								<p>Date &amp; Time: Mon Jul 20, 2020 09:14:43 EDT Position: +037.315508° / -080.544139° (-1403.1th) Altitude: 2085ft (+103.0ft) Datum: WGS-84 Azimuth/Bearing: 310° N26W 350mils True (+15.7) Elevation Angle: +02.0° Horizon Angle: -00.2° Zoom: 1.0X 11064+50</p> 							
GPS Location				5				GPS Location				6			
Field Station#				11055+00				Field Station#				11064+50			
Pic 5 Desc.				Section of RoW showing conditions and controls.				Pic 6 Desc.				Section of RoW showing conditions and controls.			

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 8:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 8:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12834
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	7/20/2020 1:57 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	90.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 1:57 PM	<b>Report #</b>	12834
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	7/20/2020 1:57 PM	Report #	
Pictures					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00		<b>Field Station#</b>	10712+50	
<b>Pic 1 Desc.</b>	Compost filter sock checks in place along access road 241.04 bar ditch.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G33.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10711+00		<b>Field Station#</b>	10698+00	
<b>Pic 3 Desc.</b>	ROW is stabilized with natural vegetation.		<b>Pic 4 Desc.</b>	Sensitive resource buffer in place at stream S-G32.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10696+00		<b>Field Station#</b>	10670+00	
<b>Pic 5 Desc.</b>	RCE in place at Buffalo Anklets Road.		<b>Pic 6 Desc.</b>	Reinforced super silt fence in place along LOD.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 1:57 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 1:57 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12835
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	7/20/2020 2:16 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	91.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

MVP-34 REV 3 Page 2 of 5

<b>AFE</b>	124300137	<b>Date/Time</b>	7/20/2020 2:16 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, Jul 20, 2020, 09:26:35 EDT Position: +037.324041 / -089.554660 (-16.4ft) Altitude: 2697ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 336° N24W 373mils True (+10°) Elevation Angle: -11.4° Horizon Angle: +02.0° Zoom: 1.0X Stream S- IJ18- Equipment bridge, buffers &amp; ECD's</p>		 <p>Date &amp; Time: Mon, Jul 20, 2020, 09:34:19 EDT Position: +037.324041 / -089.554660 (-16.4ft) Altitude: 2697ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 286° N24W 508mils True (+10°) Elevation Angle: -08.8° Horizon Angle: +01.5° Zoom: 1.0X Stream S- RR5- Equipment bridge, buffers &amp; ECD's</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11018+00		
<b>Pic 1 Desc.</b>	Stream S- IJ18- Equipment bridge, buffers & ECD's.	<b>Pic 2 Desc.</b>	Row, stream S- RR5, ECD's.		
 <p>Date &amp; Time: Mon, Jul 20, 2020, 10:54:20 EDT Position: +037.324839 / -089.562884 (-98.4ft) Altitude: 2557ft (+78.7ft) Datum: WGS-84 Azimuth/Bearing: 315° N45W 540mils True (+10°) Elevation Angle: -13° Horizon Angle: +05.2° Zoom: 1.0X Stream S- E25- Steep slope</p>		 <p>Date &amp; Time: Mon, Jul 20, 2020, 10:06:01 EDT Position: +037.325819 / -089.564951 (-60.2ft) Altitude: 2472ft (+78.7ft) Datum: WGS-84 Azimuth/Bearing: 311° N49W 588mils True (+10°) Elevation Angle: -07.8° Horizon Angle: +03.6° Zoom: 1.0X Stream S- E24- bridge, ECD's, buffers</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10986+00	<b>Field Station#</b>	10985+00		
<b>Pic 3 Desc.</b>	Steep slope, stream S- E25	<b>Pic 4 Desc.</b>	Stream S- E24, bridge, ECD's, buffers.		
 <p>Date &amp; Time: Mon, Jul 20, 2020, 10:12:20 EDT Position: +037.327290 / -089.570819 (-32.8ft) Altitude: 2363ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 331° N29W 584mils True (+10°) Elevation Angle: -19.8° Horizon Angle: +01.6° Zoom: 1.0X Stream S- E24- Sensitive resource area</p>		 <p>Date &amp; Time: Mon, Jul 20, 2020, 10:26:39 EDT Position: +037.327290 / -089.570819 (-32.8ft) Altitude: 2363ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 295° N45W 524mils True (+10°) Elevation Angle: -12.7° Horizon Angle: +05.7° Zoom: 1.0X Stream S- E24- Doe Creek Farms continue to steep slope following cattle farm access to the row</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10967+00	<b>Field Station#</b>	10950+00		
<b>Pic 5 Desc.</b>	Sensitive resource area	<b>Pic 6 Desc.</b>	Open cattle gates on Doe Creek Farms row.		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 2:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 2:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12840
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	7/20/2020 2:37 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 2:37 PM	<b>Report #</b>	12840
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 205 - MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/20/2020 2:37 PM	Report #	
Pictures					
	 <p>Date &amp; Time: Mon Jul 20 2020 08:50:34 EDT Position: +037°20'13.62" / -080°35'13.62" (+19.4m) Altitude: 2229m (+11.3m) Datum: WGS 84 Azimuth: Bearing: 349 N20W 5920mils True (+12°) Elevation Grade: +04% Horizon Grade: +04% Zoom: 1.0X 10858</p>			 <p>Date &amp; Time: Mon Jul 20 2020 09:02:29 EDT Position: +037°20'13.62" / -080°35'13.62" (+19.4m) Altitude: 2229m (+11.3m) Datum: WGS 84 Azimuth: Bearing: 099 S81E 1824mils True (+12°) Elevation Grade: +022% Horizon Grade: +011% Zoom: 1.0X 10862</p>	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10858+00		<b>Field Station#</b>	10862+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
	 <p>Date &amp; Time: Mon Jul 20 2020 09:16:55 EDT Position: +037°20'13.62" / -080°35'13.62" (+19.4m) Altitude: 2229m (+11.3m) Datum: WGS 84 Azimuth: Bearing: 099 S81E 1824mils True (+12°) Elevation Grade: +00% Horizon Grade: +012% Zoom: 1.0X 10864</p>			 <p>Date &amp; Time: Mon Jul 20 2020 09:16:55 EDT Position: +037°20'13.62" / -080°35'13.62" (+19.4m) Altitude: 2229m (+11.3m) Datum: WGS 84 Azimuth: Bearing: 106 S74E 1884mils True (+12°) Elevation Grade: +030% Horizon Grade: +016% Zoom: 1.0X 10868</p>	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10864+00		<b>Field Station#</b>	10868+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
	 <p>Date &amp; Time: Mon Jul 20 2020 09:18:50 EDT Position: +037°20'13.62" / -080°35'13.62" (+19.4m) Altitude: 2229m (+11.3m) Datum: WGS 84 Azimuth: Bearing: 275 N55W 5244mils True (+16°) Elevation Grade: -04% Horizon Grade: -00% Zoom: 1.0X 10889</p>			 <p>Date &amp; Time: Mon Jul 20 2020 09:28:31 EDT Position: +037°20'13.62" / -080°35'13.62" (+19.4m) Altitude: 2229m (+11.3m) Datum: WGS 84 Azimuth: Bearing: 078 S89E 1800mils True (+12°) Elevation Grade: -018% Horizon Grade: -00% Zoom: 1.0X 10898</p>	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10889+00		<b>Field Station#</b>	10898+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	



<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 2:37 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/20/2020 2:37 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12854
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	7/21/2020 7:36 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 7:36 AM	<b>Report #</b>	12854
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213.16 to MP 215.03 as well as assessed AR 256.02. No major issues were located. Four locations of minor wildlife or weather impact to controls were identified and placed on the punch list. PPL Environmental Coordinator Mike Perry was notified. PPL crews made all repairs prior to the end of day. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 7:36 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11286+00	<b>Field Station#</b>	11292+80		
<b>Pic 1 Desc.</b>	Clear water diversion berm and temporary vegetation.	<b>Pic 2 Desc.</b>	S-MM18 and controls.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11308+00	<b>Field Station#</b>	11327+85		
<b>Pic 3 Desc.</b>	Perimeter controls functional.	<b>Pic 4 Desc.</b>	S-NN12 and controls.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11334+00	<b>Field Station#</b>	11352+97		
<b>Pic 5 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 6 Desc.</b>	S-NN11 and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 7:36 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 7:36 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12855
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	7/21/2020 8:42 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	95.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 8:42 AM	<b>Report #</b>	12855
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at Winding Way. SWPPP inspection: Sta#11254+99 to 11158+27. MP-213 to 211 The row remains very dry and in stable condition, row has been temporarily stabilized with seed and straw mulch. Perimeter controls, silt fence, CFS, SSF are in acceptable condition. Water bars, sump pits and triple stack CFS end treatment's are in acceptable condition. Sensitive resource, drainage feature ECD's are in acceptable condition. Slope drain pipes, CWD pipe and plunge pool are in acceptable condition. Rock channel is in acceptable condition. Access roads, Winding Way, AR-249.02, AR-249.01 are maintained in good condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/21/2020 8:42 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11227+00	<b>Field Station#</b>	11225+00		
<b>Pic 1 Desc.</b>	Row vegetation in this area is acceptable.	<b>Pic 2 Desc.</b>	Steep slope controls, slope drain, end treatment & rock channel.		
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11195+00	<b>Field Station#</b>	11194+00		
<b>Pic 3 Desc.</b>	Sump pit and triple stack end treatment	<b>Pic 4 Desc.</b>	SSF perimeter controls.		
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11191+00	<b>Field Station#</b>	11184+00		
<b>Pic 5 Desc.</b>	Sensitive resource, drainage feature	<b>Pic 6 Desc.</b>	CWD pipe and plunge pool.		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 8:42 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 8:42 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12869
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	7/21/2020 3:10 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+20
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+25
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	90.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 3:10 PM	<b>Report #</b>	12869
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 3:10 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Jul 21, 2020, 09:36:28 EDT Position: +037 324527 / -080 426428 (+178.8ft) Altitude: 2248ft (+225.7ft) Datum: WGS-84 Azimuth/Bearing: 320° N20W 588mits True (+15°) Elevation Angle: -14.6° Horizon Angle: -01.5° Zoom: 1.0X 11587+00</p>		 <p>Date &amp; Time: Tue, Jul 21, 2020, 09:36:12 EDT Position: +037 311534 / -080 426524 (+181.6 ft) Altitude: 2205ft (+44.8ft) Datum: WGS-84 Azimuth/Bearing: 253° S24W 449mits True (+13°) Elevation Angle: -10.3° Horizon Angle: -02.4° Zoom: 1.0X 11489+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11507+00		<b>Field Station#</b>	11489+00	
<b>Pic 1 Desc.</b>	Plunge pool and clean water diversion pipe in place.		<b>Pic 2 Desc.</b>	RCE in place at Stevers Gap Road.	
 <p>Date &amp; Time: Tue, Jul 21, 2020, 09:38:11 EDT Position: +037 324527 / -080 431742 (+178.3ft) Altitude: 2170ft (+42.7ft) Datum: WGS-84 Azimuth/Bearing: 165° S85W 328mits True (+13°) Elevation Angle: -07.3° Horizon Angle: -01.7° Zoom: 1.0X 11487+00</p>		 <p>Date &amp; Time: Tue, Jul 21, 2020, 09:43:33 EDT Position: +037 322610 / -080 434645 (+154.5ft) Altitude: 2257ft (+48.0ft) Datum: WGS-84 Azimuth/Bearing: 259° S79W 460mits True (+13°) Elevation Angle: -00.1° Horizon Angle: -02.8° Zoom: 1.0X 11477+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11487+00		<b>Field Station#</b>	11477+00	
<b>Pic 3 Desc.</b>	Rock lined over spill channel in place.		<b>Pic 4 Desc.</b>	Two tone stabilized with ECB and slope drain pipes in place.	
 <p>Date &amp; Time: Tue, Jul 21, 2020, 10:39:40 EDT Position: +037 318292 / -080 403936 (+153.4ft) Altitude: 2327ft (+111.3ft) Datum: WGS-84 Azimuth/Bearing: 313° N47W 556mits True (+13°) Elevation Angle: -23.8° Horizon Angle: -01.8° Zoom: 1.0X 11402+00</p>		 <p>Date &amp; Time: Tue, Jul 21, 2020, 10:40:18 EDT Position: +037 318765 / -080 403937 (+153.1ft) Altitude: 2300ft (+89.3ft) Datum: WGS-84 Azimuth/Bearing: 335° S34W 610mits True (+13°) Elevation Angle: -1.1° Horizon Angle: -00.7° Zoom: 1.0X 11380+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11402+00		<b>Field Station#</b>	11380+00	
<b>Pic 5 Desc.</b>	Rock lined channel in place over fill slope.		<b>Pic 6 Desc.</b>	Triple barrier ECDs in place at off ROW karst feature.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 3:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 3:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12870
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	7/21/2020 2:30 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 2:30 PM	<b>Report #</b>	12870
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 209 - MP 211 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/21/2020 2:30 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Jul 21, 2020 18:58:25 EDT Position: +37°18'54.33" / -80°23'10" (-118.94) Altitude: 11170 (+11.40) Datum: WGS-84 Azimuth/Bearing: 295 NWSW 526mils True (+15°) Elevation Grade: +024 Horizon Grade: +005 Zoom: 1.0X 11065</p>		 <p>Date &amp; Time: Tue, Jul 21, 2020 02:01:05 EDT Position: +37°18'54.25" / -80°23'12" (-118.93) Altitude: 11698 (+11.40) Datum: WGS-84 Azimuth/Bearing: 104 SWSW 1124mils True (+10°) Elevation Grade: +008X Horizon Grade: +024X Zoom: 1.0X 11072</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11065+00		<b>Field Station#</b>	11072+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
 <p>Date &amp; Time: Tue, Jul 21, 2020 18:46:43 EDT Position: +37°18'54.25" / -80°23'10.51" (-118.94) Altitude: 11170 (+11.40) Datum: WGS-84 Azimuth/Bearing: 295 NWSW 526mils True (+15°) Elevation Grade: +024 Horizon Grade: +005 Zoom: 1.0X 11079</p>		 <p>Date &amp; Time: Tue, Jul 21, 2020 02:04:43 EDT Position: +37°18'57.39" / -80°23'00.31" (-118.94) Altitude: 11564 (+11.40) Datum: WGS-84 Azimuth/Bearing: 289 N71W 518mils True (+13°) Elevation Grade: +022 Horizon Grade: +006X Zoom: 1.0X 11089</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11079+00		<b>Field Station#</b>	11089+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
 <p>Date &amp; Time: Tue, Jul 21, 2020 02:02:05 EDT Position: +37°18'54.25" / -80°23'14.22" (-118.94) Altitude: 11207 (+11.40) Datum: WGS-84 Azimuth/Bearing: 107 SWSW 1857mils True (+10°) Elevation Grade: +030 Horizon Grade: +000X Zoom: 1.0X 11120</p>		 <p>Date &amp; Time: Tue, Jul 21, 2020 02:04:07 EDT Position: +37°18'54.25" / -80°23'13.74" (-118.94) Altitude: 11210 (+11.40) Datum: WGS-84 Azimuth/Bearing: 107 NWSW 563mils True (+10°) Elevation Grade: +012 Horizon Grade: +009X Zoom: 1.0X 11142</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11120+00		<b>Field Station#</b>	11140+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 2:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/21/2020 2:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12897
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	7/22/2020 11:48 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 11:48 AM	<b>Report #</b>	12897
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.27 to MP 225.37 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 11:48 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11792+00	<b>Field Station#</b>	11827+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11848+00	<b>Field Station#</b>	11863+65		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	P-KL2 and controls.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11886+00	<b>Field Station#</b>	11899+00		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 11:48 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 11:48 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12904
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	7/22/2020 12:56 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 12:56 PM	<b>Report #</b>	12904
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a regular scheduled VADEQ SWPPP inspection on JNF and private property at Brush Mountain. The ROW is currently stable with no erosion occurring. Slope breakers and end treatments are working properly. No disturbance has occurred beyond the LOD. Perimeter controls are in place and functioning as designed. Resource buffers are well vegetated and stable. No visible impact noted at stream crossings. Diversion berms are intact. No slips have occurred. RCEs are in good condition. The S-RR14 crossing on access road 258.04 is stable with environmental controls in place. There is no visible evidence of trespass or vandalism.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/22/2020 12:56 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11669+75	<b>Field Station#</b>	11662+00		
<b>Pic 1 Desc.</b>	ROW stable at top of Brush Mountain	<b>Pic 2 Desc.</b>	Slope breakers in place and functional		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11661+00	<b>Field Station#</b>	11652+00		
<b>Pic 3 Desc.</b>	End treatments are working as designed	<b>Pic 4 Desc.</b>	Perimeter controls are in place and functional		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11647+00	<b>Field Station#</b>	11628+00		
<b>Pic 5 Desc.</b>	Perimeter controls are functional	<b>Pic 6 Desc.</b>	Perimeter controls are functional. ROW stable.		



<b>AFE</b>	124300137	<b>Date/Time</b>	7/22/2020 12:56 PM	<b>Report #</b>	
<b>Pictures</b>					
<p><small>Date &amp; Time: Wed, Jul 22, 2020, 10:35:51 EDT Position: +037.313981° / -080.398473° (±14.4ft) Altitude: 1941ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 278° N82W 4942mils Magnetic (±12°) Elevation Angle: -01.5° Horizon Angle: -01.4° Zoom: 1.0X Brush Mtn. S-HH18 crossing stable 11626+04</small></p> 		<p><small>Date &amp; Time: Wed, Jul 22, 2020, 10:41:48 EDT Position: +037.313607° / -080.402022° (±9.84ft) Altitude: 1885ft (±78.7ft) Datum: WGS-84 Azimuth/Bearing: 279° N81W 4940mils Magnetic (±12°) Elevation Angle: -02.2° Horizon Angle: -01.5° Zoom: 1.0X Brush Mtn. S-RR14 crossing stable</small></p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+20		
<b>Pic 7 Desc.</b>	S-HH18 crossing stable. ECDs in place.	<b>Pic 8 Desc.</b>	S-RR14 crossing stable. ECDs in place.		
<p><small>Date &amp; Time: Wed, Jul 22, 2020, 10:44:28 EDT Position: +037.313926° / -080.407623° (±14.4ft) Altitude: 1721ft (±22.2ft) Datum: WGS-84 Azimuth/Bearing: 088° N88W 11607+81 Magnetic (±13°) Elevation Angle: -05.6° Horizon Angle: -01.0° Zoom: 1.0X Brush Mtn. S-006 crossing stable</small></p> 		<p><small>Date &amp; Time: Wed, Jul 22, 2020, 10:47:08 EDT Position: +037.313629° / -080.408336° (±14.4ft) Altitude: 1800ft (±34.3ft) Datum: WGS-84 Azimuth/Bearing: 348° S48W 4830mils Magnetic (±13°) Elevation Angle: +00.8° Horizon Angle: -02.8° Zoom: 1.0X Brush Mtn. RRW stable 11606+00</small></p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11607+81	<b>Field Station#</b>	11606+00		
<b>Pic 9 Desc.</b>	S-006 buffers stable	<b>Pic 10 Desc.</b>	ROW currently stable		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 12:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12905
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	7/22/2020 1:32 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





AFE	124300137	Date/Time	7/22/2020 1:32 PM	Report #	
Pictures					
<p>Date &amp; Time: Wed, Jul 22, 2020, 08:51:49 EDT Position: +037.248957 / -080.320089 (+16.4ft) Altitude: +608ft (+19.8m) Datum: WGS-84 Azimuth/Bearing: 126.5545° (2260mils True ±10°) Elevation Angle: +20.7° Horizon Angle: +00.3° Zoom: 1.0X Catawba rain gauge reading - Trace amounts</p> 		<p>Date &amp; Time: Wed, Jul 22, 2020, 09:21:21 EDT Position: +037.261931 / -080.336000 (+32.8ft) Altitude: +262ft (+80.2m) Datum: WGS-84 Azimuth/Bearing: 312.5547mils True ±10° Elevation Angle: -20.2° Horizon Angle: +00.3° Zoom: 1.0X Sta#11901+00- AR-266.03- Access road &amp; GPS chart. Same in bar ditch</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11989+00	Field Station#	11901+00		
Pic 1 Desc.	Catawba rain gauge reading - Trace amounts	Pic 2 Desc.	AR- 266.03- Access road and bar ditch controls		
<p>Date &amp; Time: Wed, Jul 22, 2020, 09:45:01 EDT Position: +037.290137 / -080.327836 (+98.4ft) Altitude: +2308ft (+703.5m) Datum: WGS-84 Azimuth/Bearing: 152.5286° (2702mils True ±10°) Elevation Angle: -18.7° Horizon Angle: +03.3° Zoom: 1.0X Sta#11936+00- Row vegetation is very good.</p> 		<p>Date &amp; Time: Wed, Jul 22, 2020, 09:47:20 EDT Position: +037.279132 / -080.327836 (+98.4ft) Altitude: +2304ft (+701.0m) Datum: WGS-84 Azimuth/Bearing: 139° 55SW 4178mils True ±10° Elevation Angle: -68° Horizon Angle: +07.0° Zoom: 1.0X Sta#11942+00- Silt fence perimeter controls damaged</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11936+00	Field Station#	11941+00		
Pic 3 Desc.	Row vegetation is very good.	Pic 4 Desc.	Silt fence perimeter controls damaged.		
<p>Date &amp; Time: Wed, Jul 22, 2020, 09:58:26 EDT Position: +037.226012 / -080.326190 (+32.8ft) Altitude: +1957ft (+59.4m) Datum: WGS-84 Azimuth/Bearing: 215.555W 3822mils True ±10° Elevation Angle: -22.1° Horizon Angle: +07.0° Zoom: 1.0X Sta#11955+00- Level spreader vegetation</p> 		<p>Date &amp; Time: Wed, Jul 22, 2020, 10:14:45 EDT Position: +037.226012 / -080.322678 (+32.8ft) Altitude: +1951ft (+59.2m) Datum: WGS-84 Azimuth/Bearing: 307° N83W 3133mils True ±10° Elevation Angle: -16.5° Horizon Angle: +00.4° Zoom: 1.0X Sta#11979+00- Karst ECD's protection</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11955+00	Field Station#	11979+00		
Pic 5 Desc.	Level spreader and row vegetation.	Pic 6 Desc.	Karst ECD's protection.		

<b>AFE</b>	124300137	<b>Date/Time</b>	7/22/2020 1:32 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11985+00		<b>Field Station#</b>	11989+00	
<b>Pic 7 Desc.</b>	Drainage feature & ECD's.		<b>Pic 8 Desc.</b>	AR-266.00 RCE off Catawba road.	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 1:32 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12909
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	7/22/2020 3:02 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	90.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Rock Construction Entrance	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 3:02 PM	<b>Report #</b>	12909
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP. Rain gauge at Mount Tabor read 0.1 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 7/22/2020 3:02 PM		Report #	
Pictures					
 <p>Date &amp; Time: Wed Jul 22, 2020 09:48:54 EDT Position: +037 2927346 / +600 921638 (+120.5ft) Altitude: 2027ft (+66.3ft) Datum: WGS-84 Azimuth/Bearing: 100.580E 1778mils True (+13.1°) Elevation Angle: -17.0° Horizon Angle: -00.3° Zoom: 1.0X 11670+00</p>		 <p>Date &amp; Time: Wed Jul 22, 2020 09:48:54 EDT Position: +037 2927346 / +600 921638 (+120.5ft) Altitude: 2027ft (+66.3ft) Datum: WGS-84 Azimuth/Bearing: 177.503E 3147mils True (+12.1°) Elevation Angle: -17.9° Horizon Angle: +00.7° Zoom: 1.0X 11687+40</p>			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11670+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Triple stack compost filter sock and priority one silt in place along LOD.		<b>Pic 2 Desc.</b>	
				Sensitive resource buffer in place at stream S-MN21.	
 <p>Date &amp; Time: Wed Jul 22, 2020 11:06:55 EDT Position: +037 292164 / +600 36797 (+35.0ft) Altitude: 2020ft (+61.1ft) Datum: WGS-84 Azimuth/Bearing: 164.514E 2951mils True (+12.1°) Elevation Angle: -09.4° Horizon Angle: -01.0° Zoom: 1.0X 11719+00</p>		 <p>Date &amp; Time: Wed Jul 22, 2020 11:06:55 EDT Position: +037 292164 / +600 36797 (+35.0ft) Altitude: 2020ft (+61.1ft) Datum: WGS-84 Azimuth/Bearing: 164.514E 2951mils True (+12.1°) Elevation Angle: -09.4° Horizon Angle: -01.0° Zoom: 1.0X 11767+00</p>			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11719+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Top soil pile stabilized with seed and mulch after 3 party damages occurred.		<b>Pic 4 Desc.</b>	
				Rain gauge at Mount Tabor Road reads 0.1 inches.	
 <p>Date &amp; Time: Wed Jul 22, 2020 10:31:30 EDT Position: +037 292591 / +600 365998 (+213.3ft) Altitude: 2059ft (+62.0ft) Datum: WGS-84 Azimuth/Bearing: 079.779E 1404mils True (+13.8°) Elevation Angle: -01.9° Horizon Angle: +00.8° Zoom: 1.0X 11745+00</p>		 <p>Date &amp; Time: Wed Jul 22, 2020 11:31:50 EDT Position: +037 292164 / +600 36797 (+35.0ft) Altitude: 2020ft (+61.1ft) Datum: WGS-84 Azimuth/Bearing: 195.515W 3467mils True (+13.1°) Elevation Angle: -28.6° Horizon Angle: -00.8° Zoom: 1.0X 11772+00</p>			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11745+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Travel lane stabilized with mulch and seed after equipment completed repairs.		<b>Pic 6 Desc.</b>	
				Clean water diversion pipe and plunge pool in place.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 3:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 3:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12912
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	7/22/2020 3:02 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 3:02 PM	<b>Report #</b>	12912
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 218 - MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Gathered rain gauge amounts					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/22/2020 3:02 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	11530+00	<b>Field Station#</b>	11566+00	<b>Field Station#</b>	11585+00
<b>Pic 1 Desc.</b>	ECD's and row conditions	<b>Pic 2 Desc.</b>	ECD's and row conditions	<b>Pic 3 Desc.</b>	ECD's and row conditions
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	11585+00	<b>Field Station#</b>	11587+00	<b>Field Station#</b>	+1
<b>Pic 4 Desc.</b>	ECD's and row conditions	<b>Pic 5 Desc.</b>	.6" of rain recorded @ AR 244	<b>Pic 6 Desc.</b>	.4" of rain recorded @ AR Kow Camp

<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 3:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/22/2020 3:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12925
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	7/23/2020 8:17 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	No
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	No
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	Yes



<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 8:17 AM	<b>Report #</b>	12925
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at the work trailer. SWPPP inspection: Sta# 12005+00 LY-29 Rain gauge readings: Buffalo Anklets- 0.40" AR-234.00- 0.80" AR-238.00 serving LY-29 is maintained in acceptable condition. The rock surface of the yard is maintained in acceptable condition. The CFS triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. Waste management is acceptable. House keeping is acceptable.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/23/2020 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Jul 23, 2020, 10:56:50 EDT Position: +400.340200° / -800.650200° (±14.4m) Altitude: 12710 (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 130° 50'W 330mils True (±25°) Elevation Angle: -11.6° Horizon Angle: -00.0° Zoom: 1.0X Buffalo Anklets rain gauge reading: 0.40"</p>		<p>Date &amp; Time: Thu, Jul 23, 2020, 10:57:40 EDT Position: +400.340200° / -800.650200° (±14.4m) Altitude: 12710 (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 130° 50'W 330mils True (±25°) Elevation Angle: -11.6° Horizon Angle: -00.0° Zoom: 1.0X AR-234.00 rain gauge reading: 0.80"</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11671+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Buffalo Anklets rain gauge reading-0.40"	<b>Pic 2 Desc.</b>	AR-234.00 rain gauge reading- 0.80"		
<p>Date &amp; Time: Thu, Jul 23, 2020, 10:16:09 EDT Position: +400.340200° / -800.650200° (±14.4m) Altitude: 12690 (±13.2ft) Datum: WGS-84 Azimuth/Bearing: 243° 56'W 432mils True (±30°) Elevation Angle: -12.3° Horizon Angle: -02.3° Zoom: 1.0X LY-29- Materials storage</p>		<p>Date &amp; Time: Thu, Jul 23, 2020, 10:16:01 EDT Position: +400.340200° / -800.650200° (±14.4m) Altitude: 12690 (±13.2ft) Datum: WGS-84 Azimuth/Bearing: 130° 50'W 330mils True (±25°) Elevation Angle: -08.2° Horizon Angle: -04.0° Zoom: 1.0X LY-29- CFS triple stack perimeter controls.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY-29- Materials storage.	<b>Pic 4 Desc.</b>	LY-29- CFS triple stack perimeter controls.		
<p>Date &amp; Time: Thu, Jul 23, 2020, 10:16:02 EDT Position: +400.340200° / -800.650200° (±14.4m) Altitude: 12690 (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 255° 57'W 453mils True (±26°) Elevation Angle: -19.5° Horizon Angle: +06.5° Zoom: 1.0X LY-29- Culvert and drainage feature</p>		<p>Date &amp; Time: Thu, Jul 23, 2020, 10:17:06 EDT Position: +400.340200° / -800.650200° (±14.4m) Altitude: 12648 (±13.3ft) Datum: WGS-84 Azimuth/Bearing: 224° 54'W 398mils True (±26°) Elevation Angle: -08.3° Horizon Angle: +01.3° Zoom: 1.0X AR-238.00- Serving LY-29</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	LY-29- Culvert and drainage feature.	<b>Pic 6 Desc.</b>	AR-238.00 serving LY-29.		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12939
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	7/23/2020 2:44 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	86.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 2:44 PM	<b>Report #</b>	12939
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Mount Tabor Road - 0.1 inches and at Catawba Road - 0.1 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 7/23/2020 2:44 PM		Report #	
Pictures					
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		11990+00		Field Station#	
Pic 1 Desc.		Rain gauge at Catawba Road reads 0.1 inches.		Pic 2 Desc.	
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 3 Desc.		Secondary containment in place under fuel.		Pic 4 Desc.	
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 5 Desc.		RCE in place at Lay Down Yard 26 entrance.		Pic 6 Desc.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 2:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 2:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12942
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	7/23/2020 3:24 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Secondary Containment	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 3:24 PM	<b>Report #</b>	12942
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Gathered rain gauge amounts					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 3:24 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Jul 23, 2020, 05:49:10 EDT Position: +37°29'1.31" / -88°28'42.36" (±31.6m) Altitude: 2155ft (±61.1m) Datum: WGS-84 Azimuth/Bearing: 32° N47°W 313mils True (±13°) Elevation Grade: +010% Horizon Grade: +001% Zoom: 1.0X 3 kow</p>		 <p>Date &amp; Time: Thu, Jul 23, 2020, 05:49:10 EDT Position: +37°19'4.72" / -88°28'13.88" (±34.2m) Altitude: 2155ft (±29.8m) Datum: WGS-84 Azimuth/Bearing: 32° N47°W 313mils True (±13°) Elevation Grade: +000% Horizon Grade: +000% Zoom: 1.0X 3" 566</p>		<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	+1	<b>Field Station#</b>	+1	<b>Field Station#</b>	See picture above for GPS coordinates
<b>Pic 1 Desc.</b>	.3" of rain recorded @ Kow Camp	<b>Pic 2 Desc.</b>	.2" of rain recorded @ AR 244	<b>Pic 1 Desc.</b>	
 <p>Date &amp; Time: Thu, Jul 23, 2020, 05:49:10 EDT Position: +37°19'4.72" / -88°28'13.88" (±34.2m) Altitude: 2155ft (±29.8m) Datum: WGS-84 Azimuth/Bearing: 32° N47°W 313mils True (±13°) Elevation Grade: +000% Horizon Grade: +000% Zoom: 1.0X 1" 566</p>		 <p>Date &amp; Time: Thu, Jul 23, 2020, 05:49:10 EDT Position: +37°19'4.72" / -88°28'13.88" (±34.2m) Altitude: 2155ft (±29.8m) Datum: WGS-84 Azimuth/Bearing: 32° N47°W 313mils True (±13°) Elevation Grade: +000% Horizon Grade: +005% Zoom: 1.0X LDY 28</p>		<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	+1	<b>Field Station#</b>	1200+50	<b>Field Station#</b>	See picture above for GPS coordinates
<b>Pic 3 Desc.</b>	.1" of rain recorded @ Stevers gap	<b>Pic 4 Desc.</b>	ECD's and row conditions	<b>Pic 3 Desc.</b>	
 <p>Date &amp; Time: Thu, Jul 23, 2020, 05:49:10 EDT Position: +37°19'4.72" / -88°28'13.88" (±34.2m) Altitude: 2155ft (±29.8m) Datum: WGS-84 Azimuth/Bearing: 32° N47°W 313mils True (±13°) Elevation Grade: +021% Horizon Grade: +021% Zoom: 1.0X LDY 28</p>		 <p>Date &amp; Time: Thu, Jul 23, 2020, 05:49:10 EDT Position: +37°19'4.72" / -88°28'13.88" (±34.2m) Altitude: 2155ft (±29.8m) Datum: WGS-84 Azimuth/Bearing: 32° N47°W 313mils True (±13°) Elevation Grade: +000% Horizon Grade: +002% Zoom: 1.0X LDY 28</p>		<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00	<b>Field Station#</b>	See picture above for GPS coordinates
<b>Pic 5 Desc.</b>	Secondary containment	<b>Pic 6 Desc.</b>	ECD's and row conditions	<b>Pic 5 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 3:24 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/23/2020 3:24 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12954
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	7/24/2020 8:33 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.25
				<b>Rain Accumulation Time (days)</b>	1.00




1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 8:33 AM	<b>Report #</b>	12954
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection:Sta#11023+88 to 10930+00. MP- 208.6 to 206.2 AR-244.00 rain gauge reading for this inspection area was- 0.25" The row was wet but remains in stable condition. Temporary stabilization is good vegetation is acceptable. Water bars are stable. Sump pits and end treatments are in acceptable condition. Perimeter controls, silt fence, CFS, SSF are in acceptable condition. Streams S- IJ18, S-RR5, S-E24, S-E25 are in good condition, Bridges, buffers, ECD's are in acceptable condition. AR-244 is showing erosion from recent rain events, Doe Creek RCE is in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/24/2020 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Jul 24, 2020, 10:15:20 EDT Position: +037.322505° / -080.554915° (+32.40ft) Altitude: 2324ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 137° 54SE 3076mils True (+10°) Elevation Angle: -23.2° Horizon Angle: -00.2° Zoom: 1.0X AR-244.00- rain gauge reading 0.25"</p>		 <p>Date &amp; Time: Fri, Jul 24, 2020, 10:21:19 EDT Position: +037.322505° / -080.553270° (+32.40ft) Altitude: 2324ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 173° 507E 3076mils True (+10°) Elevation Angle: -23.2° Horizon Angle: -00.2° Zoom: 1.0X Stream S-IJ18- AR-244.00- Bridge, buffers, ECD's signage</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11024+00		
<b>Pic 1 Desc.</b>	AR-244.00 rain gauge reading - 0.25"	<b>Pic 2 Desc.</b>	Stream S- IJ18- Equipment bridge, ECD's, buffers.		
 <p>Date &amp; Time: Fri, Jul 24, 2020, 10:28:29 EDT Position: +037.322505° / -080.554915° (+32.40ft) Altitude: 2410ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 235° N72W 5120mils True (+10°) Elevation Angle: -03.8° Horizon Angle: +01.6° Zoom: 1.0X Stream S-RR5- Bridge, buffers, ECD's signage</p>		 <p>Date &amp; Time: Fri, Jul 24, 2020, 10:52:08 EDT Position: +037.325322° / -080.564460° (+32.40ft) Altitude: 2393ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 308° N82W 5476mils True (+10°) Elevation Angle: -23.8° Horizon Angle: -03.8° Zoom: 1.0X Stream S-E25- Bridge, buffers, ECD's signage</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11017+00	<b>Field Station#</b>	10986+00		
<b>Pic 3 Desc.</b>	Stream S- RR5- Equipment bridge, ECD's, buffers.	<b>Pic 4 Desc.</b>	Stream S- E25- Equipment bridge, buffers, ECD's		
 <p>Date &amp; Time: Fri, Jul 24, 2020, 10:54:00 EDT Position: +037.325409° / -080.564972° (+32.40ft) Altitude: 2369ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 314° N42W 5382mils True (+10°) Elevation Angle: -11.9° Horizon Angle: +06.3° Zoom: 1.0X Stream S-E24- Bridge, buffers, ECD's signage</p>		 <p>Date &amp; Time: Fri, Jul 24, 2020, 11:01:39 EDT Position: +037.325811° / -080.565000° (+32.40ft) Altitude: 2369ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 306° N42W 5403mils True (+10°) Elevation Angle: -11.3° Horizon Angle: +07.9° Zoom: 1.0X Silt fence protection for off row water source crossing row.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10985+00	<b>Field Station#</b>	10977+00		
<b>Pic 5 Desc.</b>	Stream S- E24- Equipment bridge, buffers, ECD's.	<b>Pic 6 Desc.</b>	Silt fence protection for off row water source crossing row.		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12969
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	7/24/2020 2:44 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 2:44 PM	<b>Report #</b>	12969
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Mount Tabor Road - 0.2 inches, Buffalo Anklets Road - 0.2 inches and AR 234 - 0.3 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/24/2020 2:44 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri Jul 24, 2020 10:17:41 EDT Position: +037.349144, -080.613218, ±0.078 1m Altitude: 2310ft (±75.5m) Datum: WGS-84 Azimuth/Bearing: 096.584E 1707mils True (±13.1) Elevation Angle: -10.3 Horizon Angle: -03.5 Zoom: 1.0X 10712+50</p>		 <p>Date &amp; Time: Fri Jul 24, 2020 10:38:00 EDT Position: +037.349144, -080.613218, ±0.078 1m Altitude: 2310ft (±75.5m) Datum: WGS-84 Azimuth/Bearing: 122.558E 1699mils True (±12.1) Elevation Angle: -02.6 Horizon Angle: -06.4 Zoom: 1.0X 10698+00 S-G32</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10712+50		<b>Field Station#</b>	10698+00	
<b>Pic 1 Desc.</b>	Sensitive resource buffer in place at stream S-G33.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G32.	
 <p>Date &amp; Time: Fri Jul 24, 2020 10:15:00 EDT Position: +037.349144, -080.613218, ±0.078 1m Altitude: 2063ft (±10.9m) Datum: WGS-84 Azimuth/Bearing: 198.518W 3520mils True (±10.1) Elevation Angle: -04.3 Horizon Angle: -01.5 Zoom: 1.0X 10696+00</p>		 <p>Date &amp; Time: Fri Jul 24, 2020 10:16:00 EDT Position: +037.349263, -080.652852, ±0.15 4m Altitude: 2056ft (±11.2m) Datum: WGS-84 Azimuth/Bearing: 113.547E 2009mils True (±10.1) Elevation Angle: -08.5 Horizon Angle: -02.5 Zoom: 1.0X 10696+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10696+00		<b>Field Station#</b>	10696+00	
<b>Pic 3 Desc.</b>	Rain gauge at Buffalo Anklets Road reads 0.2 inches.		<b>Pic 4 Desc.</b>	RCE in place at Buffalo Anklets Road.	
 <p>Date &amp; Time: Fri Jul 24, 2020 10:15:00 EDT Position: +037.349144, -080.613218, ±0.078 1m Altitude: 1253ft (±38.1m) Datum: WGS-84 Azimuth/Bearing: 101.572E 1702mils True (±10.1) Elevation Angle: -12.1 Horizon Angle: -00.4 Zoom: 1.0X 12005+00</p>		 <p>Date &amp; Time: Fri Jul 24, 2020 10:15:00 EDT Position: +037.349144, -080.613218, ±0.078 1m Altitude: 2015ft (±42.0m) Datum: WGS-84 Azimuth/Bearing: 032.132E 0569mils True (±12.1) Elevation Angle: -02.2 Horizon Angle: -02.3 Zoom: 1.0X 11767+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	11767+00	
<b>Pic 5 Desc.</b>	Rain gauge at Access Road 234 reads 0.3 inches.		<b>Pic 6 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.2 inches.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 2:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 2:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12974
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	7/24/2020 3:37 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.25
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 3:37 PM	<b>Report #</b>	12974
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.78 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 3:37 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11025+50		
<b>Pic 1 Desc.</b>	Perimeter controls functional.		<b>Pic 2 Desc.</b>	S-IJ18 and controls.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11034+00	<b>Field Station#</b>	11050+10		
<b>Pic 3 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	S-IJ16B/S-IJ17 and controls.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11055+00	<b>Field Station#</b>	11064+50		
<b>Pic 5 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 3:37 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 3:37 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12978
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	7/24/2020 2:55 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 2:55 PM	<b>Report #</b>	12978
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 205 - MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Gathered rain gauge amounts					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/24/2020 2:55 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	10858+00	<b>Field Station#</b>	10866+00	<b>Field Station#</b>	10883+00
<b>Pic 1 Desc.</b>	ECD's and row conditions	<b>Pic 2 Desc.</b>	ECD's and row conditions	<b>Pic 3 Desc.</b>	ECD's and row conditions
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	10883+00	<b>Field Station#</b>	10880+00	<b>Field Station#</b>	10898+00
<b>Pic 3 Desc.</b>	ECD's and row conditions	<b>Pic 4 Desc.</b>	ECD's and row conditions	<b>Pic 5 Desc.</b>	ECD's and row conditions
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	10898+00	<b>Field Station#</b>	10920+00	<b>Field Station#</b>	10920+00
<b>Pic 5 Desc.</b>	ECD's and row conditions	<b>Pic 6 Desc.</b>	ECD's and row conditions	<b>Pic 5 Desc.</b>	ECD's and row conditions

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 2:55 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/24/2020 2:55 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		